

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

27 May 2019

Attn: Motor Claim Department
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower
Singapore 068811

LIAN SENG COMPANY
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 22 May 2019 at Loyang Way at Entrance of 23 Loyang Way involving vehicle FBP1508M/SJK1643L.

Quotation for Repair Vehicle No: SJK1643L (Third Party Claim)

Quantity	List Item	Price
1	Tail Lamp LH	\$ 423.50
2	Tail Lamp Clip	\$ 11.00
1	Rear Bumper	\$ 729.55
1	Rear Bumper Reflector LH	\$ 69.30
2	Rear Bumper Side Retainer	\$ 282.00
6	Rear Bumper Clip	\$ 30.00
		<hr/>
		\$ 1,545.35
		Less 25%
		<hr/>
		\$ 386.34
		<hr/>
		\$ 1,159.01
	<u>S NETT</u>	
	Rear Bumper Sensor	\$ 220.00

Labour

1	To repair Rear Fender, Rear Panel, Back Door, remove & re-fix damaged parts and realign affected areas	\$ 550.00
2	To spray paint on affected area.	\$ 680.00
3	To remove and re-fix Rear Side Trim Board, Side Garnish and other attachment parts	\$ 80.00
4	To install Reverse Sensor and check water seepage	\$ 60.00
5	To rust proof affected area	\$ 30.00
		<hr/>
		Total Amount
		\$ 2,789.00
		<hr/>

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.

Thank you.

Yours Faithfully

Mr Wong

81122116