

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Photo Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GB6 9219S Yr Regn: 2017, NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna cc 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 54005 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEAT35Y10K 209335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155R15C Beesway

R: 155R15C Beesway

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____ D.O.I. 28/05/19

Survey held at Premium Carz

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TPAXA

LS \$5000.00 (Red = \$8136.45 / 62%)

MV: 59K

PV: 26.1K

Nett: 32.9K

Date/Time, File Pass to?

Date/Time, File Return to?

1) _____ 2) _____
3) _____ 4) _____
5) _____ 6) _____

Preli. Report: _____

Final Report: _____

Part Prices Check:

IN _____ OUT _____

Survey Fee:

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

Date:

| |
|--|
| |
| |
| |
| |

Date : 27/05/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Cecilia.

Our Customer : Ascend Com Pte Ltd

Vehicle No : GBG9219S

Model : Toyota Dyna 150 5MT

Manufacture Year : 2017

Date of Accident : 26/5/2019

Total Estimate Repair Days : 15

Total Pages : 2

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SJA3627Z

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-----------|---|-----|--------------------|---------------------|-----------------------|
| A. | Spare Parts | | | | |
| 1 | Front lining RH <i>Dented</i> | 1 | \$365.20 | \$365.20 | ✓ |
| 2 | Front fender mudflap RH <i>Neu</i> | 1 | \$68.00 | \$68.00 | + |
| 3 | Front fender centre RH <i>Dented</i> | 1 | \$180.00 | \$180.00 | ✓ |
| 4 | Radiator spare tank w/cap <i>Dented</i> | 1 | \$178.00 | \$178.00 | ✓ |
| 5 | Air filter housing <i>Touchid</i> | 1 | \$675.00 | \$675.00 | ✓ |
| 6 | Fuel tank <i>Dented</i> | 1 | \$925.00 | \$925.00 | ✓ |
| 7 | Fuel tank cap <i>Neu</i> | 1 | \$78.00 | \$78.00 | + |
| 8 | Fuel tank bracket - front <i>2 Bent</i> | 2 | \$190.00 | \$380.00 | <i>120 (SN)</i> |
| 9 | Fuel tank bracket - rear | 2 | \$90.00 | \$180.00 | <i>120 (SN)</i> |
| 10 | Exhaust tail pipe <i>Neu</i> | 1 | \$594.80 | \$594.80 | + |
| 11 | Exhaust mounting <i>Neu</i> | 2 | \$58.00 | \$116.00 | + |
| 12 | Exhaust bracket <i>Neu</i> | 2 | \$98.00 | \$196.00 | + |
| 13 | Tail gate stopper bracket RH <i>Bent</i> | 1 | \$183.20 | \$183.20 | ✓ |
| 14 | Tail gate stopper RH <i>cut</i> | 1 | \$121.60 | \$121.60 | <i>40 (SN)</i> |
| 15 | Rear fender RH <i>Bent Dented</i> | 1 | \$180.00 | \$180.00 | ✓ |
| 16 | Rear mudflap RH <i>Neu</i> | 1 | \$98.00 | \$98.00 | + |
| 17 | Rear axle <i>2 Neu</i> | 1 | \$3,785.80 | \$3,785.80 | + |
| 18 | Rear axle spring bush | 2 | \$68.00 | \$136.00 | + |
| | <i>2686.40 SW:280</i> | | Total | \$8,440.60 | |
| | <i>2014.80</i> | | Less 25% | \$2,110.15 | |
| | | | Sub Total 1 | \$6,330.45 | |
| B. | Spare Parts (S/Nett) | | | | |
| 1 | Deck bed complete <i>Repis</i> | 1 | \$3,500.00 | \$3,500.00 | + |
| 2 | Deck bed lower bracket RH <i>Neu Bent</i> | 1 | TBA | 80 TBA | + |
| 3 | Rear tyre RH <i>cut</i> | 2 | \$350.00 | \$700.00 | <i>150</i> |
| 4 | Rear rim RH <i>cut</i> | 2 | \$300.00 | \$600.00 | <i>280</i> |
| 5 | Reverse sensor (set) <i>Neu</i> | 1 | \$250.00 | \$250.00 | + |
| 6 | Diesel <i>Neu</i> | 60L | \$150.00 | \$150.00 | <i>50</i> |
| 7 | Coolant <i>Neu</i> | 1 | \$80.00 | \$80.00 | <i>40</i> |
| 8 | Rear bracket assy RH <i>Neu</i> | 1 | \$550.00 | \$550.00 | + |
| 9 | Rear box up - front door RH <i>Dented</i> | 1 | TBA | 1500 TBA | <i>1200</i> |
| 10 | Rear box up - rear door RH <i>Repis</i> | 1 | TBA | TBA | + |
| 11 | Rear box up - front pillar RH <i>Dented</i> | 1 | TBA | 1500 TBA | <i>800</i> + |

Repis

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|-------------------------|---|-----|---------------------|----------------|-----------------------|
| 12 | Rear box up - rear door pillar RH <i>Defect</i> | 1 | 1500 TBA | TBA | 860 |
| 13 | Rear box up lock RH <i>new</i> | 1 | TBA | TBA | 8 |
| 14 | Front fender lining clip <i>new</i> | 10 | \$5.00 | \$50.00 | 30 |
| <i>2580</i> Sub Total 2 | | | | \$5,880.00 | |
| Total for Parts | | | | \$12,210.45 | |
| C. Labour | | | | | |
| 1 | To check wiring. | | | \$120.00 | 30 |
| 2 | Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas. | | | 1000 TBA | 650 |
| 3 | Spray painting all affected parts & areas. | | | 1000 TBA | 500 |
| 4 | To remove and replace fuel tank. | | <i>1310</i> | \$250.00 | 80 |
| 5 | To remove and replace rear box up. | | | 500 TBA | x |
| 6 | To remove and replace exhaust silencer. | | | \$250.00 | x |
| 7 | To spray anti-rust undercoat. | | | \$150.00 | 50 |
| Total Labour | | | | \$770.00 | |
| Total Repair Cost | | | | \$12,980.45 | |

20360.45
20516.45

Supplementary : 60

Adair him, total 6244.8
L/S 28/05/19. H/S. 5K

07 Days. (SLC)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

| Surveyor's Details | |
|--------------------|---------------------------|
| Name | |
| Contact | |
| Survey Date | |
| Recommender | Authorize / Not Authorize |
| Before Paint | Yes / No |



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

Date : 28/5/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Ascend Com Pte Ltd
Vehicle No : GBG9219S
Model : Toyota Dyna 150 5MT
Manufacture Year : 2017
Date of Accident : 26/5/2019
Total Estimate Repair Days : 15
Total Pages : 1

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Re: Supplementary Repair Estimate For Third Party Claim against SJA3627Z

| No. | Item Descriptions | Qty | Unit Price | Amount | Remarks From Surveyor |
|---------------------------------|--|-----|------------|--------------------|-----------------------|
| A. | Spare Parts (S/Nett) | | | | |
| 1 | Sliding door rail front RH <i>Repair</i> | 1 | repair | repair | <i>X.</i> |
| 2 | Bracket stopper RH <i>Missing</i> | 1 | \$58.00 | \$58.00 | <i>30(SW)</i> |
| 3 | Bracket stopper RH rivet <i>New</i> | 2 | \$5.00 | \$10.00 | <i>✓</i> |
| 4 | Bracket reflector sticker RH <i>new</i> | 1 | \$68.00 | \$68.00 | <i>X</i> |
| 5 | Bracket aluminium plate rivet <i>new</i> | 4 | \$5.00 | \$20.00 | <i>✓</i> |
| Total Supplementary Repair Cost | | | | \$156.00 | |

Supplementary : 60(SW).

Yours faithfully,

Aun Teng

| Surveyor's Details | |
|--------------------|---------------------------|
| Name | |
| Contact | |
| Survey Date | |
| Recommender | Authorize / Not Authorize |

#13136.45

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Details | |
|-------------------------------|-------------------------|
| Owner ID Type: | Company |
| Owner ID: | 2692H |
| Vehicle Details | |
| Vehicle No.: | GBG9219S |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 28 May 2019 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | DYNA 150 5MT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2017 |
| Engine No.: | 1KD2758574 |
| Chassis No.: | JTFAT35Y10K209335 |
| Maximum Power Output: | - |
| Open Market Value: | \$27,084.00 |
| Original Registration Date: | 29 Nov 2017 |
| First Registration Date: | 29 Nov 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$1,355.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 28 Nov 2027 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$32,642.00 |
| COE Rebate Amount: | \$26,113.00 |
| Total Rebate Amount: | \$26,113.00 |

The information contained herein is correct as at 28 May 2019

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)





Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Up To 100% Loan. 1 Owner. Low Mileage With Records.



Original Paintwork. Fully Serviced By Hitachi Capital Since Day 1. Not A PHV.
SKL Automobile StarAd

















HIN LUNG AUTO
Ho Bee Group





One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars







30 years
of car sale


Browse by Category  [Save Search](#) [Print](#) [Sort by Date Posted](#)  20 results/page 

8 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)




Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status 

| Search Selection | toyota dyna | Any | Any | 2017 | Any | Any | Any | Available |
|---|---|----------|--------------|-------------|----------|-----------|-------|-----------|
|  | <input type="checkbox"/> Toyota Dyna Dump Fuel Type: Diesel | \$88,000 | \$11,390 /yr | 16-Feb-2017 | 4,009 cc | 3,000 km | Truck | Available |
| ★ Posted: 31-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel Excellent Condition, Seldom Driven, \$15k Per Year. Good Mileage. Sale Without Canopy. | \$59,500 | \$7,570 /yr | 05-Apr-2017 | 2,982 cc | 30,000 km | Truck | Available |
| ★ Posted: 18-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel June 2017 Registered. Toyota Dyna Euro 6 Diesel. | \$61,000 | \$7,570 /yr | 16-Jun-2017 | 2,982 cc | 78,500 km | Truck | Available |
| ★ Posted: 26-Apr-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel Original Condition, Still Under Borneo Warranty, Full Loan Trade In Welcome. Call Us Now For Viewing! ABWIN (1994) Pte Ltd | \$62,800 | \$7,750 /yr | 03-Jul-2017 | 2,982 cc | 33,800 km | Truck | Available |
| ★ Posted: 14-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |


 Car Buying  Car Selling  Car Ownership
 Car Aftermarket  On The Move  Lifestyle



Buying a pre-owned car, but Unsure of its Condition?
Get STA Car Evaluation

| | | | | | | | | |
|---|---|----------|-------------|-------------|----------|-----------|-------|-----------|
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel Almost New Condition! Still Under Warranty! Most Reliable Lorry In The Market. One Meticulous Owner That Takes Excellent Care. Retractable Side Mirror Option. Euro 6 Engine. No Admin Charges For Full ... ABWIN (1994) Pte Ltd | \$59,800 | \$7,310 /yr | 02-Aug-2017 | 2,982 cc | 21,650 km | Truck | Available |
| ★ Posted: 27-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel One Owner, Still Under Warranty! Most Reliable Lorry In The Market. Feel Free To Call Our Friendly Sales To Arrange For Viewing. | \$59,800 | \$7,270 /yr | 17-Aug-2017 | 2,982 cc | 57,000 km | Truck | Available |
| ★ Posted: 26-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |
|  | <input type="checkbox"/> Toyota Dyna 150 3.0M Fuel Type: Diesel Cheapest In Town, Price Negotiable, No Need Repair, Still Under Warranty, Flexible In House Finance, Super High Trade In, Call Now! ABWIN Bus Pte Ltd | \$57,800 | \$6,800 /yr | 27-Nov-2017 | 2,982 cc | 7,689 km | Truck | Available |
| ★ Posted: 10-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota | | | | | | | | |

SHORTLISTED HISTORY

[Compare](#) 

| | | | | | | | |
|--|----------|-------------|-------------|----------|---|-------|-----------|
| <input type="checkbox"/> Toyota Dyna 150 3.0M | \$63,838 | \$7,430 /yr | 27-Dec-2017 | 2,982 cc | - | Truck | Available |
|--|----------|-------------|-------------|----------|---|-------|-----------|



Fuel Type: Diesel

Owner One Toyota Dyna 150 Diesel, Well Taken Care By Owner, Beautiful Condition, 5x Free Servicing. Serious Offers Will Be Considered, High Trade In Welcome! 100% In House Loan Available.



Posted: 07-May-2019 Tags: 2017 Toyota Dyna, 2017 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CQE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota dyna, toyota dyna Singapore, used toyota dyna Singapore, used vehicles Singapore or even buy used toyota dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CQE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel: 6636 9100 Fax: 6636 9113

SATISFACTION VOUCHER

Our ref.: 0385/GBG92495/TP/PC/0519

To : AXA Insurance Pte Ltd

ACCIDENT INVOLVING GBG92495 AND SJA36277 ON 26/5/2019
ALONG JUNCTION BETWEEN THANNERY ROAD & GENTING ROAD

I/We hereby acknowledge having received from Premium Carz Services Pte Ltd, 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883, my/our vehicle number GBG92495 which has been repaired to my/our satisfaction and acceptance. I/We admit that the payment of *SGD _____ account for such repairs is in full discharge of my/our claim.

Dated : 1 day of June 2019

Signature :



Owners' name: Ascend Com Pte Ltd

NRIC/Co. Reg.: 1A9802692H

Address : 12 Long Baker Bate
#07-10/11
Singapore 348745

(*Based on final settlement from insurance)

Premium Carz Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

LETTER OF AUTHORITY AND INDEMNITY

ACCIDENT INVOLVING VEHICLE NO. GBG92495 AND SJA36277
AT/ALONG JUNCTION BETWEEN TANNERY ROAD & GENTING ROAD
ON 26 DAY MAY MONTH 2019 YEAR

- I/We, the owner of vehicle no. GBG92495 hereby instruct and authorize you to commence repair to the said vehicles.
- You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment are given by me/us with respect to the conduct of my/our claims against third party driver and/or his insurers including if necessary, to commence legal proceedings in Court in my/our name against the third party.
- You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit. Upon settlement of my claim, you are authorized to sign any Discharge Voucher or any document to confirm my acceptance of the settlement as full and final discharge of my claim, on my behalf.
- Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional cost and disbursements for acting for me/us and to relieve payment of the balance of the settlement sum on my/our behalf directly into your account.
- In the event that, I/we am/are required to attend at my/our solicitors' office or to attend court in connection to my/our claim, I/we shall render full co-operation.
- In the event that my/our claim against the third party and/or his insurers is Not successful or cannot be proceeded with, I/we authorized you to make a claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respects, I/we understand and accept that the excess amount applicable under the policy of insurance shall be borne by me/us. I/we shall also be personally liable to bear all legal cost incurred by you in claiming back for the repair cost by your Solicitors.
- If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any losses recoverable under the policy of insurance or make any offer to pay less than the amount claimed by you, I/we agree to undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
- I/we have read and understand the above statement and agreed.

Dated this 27 day May month 2019 year

Signature

Name

: Ascend Com Pte Ltd

NRIC/ROC No.

: 194802692H

Address

: 12 Lorong Bakar Batu

#07-10/11

Singapore 348745

Company Stamp



Service Request Details

Claim

S9M01OPJ

Reference

None 

Loss Date

26 May 2019

Report Date

27 May 2019 12:00:00 AM

Request Date

28 May 2019

Due Date

4 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

GBG9219S

P: Ann Ting

T: 10.07a.m

Y: 11

E: ✓

EX101121

DYNA 150-3.0 D (M)

Service Address

...

Primary Contact/Insured

CHEW PECK YAM

APT BLK 794 WOODLANDS DRIVE 72, #06-17, 730794, Singapore

98710795

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Aunteng <aunteng@premiumcarz.com.sg>
Sent: Monday, 27 May, 2019 4:38 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: Pre-repair inspection! Accident involving GBG9219S & SJA3627Z on 26/5/2019
Attachments: GBG9219S_GIA RPT.pdf

Categories: Raghav

Dear Officer-in-charge

Refer to the above matter.

Attached our client's accident report for you to create a third party file.

Your insured's vehicle is SJA3627Z.

Our client's vehicle is ready for survey.

A copy of estimate will be ready and made available to surveyor on site inspection at our workshop. Please indicate whether you are sending your surveyor to our workshop.

Please provide us a list of surveyors' of your choice for our selection.

Regards

Aun Teng

Premium Carz Services Pte Ltd

Tel: 6636 9100 Fax: 6636 9113

1 Kaki Bukit Avenue 6

#01-90 Autobay@Kaki Bukit

Singapore 417883



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 05/08/2019

Survey Details:

| | |
|---------------------|-------------------------------|
| Date of loss | 26-May-19 |
| Date of appointment | 28-May-19 |
| Date of survey | 28-May-19 |
| Location of survey | PREMIUM CARZ SERVICES PTE LTD |

Vehicle Details:

| | |
|----------------------|---------------------|
| Claim Type: | Third party |
| Vehicle number | GBG 9219S |
| Make and Model | TOYOTA DYNA 150 5MT |
| Date of registration | 29/11/2017 |
| Excess | |
| Market Value | \$59,000 |
| Parf Rebate | \$26,113 |
| Nett Loss | \$32,887 |

Repair details:

| | |
|------------------|--------------|
| Initial Estimate | \$ 13,136.45 |
|------------------|--------------|

Proposed/Revised repair cost:

| | |
|--------------------------------|--------------------|
| Parts | \$ 4,934.80 |
| Check items (estimate) | \$ - |
| Labour | \$ 1,310.00 |
| Total | \$ 6,244.80 |
| Lump Sum(if applicable) | \$ 5,000.00 |

| | |
|---------------------------|---|
| Number of days for repair | 7 |
|---------------------------|---|



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

| |
|--|
| |
|--|

Mandate:

| Liability(TP) | | 100% | |
|------------------------|----|----------|---------------|
| Proposed repair cost | \$ | 5,000.00 | |
| Loss of use | \$ | - | |
| Loss of rental (W/GST) | \$ | 535.00 | 5days x \$107 |
| Loss of income | \$ | - | no. of days |
| LTA search fees | \$ | 7.45 | |
| Others | \$ | - | |
| Proposed Total | \$ | 5,542.45 | |



<MANDATE IA> - S9M01OPJ {ACCIDENT INVOLVING SJA 3627Z(OI) & GBG 9219S(TP) ON 26/05/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S8 INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$5542.45 (CLAIMING LOR). MANDATE IA HAD BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



**Re:<MANDATE IA> - S9M01OPJ {ACCIDENT INVOLVING
SJA 3627Z(OI) & GBG 9219S(TP) ON 26/05/2019}**

Type

 Question

Message

pls proceed

Reply

Premium Carz
Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel: 6636 9100 Fax: 6636 9113

Date : 30/07/2019

Your Ref : SJA3627Z

Our Ref : 0385/GBG9219S/TP/PC/0519

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn : Motor Claims Dept.

Dear Sir/Madam

**ACCIDENT INVOLVING GBG9219S & SJA3627Z ON 26/05/2019 ALONG
JUNCTION BETWEEN TANNERY ROAD & GENTING ROAD**

We refer to the above accident.

The accident was caused solely by the negligence of your insured and as a result, we had incurred the following Costs and Losses: -

| | |
|-------------------------------------|---------------------------|
| Costs of Repair (Lump Sum) | \$ 5,000.00 |
| Rental Fee (5 days at \$192.60/day) | \$ 963.00 |
| LTA TP Search Fee | \$ 7.45 |
| Claimed Amount | <u>\$ 5,970.45</u> |

Enclosed are the supporting documents for your perusal:

1. Invoice 0385
2. Rental Tax Invoice/Agreement
3. LTA Tax Invoice/Receipt
4. Certificate of Insurance
5. Satisfaction Voucher
6. Letter of Authority and Indemnity
7. Letter of Authority

Please let us hear from you within the next 14 days.

Yours faithfully



PREMIUM CARZ SERVICES PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19009426/Agb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: STACEY NG

Date : 02-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|------------|----------------|------------|
| Insured Veh. | SJA 3627Z | Veh. Inspected | GBG 9219S |
| Policy No. | GA294799/1 | Coverage (\$) | 0.00 |
| Claim No. | S9M01OPJ | Excess (\$) | 0.00 |
| Assign From | STACEY NG | Assign Date | 28/05/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | TOYOTA DYNA | c.c | 2982 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | JTFAT35Y10K209335 | Colour | SILVER |
| Odometer | 54005 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|----------|---------|---------|
| R/H Front Tyre | 195 R15C | BEARWAY | 6 mm |
| L/H Front Tyre | 195 R15C | BEARWAY | 6 mm |
| R/H Rear Tyre | 155 R12C | BEARWAY | 6 mm |
| L/H Rear Tyre | 155 R12C | BEARWAY | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 26/05/2019 | Inspection Date | 28/05/2019 |
| Survey held at | PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 9219S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | FRONT LINING RH (CONSISTENT) | DEFORMED | 365.20 | 365.20 |
| 1 | FRONT FENDER MUDFLAP RH (CONSISTENT) | NOT NECESSARY | 68.00 | - |
| 1 | FRONT FENDER CENTRE RH (CONSISTENT) | DENTED | 180.00 | 180.00 |
| 1 | RADIATOR SPARE TANK W/CAP (CONSISTENT) | DEFORMED | 178.00 | 178.00 |
| 1 | AIR FILTER HOUSING (CONSISTENT) | CRACKED | 675.00 | 675.00 |
| 1 | FUEL TANK (CONSISTENT) | DENTED | 925.00 | 925.00 |
| 1 | FUEL TANK CAP (CONSISTENT) | NOT NECESSARY | 78.00 | - |
| 1 | EXHAUST TAIL PIPE (CONSISTENT) | NOT NECESSARY | 594.80 | - |
| 2 | EXHAUST MOUNTING @ \$58.00 (CONSISTENT) | NOT NECESSARY | 116.00 | - |
| 2 | EXHAUST BRACKET @ \$98.00 (CONSISTENT) | NOT NECESSARY | 196.00 | - |
| 1 | TAIL GATE STOPPER BRACKET RH (CONSISTENT) | BENT | 183.20 | 183.20 |
| 1 | REAR FENDER RH (CONSISTENT) | DENTED | 180.00 | 180.00 |
| 1 | REAR MUDFLAP RH (CONSISTENT) | NOT NECESSARY | 98.00 | - |
| 1 | REAR AXLE (CONSISTENT) | NOT NECESSARY | 3,785.80 | - |
| 2 | REAR AXLE SPRING BUSH @ \$68.00 (CONSISTENT) | NOT NECESSARY | 136.00 | - |
| | LESS 25% DISCOUNT | | -1,939.75 | -671.60 |
| | | | 5,819.25 | 2,014.80 |
| 2 | FUEL TANK BRACKET - FRONT @ \$190.00 (SN) (CONSISTENT) | BENT | 380.00 | 120.00 |
| 2 | FUEL TANK BRACKET - REAR @ \$90.00 (SN) (CONSISTENT) | BENT | 180.00 | 120.00 |
| 1 | TAIL GATE STOPPER RH (SN) (CONSISTENT) | CUT | 121.60 | 40.00 |
| | LESS 25% DISCOUNT | | -170.40 | - |
| | | | 511.20 | 280.00 |
| SPECIAL NETT ITEMS | | | | |
| 1 | DECK BED COMPLETE (SN) (CONSISTENT) | TO REPAIR SEE LABOUR | 3,500.00 | - |
| 1 | DECK BED LOWER BRACKET RH (SN) (CONSISTENT) | BENT | 80.00 | 80.00 |
| 2 | REAR TYRE RH @ \$350.00 (SN) (CONSISTENT) | CUT | 700.00 | 150.00 |
| 2 | REAR RIM RH @ \$300.00 (SN) (CONSISTENT) | CUT | 600.00 | 180.00 |

Report Ref No. CC4/ASM19009426/Agb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| 1 | SET REVERSE SENSOR (SN) (CONSISTENT) | NOT NECESSARY | 250.00 | - |
| 60 | L DIESEL (SN) (CONSISTENT) | NECESSARY | 150.00 | 50.00 |
| 1 | COOLANT (SN) (CONSISTENT) | NECESSARY | 80.00 | 40.00 |
| 1 | REAR BRACKET ASSY RH (SN) (CONSISTENT) | NOT NECESSARY | 550.00 | - |
| 1 | REAR BOX UP - FRONT DOOR RH (SN) (CONSISTENT) | DENTED | 1,800.00 | 1,200.00 |
| 1 | REAR BOX UP - REAR DOOR RH (NPA) (SN) (CONSISTENT) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR BOX UP - FRONT PILLAR RH (SN) (CONSISTENT) | TO REPAIR SEE LABOUR | 1,500.00 | - |
| 1 | REAR BOX UP - REAR PILLAR RH (SN) (CONSISTENT) | DENTED | 1,500.00 | 850.00 |
| 1 | REAR BOX UP LOCK RH (NPA) (SN) (CONSISTENT) | NOT NECESSARY | - | - |
| 10 | FRONT FENDER LINING CLIP @ \$5.00 (SN) (CONSISTENT) | NECESSARY | 50.00 | 30.00 |
| 1 | SLIDING DOOR RAIL FRONT RH (NPA) (SN) (CONSISTENT) (ADDITIONAL) | TO REPAIR SEE LABOUR | - | - |
| 1 | BRACKET STOPPER RH (SN) (CONSISTENT) (ADDITIONAL) | MISSING | 58.00 | 30.00 |
| 2 | BRACKET STOPPER RH RIVET @ \$5.00 (SN) (CONSISTENT) (ADDITIONAL) | NECESSARY | 10.00 | 10.00 |
| 1 | BRACKET REFLECTOR STICKER RH (SN) (CONSISTENT) (ADDITIONAL) | NOT NECESSARY | 68.00 | - |
| 4 | BRACKET ALUMINIUM PLATE RIVET @ \$5.00 (SN) (CONSISTENT) (ADDITIONAL) | NECESSARY | 20.00 | 20.00 |
| | | | 10,916.00 | 2,640.00 |
| | LABOUR | | | |
| | TO CHECK WIRING. | | 120.00 | 30.00 |
| | PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS. INCLUSIVE OF THE REPAIR OF DECK BED COMPLETE, REAR BOX UP - REAR DOOR RH, REAR BOX UP - FRONT PILLAR RH AND SLIDING DOOR RAIL FRONT RH. | | 1,000.00 | 650.00 |
| | SPRAY PAINTING ALL AFFECTED PARTS & AREAS. | | 1,000.00 | 500.00 |
| | TO REMOVE AND REPLACE FUEL TANK. | | 250.00 | 80.00 |
| | TO REMOVE AND REPLACE REAR BOX UP. | NOT NECESSARY | 500.00 | - |
| | TO REMOVE AND REPLACE EXHAUST SILENCER. | NOT NECESSARY | 250.00 | - |

Report Ref No. CC4/ASM19009426/Agb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|-------------------------------|-----------|---------------------------|-------------------|
| | TO SPRAY ANTI-RUST UNDERCOAT. | | 150.00 | 50.00 |
| | | | 3,270.00 | 1,310.00 |
| GRAND TOTAL | | | 20,516.45 | 6,244.80 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 5,000.00 |

Report Ref No. CC4/ASM19009426/Agb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.