



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE

SINGAPORE 038985

INV No. AC2006297
INV Date 14/09/2020
Reference CC4/EGI19009427/Kka3s2
Code EGI



PROFESSIONAL SERVICE FEE

Vehicle No. SFW 9669U
Insured Veh. YQ 6Z
Claim No. CDMCG19000969/SL/jc
Policy No. DMCV18S009990
Accident Date 13/05/2019
Inspection Date 27/05/2019

| Description | Total |
|---------------------|---------------|
| Survey Inspection | 250.00 |
| Resurvey Inspection | |
| Digital Photographs | |
| Transportation | |
| Subtotal | 250.00 |
| GST (7%) | 17.50 |
| Grand Total | 267.50 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC4/EGI19009427/Kka3s2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 14-09-2020



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|---------------------|----------------|------------|
| Insured Veh. | YQ 6Z | Veh. Inspected | SFW 9669U |
| Policy No. | DMCV18S009990 | Coverage (\$) | 0.00 |
| Claim No. | CDMCG19000969/SL/jc | Excess (\$) | 0.00 |
| Assign From | JEANNIE CHENG | Assign Date | 24/05/2019 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|----------------------|--------------|---------------|
| Make & Model | mitsubishi EVO X (M) | c.c | 1998 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | CZ4A0001083 | Colour | METALLIC BLUE |
| Odometer | 013768 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-------------|------|---------|
| R/H Front Tyre | 265/35 ZR18 | TOYO | 7 mm |
| L/H Front Tyre | 265/35 ZR18 | TOYO | 7 mm |
| R/H Rear Tyre | 265/35 ZR18 | TOYO | 7 mm |
| L/H Rear Tyre | 265/35 ZR18 | TOYO | 7 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 13/05/2019 | Inspection Date | 27/05/2019 |
| Survey held at | ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 9669U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|------------------------------------|---|-----------|----------------------------|-------------------|
| | LABOUR | | | |
| | SPRAY PAINTING ON ALL AFFECTED AREA. | | 400.00 | 360.00 |
| | LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. | | 350.00 | 180.00 |
| | | | 750.00 | 540.00 |
| | GRAND TOTAL | | 750.00 | 540.00 |
| RECOMMENDED COST OF REPAIRS | | | | 540.00 |

Report Ref No. CC4/EG19009427/Kka3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFW 9669U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFW 9669U

RE-INSPECTION

