

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

*Not Authorised
L1 Imp &?
Assembly After Paint
Today*

TIDAL CARS PTE LTD

c/o 46 Lenton Plain
Singapore 786548

Date: 28/5/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SJL 9498 G / TOYOTA ALTIS	
1 pc	rear bumper	MIT 459.80 ✓
10 pcs	rear bumper clips @ 5.50	MA 55.00 ✓
1 pc	rear bumper bracket	NLS MIT 110.90 ✓
2 pcs	rear bumper side retainer (a) @ 121.50	NLS D11 243.00 ✓
2 pcs	rear bumper side retainer (b) @ 73.80	NLS D11 147.60 ✓
2 pcs	rear bumper side retainer (c) @ 76.30	NLS CM 152.60 ✓
1 pc	rear bumper dust cover	SN 85.60 X
5 pcs	rear bumper dust cover clip @ 4.80	UN 24.00 X
1 pc	rear end panel	BN 483.90 ✓
1 pc	rear end panel garnish	SVC 318.50 X
1 pc	rear spare tyre board	CM 329.10 ✓
1 pc	rear bootlid	BN 638.10 ✓
1 pc	rear bootlid hinge	N 160.80 X
1 pc	rear boot lock	N 297.30 X
1 pc	rear boot lamp	BN 197.60 ✓
1 pc	rear weatherstrip	D11 308.90 ✓
1 pc	rear LOGO emblem	MA 96.30 ✓
1 pc	rear "1.6" emblem	MA 39.20 ✓
1 pc	rear "ALTIS" emblem	MA 48.30 ✓
1 pc	rear "COROLLA" emblem	MA 50.20 ✓
1 pc	rear "LX" emblem	MA 40.30 ✓
1 pc	rear boot moulding	SN 367.80 X
1 pcs	rear fender	BN 1,129.70 ✓
1 pcs	rear fender air vent	CM 181.80 ✓
1 pcs	rear fender inner trimboard	MA 308.70 ✓
8 pcs	rear fender inner trim clips @ 4.80	MA 38.40 ✓
2 pcs	taillamp clips @ 12.90	NLS MA 25.80 ✓
1 pc	taillamp	BN 281.45 ✓
1 pc	tailamp sealant	UN 50.00 X
1 pcs	rear windscreen moulding	MA 182.70 ✓
1 pc	rear door lock	N 385.7 X
	sub-total	7,239.05
	less 25%	1809.7625
	sub-total	5,429.29

balance brought forward			5,429.29	
rear windscreen sealant	s.nett	Mr 40sn	60.00	
rear windscreen inner seal	s.nett	Mr 30sn	50.00	
rear number plate	s.nett	sn	35.00	X
rear number plate housing	s.nett	sn	35.00	X
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.			900.00	✓
To check wiring system.			201 50.00	
To apply rust proofing on affected areas.			80.00	✓
To apply waterproof sealant on affected areas.			301 80.00	
To apply putty and spray painting on affected areas.			800.00	✓
To install reverse sensors and reverse camera.			501 100.00	
To remove rear windscreen glass to enable repair.			1201 150.00	
To remove carpet, trimming and seats to enable repair.			100.00	✓
Towing charges.			501 60.00	
	Total		7,929.29	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: