## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\*** 

VEHICLE NO

: SHC 809Z

: MERCEDES

MAKE

27. May. 2019 DATE:

**CHINA** 

EL	: E220 (E5)	DOA:	26. May. 2019	CHINA
Qty	Parts Description/ Labo	ur Type	Unit Price	Amount
	1 Front Fender – LH			\$996.10
	1 Wheel Rim Hub cap LH 🗶			\$130.50
	1 Wheel Rim – LH		- 2 - 55 - 5 - 7	\$1,250.00
	1 Front Door - LH XM.2			\$2,970.00
	1 Wheel Rim - LH / 1 Front Door - LH × 14.2 Rocker puel grail (LM) X	- M2		
	700.		33 37.4	
			1.47	ĆF 246 66
		SUB TOTAL		\$5,346.60
		LESS 20%		\$1,069.32
	DISCO	DUNTED TOTAL		\$4,277.28
	k	22/5/19 1410h 3 Rys.		\$
	Labour Charge	1 -1/2/2 /4/		300
	1 Panel Beating	34/2/4 1,100		\$600.00
	1 Spray Painting Charge	3 Porce		\$ 600.00
	1 Wiring Charge			\$50.00
	1Tuff Kote			\$100.00
	1 Front Wheel Alignment	After Rom pl		\$120.00
		TOTAL LABOUR		\$1,470.00
	E	STIMATE TOTAL		\$5,747.28
en ma			TIS heroe notify	
3/11		WK and Coreally	Cis heros	
		THE REPAIRE OF THE	arer scray painting arer scray painting resurvey	3/15
	This is an initial estimate based on a vis	sual inspection of the above ve	ehicle. The final repair of	quantum will

\* No please not be seen of the subject to less of the subject to les Acknowledged by Repairer Signature;