

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0680/2019/DY/TF
Date : 27-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SCW 8166 X**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Sim Kian Ann
Address : Blk 45 Marina Crescent
#15-36
Singapore 440045
Telephone : (HP) +65 97450599
Type of Claim : Third Party Claims
Policy No. : 2100483425-02
Vehicle No : **SJA 1989 S**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Sep-16
Engine No : CVN 016743
Chassis No : WAUZZZF47HA020454
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-May-19
Place of Accident : Upper Serangoon Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJA 1989 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Calibrate park assistance	S/N \$	280.00	✓
2	To dismantle and renew rear bumper and lower spoiler. Re-organise rear crash management components. Reinstall all parts removed.	\$	700.00	500
3	To respray rear bumper.	\$	700.00	550
4	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$	<u>1,872.00</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJA 1989 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>re-ltd</i>	\$ 2,422.00	✓ 1992.80
2	REAR BUMPER SECURING STRIP <i>Not Nec</i>	\$ 203.00	3x
3	REAR BUMPER SPOILER GRILLE - CENTRE <i>could</i>	\$ 265.00	✓ 212
4	REAR BUMPER SPOILER <i>cut</i>	\$ 714.00	✓ 571.20
5	REAR BUMPER SIDE TRIM - LH / RH <i>free</i>	\$ 74.00	x
6	REAR BUMPER REFLECTOR - LH / RH <i>free</i>	\$ 76.00	x
7	REAR BUMPER CARRIER <i>new Best</i>	\$ 819.00	✓ 655.20
8	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 81.00	x
9	SUNDRIES <i>New</i>	\$ 300.00	? 15.92
TOTAL SPARE PARTS CHARGES		\$ 4,954.00	
TOTAL LABOUR CHARGES		\$ 1,872.00	
GRAND TOTAL		\$ 6,826.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Netl.

3 repair days