

Date: 27.05.2019
Vehicle No: SLK1596R
Model: HONDA VEZEL HYBRID 1.5X AUTO
Chassis: RU31222916 - 2016
Reg.Year: 2017

Third Party Insurer: AXA
Third Party Veh No: SLF2149T
Date of Accident: 24.05.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Bz</i> \$953.30 ✓
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>M</i> \$68.30 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>M</i> \$95.00 ✓
4	REAR TAILGATE "H" EMBLEM	1		<i>M</i> \$75.00 X
5	REAR WINDSCREEN MOULDING	1		<i>M</i> \$180.00 ✓
6	REAR BUMPER	1		<i>Bu</i> \$935.60 ✓
7	REAR END PANEL	1		REPAIR
			SUB TOTAL	\$2,307.20
			LESS 20%	-\$461.44
			PARTS TOTAL	\$1,845.76

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>M</i> \$100.00 <i>405A</i>
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>M</i> \$30.00 ✓
3	REAR BUMPER CLIPS	1		<i>M</i> \$50.00 ✓
4	REAR BUMPER REVERSE SENSOR	1		<i>M</i> \$250.00 X
			S/N TOTAL	\$430.00

Not Authorized
Resurvey B4 paint
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date:	27.05.2019	Third Party Insurer:	AXA
Vehicle No:	SLK1596R	Third Party Veh No:	SLF2149T
Model:	HONDA VEZEL HYBRID 1.5X AUTO	Date of Accident:	24.05.2019
Chassis:	RU31222916 - 2016		
Reg.Year:	2017		

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REPLACE, REMOVE, REPAIR REAR ACCIDENT AREAS & ETC. BACK TO ORIGINAL CONDITIONS.	\$500.00	4001
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIAL AT REAR BUMPER, REAR TAILGATE, REAR END PANEL & ETC	\$800.00	4401
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC.	\$150.00	1201
TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM BACK TO ORIGINAL FUNCTIONS & ETC	\$100.00	601
TO CHECK WIRING & ELECTRICAL DIAGNOSTIC	\$100.00	201
TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	\$50.00	✓
	LABOUR TOTAL	\$1,700.00
ONG	TOTAL	\$3,975.76