

Date: 27.05.2019
Vehicle No: SLK1596R
Model: HONDA VEZEL HYBRID 1.5X AUTO
Chassis: RU31222916 - 2016
Reg.Year: 2017

Third Party Insurer: AXA
Third Party Veh No: SLF2149T
Date of Accident: 24.05.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$953.30 ✓
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Me</i> \$68.30 ✓
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Me</i> \$95.00 ✓
4	REAR TAILGATE "H" EMBLEM	1		<i>Me</i> \$75.00 X
5	REAR WINDSCREEN MOULDING	1		<i>Me</i> \$180.00 ✓
6	REAR BUMPER <i>762.70</i>	1		<i>Buy</i> \$935.60 ✓
7	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,307.20
LESS 20%				-\$461.44
PARTS TOTAL				\$1,845.76

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Me</i> \$100.00 ✓
2	REAR WINDSCREEN STOPPER	2	\$15.00	<i>Me</i> \$30.00 ✓
3	REAR BUMPER CLIPS	1		<i>Me</i> \$50.00 ✓
4	REAR BUMPER REVERSE SENSOR	1		<i>Me</i> \$250.00 X
S/N TOTAL				\$430.00

Not Notified
Resurvey B4 paint
4 days @ 2857.4p ✓ ok

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date: 27.05.2019
Vehicle No: SLK1596R
Model: HONDA VEZEL HYBRID 1.5X AUTO
Chassis: RU31222916 - 2016
Reg.Year: 2017

Third Party Insurer: AXA
Third Party Veh No: SLF2149T
Date of Accident: 24.05.2019

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REPLACE, REMOVE, REPAIR REAR ACCIDENT AREAS & ETC.
BACK TO ORIGINAL CONDITIONS.

\$500.00 *4001*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINTS & FURNISHING MATERIAL
AT REAR BUMPER, REAR TAILGATE, REAR END PANEL & ETC

\$800.00 *4401*

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN
SEALANT, REAR WINDSCREEN MOULDING & ETC.

\$150.00 *1201*

TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM BACK TO ORIGINAL
FUNCTIONS & ETC

\$100.00 *601*

TO CHECK WIRING & ELECTRICAL DIAGNOSTIC

\$100.00 *201*

TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC

\$50.00 ✓

	LABOUR TOTAL	\$1,700.00
ONG	TOTAL	\$3,975.76

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

