



Reg No : 196700086Z ST Reg No : MR-8500000-9

clear TP/DS

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Mr Chew Ee Ming Darryl (Zhou YiM) 8 Ridgewood Close #21-09 Singapore 276698 Mobile: 81216549
	Document No	
	Document Date	
	0	
	25/05/2019	

Liability check

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GEXGPZ	C1	08/01/2018	SLV6206B	0	45350	9DS/SLV6206B-23051'
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
R053REH604576793	1ZROA56906	30	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

R053REH604576793	1ZROA56906	30	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00
------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH:GY4961K ACC DATE:23/05/2019 TP INS:EQ INS NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORIZED ON: -TP/DS CLAIM				30.00
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				164.00
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.				111.52
4	B	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. 656 STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				2624.00
5	B	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT 538 AFFECTED AREAS.				2152.00
6	1	S81110-02R40 HEADLAMP ASSY, RH / RR	1.00	2455.00		2455.00
7	2	S81150-02R40 HEADLAMP ASSY, LH X	1.00	2455.00		2455.00
8	3	SPC593-1200F LED FOG LAMP ?	1.00	387.80		387.80
9	4	S53112-02300 GRILLE, RADIATOR, LW ?	1.00	167.40		167.40
10	5	S81481-02690 COVER, FOG LAMP, RH / RHT	1.00	178.60		178.60
11	6	S52119-02982 COVER, FR BUMPER, L / DD	1.00	524.20		524.20
12	7	S52161-0K040 PIECE, RR BUMPER / NEC	10.00	4.00		40.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			<b>Amount Due</b>

PLEASE TEAR ALONG PERFORATED LINE

3969070

3969070

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/05/2019 TIME 09:23

VEHICLE NO SLV6206B

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Reg No : 196700086Z  
ST Reg No : MR-8500000-9

# ESTIMATE

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ML account & more!

Account Detail		Account No	Customer Detail	
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		S1000021 / ICEQI1	Mr Chew Ee Ming Darryl (Zhou YiM) 8 Ridgewood Close #21-09 Singapore 276698 Mobile: 81216549	
		Document No		
		0		
		Document Date		
		25/05/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	GEXGPZ C1	ZRE171R	08/01/2018	SLV6206B	0	45350	9DS/SLV6206B-23051'
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

RO53REH604576793      1ZROA56906      30      Raymond Seah L M      --/--/---- 0.00      --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	8	T90467-05170 CLIP / M-C	2.00	2.10		4.20
14	9	T53879-58010 RETAINER, FR FENDER / M-C	2.00	8.50		17.00
15	0	S52115-02380 SUPPORT, FR BUMPER S (RM)?	1.00	67.30		67.30
16	1	S52116-02370 SUPPORT, FR BUMPER S X	1.00	67.30		67.30
17	2	S52611-02430 ABSORBER, FR BUMPER X	1.00	110.00		110.00
18	3	S52131-02190 REINFORCEMENT, FR X	1.00	393.90		393.90
19	4	S53100-02B90 GRILLE ASSY, RADIATO X	1.00	704.30		704.30
20	5	S53141-02110 COVER, RADIATOR RH X	1.00	79.80		79.80
21	6	S75311-02190 RADIATOR GRILLE EMBLEM, X	1.00	47.20		47.20

Steve CLKK) 8322 8813  
 Mr Provl 21/5/19, 10.35am  
 3 days  
 P/P  
 Rj Bek spy

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	12,780.52	
	<b>LKK Auto Consultants hence notify the Repairer of the following:</b> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Parts			
		Labour	7,699.00	GST 7.00%	894.64
		Material	5,081.52	Less	0.00
		Lubrication/Fluid	0.00		
	Others	0.00	Amount Due	13,675.16	
		0.00		3969071	

PLEASE TEAR ALONG PERFORATED LINE

Signature: \_\_\_\_\_ DATE: 25/05/2019 TIME: 09:23

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.