

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

LIM SIOK HUI

31/05/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 27/05/2019

Estimated repair cost for vehicle no: SLG9180A TOYOTA VELLFIRE 2.5 A '16

CHASSIS: AGH300036184

S/n	Qty	Items	U/price	Amount
1	1	Rear L/H Tail Lamp Lower Cover <i>Repair</i>		\$365.00 <i>x</i>
2	1	Rear L/H Tail Lamp Lower Cover Retainer <i>AS per</i>		\$155.00 <i>x</i>
3	1	Rear L/H Fender <i>Repair</i>		\$1,650.00 <i>x</i>
5	1	Rear Bumper <i>Delam.</i>		\$1,800.00 <i>1480</i>
6	10	Rear Bumper Clip <i>AS per</i>	\$6.50	\$65.00 <i>x</i>
7	1	Rear L/H Bumper Side Retainer <i>AS per</i>		\$155.00 <i>x</i>

1480

1110

Subtotal :- \$4,190.00

Labour charges

To remove & refit reverse sensor ~~\$100.00~~ *40*

To remove & refit rear L/H fender glass ~~\$120.00~~ *x*

Gum ~~\$50.00~~ *x*

To check wiring ~~\$100.00~~ *30*

Tuff kote ~~\$150.00~~ *x*

Panel beating ~~\$800.00~~ *200*

Spray painting ~~\$1,200.00~~ *500*

Subtotal :- \$2,520.00

Total:- \$6,710.00

1.5K

total: 1880
h/s: 1.5K
02 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: