***	ASS. REC. BY: REF: CS / MSG 1900 C	1449/ kad302   Special Instruction:
WinM n	Surveyor: Kemeth ASSIGNMENT ASSIGNMENT OF MSLG	NT (Office)
	Estimated Cost:  OD TP WS/TP RES/OD RES/EVA/INV/MV/CS  To Inspect Vehicle No: FH 3836	Bill to:
1	of BIK 32 Sin Ming Dave # 01-331	Tel: 64539903
	Policy No: 1)29096812 Q my Sum Insured:	Claim No: 591211  Excess:
	Make of Veh: (Client's Record)  CA / REV / REP. / REV 24 HRS	D.O.A 19.4.2019
_	Date/Time_29.5.19 10.500 m Person Contacted:	Mr Tan Vehicle IN OUT
	Date/Time Action/Instruction Estimate (1)  PH 3836Y - (CT / AIG 120 6205/ K	
	30/1/190230p verised to Jowyn Tay	Ma Merinien.
,	19219 Offer, Journ an Aprimed that	the repairer already subject 100 CES \$ 1500,

Tenneth	ASSIGNMENT
From: Date:	
Estimated Cost:	- Yr Regn
OD LAP WS ITP RES I OD RES I EVA I INV I MV	Type: M.Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Traller or
To Inspect Vehicle No:	
at Workshop m/s	- CONTARY NX t C.C 13
of	~C. Insured / Std / NI / NA
Insured:	Sp.Reading 22409 T/Radio: Insured / Std / NI / N. Eng/No:
Policy No.	
Claims No.	700446
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorger Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inodor / Jammed / Leaked / Burnt or
	Modi: MID S/Rim / STD A/Rim or
(Policy Condition)	Tyre Size: F: Pun dolforld
Remark: The veh had commenced Its N/S	OS BSIDINIENDON BOY SOIPURIS
repair at the time of inspection.	BS / BON / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 8900h	TOYO/YOKO or
IDAC Accident Rport: Consistent? : Yes or No	Fron! Rear
GIA / PR Seen: Consistent? : Yes or No	R/Bal. 4 mm R/Bal. 2 mm
Est. Repairs: 05 days Res.: Yes or No	L/Bal. mm L/Bal mm
Lum Sum: 20 % 3 Val.: Yes or No	D.O.A. 19/4/19 DOI 29/5/19
	Survey held at
CA REV REP. / 24 HRS Vehicle: IN	Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN	- John Jean
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
File pars To	
16/2/19 Subruit Preli- report.	
* MV : \$ 900 (est) 7 MA	: 829; M= 8371
E A E IVE	2040
RECEIVE	D 1 6 JUL 2019
Onto/Time, File Pass to? : Prell. Report	Days Of Repair:
16/2 mild : Final Report	Resurvey No. of Tales
Jute/Firne, File Return to?	Transportation
I bbA	Fee: Site Insp (\$ )_s.Rs_si
	Interview (\$ ) 5.4%
eport Format :	Tech Invs (\$
ump Sum / I.B.I: (S	Weekend (\$
	161

No results.

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	22 Apr 2019 29 May 201			7			New Assign Cancel Case	
	Main	Ref	erence	Claim	Details	Documen	ts	Show All
CLAIM S	UBFOLDER DET	TAILS				[Crea	ited by insure	erl
Insured:		HOR TS	UNG WEI, ID: S	57876222E, T	el: +6592983984, E	mail: MichaelHor	@gmail.com	•
Main Clain	nant:	MUHAM	IMAD NADZRI BI	N GAZALEE,	ID: S8633146B			
Vehicle Reg. No.: FH3836Y Date of Loss: [351 N		/2019 17:00 - :59 Months and <b>1</b> Days From eg Date (Man Yr)]						
Claim Typ			age: 17/09/20:					
Vehicle Re	g. No. (Insured):	SKQ927	71E	Polic	Policy No. (Claimant):			
	Excess:		S\$500	.00				
Repairer:		Ga Mot	or (HQ) Blk 32 Si	n Ming Drive, #	01-331, 575706 Sin I	Ming - Tel: 64539	903	
Handling I	nsurer:	MSIG I			. (HQ) - Tel: +65 68			Tay Mei
Adjuster:		LKK Au	to Consultants P	te Ltd (HQ) -	Tel: 6256-3561 [I	mm.Advice di	ue 30/05/20	191
	todian (Insured)		JNG WEI (40 / Ma	le) , NRIC: S	7876222E, Tel: +65	92983984 Email:	: MichaelHor@g	gmail.com
Adj Asg. Remarks: On WP. Liab: dispute. TP agr			agree on SJE - a	ssign Kenneth Kong	from LKK. Contac	t: Mrs Tan @ 6	453 9903	
ASSOCIA	TED MAIL REC	EIVED				View All	Compose	Case Mail
There are	no mail for this c	ase.						

### Note: This document has not been finalised.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Jowyn Tay Mei Ling

Date:

30 May 2019

## Preliminary Advice

Insured Vehicle No : SKQ9271E

TP Vehicle No

: FH3836Y

Accident Date

: 19/04/2019

Make

: YAMAHA RXZ

Assignment Date

: 29/05/2019

Date of Inspection : 29/05/2019

Est. Duration of Repair

: 5.00

Inspection At

: GA MOTOR (HQ)

BLK 32 SIN MING DRIVE, #01-331

SINGAPORE 575706

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,075.00
Revised Amount	:S\$	3,118.50
Check Items (Estimated)	:S\$	400.50
Total	:S\$	3,519.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

( )	The vehicle	is	economical/not	economical	for	repair.
-----	-------------	----	----------------	------------	-----	---------

(X) The above survey was conducted on a 'without prejudice' basis.

### » Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	3146B
Vehicle No.:	FH3836Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Blue
Manufacturing Year:	1989
Engine No.:	2UX004446
Chassis No.:	2UX004446
Maximum Power Output:	
Open Market Value:	\$2,341.00
Original Registration Date:	18 Jan 1990
First Registration Date:	18 Jan 1990
Transfer Count:	5
Actual ARF Paid: Intended PARF Rebate Details	\$352.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	30 Sep 2019
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$894.00
COE Rebate Amount:	\$29.00
Total Rebate Amount: Message	\$29.00

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.

The information contained herein is correct as at 30 May 2019

OK





1 of 2

1012

Report No. E/20190526/7026

## **POLICE REPORT (NP299)**

Police Station Of Origin Tanglin Division HQ 21 Kampong Java Road SINGAPORE 228892

Tel No:1800-3910000

Date/Time Report Made	Vide Re	port No.	361 AVS	Station Diary No.	
26/05/2019 22:22					
Name Of Informant	Address				
MUHAMMAD NADŽRI BIN GAZALEE	APT BL	K 64 LORO	NG 5 TOA PAYO	H #12-350	
	SINGAP	ORE 3100	64 :		
ID Type / ID No.	Contact				
NRIC NO / S8633146B	Home/Office: Mobile:				
			87771789		
Nationality	Email A	ddress			
SINGAPORE CITIZEN	nazelmo	86@hotma	il.com		
Occupation	Sex	Age	Date of Birth	Race	
Building technician	Male	32	17/11/1986	Malay	
Institution/School Name	Languaç English	je			
Date/Time Of Incident	Location Of Incident				
19/04/2019 17:35 - 19/04/2019 18:00	RIVER \	ALLEY RO	AD		
Brief details.			i i		

On the 19 April 2019, I was riding along river valley road towards Clemencue Road. I was heading back home at 1735hrs. The road condition is abit wet due to rain just stopped. As I was picking up on the road, I saw a mercedez car by the plate of SKQ9271E was queing behind a car turning to the right. I was going straight on the left lane when I reached his front passenger door, the car suddenly cut into my lane without any signal or checking of blind spot. His left front bumper hit my right leg hence I swerved to the left and flung from my bike.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 22:22
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	-





2 of 2

POLICE REPORT (NP299)

## CONTINUATION OF REPORT

Report No. E/20190526/7026

I got an eye witness by the name of Hafiz who saw the whole accident. I sustained a very deep cut on my right foot from the accident and fractured my tail bone. Conveyed to SGH at 1800hrs.

Person Name	MUHAMMAD NADZRI BIN GAZ	ALEE	A STATE OF THE PARTY OF THE PAR
ID Type	NRIC NO	ID No	S8633146B
Gender	Male	Age	32
Race	Malay	Language	English
Occupation	Building technician	Address Type	
Address	APT BLK 64 LORONG 5 TOA PAYOH #12-350 SINGAPORE 310064	Mobile No	87771789
s Informant A	Yes		

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/05/2019 22:22
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	



# MOTOR





Block 32, Sin Ming Drive, #01-331, Singapore 575706 TEL:64539903,64539904 FAX:64539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories. Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.

Date:28-05-2019

Estimated repair list for the accident motorcycle Yamaha RXZ Vehicle No. FH3836Y

			T excess
1 set	Head light	B	4/cm \$125.00 L
1 pc	Head light bracket		bil \$75.00 w
1 pc	Head light fairing & windshield		Ary \$135.00
1 pc	Head light fairing bracket		DIT \$90.00 -
1 pc	Signal light (right)		BN \$65.00 -
1 pc	Handle bar ( right)		By \$90.00 -
1 set	Handle banlancer		nu \$28.00 -
1 set	Mirror		cm \$45.00 —
1 pc	Horn		\$15.00 X
1 pc	Horn backet		1 \$20.00 X
1 pc	Top brake pump	M	3 cm \$80.00 — R \$16.00 —
1 pc	Brake lever		R \$16.00 —
1 pc	I.U. unit		cm \$156.00 —
1 pc	I.U. bracket		By \$40.00 —
1 pc	Right hand switch		Res \$65.00 -
1 set	Meter		cm \$530.00 -
1 pc	front mudguard		cm \$98.00 —
1 pc	Front No. plate		417 \$12.00 W
2 pcs	Front fork inner tube		\$220.00
2 pcs	Fork oil seal		\$50.00 7 6
1 pc	Bottom steering stem		\$120.00
1 pc	steering cone & bearing		\$55.00 🕫
1 pc	Tank		\$380.00
1 pc	Side cover (right)		cm \$120.00 -
1 set	Front footrest		nr1 \$80.00 -
1 set	Rear footrest		<b>R</b> \$50.00 —
1 pc	Footrest bracket (right)		3 \$85.00 —
1 pc	Brake padel		717 \$35.00
1 pc	Exhaust pipe		nes \$450.00
1 pc	Rear tail board	и	\$125.00 U
1 pc	Rear Box		al 6 \$120.00
1 pc	Rear carrier		7/1/2 \$120.00 -
	Towing		\$30.00 25%
	Labour		\$350.00 2001
	( ( \		4.000
	1/2/19	Total :	\$4075.00

716051, 118m 8? 5days



# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	j Submitted	Ins Auth'ed	Status	
	22 Apr 2019	25.500	29 May 2019 10:28 Edit Adj Rpt	\$\$3,118 Edit Est	.50 S\$	3,118.50 View Rpt			or Survey
4	lain	R	eference	CI	aim Details		Document	s	Show All
CLAIM SU	SFOLDER DE	TAILS				[Created I	by insurer]		
Insured:	HOR TSU	NG WEI, ID: S7	876222E, Tel: +6	592983984,	Email: Mich	aelHor@gmail	l.com		
Main Claimant:	минамм	AD NADZRI BIN	GAZALEE, ID: S	8633146B					
Vehicle Reg. No.:	FH3836	Y			Date of Loss		9 17:00 - :59 ns and <b>1</b> Days Fro	om LTA Reg Dat	e (Man Yr)]
Claim Type:	<b>TP</b> / 591	211			Policy/Cover Note No.:		QMY (Compreher 17/09/2018 - 05/		
Vehicle Reg. No. (Insured):	SKQ9271	E			Policy No. (Claimant):				
					Excess:	S\$500.00			
Repairer:	Ga Motor	(HQ) Blk 32 Sin I	Ming Drive, #01-331	1, 575706 S	n Ming - Tel:	64539903			
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (HQ)	- Tel: +65	5827 7888	. [Handled by	Jowyn Tay Mei	Ling - 6643 13	07]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled by	KENNETH KO	NG] [Final	Rpt due 28/0	6/20191
Driver/Custo dian (Insured):	)		) , NRIC: S787622					•	
Adj Asg. Remarks:	On WP, Lia	b: dispute. TP ag	ree on SJE - assign	Kenneth Kor	g from LKK.	Contact: Mrs	Tan @ 6453 9903	3	
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w All Comp	ose Case Ma
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	KS⊡				View All S	earch Tasks (	Create New Task	Complet
	Priority	Type Task	Group Subject	t Handl	er Assig	ned By	Completed On	Created	On Don
<b>Due Date</b>									

### **Claim Documents**

\*FH3836Y (591211)

[SKQ9271E]

TP

MUHAMMAD NADZRI BIN GAZALEE

Apr 19 2019 5:00PM

[HOR TSUNG WEI]

Ga Motor

_		load Photos Compose New Letter	View View in Browser ∨
30	essment Reports	MCTC T (Ci	1 per page ✓ ✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement	Thumbnail Print
1	28/05/19 16:00	From:OD - Reg. No: SKQ9271E, Claimant: HOR TSUNG WEI	1 Load HTM
No.	Finalized On 30/05/19 14:30	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Prin
1	30/05/19 14:30	Adjuster Immediate Advice	E LOAD HIM
Pho	otos/Images		3 per page
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Prin
1	16/07/19 12:08	General View	■ Load JPG
2	16/07/19 12:08	General View	■ Load JPG
3	16/07/19 12:08	General View	■ Load JPG
4	16/07/19 12:08	General View	■ Load JPG
5	16/07/19 12:08	General View	■ Load JPG
6	16/07/19 12:08	General View	■ Load JPG
7	16/07/19 12:08	General View	1 Load JPG
8	16/07/19 12:08	General View	1 Load JPG ✓
9	16/07/19 12:08	General View	■ Load JPG
10	16/07/19 12:08	General View	■ Load JPG
11	16/07/19 12:08	General View	1 Load JPG ✓
12	16/07/19 12:08	General View	■ Load JPG
13	16/07/19 12:08	General View	■ Load JPG
14	16/07/19 12:08	General View	■ Load JPG
15	16/07/19 12:08	General View	■ Load JPG
16	16/07/19 12:08	General View	■ Load JPG
17	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
18	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
19	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
20	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
21	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
22	16/07/19 12:08	General View	1 Load JPG ✓
23	16/07/19 12:08	General View	1 Load JPG ✓
24	16/07/19 12:08	General View	1 Load JPG ✓
25	16/07/19 12:08	General View	1 Load JPG ✓
26	16/07/19 12:08	General View	<b>1</b> Load JPG ✓
27	16/07/19 12:08	Chassis Number	■ Load JPG
28	16/07/19 12:08	Odometer Reading	1 Load JPG
		J	
Doc	cumentation		1 per page 🗸
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Prin
1	28/05/19 16:06	TP PRI & POLICE REPORT	1 Load PDF

Merimen e-Claims Page 2 of 2

Ass	Assessment Reports		1 per pa	age 🔻	<b>✓</b>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
2	28/05/19 16:52	TP agree on SJE.	0	Load PDF	

## **Documents Checklist**

	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			,
			1
Show Remarks To: Handling Insurer			

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19009449/KQD3E2

Date:

16/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

D29096812QMY

Claimant Vehicle FH3836Y No:

Insured Vehicle No:

SKQ9271E

Date of Loss:

19/04/2019

Nature of Claim:

TP

Claim No: 591211

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

FH3836Y

Make & Model:

YAMAHA RXZ, 133cc (M)

Engine No:

2UX004446

Reg. Date: Colour:

18/01/1990 (Man. Year: 1989) Yellow/Blue

Chassis No: Odometer:

2UX004446 22409 km

**Engine Capacity:** 

133 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

80/80 R18

Rear Tyre Size:

80/90 R18

Front Left Side:

Dunlop 4 mm

Rear Left Side:

Golden Boy 2 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,695.00	2,893.50	801.50	21.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	380.00	225.00	155.00	40.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,075.00	3,118.50	956.50	23.47

INSPECTION

Date of Assignment:

29/05/2019

Date Inspected:

29/05/2019

Inspected At:

Ga Motor (HQ)

Blk 32 Sin Ming Drive, #01-331

Singapore 575706

Estimated Period of Repair:

5.0 days

Adjuster:

KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_... 16/7/2019

(REPAIR COST NOT CONCLUDE)

MARKET VALUE: \$900.00 (EST)-LTA REIMBURSEMENT VALUE: \$29.00 =NETT VALUE: \$871.00

# **REPAIR DETAILS**

Referen		(Last Synchronised: 16 Jul 2019)
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, r	no print-code for FH3836Y)
Validity:		s are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values no	t in reference catalogue are prefixed with an asterisk *.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET HEAD LIGHT	Bent/Cracked	125.00 F	*125.00 FL
2	1		*HEAD LIGHT BRACKET	Distorted	75.00 F	*75.00 FL
3	1		*HEAD LIGHT FAIRING & WINDSHIELD	Missing	135.00 F	*135.00 FL
4	1		*HEAD LIGHT FAIRING BRACKET	Distorted	90.00 F	*90.00 FL
5	1		*SIGNAL LIGHT (RIGHT)	Broken	65.00 F	*65.00 FL
6	1		*HANDLE BAR (RIGHT)	Bent	90.00 F	*90.00 FL
7	1		*SET HANDLE BALANCER	Dented	28.00 F	*28.00 FL
8	1		*SET MIRROR	Cracked	45.00 F	*45.00 FL
9	1		*HORN	Serviceable	15.00 F	*- FL
10	1		*HORN BRACKET	Repair	20.00 F	*-FL
11	1		*TOP BRAKE PUMP	Mtg Cracked	80.00 F	*80.00 FL
12	1		*BRAKE LEVER	Bent	16.00 F	*16.00 FL
13	1		*I.U UNIT	Cracked	156.00 F	*156.00 FL
14	1		*I.U BRACKET	Bent	40.00 F	*40.00 FL
15	1		*RIGHT HAND SWITCH	Dented	65.00 F	*65.00 FL
16	1		*SET METER	Cracked	530.00 F	*530.00 FL
17	1		*FRONT MUDGUARD	Cracked	98.00 F	*98.00 FL
18	1		*FRONT NO PLATE	Missing	12.00 F	*12.00 FL
19	2		*FRONT FORK INNER TUBE	Serviceable	220.00 F	*-FL
20	2		*FORK OIL SEAL	Serviceable	50.00 F	*-FL
21	1		*BOTTOM STEERING STEM	Serviceable	120.00 F	*-FL
22	1		*STEERING CONE & BEARING	Serviceable	55.00 F	*-FL
23	1		*TANK	Bent	380.00 F	*380.00 FL
24	1		*SIDE COVER (RIGHT)	Cracked	120.00 F	*120.00 FL
25	1		*SET FRONT FOOTREST	Distorted	80.00 F	*80.00 FL
26	1		*SET REAR FOOTREST	Bent	50.00 F	*50.00 FL
27	1		*FOOTREST BRACKET (RIGHT)	Bent	85.00 F	*85.00 FL
28	1		*BRAKE PEDAL	Distorted	35.00 F	*35.00 FL
29	1		*EXHAUST PIPE	Dented	450.00 F	*450.00 FL
30	1		*REAR TAIL BOARD	Cracked	125.00 F	*125.00 FL
31	1		*REAR BOX	Dented/Cut	120.00 F	*120.00 FL
32	1		*REAR CARRIER	Distorted/Bent	120.00 F	*120.00 FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	3,695.00	3,215.00
			- List Item Discount on L	Items 0.00/10.00% (S\$)_	0.00	321.50
				Total Parts (S\$)	3,695.00	2,893.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING	New	30.00	25.00
2	LABOUR	New	350.00	200.00
		Gross Labour Cost (S\$)	380.00	225.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >