(SATURE)	Kalm REF: TO	T				
Surregue	Calhh		10 A 4 A 4 A 4 A 4 A 4 A 4 A 4 A 4 A 4 A			
100			GNMENT		2.7	NA DE SYN
From	Date: 38	5. 2019			P Yr Regn: 27	
Estimated Cost:			Type: M.Car./ M.C	ycle / Bus / Van / I	Lorry / Toi / Prime !	Mover /
/ \	TP RES / OD RES / EVA / INV / MV		Truck / Tra			
To Inspect Vehic	aria Code		Make:	KIA OPT	tan c	1685
at Workshop m/s	B		Colour	Silve	A/C: Insuge	d/Std/NI/NA
of 23 char	ngi south ave 2		Sp.Reading	582958	T/Radio: Ins de	d / Std / NI / NA
Insured:			Eng/No:			
Policy No.			C/No:	KNAGMY	HYMETK:551	90
Claims No.			Gen. Cond: Good	I F Poor / Bur	nt	
Sum Insured:	Excess		Steering: Inord	/ Jammed / Leake	d/Burnt or	
(Client's Recor	rd)		Brake: Inorder	/ Jammed / Leake	d / Burnt or	
Make of Veh.			Modi: Nil / S/F	Rim / STD A/RON	of	
		V.	Tyre Size: F	: 2	205/65 RU	5
(Policy Conditi	ion)		9	R: .		
Mary Market Street	eh had commenced its	N/S 0/S	BS / DUN / EXNO	OVA / GY / FS / LIZ	A / MIC / OHTSU / PI	R/SUMI/
repair	at the time of inspection.		тоуо / уоко		Has Kak	
Bal. or Market V	falue:		Front	2	Rear	1
IDAC Accident F	Rport: Consistent? : Yes	or No	R/Bal. 7	mm	R/Bal) mm
GIA / PR Seer	n: Consistent? : Yes	or No	L/Bal. +	mm	L/Bal.	, mm
Est. Repairs:	3 days Res.: Yes	or No	D.O.A.	,	7	15/19
Lum Sum:	20.% 3 Val.: Yes	or No	Survey held at	17	remie	
CA / REV /	REP. / 24 HRS	WAR BUILDING	Des. of Damages		S / N/S / U/C / Ro	oftop or
Date:	Person Contacted:	Vehicle: IN / OUT	The U/C / C		ody Structure affects	ed due to collision.
Date / Time	Action / Instruction		The State of	Illiania (Tallia		
	YS# 13W (led #	1387.90	17(-)		
	1-					
Date/Time. File Pas	: Preli. Report		Days Of Repair	r:		
9	: Final Report		Resurvey No. o	of Trip:	Survey Fee:	
Date/Time, File Ref	turn to?			Val.	Transportation:	
2)		Add Fee)S+RSSI	
			Interviev) Photos	
Report Form	nat :		: Tech. In	VS (\$) Others	

Weekend (\$

TOTAL

Lump Sum / I.B.I: (\$

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

28-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8877 D

1 pc	Front bumper / Achd		E21 00
20000	and the state of t	\$	531.00
1 pc	Front bumper emblern	\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00 ×	\$	16.00
1 pc	Front o/s fender inner shield @ \$120.00 KM	\$	120.00
1 pc	Front o/s fender @ \$384.00	\$	384.00
1 pc	Front o/s wheel cover @ \$116.00 X	\$	116.00
		\$	1,211.00
	Less 10%	5	121.10
S/NETT		\$	1,089.90
1 pc	Front bumper clips	s	48.00
1 pc	Front o/s fender sticker > 1	5	30.00
1 set	Front o/s fender inner shield clips X **	5	28.00
	Sundry	s	5000 24
	To check wheel alignment	s	80.00 1
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	s	5000 20 80.00 x 11,
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	-	300
	resimple and adjust of the same, etc.	\$	360
	To putty and spray painting on front bumper, front o/s fender	\$	\$80.00
	To apply rustproofing on the repaired and replaced panels	\$	12000 50
		S	2,675.90
	Α.		

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

18/6/19 45 \$1200/2 Pm

Kalu 11109

M 28/5/14 1705L

3 07,

1/5

Aller Repair plato

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

27 Mar 2014 / 10:19:06

Receipt No.:

AACCK001-AX239-140327-000021

Asset Type:

Vehicle

Transaction Amount

\$71,081.00

Asset ID:

SHB8877D

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction

Reference No.:

20140327101906778635

Vehicle No.:

SHB8877D

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 27 Mar 2014

Original Registration

27 Mar 2014

Date:

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414ME5455290

Engine No.:

D4FDDH308962

Motor No.:

Trailer Chassis No.:

Propellant:

Diesa

Passenger Capacity:

Engine Capacity:

1685

Power Rating:

1584

Unladen Weight: Maximum Laden

2050

Weight:

Primary Color:

Silver

Secondary Color: Manufacturing Year:

2013

Open Market Value:

\$19,696.00

Minimum PARE

\$7,317.00

Benefit: PARF Eligibility:

No. of Transfer:

0

Effective Ownership

27 Mar 2014 10:19:06

Date/Time: COE No:

2014032701001188W

COE Expiry Date:

26 Mar 2022

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$58,745.00

Lifespan Expiry Date:

26 Mar 2022

Owner ID Type:

Company

Hsiao Tong (LKKAuto)

From:

Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Sent:

Monday, 15 July 2019 3:48 PM

To:

Joy Irene (LKKAuto); Asher Sng (LKKAuto)

Cc:

AccReport; CS A Team

Subject:

(III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

Attachments:

SHB8877D 22052019.pdf

WITHOUT PREJUDICE

Dear all.

Your Ref

GBF3027Z

Our Ref

SHB8877D/SJ

Date of accident

27.05.2019

We refer to the above mentioned accident.

Hereby we would like to append our losses from **India International Insurance Pte Ltd**, as insurers of vehicle number **GBF3027Z** which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Thank you.

Regards,

Foong Shiuh Jye Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

27 Mar 2014 / 10:19:06

Receipt No .:

AACCK001-AX239-140327-000021

Asset Type:

Vehicle

Transaction Amount:

\$71,081.00

Asset ID:

SHB8877D

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction

Reference No.:

20140327101906778635

Vehicle No.:

SHB8877D

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi) Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 27 Mar 2014

Original Registration

27 Mar 2014

KIA

Vehicle Make: Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414ME5455290

Engine No.:

D4FDDH308962

Motor No.:

Trailer Chassis No.:

Propellant:

Diesel

1685

Passenger Capacity:

Engine Capacity:

Power Rating:

Unladen Weight:

1584

Maximum Laden Weight:

2050

Primary Color:

Silver

Secondary Color:

2013

Manufacturing Year: Open Market Value:

\$19,696.00

Minimum PARF

\$7,317.00

Benefit PARF Eligibility:

No. of Transfer:

Effective Ownership

0

Date/Time:

27 Mar 2014 10:19:06

COE No :

2014032701001188W

COE Expiry Date:

26 Mar 2022

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$58,745 00

Lifespan Expiry Date:

26 Mar 2022

Owner ID Type:

Company



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5107202885-000377

Cover : Third Party

1. Index mark and Registration Number of Vehicle

: SHB8877D

Chassis Number

: KNAGM414ME5455290

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 01 Feb 2019

4. Explry Date of Insurance

: 31 Jan 2020

5. Persons or Classes of Persons entitled to drive*

(a) The Policyholder.

- (b) Any Ilcensed taxl driver driving on the Policyholder's order or with his/her permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to Use*
 - (a) Use as a Taxl.
 - (b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.
 - Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation)
 Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)

: N/A

EXCESS (SECTION II)

: \$\$3,500

INSURE WITH COE

: N/A

HIRE PURCHASE COMPANY

N/A

SUM INSURED

: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: HL SUNTEX INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue

: 01 Feb 2019 09:37 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

28-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8877 D

1 pc	Front bumper /		\$	531.00
1 pc	Front bumper emblem		\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00 ×		S	16.00
1 pc	Front o/s fender inner shield @ \$120.00 K		\$	120.00
1 pc	Front o/s fender @ \$384.00		\$	384.00
1 pc	Front o/s wheel cover @ \$116.00 X		\$	116.00
			\$	1,211.00
	L	ess 10%	\$	121.10
			\$	1,089.90
S/NETT				
1 pc	Front bumper clips		s	48.00
1 pc	Front o/s fender sticker 🗡		\$	30.00
1 set	Front o/s fender inner shield clips 🗶		\$	28.00
	Sundry		\$	59:00 2-
	To check wheel alignment		S	80.00-4
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 4
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair,			300
	reshape and adjust of the same, etc.		\$	650.00
	To putty and spray painting on front bumper, front o/s fender		\$	\$80.00
	To apply rustproofing on the repaired and replaced panels.		\$	120.00 50
			\$	2,675.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalu Illey

M 28/5/19 1705L

3 Oys

U/S

After Repair plots

Hsiao Tong (LKKAuto)

From:

Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Sent:

Monday, 9 September 2019 9:37 AM

To:

Hsiao Tong (LKKAuto)

Cc:

AccReport

Subject:

(III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK

REF: CC3/III19009453/K1pb3

Without Prejudice

Dear Sirs,

Referring to the email below,

There was no video for the case.

Sorry for inconvenience.

Thank you.

Regards,

Foong Shiuh Jye Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Wednesday, 28 August, 2019 10:19 AM

To: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Cc: AccReport < AccReport@Premier-Corp.net>

Subject: RE: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK REF:

CC3/III19009453/K1pb3

Without Prejudice


Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. Attached is a copy of our insured accident report for your easy reference.

As per III instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.



In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[&]quot;Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

From: Su Li (LKK Auto) <<u>suli@lkkauto.com</u>> Sent: Monday, 26 August 2019 2:02 PM

To: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: AccReport < AccReport@Premier-Corp.net >; CS A Team < cs-a@lkkauto.com >

Subject: RE: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

Without Prejudice

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Ms Hsiao Tong.

Hi Hsiao Tong,

FYNA, our ref CC3/III19009453/K1pb3

Thank you.

Best Regards,

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 (Ext:119) Email: <u>SuLi@lkkauto.com</u> Fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Foong Shiuh Jye [mailto:shiuhjye.foong@premiertaxi.com]

Sent: Monday, 26 August 2019 11:28 AM

To: Asher Sng (LKKAuto)
Cc: AccReport; CS A Team

Subject: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

Without Prejudice

Dear all,

Wish to follow up the case.

Appreciate your reply.

Thank you.

Regards,

Foong Shiuh Jye Claims Settlement Assistant Premier Automotive Services Pte Ltd Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel; 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Foong Shiuh Jye

Sent: Monday, 15 July, 2019 3:48 PM

To: Joylrene@lkkauto.com; AsherSng@lkkauto.com

Cc: AccReport < AccReport@Premier-Corp.net>; cs-a@lkkauto.com

Subject: (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

WITHOUT PREJUDICE

Dear all,

Your Ref : GBF3027Z

Our Ref : SHB8877D/SJ

Date of accident : 27.05.2019

We refer to the above mentioned accident.

Hereby we would like to append our losses from India International Insurance Pte Ltd, as insurers of vehicle number GBF3027Z which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Thank you.

Regards,

Foong Shiuh Jye
Claims Settlement Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

Claim Audit



Print Received Message

This mail is associated with:

*SHB8877D (MCV2019D0000547) [GBF3027Z] TP PREMIER TAXIS PTE LTD May 27 2019 10:00AM

Premier Automotive Services Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 23/09/2019 11:14 AM.

To

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$0.00) - SHB8877D - Claim Handler; Lalitha Krishnan

Approved:0.00:You may agree to 50/50 settlement on liability. Please revert on quantum

Claim Audit

4	AUDIT TRAIL			BY
n.	On	Audit	Remarks	[A] La
	29 May 2019 12:33	Clm Dtl Modified	Claimant's Name: -> PREMIER TAXIS PTE LTD. Claimant's ID: -> 200304975H.	Shu Pe
	29 May 2019 12:33	Cim Veh Model Changed	(204023) KIA OPTIMA 1.7 D (A).	Shu P
	29 May 2019 12:33	Clm Created	Reg No: SHB8877D, Acct Date: 2019/05/27, Claim Type: TP, Insurer: India Internation al Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Premier Automotive Services Pte Ltd (HQ)	[A] La Shu P
	29 May 2019 12:33	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] La Shu P
	29 May 2019 12:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/05/10	[A] La Shu P
	29 May 2019 12:33	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] La Shu P
	29 May 2019 12:33	Label Added	(30653):Direct Settlement.	[A] Li Shu P
	29 May 2019 12:33	Adj Adjuster Assigned	[None] -> KALVIN ANG WEI KUN	[A] Li Shu P
1	29 May 2019 17:24	Clm Registration Modified	Pol No:->D18MCV0001327.	[1] Natal Lim
0	21 Sep 2019 13:42	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 50% Remarks: Conflicting version. TP has no video foota ge.	(A) CHE HSIA TON
1	23 Sep 2019 11:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/10. Mandate Remarks: You may agree to 50/50 settlement on liability. Please revert on quantum	[1] Laliti Krishr
2	23 Sep 2019 11:14	Adj Mandate Set	Approved: 0.00: You may agree to 50/50 settlement on liability. Please revert on quantum	[1] Lalit Krishi (A)
3	04 Oct 2019 13:56	Adj Rpt Initiated		Elair Kua Hw Mee
4	04 Oct 2019 13:56	Clm Dtl Modified	Insured Name: -> -, Insured ID: ->	Elair Kua Hwi Mee
5	04 Oct 2019 13:56	Clm Dtl Modified	JPJ Reg. Date: -> 2014/03/27.	Elair Kua Hw Mee
:6	04 Oct 2019 13:56	Clm Details Notified		[A Elair Kua Hw Mee
1.7	, 01 Nov 2019 09:20	Adj Mandate Request	Cur.Req:976.14:PODS Liability: 50% *Quantum: [(a)CORw/GST: \$1,391.00 + (b)LOR (4days x \$99.32); \$397.28 + (c)LOI(4days x \$40.00):\$160.00]@50% + (d)LTA/GIA S earch Fee:\$2.00 = Total: \$976.14 *Vehicle Model: Kia Optima (1685cc) *3 recommendation repa	CHE HSI/ TON

 **	1/1	-	v	

No record

BIL Ref No	Bill Diese	THE TYPE	Acc Type	Act Name	(Soarch)	BiFL	Milt 2	Amount
2287832	23 Sep 2019 09:44:09	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	SHB8877D	GBF3027Z	11.77
2302564	04 Oct 2019 13:56:23	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHB8877D	GBF3027Z	11.77

Print Received Message

This mail is associated with:

*SHB8877D (MCV2019D0000547) [GBF3027Z]

TP PREMIER TAXIS PTE LTD May 27 2019 10:00AM

[-] Premier Automotive Services Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/11/2019 12:01 PM.

To Subject

Alert - Adj Mandate Approved (S\$976.14) - SHB8877D - Claim Handler: Lalitha Krishnan

Approved:976.14.

Hsiao Tong (LKKAuto)

From:

Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Sent:

Wednesday, 20 November 2019 2:15 PM

To:

Hsiao Tong (LKKAuto)

Cc:

AccReport: CS A Team; Admin A

Subject:

(Accept offer) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on

27.05.2019 //LKK REF: CC3/III19009453/K1pb3

WITHOUT PREJUDICE

Dear Hsiao Tong,

We thank you for your email.

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHB8877D, our client is agreeable on your offer of \$970.00 for the settlement on the above claim.

Kindly let us have your <u>DV</u> and settlement sum of <u>\$970.00</u> in favour of Premier Automotive Services Pte Ltd at earliest convenience.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damages only.

Thank you.

Regards,

(Mr) Foong Shiuh Jye Claims Settlement Assistant

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Monday, 4 November, 2019 8:26 AM

To: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Cc: AccReport <AccReport@Premier-Corp.net>

Subject: RE: (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK REF:

CC3/III19009453/K1pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$970.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Sent: Tuesday, 15 October 2019 11:14 AM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com Cc: AccReport < AccReport@Premier-Corp.net

Subject: (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK REF:

CC3/III19009453/K1pb3

Without Prejudice

Dear Hsiao Tong,

Wish to follow up the case.

Appreciate your reply.

Thank you.

Regards,

(Mr) Foong Shiuh Jye
Claims Settlement Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Foong Shiuh Jye

Sent: Monday, 9 September, 2019 9:37 AM

To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com > Cc: AccReport < AccReport@Premier-Corp.net >

Subject: (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK REF:

CC3/III19009453/K1pb3

Without Prejudice

Dear Sirs,

Referring to the email below,

There was no video for the case.

Sorry for inconvenience.

Thank you.

Regards,

Foong Shiuh Jye
Claims Settlement Assistant
Premier Automotive Services Pte Ltd
Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Wednesday, 28 August, 2019 10:19 AM

To: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>

Cc: AccReport < AccReport@Premier-Corp.net>

Subject: RE: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019 //LKK REF:

CC3/III19009453/K1pb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. Attached is a copy of our insured accident report for your easy reference.

As per III instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

n roo,ugunat mnom:

Circumstances of Accident

ON THE STATED DATE AND TIME, MY VEHICLE WAS PARKED AT THE CARPARK OF BET HAMILTON RD / CAVAN WHILE I WAS REVERSING MY VEHICLE, I SAW A TAXI (VEHICLE B -SHB8877D) COMING FROM FAR HOWEVER II WRONG DIRECTION THEREFORE I STOPPED MY VEHICLE TO LET IT PASSED THROUGH. VEHICLE B CAME STR AND HIT ONTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?


NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB8877D

Vehicle Make/Model/Colour



"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Su Li (LKK Auto) <suli@lkkauto.com> Sent: Monday, 26 August 2019 2:02 PM

To: Foong Shiuh Jye <shiuhjye.foong@premiertaxi.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: AccReport <AccReport@Premier-Corp.net>; CS A Team <cs-a@lkkauto.com>

Subject: RE: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

Without Prejudice

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Ms Hsiao Tong.

Hi Hsiao Tong,

FYNA, our ref CC3/III19009453/K1pb3

Thank you.

Best Regards,

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 (Ext:119) Email: <u>SuLi@lkkauto.com</u> Fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Foong Shiuh Jye [mailto:shluhjye.foong@premiertaxi.com]

Sent: Monday, 26 August 2019 11:28 AM

To: Asher Sng (LKKAuto)
Cc: AccReport; CS A Team

Subject: (Reminder) (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

Without Prejudice

Dear all,

Wish to follow up the case.

Appreciate your reply.

Thank you.

Regards,

Foong Shiuh Jye
Claims Settlement Assistant
Premier Automotive Services Pte Ltd
Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

From: Foong Shiuh Jye

Sent: Monday, 15 July, 2019 3:48 PM

To: JovIrene@lkkauto.com; AsherSng@lkkauto.com

Cc: AccReport <AccReport@Premier-Corp.net>; cs-a@lkkauto.com

Subject: (III case) LOD / Accident Involving SHB8877D and GBF3027Z on 27.05.2019

WITHOUT PREJUDICE

Dear all,

Your Ref : GBF3027Z

Our Ref : SHB8877D/SJ

Date of accident : 27.05.2019

We refer to the above mentioned accident.

Hereby we would like to append our losses from India International Insurance Pte Ltd, as insurers of vehicle number GBF3027Z which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand and supporting documents for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Thank you.

Regards,

Foong Shiuh Jye Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 069 | DID: 65446671 | Fax: 6214 1511

Premier Automotive Services Pte Ltd

23 Changi South Avenue 2 #04-02

Singapore 486443

GST 200707743D ROC 200707743D

Phone: (6 Fax: (6

(65) 6214 8880 (65) 6214 4498

Tax Invoice



Date	Page
Dec 04, 2019	1
Invoice N	umber
IV19120	18636

Sold To:

INDIA INTERNATIONAL INSURANCE PTE LTD 64 Cecil Street #04/#05

IOB Building Singapore 049711 049711 Ship To:

INDIA INTERNATIONAL INSURANCE PTE LTD 64 Cecil Street #04/#05 IOB Building Singapore 049711 049711

	Shipment / DO No. SM1911023608	Order Date	Vehicle No. SHB8877D	TP/19052	ase ID 27/SH		PO Numbe	r	Terms 30D
3/N	Item Number	De	scription	S	ity.	Unit Price	Total Discount	Total	Amount
1	ICGST1	Cost of Repair (subject to	g GST)				0.00		650.00
2	ICGST2	Loss of Rental (subject to	GST)				0.00		139.2
3	ICGIA	GIA Search Fee (subject					0.00		1.8
4	ICNGST	Misc Charges (not subje					0.00		123.5
Ac	omments: ccident involving GBF30	27Z on 27/5/19				Subtotal Less disco Total amou			914. 0. 914. 55.
Αı	uthorised By:					Grand tota	I)		970.

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

LAIM SUBF	OLDER TRA	CKING						7		
Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Statu		
Main:	29 May 2019 Edit Reg		28 May 2019 00:00 Edit Adj Rpt	5\$1,300.00 Edit Estima	4 1 70	1,300.00 lew Rpt		Repo	ing for 5 et cei Case	l
	tain	R	eference	Clair	n Details		Documents		1 4	Show All
CLAIM SUE	SFOLDER DE	TAILS				[Created	by adjuster]			
Insured:	LI TAT RE	NOVATION, CO	o. Reg. No.: -							
Main Claimant:	PREMIER	TAXIS PTE LTD	, Co. Reg. No.: 20	0304975H						
Vehicle Reg. No.:	SHB887	7D		Da	te of Loss:		9 10:00 - :59 s From LTA Reg Dat	e (Man '	(r)]	
Claim Type:	TP / MC	/2019D000054	17		icy/Cover te No.:	D18MCV00	01327			
Vehicle Reg. No. (Insured):	o. GBF3027Z (Claimant): 51072028				510720288	7202885				
				Ex	cess:					
Repairer:	Premier A	Automotive Serv	ices Pte Ltd (HQ)	23 Changi Sout	h Ave 2, #	01-02, 48644	13 Changi - Tel: 62	148880		
Handling Insurer:	India Int	ernational Insur	rance Pte Ltd (HQ)	- Tel: 6347610	0 [Hand	fied by Laliti	na Krishnan - 634	7 6139]		
Claimant's Insurer:			Co-operative Ltd (STATE THE						
Adjuster:	10/06/20		e Ltd (HQ) - Tel: 62	756-3561 [Hi	indled by P	CALVIN ANG	WEI KUN] [F	inal Rp	ot due	
ASSOCIAT	ED MAIL RE	CEIVED					View	All I	Compose	Case Ma
• 111_SG (2	23/09/2019): CIATED TAS	Alert - Adj Mand KS⊟	date Approved (S\$ date Approved (S\$ k Group Subje	0.00) - SHB88	770 - Cla	im Handler:	Lalitha Krishn	eate New Crea	Task on	Complet

Claim Documents

*SHB8877D (MCV2019D0000547)

[GBF3027Z]

TP

PREMIER TAXIS PTE LTD

May 27 2019 10:00AM

[LI TAT RENOVATION]

Premier Automotive Services Pte Ltd

Up	load Documents Up	ioad Photos Compose New Letter	View	View in Brows	-
Pho	tos/Images		3 per pi	ige 🔽	V
Nα	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	30/05/19 06:12	General View	0	Load JPG	2
2	30/05/19 08:12	General View	0	Load JPG	∇
3	30/05/19 08:12	General View	0	Load 3PG	2
4	30/05/19 08:12	General View	0	Load JPG	
5	30/05/19 08:12	General View	0	Load 3PG	Z
6	30/05/19 08:12	General View	0	Load JPG	V
7	30/05/19 08:12	General View	0	Load JPG	1
8	30/05/19 08:12	General View	0	Load 3PG	2
9	30/05/19 08:12	General View	0	Load JPG	2
10	30/05/19 08:12	General View	0	Load 3PG	2
11	30/05/19 08:12	General View	0	Load JPG	50
-	Total Control of the Control of the	General View	0	Load JPG	V
12	30/05/19 08:12		0	Load JPG	82
13	30/05/19 08:12	General View			EZ
14	30/05/19 08:12	General View	0	Load 3PG	
15	30/05/19 08:12	General View	0	Load JPG	Ø
16	18/06/19 09:24	Reinspection Photo	0	Load JPG	80
17	18/06/19 09:24	Reinspection Photo	0	Load JPG	
18	18/06/19 09:24	Reinspection Photo	0	Load JPG	2
19	18/06/19 09:24	Reinspection Photo	0	Load JPG	
Doc	umentation		1 per p	age V	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	29/05/19 17:55	TP ESTIMATE- MARKED	0	Load PDF	
2	29/05/19 17:55	TP GIA REPORT	0	Load PDF	
3	21/10/19 12:50	RENTAL RECEIPT	0	Load PDF	
4	21/10/19 12:50	RENTAL MILEAGE	0	Load PDF	
5	21/10/19 12:50	LOD	0	Load PDF	
6	21/10/19 12:50	GIA SEARCH	0	Load PDF	
7	27/12/19 15:26	WORKSHOP INVOICE	0	Load PDF	
В	27/12/19 15:26	AUTHORISATION TO ACT FORM	0	Load PDF	
9	27/12/19 15:26	DISCHARGE VOUCHER	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Prin
1	20/08/19 14:34	Singapore Accident Statement IV GBF3027Z	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			0
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg. No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/III19009453/K1PB3Q2

Date:

27/12/2019

REFERENCE

India International Insurance Pte Handling Insurer.

Policy No:

D18MCV0001327

Claimant Vehicle No: SHB8877D

Insured Vehicle No:

GBF3027Z

TP

Date of Loss:

27/05/2019

Nature of Claim:

Claim

MCV2019D0000547

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHB8877D

Make & Model:

KIA OPTIMA, 1.7 D (A)

27/03/2014 (Man. Year: 2013)

Engine No: Chassis No:

Odometer:

D4FDDH308962

582958 km

KNAGM414ME5455290

Reg. Date: Colour:

Silver

Engine Capacity: Market Value/New Car 1685 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

970.00

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Rear Tyre Size:

205/65 R16

Front Tyre Size: Front Left Side:

205/65 R16 Hankook 7 mm

Rear Left Side:

Hankook 7 mm

Front Right Side:

Hankook 7 mm

Rear Right Side:

Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,245.90	931.10	314.80	25.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	710.00	720.00	50.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,675.90	1,641.10	1,034.80	38.67
Approved Total (Overridden) (S\$)		1,300.00		
(SS)	2,675.90	1,300.00	1,375.90	51.42
+ GST 7.00/7.00% (S\$)	187.31	91.00	96.31	51.42
Nett Amount (S\$)	2,863.21	1,391.00	1,472.21	51.42
+ Loss of Use (4.0 x S\$	40.00/day) (S\$)	160.00		
+ Car Rental (4.0 x S\$	99.32/day) (S\$)	397.28		
	(S\$)	1,948.28		
Liable Amoun	Liable Amount (50.00%) (S\$)			
	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	976.14		

INSPECTION

Global Sum Settlement (S\$)

Adjuster Report

Date of Assignment:

28/05/2019

Date Inspected:

28/05/2019 Inspected At:

Premier Automotive Services Pte Ltd

(HQ)

23 Changi South Ave 2, #01-02

Singapore 486443

Estimated Period of Repair:

3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Referen	ce			
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 21 Oct 2019)		
Parts:	143	KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SHB8877D)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Deformed	531.00 FL	*531.00 FL
1		*FRONT BUMPER EMBLEM	Necessary	44.00 FL	*44.00 FL
1		*FRONT BUMPER O/S SIDE RETAINER	Serviceable	16.00 FL	*-FL
1		*FRONT O/S FENDER INNER SHIELD	Serviceable	120.00 FL	*-FL
1		*FRONT O/S FENDER	Buckled	384.00 FL	*384.00 FL
1		*FRONT O/S WHEEL COVER	Serviceable	116.00 FL	*-FL
1		*FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
1		*FRONT O/S FENDER STICKER	Not Necessary	30.00 FS	*-FS
1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*-FS
1		*SUNDRY	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)			1,367.00 121.10	1,027.00 95.90	
			Total Parts (S\$)	1,245.90	931.10
	1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1	1 *FRONT BUMPER EMBLEM 1 *FRONT BUMPER O/S SIDE RETAINER 1 *FRONT O/S FENDER INNER SHIELD 1 *FRONT O/S FENDER 1 *FRONT O/S WHEEL COVER 1 *FRONT BUMPER CLIPS 1 *FRONT O/S FENDER STICKER 1 *SET FRONT O/S FENDER INNER SHIELD CLIPS 1 *SUNDRY nchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER EMBLEM Necessary 1 *FRONT BUMPER O/S SIDE RETAINER Serviceable 1 *FRONT O/S FENDER INNER SHIELD Serviceable 1 *FRONT O/S FENDER Buckled 1 *FRONT O/S WHEEL COVER Serviceable 1 *FRONT O/S WHEEL COVER Serviceable 1 *FRONT BUMPER CLIPS Necessary 1 *FRONT O/S FENDER STICKER Not Necessary 1 *SET FRONT O/S FENDER INNER SHIELD CLIPS Necessary 1 *SUNDRY Necessary 1 *SUNDRY SUNDRY Necessary 1 *SUNDRY SUNDRY SUNDRY SUND SUND TOtal (S\$)	1 *FRONT BUMPER Deformed 531.00 FL 1 *FRONT BUMPER EMBLEM Necessary 44.00 FL 1 *FRONT BUMPER O/S SIDE RETAINER Serviceable 16.00 FL 1 *FRONT O/S FENDER INNER SHIELD Serviceable 120.00 FL 1 *FRONT O/S FENDER Buckled 384.00 FL 1 *FRONT O/S WHEEL COVER Serviceable 116.00 FL 1 *FRONT BUMPER CLIPS Necessary 48.00 FS 1 *FRONT O/S FENDER STICKER Not Necessary 30.00 FS 1 *SET FRONT O/S FENDER INNER SHIELD CLIPS Not Necessary 28.00 FS 1 *SUNDRY Necessary 50.00 FS nchise part. S=SpcNett. L=ListItemDisc Sub Total (S\$) 1,367.00 - List Item Discount on L Items 10.00/10.00% (S\$) 121.10

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ,ETC	New	650.00	300.00
4	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER	New	400.00	360.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	50.00
	Gross Labour Cost (S\$)		1,430.00	710.00

< END OF ESTIMATES >