

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

28-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8877 D

1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper o/s side retainer @ \$16.00 ✕	\$	16.00
1 pc	Front o/s fender inner shield @ \$120.00 ✕	\$	120.00
1 pc	Front o/s fender @ \$384.00 ✓	\$	384.00
1 pc	Front o/s wheel cover @ \$116.00 ✕	\$	116.00
		\$	1,211.00
Less 10%		\$	121.10
		\$	1,089.90

S/NETT

1 pc	Front bumper clips ✓	\$	48.00
1 pc	Front o/s fender sticker ✕	\$	30.00
1 set	Front o/s fender inner shield clips ✕	\$	28.00

Sundry

\$ ~~50.00~~ 20

To check wheel alignment

\$ ~~80.00~~ ✕

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ ✕

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.

\$ ~~650.00~~ 300

To putty and spray painting on front bumper, front o/s fender

\$ ~~400.00~~ 360

To apply rustproofing on the repaired and replaced panels.

\$ ~~120.00~~ 50

\$ 2,675.90

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

The Repairer's liability is limited to the following:
• To comply with the relevant insurance survey
• Parts provided are of standard quality
• Third party survey is not allowed
• No illegal modification or alteration on the basis
• Supplementary damage may be reserved and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Kelvin 16/05/19
28/5/19 17:05h
30y
4/5
After Repair photo