

PERFECT WERKZ

Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800
 HP: 92712214 Fax: (65) 69664526 ROC : 53364512C

EXCEL HARDWARE PTE LTD
 Bk 25 Kaki Bukit Rd 4
 # 06-51 SYNERGY @KB
 Singapore 417800

TP China
 Jia Le

27th MAY 2019

JNIMC2E26Z0008117

Accident date: 25th MAY 2019

Estimated repair cost for vehicle no: GBG3847T NISSAN NV350

S/n	Qty	Items	U/price	Amount
				\$3,500.00 210.40
1	1	Rear Boot Lid Distorted		\$760.00 ✓
2	1	Rear Bumper Distorted		\$176.40 ✓ 58.
3	2	Rear Bumper Side Bracket New	\$88.20	\$65.00 30
4	10	Rear Bumper Clips New	\$6.50	\$188.20 X
5	1	Rear Bumper Inner Sponge New		\$468.10 ✓
6	1	Rear End Panel Outer Dented		\$841.80 X
7	1	Rear End Panel Inner Repair		\$852.10 X
8	1	Rear Exhaust New		\$858.50 ✓
9	1	Front Bonnet Distorted		\$57.90 +
10	1	Front Bonnet Lock Panel New		\$348.60 +
11	1	Front Head Lamp Lower Cover New		\$612.00 ✓
12	1	Front Bumper Deformed		\$116.00 ✓
13	2	Front Bumper Side Bracket New	\$58.00	\$50.00 30(SW)
14	1	Front Bumper Number Plate Bent		\$65.00 30(SW)
15	10	Front Bumper Clips New	\$6.50	\$280.70 X
16	1	Front Bumper Inner Sponge New		\$591.90 X
17	1	Front Bumper Reinforcement New		\$295.70 X
18	1	Front Support Panel Top 2 x 1		\$253.50 X
19	1	Front Support Panel Lower New		\$92.60 X
20	2	Front Support Panel Side Cover	\$46.30	
Subtotal :-				\$5,999.50

S/n	Qty	Items/Nett	U/price	Amount
1	10	Rear boot lid inner trim board clips <i>Not New</i>	\$5.50	\$55.00 ✓
2	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$220.00 ✓
3	1	Rear Boot Lid Center Moulding <i>cracked</i>		\$168.20 ✓
4	10	Rear Boot Lid L/H Inner Trim Board Clips <i>Not New</i>	\$5.50	\$55.00 ✓
5	1	Rear Boot Lid Inner Rubber <i>cut</i>		\$220.20 ✓
6	2	Rear Tail Lamp <i>LH cracked</i>	\$360.20	\$720.40 360.20 ✓
7	1	Rear End Panel Top Garnish <i>3 new</i>		\$185.20 ✓
8	1	Rear Spare Tyre Bracket		\$212.70 ✓
9	1	Rear Boot Lid Inner Trim board <i>deformed</i>		\$488.50 129 ✓
10	1	Rear centre step panel <i>Box</i>		\$188.60 ✓
11	1	Front Bonnet Lock <i>New</i>		\$95.20 ✓
12	1	Front Grille <i>cracked</i>		\$325.10 ✓
13	1	Front Grille Emblem Logo <i>New</i>		\$55.20 ✓
14	8	Front Grille Clips <i>New</i>	\$5.50	\$44.00 20 ✓
15	2	Front Head Lamp- <i>cracked</i>	\$520.10	\$1,040.20 ✓
16	10	Front Support Panel Side Cover Clips <i>New</i>	\$6.50	\$65.00 ✓
17	1	Front Bumper Towing Cover <i>New</i>		\$38.20 ✓
18	1	Front bumper lower cover <i>Not New</i>		\$234.90 ✓
19	1	Front Air-Con Condenser <i>3 new</i>		\$861.20 ✓
20	1	Front condenser Fan Motor Assy <i>new</i>		\$652.70 ✓
		Air Con Blower <i>cracked</i> 680.40 ✓	8411.10	5. N: 60
		Subtotal :-		\$5,917.50
		7569.99		

S/n	Qty	Items/S.Nett	U/price	Amount
1	1	Rear boot lid Emblem logo ?		\$60.00 ✓
2	1	Rear Boot Lid body logo <i>New</i>		\$500.00 ✓
3	1	Rear Boot Lid NV350 Logo		\$77.40 ✓
4	1	Rear Bumper Reverse Sensor-set <i>Damaged</i>		\$300.00 200 ✓
5	1	Rear Boot Lid 70 pax Logo <i>New</i>		\$30.00 15 ✓
6	1	Rear Boot Lid Number Plate <i>New</i>		\$50.00 ✓
7	2	Front Bumper Fog Lamp <i>3 new</i>	\$278.10	\$556.20 ✓
8	2	Front Bumper Fog Lamp Cover <i>new</i>	\$125.20	\$250.40 ✓
9	1	Front body logo <i>New</i>		\$250.00 ✓
10	8	Front bumper clips <i>New</i>	\$2.60	\$20.80 ✓
		Subtotal :-		\$2,094.80

1123.20

Labour charges

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit front windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To remove & refit rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

Remove & refix front air cond & in gas

\$250.00 X

To Check Wiring

~~\$80.00~~ 60

Wheel alignment (computer)

\$120.00 X

Tuff kote

~~\$100.00~~ 60

Panel beating

2000 1800

Spray painting

2000 1500

Subtotal :- \$3,790.00

Total:- \$17,801.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 12563.19

4/5: 10K.

20 days.

Date _____
 Signature _____
 Acknowledged by Repairer

is subject to that approval from Insurance Company
 • Supplemental items must be reviewed and
 • No illegal modifications allowed
 • Third party survey at a "Vehicle Inspection" base
 • Parts prices are subject to confirmation
 • To display damaged part(s) during survey
 • To restore interior/exterior paint
 the Repairer of the following:

LKK Auto Consultants hence notify