

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department \ CLAIMS

Estimate No: EST1900156

Date: 27 May 2019

Veh Reg No: SKD8730Y

Make/Model: TOYOTA VIOS E
MANUAL

Chasis No: MR053HY9305283596

Reg. Date: 16/01/2012

Your Ref No: SHC8931A

Claim Type: Third Party

Accident Date: 25/05/2019

TP Veh Reg No: SHC8931A

Vivian

Estimate Repair Cost to Vehicle No :SKD8730Y

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR BUMPER <i>Dehd</i>	407.50 ✓	
2	2 PCS REAR BUMPER BRACKET <i>new RH Best</i>	127.40 + 63.70	
3	1 PC REAR BUMPER RETAINER RH <i>new</i>	92.30 ✓	
4	1 PC REAR BUMPER RETAINER RH (SMALL) <i>new</i>	28.40 +	
5	1 PC REAR BUMPER REFLECTOR - RH <i>cracked</i>	82.80 ✓	
6	1 PC BOOT LID <i>Backhd.</i>	584.80 ✓	
7	1 PC BOOT LID LOGO	50.80 ✓	
8	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	44.20 ✓	
9	1 PC BOOT LID "E" EMBLEM	34.40 ✓	
10	2 PCS BOOT LID HINGE <i>new</i>	95.80 +	
11	1 PC BOOT LID LOCK <i>new</i>	95.80 +	
12	1 PC BOOT LID LOCK CHECKER <i>new</i>	24.80 +	
13	1 PC BOOT LID RUBBER <i>new</i>	175.30 ✓	
14	1 PC REAR FENDER TRIM RH <i>new</i>	224.20 +	
15	1 PC TAIL LAMP - RH <i>cracked</i>	409.90 325	
16	1 PC REAR PANEL <i>Dented</i>	571.80 ✓	
17	1 PC REAR PANEL TRIM <i>Dehd</i>	200.70 ✓	
18	1 PC SPARE TYRE COVER <i>torn</i>	144.70 ✓	
19	1 PC SPARE TYRE PANEL RH SPONGE <i>Dehd</i>	214.10 ✓	
		3,609.70	
	Less 25%	902.43	2,707.31
	Special Net		
20	1 SET REAR BUMPER CLIPS <i>new</i>	48.00 - 50	
21	1 PC "L" PLATE <i>Best</i>	50.00 ✓	
22	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 - 40	
23	1 SET REAR BUMPER STICKER <i>new</i>	195.00 ✓	
24	1 PC BOOT LID NUMBER '292' STICKER <i>new</i>	35.00 ✓	
25	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	48.00 +	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62244174
ATTN: Motor Claim Department \ CLAIMS

Claim Type: Third Party
Accident Date: 25/05/2019
TP Veh Reg No: SHC8931A

Estimate No: EST1900156
Date: 27 May 2019

Veh Reg No: SKD8730Y
Make/Model: TOYOTA VIOS E
MANUAL
Chasis No: MR053HY9305283596
Reg. Date: 16/01/2012
Your Ref No: SHC8931A

Estimate Repair Cost to Vehicle No :SKD8730Y

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
26	1 PC REAR FENDER STICKER RH HE Nec 550	190.00 ✓	
27	1 SET REAR PANEL TRIM CLIPS ME	40.00 10.	
		676.00	676.00
	Labour		
28	1 TO CHECK WIRING	50.00 30	
29	1 TO REPLACE STICKERS	80.00 50.	
30	1 TO SPRAY UNDERSEAL	180.00 60.	
31	1 (REAR) TO SPRAY PAINTING	1,300.00 1000.	
32	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00 80	
33	1 TO REMOVE AND REFIT INNER TRIM	180.00 60	
		3,090.00	3,090.00
	Total		S\$ 6,473.31
	Add GST @ 7%		453.13
	Total Amount Payable		S\$ 6,926.44

TOTAL: SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED TWENTY SIX AND CENTS FORTY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total: 4754.07
4/8/13 3.8K/s 28/05/19.
07 days
Adrian Lij