

ASS. REC. BY:

REF:

TM1/ C03/TM119009466/1cfd3n2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

SHD 3211Y - X

SLW 3422G - X

RECEIVED 27 AUG 2019

29/5@2:54pm Sent email GIA & estimate. xaa

Part by Part \$1500.53 (Red: 22468.10; 93%)

Date/Time, File Pass to?

21/8 TUPIST

Date/Time, File Return to?



Preil. Report



Final Report

Days Of Repair: 1

Resurvey No. of Trip:

Survey Fee:

Transportation

) S. R. S. Si

) F. R. S.

) Others

) Total

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

TP

Lump Sum / L.S. (\$

1500.53

250

11

261

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 29 May 2019 2:54 PM
To: Motor Claims
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA: 23/5/2019, SHD 5241Y (TP VEHICLE), SKJ 7069Z (OI VEHICLE)
Attachments: ESTIMATE.pdf; GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5241Y at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 22/05/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 13 June 2019 2:19 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SHD 5241Y / TP / TOKIO / DOA: 23/5/2019 -- AAD1905-219

Hi Denise

We propose COR amount \$ 1,500.53 (b4 GST).

Will send you the photo after get it from our workshop.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: Thursday, 13 June, 2019 1:37 PM
To: 'Denise Tay (LKKAUTO)' <denisetay@lkkauto.com>
Subject: RE: SHD 5241Y / TP / TOKIO / DOA: 23/5/2019 -- AAD1905-219

Hi Denise

Please on hold this case.

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: Thursday, 13 June, 2019 1:34 PM
To: 'Denise Tay (LKKAUTO)' <denisetay@lkkauto.com>
Subject: RE: SHD 5241Y / TP / TOKIO / DOA: 23/5/2019 -- AAD1905-219

Hi Denise

We propose COR amount \$917.48 (b4 GST).

Will send you the photo after get it from our workshop.

Thank You
Best Regards,
Ng Wai Yin

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2019 15:41
Date Of Accident	23/05/2019 17:20
Exact Location Of Accident	AYE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5241Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LIM EK LIONG
NRIC No	S2198974F
Date Of Birth	25/11/1967
Occupation	OUTDOOR
Date Of Driving Pass	27/10/1997
Driving Experience	21 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96672602
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 569 PASIR RIS STREET 51 #04-74
Postcode	510569
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 23/05/2019 AT ABOUT 1720HRS, I WAS TRAVELLING STRAIGHT ALONG THE FIRST LANE OF AYE TOWARDS CHANGI AIRPORT. THE VEHICLES IN FRONT OF ME STOPPED AND I FOLLOWED SUIT. WHILE STATIONARY, I SUDDENLY FELT AN IMPACT FROM THE REAR OF MY TAXI. VEHICLE B(SLW3922G) HAS COLLIDED ONTO THE REAR PORTION OF MY TAXI. I ALIGHTED FROM MY TAXI AND NOTED THAT I WAS INVOLVED IN A CHAIN COLLISION CONSISTING OF VEHICLE C(SKR2068S) AND VEHICLE D(SJS5904R).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW3922G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKR2068S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJS5904R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y

AAD1905-219

Not Notified
Resurvey B4 painting

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 5241Y

JTDKB3FU103078350

TOYOTA

PRIUS

23.5.2019

TOKIO MARINE

12/12/2018

PART**LIST**

- | | |
|----|-------------------------------------|
| 1 | 1 REAR BUMPER |
| 2 | 1 REAR BUMPER RE-INFORCEMENT |
| 3 | 1 REAR BUMPER TOWING COVER |
| 4 | 1 REAR BUMPER UNDER COVER (BLACK) |
| 5 | 1 REAR BUMPER SIDE RETAINER LH |
| 6 | 1 REAR BUMPER SIDE RETAINER RH |
| 7 | 1 REAR TAILGATE |
| 8 | 1 REAR TAILGATE OUTER GARNISH |
| 9 | 1 COVER, REAR COMBINATION LAMP, RH |
| 10 | 1 COVER, REAR COMBINATION LAMP, RH |
| 11 | 1 GARNISH, BACK DOOR SIDE, LH |
| 12 | 1 GARNISH, BACK DOOR SIDE, RH |
| 13 | 1 BOARD ASSY, BACK DOOR TRIM |
| 14 | 1 PANEL ASSY, BACK DOOR TRIM, UPPER |
| 15 | 1 REAR TAILGATE WEATHERSTRIP |
| 16 | 1 REAR END PANEL |
| 17 | 1 TAILLAMP LOWER RH |
| 18 | 1 TAILLAMP UPPER RH |
| 19 | 1 REAR BUMPER SIDE RH |
| 20 | 1 REAR BUMPER SIDE LH |
| 21 | 1 TAILLAMP LOWER LH |
| 22 | 1 TAILLAMP UPPER LH |

\$	<i>Myom</i> *	458.60	X
\$	<i>Ry</i>	318.80	2
\$	<i>cm</i>	14.70	1
\$	<i>Bu</i>	552.60	1
\$	<i>su</i>	112.70	}
\$	<i>su</i>	112.70	
\$	<i>su</i>	1,547.27	
\$	<i>su</i>	905.10	
\$	<i>su</i>	54.70	
\$	<i>su</i>	54.70	
\$	<i>su</i>	93.60	
\$	<i>su</i>	93.60	
\$	<i>su</i>	254.40	
\$	<i>su</i>	51.20	
\$	<i>su</i>	365.20	
\$	<i>su</i>	602.10	
\$	<i>su</i>	548.40	
\$	<i>su</i>	557.90	
\$	<i>su</i>	232.00	
\$	<i>su</i>	232.00	
\$	<i>su</i>	548.40	
\$	<i>su</i>	557.90	

\$	8,268.82
25% \$	2,067.21
\$	6,201.62

Trans-cab Auto Services Pte Ltd

AAD1905-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y

Special Nett

1 1SET PARKING AID	\$	Sm 700.00 X
2 1SET REAR BUMPER CLIP	\$	na 22.00
3 2 REAR WINDSCREEN SELANT	\$	na 80.00
4 1 WINDSCREEN MOULDING	\$	na 100.00
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00
6 1 REAR TAILGATE TOYOTA LOGO	\$	na 47.00
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	na 52.90
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	na 53.50
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na 80.00
10 1 REAR TAILGATE STICKER '6555-3333'	\$	na 80.00
11 1 REAR BUMPER PROTECTOR	\$	na 100.00 50na

TOTAL \$ 1,415.40

TOTAL PARTS \$ 7,617.02**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	2200 / 4,200.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 2000 /
To Rust-Proofing Of The Affected Areas.	\$	na 170.00 X
To reinstall rear bumper parking sensor.	\$	na 170.00 X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	na 170.00 X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	na 170.00 X
To repair and realign rear exhaust pipe.	\$	na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1905-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y

To drop rear exhaust box, renew the same, to repair and
realign centre exhaust pipe. \$ *nn* 170.00 X

To transfer of rear end panel fittings, attachment and
perform water seepage test. \$ *nn* 170.00 X

To transfer of rear windscreen fittings and conduct water
seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment \$ *nn* 220.00 X

To transfer of Rear fender fittings, attachments and
perform water seepage test. \$ *nn* 170.00 X

TOTAL \$ 10,150.00

Over All Total \$ 23,968.63

17766.83

(PART-BY-PART) Repair Days

~~20~~ DAYS

1 day

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y**AAD1905-219***Not Authorised
Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5241Y

JTDKB3FU103078350

TOYOTA

PRIUS

23.5.2019

TOKIO MARINE

12/12/2018

PART**LIST**

- | | |
|----|-------------------------------------|
| 1 | 1 REAR BUMPER |
| 2 | 1 REAR BUMPER RE-INFORCEMENT |
| 3 | 1 REAR BUMPER TOWING COVER |
| 4 | 1 REAR BUMPER UNDER COVER (BLACK) |
| 5 | 1 REAR BUMPER SIDE RETAINER LH |
| 6 | 1 REAR BUMPER SIDE RETAINER RH |
| 7 | 1 REAR TAILGATE |
| 8 | 1 REAR TAILGATE OUTER GARNISH |
| 9 | 1 COVER, REAR COMBINATION LAMP, RH |
| 10 | 1 COVER, REAR COMBINATION LAMP, RH |
| 11 | 1 GARNISH, BACK DOOR SIDE, LH |
| 12 | 1 GARNISH, BACK DOOR SIDE, RH |
| 13 | 1 BOARD ASSY, BACK DOOR TRIM |
| 14 | 1 PANEL ASSY, BACK DOOR TRIM, UPPER |
| 15 | 1 REAR TAILGATE WEATHERSTRIP |
| 16 | 1 REAR END PANEL |
| 17 | 1 TAILLAMP LOWER RH |
| 18 | 1 TAILLAMP UPPER RH |
| 19 | 1 REAR BUMPER SIDE RH |
| 20 | 1 REAR BUMPER SIDE LH |
| 21 | 1 TAILLAMP LOWER LH |
| 22 | 1 TAILLAMP UPPER LH |

\$	R	458.60	X
\$	B	318.80	2
\$	CM	14.70	✓
\$	Bu	552.60	✓
\$	Sn	112.70	} X
\$	Sn	112.70	
\$	R	1,547.27	
\$	Sn	905.10	
\$	Sn	54.70	
\$	Sn	54.70	
\$	Sn	93.60	
\$	Sn	93.60	
\$	Sn	254.40	
\$	Sn	51.20	
\$	Sn	365.20	
\$	R	602.10	
\$	Sn	548.40	
\$	Sn	557.90	
\$	Sn	232.00	
\$	Sn	232.00	
\$	Sn	548.40	
\$	Sn	557.90	

	\$	8,268.82	57
25%	\$	2,067.21	
	\$	6,201.62	

42

Trans-cab Auto Services Pte Ltd

AAD1905-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y

Special Nett

1 1SET PARKING AID	\$	700.00	X
2 1SET REAR BUMPER CLIP	\$	22.00	
3 2 REAR WINDSCREEN SELANT	\$	80.00	
4 1 WINDSCREEN MOULDING	\$	100.00	
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
6 1 REAR TAILGATE TOYOTA LOGO	\$	47.00	
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	52.90	
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	53.50	
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	
10 1 REAR TAILGATE STICKER '6555-3333'	\$	80.00	
11 1 REAR BUMPER PROTECTOR	\$	100.00	50%

TOTAL \$ 1,415.40**TOTAL PARTS \$ 7,617.02****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	220%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	200%
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-219**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5241Y

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	~ 170.00 X

TOTAL \$ 10,150.00**Over All Total \$ 23,968.63**

17766.83

(PART-BY-PART) Repair Days**20 DAYS**

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19009466/KTD3N2

Date: 02/09/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000250
Claimant Vehicle No :	SHD5241Y	Insured Vehicle No :	SLW3922G
Date of Loss:	23/05/2019	Nature of Claim:	TP
		Claim No:	M1903774

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5241Y	Engine No:	2ZR2B90313
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU103078350
Reg. Date:	12/12/2018 (Man. Year: 2018)	Odometer:	37068 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,616.83	1,080.52	6,536.31	85.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,150.00	420.00	9,730.00	95.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,766.83	1,500.52	16,266.31	91.55
+ GST 7.00/7.00% (S\$)	1,243.68	105.04	1,138.64	91.55
Nett Amount (S\$)	19,010.51	1,605.56	17,404.95	91.55

INSPECTION

Date of Assignment:	29/05/2019	
Date Inspected:	28/05/2019 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$1,500.53

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2019)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5241Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	458.60 FL	*458.60 FL
2	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
3	1		*REAR BUMPER TOWING COVER	Cracked	14.70 FL	*14.70 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Buckled	552.60 FL	*552.60 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,547.27 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	905.10 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
10	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	54.70 FL	*- FL
11	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	93.60 FL	*- FL
12	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	93.60 FL	*- FL
13	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	254.40 FL	*- FL
14	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	51.20 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	365.20 FL	*- FL
16	1		*REAR END PANEL	Repair	602.10 FL	*- FL
17	1		*TAILLAMP LOWER RH	Serviceable	548.40 FL	*- FL
18	1		*TAILLAMP UPPER RH	Serviceable	557.90 FL	*- FL
19	1		*REAR BUMPER SIDE RH	Serviceable	232.00 FL	*- FL
20	1		*REAR BUMPER SIDE LH	Serviceable	232.00 FL	*- FL
21	1		*TAILLAMP LOWER LH	Serviceable	548.40 FL	*- FL
22	1		*TAILLAMP UPPER LH	Serviceable	557.90 FL	*- FL
23	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
24	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
25	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
26	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
27	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
28	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
29	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
30	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
31	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
32	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
33	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,683.97	1,416.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,067.14	336.18
Total Parts (\$\$)	7,616.83	1,080.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
8	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
11	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
12	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			10,150.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >