

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

XE3700H UD Trucks

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy (inner)	\$ 1,670.00
2	1	Front bumper assy (outer)	\$ 1,478.00
3	1	Front bumper top protector	\$ 258.00
4	1	Front bumper reinforcement	\$ 392.00
5	1	Front bumper reinforcement left side bracket	\$ 125.00
6	1	Front towing hock	\$ 182.00
7	1	Front towing hock plate	\$ 46.00
8	1	Front bumper left bracket	\$ 51.00
9	3	Front bumper left side stay	\$ 129.00
10	1	Front torsion bar	\$ 824.00
11	1	Front torsion bar bracket	\$ 232.00
12	2	Front torsion bar mounting	\$ 364.00
13	1	Front torsion bar left side absorber	\$ 435.00
14	1	Front grille assy	\$ 552.00
15	2	Front grille cover	\$ 195.00
16	1	Front panel assy	\$ 1,780.00
17	1	Front panel lock assy	\$ 185.00
18	1	Front panel lock catch	\$ 135.00
19	1	Front panel Quon emblem	\$ 128.00
20	2	Front panel lock assy	\$ 180.00
21	2	Front panel lock catch	\$ 160.00
22	1	Front dashboard assy	\$ 3,630.00
23	1	Front dashboard centre console	\$ 2,830.00
24	1	Front dashboard glove box	\$ 323.00
25	1	Front air-con condenser assy	\$ 1,270.00
26	2	Front air-con blower filter	\$ 120.00
27	1	Front radiator assy	\$ 1,653.00
28	1	Front left corner panel	\$ 632.00
29	1	Front windscreen glass assy	\$ 11,000.00
30	1	Front windscreen glass moulding	\$ 480.00
31	3	Front wiper arm	\$ 398.00
32	3	Front wiper arm cover	\$ 79.00
33	3	Front wiper link	\$ 274.00
34	3	Front wiper pivot	\$ 160.00
35	3	Front wiper pivot cover	\$ 68.00
36	3	Front wiper blade	\$ 206.00
37	1	Front wiper tank	\$ 315.00
			\$ 32,939.00
Less 10%			\$ 3,293.90
			\$ 29,645.10

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

XE3700H UD Trucks

			Estimated
No	Qty	Parts Description	Parts Price
38	1	Front wiper outer garnish	\$ 643.00
39	1	Front wiper motor	\$ 495.00
40	1	Front view mirror	\$ 180.00
41	1	Front left wing mirror	\$ 1,059.00
42	1	Front left wing mirror support bar	\$ 278.00
43	1	Front left wing mirror bracket	\$ 156.00
44	1	Front cabin left inner handle	\$ 96.00
45	1	Front cabin left inner handle cover	\$ 66.00
46	1	Front left headlamp	\$ 1,280.00
47	1	Front left headlamp bracket	\$ 220.00
48	1	Front left headlamp holder	\$ 65.00
49	1	Front left headlamp wire harness	\$ 650.00
50	1	Front left signal lamp	\$ 155.00
51	1	Front left step garnish (upper)	\$ 1,275.00
52	1	Front left step garnish (lower)	\$ 1,295.00
53	1	Front left foot step (upper)	\$ 393.00
54	1	Front left foot step (lower)	\$ 393.00
55	1	Front left step garnish bracket	\$ 95.00
56	1	Front left step garnish reflector	\$ 88.00
57	1	Front left door panel assy	\$ 3,675.00
58	2	Front left door hinges	\$ 265.00
59	1	Front left door lock	\$ 195.00
60	1	Front left door outer handle	\$ 389.00
61	1	Front left door weatherstrip	\$ 388.00
62	1	Front left door inner insulation	\$ 260.00
63	1	Front left door inner rubber	\$ 128.00
64	1	Front left door regulator with motor	\$ 495.00
65	1	Front left door panel GK17420 emblem	\$ 180.00
66	1	Front left fender	\$ 889.00
67	1	Front left fender inner shield	\$ 325.00
68	1	Front left support bracket	\$ 190.00
			\$ 16,261.00
Less 10%			\$ 1,626.10
			\$ 14,634.90

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

XE3700H UD Trucks

			Estimated
No	Qty	Parts Description	Parts Price
69	1set	Front cabin mounting bracket	\$ 480.00
70	1	Front cabin bracket 1st	\$ 95.00
71	1	Front cabin bracket 2nd	\$ 95.00
72	1	Front cabin bracket 3rd	\$ 354.00
73	1	Front cabin bracket 4th	\$ 354.00
74	1	Front instrument panel link	\$ 233.00
75	1	Front instrument panel reinforcement	\$ 960.00
76	1	Front instrument panel reinforcement bracket	\$ 125.00
77	1set	Front power steering pipe	\$ 1,200.00
78	1	Front left leaf spring suspension assy	\$ 2,400.00
79	1	Front stabilizer bar	\$ 850.00
80	1	Front left shock absorber assy	\$ 650.00
81	1	Front left lower arm	\$ 750.00
82	1	Front steering rack assy	\$ 4,300.00
83	1	Front steering box assy	\$ 4,200.00
84	1	Front steering column assy	\$ 3,600.00
			\$ 20,646.00
Less 10%			\$ 2,064.60
			\$ 18,581.40
<u>Special Nett Items</u>			
1	16	Front bumper clips	\$ 80.00
2	1	Front bumper top protector sealant	\$ 80.00
3	8	Front grille clips	\$ 50.00
4	8	Front wiper outer garnish clips	\$ 30.00
5	8	Front left door inner insulation clips	\$ 30.00
6	1set	Front left door company advertisement sticker	\$ 350.00
7	8	Front left fender inner shield clips	\$ 40.00
8	1set	Front panel company advertisement sticker	\$ 450.00
9	1	Front left windscreen glass sealant	\$ 80.00
10	1	Front left wheel rim	\$ 1,200.00
11	1	Front left tyre	\$ 600.00
12	1	Front no plate	\$ 80.00
			\$ 3,070.00
Total Parts			\$ 65,931.40

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

XE3700H UD Trucks

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front, front left affected area and replace front and front left damaged parts.	\$ 10,000.00
2	To putty and spray painting front and front left affected portion.	\$ 10,000.00
3	To check wiring and focus front headlamp.	\$ 50.00
4	To apply anti rust proofing to front and front left affected area.	\$ 150.00
5	To remove and install front left door lock mechanism.	\$ 80.00
6	To check door central locking for function.	\$ 80.00
7	To transfer left door glass to new door.	\$ 80.00
8	To remove and install air con system to facilitate the repair and refill gas.	\$ 250.00
9	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 250.00
10	To repair, straighten and align top roof panel.	\$ 2,500.00
11	To remove and install front dashboard panel assy.	\$ 650.00
12	To remove and install front left undercarriage parts.	\$ 350.00
13	To remove and install front power steering rack, steering pipe and steering box.	\$ 350.00
14	To balance front left wheel.	\$ 50.00
15	To conduct wheel alignment.	\$ 120.00
16	To remove and install front windscreen glass assy.	\$ 800.00
17	Towing service.	\$ 300.00
		<u>\$ 26,060.00</u>

Total parts : \$ 65,931.40
Total labour : \$ 26,060.00
Total repair cost : \$ 91,991.40