

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714
 Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526
 Email : chris_chanbebe@hotmail.com

28th MAY 2019

THE CONSTRUCTION PTE LTD
 BLOCK 3020A UBI ROAD 1
 # 01-33
 Singapore 408714

TPAIG.
 Khachana

Accident date: 16th MAY 2019
 Estimated repair cost for vehicle no: GBE9495X NISSAN NV200 '16

S/n	Qty	Items	U/price	Amount
				\$1,253.10 ✓
1	1	Rear Boot Lid L/H Distorted.		\$131.80 x
2	1	Rear Boot Lid L/H Lower Hinge Not nec		\$98.00 ✓
3	1	Rear Boot Lid L/H Windscreen Seal nec		\$460.80 ✓
4	1	Rear Bumper Deformed		\$70.40 ✓
5	2	Rear Bumper Side Bracket nec	\$35.20	\$65.00 30
6	10	Rear Bumper Clips nec	\$6.50	\$41.60 x
7	1	Rear Bumper Side Reflector Not nec		\$88.90 ✓
8	1	Rear Bumper Inner Sponge could		
Subtotal :-				\$2,209.60

S/n	Qty	Items/Nett	U/price	Amount
				\$55.00 x
1	10	Rear Boot Lid L/H Inner Trim Board Clips Not nec	\$5.50	\$91.80 ✓
2	1	Rear Boot Lid L/H Inner Lock Lower Dented		\$102.00 x
3	1	Rear Boot Lid L/H Inner Lock Top Not nec		\$45.60 ✓
4	1	Rear Boot Lid Logo nec		\$143.60 x
5	1	Rear Boot Lid Inner Rubber Not nec		\$203.40 x
6	1	Rear Tail Lamp L/H Not nec	\$203.40	\$55.50 ✓
7	1	Rear End Panel Top Garnish Deformed		\$766.00 x
8	1	Rear Exhaust 3 Not nec		\$131.10 x
9	1	Rear mud flap L/H Not nec		
Subtotal :-				\$1,594.00

2194.10

1974.69

S/n	Qty	Items/S.Nett	U/price	Amount
1	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$250.00 200
2	1	Rear Boot Lid nv200 Logo <i>3 New</i>		\$30.00 ✓
3	1	Rear Boot Lid emble Logo		\$50.00 ✓
4	1	Rear Boot Lid 70km Logo <i>New</i>		\$20.00 10
5	1	Rear Boot Lid 6 pax logo <i>NTM</i>		\$20.00 X
			Subtotal :-	\$370.00

290

Labour charges

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit rear windscreen

~~\$120.00~~ 80

Gum

\$50.00 ✓

To remove & refit rear exhaust

\$200.00 X

To Check Wiring

~~\$60.00~~ 30

Tuff kote

~~\$100.00~~ 50

Panel beating

~~\$700.00~~ 600

Spray painting

~~\$700.00~~ 500

Subtotal :- \$2,030.00

Total:- \$6,203.60

1360

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 362469

4/s: 2.9K.

04 Days.