

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

not Anthony

29/5/18

3 day. 1/5/5
Emergency repair

SLS9081P Toyota Vellfire

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	DIJ \$ 2,817.00 ✓
2	1	Rear bumper left bracket	15 \$ 186.00 X
3	1	Rear bumper left retainer	3M \$ 189.00 ✓
4	1	Rear bumper left reflector	\$ 262.00 ?
5	2	Rear bumper tow cover	17 \$ 192.00 X
6	1	Rear tailgate assy	R \$ 4,812.00 X
7	1	Rear tailgate lock actuator with motor assy	17 \$ 1,161.00 X
8	2	Rear tailgate rubber stopper	17 \$ 66.00 X
9	1	Rear tailgate inner handle	17 \$ 161.00 X
10	1	Rear tailgate lock mechanism	17 \$ 581.00 X
11	1	Rear tailgate lock catch	17 \$ 86.00 X
12	1	Rear tailgate inner board	17 \$ 549.00 X
13	1	Rear tailgate centre logo	nu \$ 146.00 ✓
14	1	Rear tailgate vellfire emblem	nu \$ 151.00 ✓
15	1	Rear tailgate solenoid switch	17 \$ 491.00 X
16	1	Rear tailgate opener switch	17 \$ 295.00 X
17	1	Rear end lower panel	17 \$ 1,482.00 X
18	1	Rear left taillamp	502 \$ 993.00 ✓
19	1	Rear left tailgate taillamp lower garnish	70.11 \$ 867.00 ✓
20	1	Rear left fender assy	17 \$ 3,306.00 X
21	1	Rear windscreen glass moulding	17 \$ 388.00 X
			\$ 19,181.00
Less 25%			\$ 4,795.25
			\$ 14,385.75

Special Nett Items

1	16	Rear bumper clips	nu \$ 60.00 ✓
2	12	Rear tailgate inner board clips	17 \$ 30.00 X
3	1	Rear end lower panel sealant	17 \$ 120.00 X
4	1	Rear windscreen glass sealant	17 \$ 80.00 X
5	1	Rear view camera	17 \$ 350.00 X
6	4	Rear bumper reverse sensor	502 \$ 1,000.00 200
7	1	Rear left fender sealant	17 \$ 80.00 X
8	1	Rear no plate with garnish	17 \$ 80.00 X
			\$ 1,800.00

Total Parts

\$ 16,185.75

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

SLS9081P Toyota Vellfire

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear left, rear affected area and replace rear left and rear damaged parts.	\$ 1,200.00	400
2	To putty and spray painting rear left and rear portion.	\$ 1,200.00	600
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 1780.00	X
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00	50
6	To apply anti rust proofing to rear left and rear affected area.	\$ 1120.00	X
7	To remove and install rear bumper reverse sensor.	\$ 80.00	50
8	To remove and install rear view camera.	\$ 1180.00	X
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 1150.00	X
10	To remove and install rear fuel tank to facilitate the repair.	\$ 1180.00	X
11	Towing service.	\$ 1100.00	X
Total labour :		\$ 3,390.00	

Total parts : \$ 16,185.75

Total labour : \$ 3,390.00

Total repair cost : \$ 19,575.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary damage(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: