



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7041R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (SN) (CONSISTENT)	DEFORMED	2,100.00	2,100.00
1	FRONT BUMPER FIXING PARTS (SN) (CONSISTENT)	NOT NECESSARY	234.00	-
1	RADIATOR GRILLE (SN) (CONSISTENT)	NOT NECESSARY	1,005.00	-
2	FRONT BUMPER GUIDE SECTION -LH/RH (SN) (CONSISTENT)	NOT NECESSARY	64.00	-
1	FRONT FENDER -RH (SN) (CONSISTENT)	BUCKLED	904.00	903.50
1	FRONT FENDER BRACE-RH (SN) (CONSISTENT)	NOT NECESSARY	107.00	-
1	FRONT FENDER BRACKET -RH (SN) (CONSISTENT)	NOT NECESSARY	48.00	-
1	FRONT FENDER DEFORMATION BRACKET -RH (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT FENDER RIVET (SN) (CONSISTENT)	NECESSARY	24.00	24.00
1	FRONT FENDER STONE CHIP GUARD (SN) (CONSISTENT)	NECESSARY	48.00	47.40
1	HEADLIGHT-RH (SN) (CONSISTENT)	NOT NECESSARY	2,152.00	-
1	HEADLIGHT BRACKET -RH (SN) (CONSISTENT)	NOT NECESSARY	96.00	-
1	HEADLIGHT MOUNTING -RH (SN) (CONSISTENT)	NOT NECESSARY	107.00	-
1	FRONT NO.PLATE (SN) (CONSISTENT)	NOT NECESSARY	40.00	-
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	280.00	-
1	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM RHS (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	191.50	191.50
			7,445.50	3,266.40
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY .		280.00	280.00
	TO REMOVE FRONT FITTINGS ,DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND ALIGN TO POSITION .TO ENEW RHS HEADLAMP ASSY .REINSTALL ALL PARTS REMOVED.		2,500.00	1,400.00
	TO RESPRAY PAINT ON FRONT BUMPER ,RHS FRONT FENDER .		1,800.00	1,400.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			4,772.00	3,272.00



GRAND TOTAL		12,217.50	6,538.40
RECOMMENDED COST OF REPAIRS			6,538.40

Report Ref No. CC4/ASM19009483/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.