

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5005T**AAD1905-224***Not Authored
L1 Sup & 6100h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5005T

VF1ABL15AUC275169

RENAULT

LATITUDE

25.5.19

CHINA TAIPING

30/10/2013

PART		LIST	
1	DOOR PANEL REAR LH	\$	<i>Bl/wap</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>N</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sn</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>na</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i> 6.91
1	DOOR CASING REAR LH	\$	<i>Sn</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>Sn</i> 30.39
1	DOOR CASING CLIP	\$	<i>na</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sn</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>na</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
1	DOOR BLIND REAR LH	\$	<i>Sn</i> 741.80

X

Trans-cab Auto Services Pte Ltd**AAD1905-224**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5005T

1	DOOR WHEATHESTRIP REAR LH	\$	SL 410.66	X
1	DOOR SEAL REAR LH	\$	SL 162.02	X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	SL 229.31	X
1	DOOR WAIST SEAL OUTER REAR LH	\$	SL 334.69	X
1	DOOR WAIST SEAL INNER REAR LH	\$	SL 115.64	X
1	DOOR PANEL FRT LH	\$	BZ 2,844.66	✓
1	DOOR HINGE UPPER LH	\$	SL 261.28	X
1	DOOR HINGE LOWER LH	\$	SL 300.55	
1	DOOR CHECK FRT LH	\$	SL 194.77	
1	DOOR LOCK FRT LH	\$	SL 908.75	
1	DOOR CATCH FRT LH	\$	SL 131.23	
1	DOOR HANDLE OUTER FRT LH	\$	SL 477.76	
1	DOOR HANDLE COVER FRT LH	\$	SL 13.22	
1	DOOR HANDLE MODULE FRT LH	\$	SL 133.60	
1	DOOR REGULATOR FRT LH	\$	SL 505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	SL 796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	SL 120.97	
1	DOOR MOULDING FRONT LH	\$	SL 176.82	
1	DOOR FINISHER INNER FRONT LH	\$	SL 323.44	
1	DOOR FINISHER FRONT LH	\$	SL 423.10	
1	DOOR CASING FRONT LH	\$	SL 1,509.06	
1	DOOR GRAB HANDLE FRONT LH	\$	SL 210.96	X
1	DOOR BLIND FRONT LH	\$	SL 741.80	
1	DOOR WHEATHESTRIP FRONT LH	\$	SL 410.66	
1	DOOR SEAL FRONT LH	\$	SL 162.02	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	SL 229.31	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	SL 334.69	
1	DOOR WAIST SEAL INNER FRONT LH	\$	SL 115.64	
1	ROCKER PANEL INNER GARNISH LH	\$	SL 466.51	
1	ROCKER PANEL INNER LH	\$	SL 1,024.79	
1	ROCKER PANEL OUTER LH	\$	SL 1,184.99	
1	ROCKER PANEL CENTER LH	\$	BZ 990.25	✓
1	DOOR MIRROR ASSY LH	\$	SL 1,483.40	X
1	DOOR MIRROR GLASS LH	\$	SL 148.20	
1	DOOR MIRROR BACK COVER LH	\$	SL 218.46	
1	DOOR HARNESS WIRE LH	\$	SL 2,670.00	
1	FENDER PANEL REAR LH	\$	SL 3,299.13	
1	FENDER PANEL INNER TRIM REAR LH	\$	SL 671.45	

Trans-cab Auto Services Pte Ltd

AAD1905-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5005T

1 WHEELARCH REAR LH

\$	<i>Sn</i> 543.47 <i>X</i>
TOTAL \$	35,949.28

10% \$	3,594.93
\$	32,354.36

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	<i>nn</i> 100.00 <i>601n</i>
1	FRONT DOOR STICKER 'Trans-Cab'	\$	<i>nn</i> 80.00 <i>601n</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>nn</i> 80.00 <i>155n</i>
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR GUIDE SCREW	\$	<i>nn</i> 10.85
1	DOOR HINGE BOLT	\$	<i>nn</i> 10.85
1	DOOR HINGE NUT LH	\$	<i>nn</i> 14.60
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR CHECK NUT	\$	<i>nn</i> 3.75
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06
1	REAR LEFT TYRE	\$	<i>Sn</i> 300.00
1	REAR LEFT TYRE RIM	\$	<i>Sn</i> 380.00
1	FRONT LEFT TYRE	\$	<i>Sn</i> 300.00
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 30.50
1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00
1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00
1	FRONT LEFT TYRE RIM	\$	<i>Sn</i> 380.00
2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00
1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00
TOTAL	\$	2,095.13	<i>X</i>

TOTAL PARTS \$	34,449.49
-----------------------	------------------

LABOUR

To remove and refit interior fittings, trimings, garnish,
fittings and other, to enable repair.

\$	<i>nn</i> 380.00 <i>X</i>
----	---------------------------

Trans-cab Auto Services Pte Ltd

AAD1905-224

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5005T

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	6001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty and spray painting of the affected portion.	\$	7,500.00	6001
To rust-proofing of the affected areas.	\$	170.00	9001
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	2001
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	6001
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	380.00	6001
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
To transfer of Front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL

\$ 18,560.00

Over All Total

\$ 53,009.49

LUMP SUM (REPAIR DAY)

25 DAYS

4 days

LKK Auto Consultants hence notify

the Repairer that the Repairer is to

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplemental charges for repair and replacement

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: