

ASS. REC. BY:

REF: CS/FCI/9009448/K4d3n2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

CWS

From (Person): May Chun of FCI Date/Time: 12:29pm @ 24/5/2019

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHD 5747E Insured: SH 6400Y

at Workshop m/s Transcab Tel: 6276666

of No. 2 Amk 8f-63

Policy No: Claim No: D19003481MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 23/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(OS)

H.O.D. Endorsement:

Date/Time: 12:29pm @ 24/5/19

Person Contacted:

Zhenci

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SHD 5747E - WA/INC 10024043/r	DOA: 25/11/2010
	SH 6400Y - CE3/ATG/2402/0189/H/10392	DOA: 22/11/2019
20/5 @ 2:26pm	received via email preli advise.	
	Part by Part \$4786.90 (Red: 23737 46, 83%)	

ASS. REC. BY:

REF:

1021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 5747E

Yr Regn:

01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prits

c.c.

1798

Colour

Mt. White 1Rw

A/C:

Insured / Std / NI / NA

Sp. Reading

26841

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 703079230

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee

Transportation

S + P.S. SI

F.L.I.S.

Others:

350

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

4786.90



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003259MFSH

Date: 30/5/2019

Our Ref: CS/FCI19009498/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5747E

Please be informed that we had conducted the inspection of the abovementioned vehicle 29/05/2019 at the premises of M/s Trans-cab have the following to report: -

Workshop Estimate Amount	: S\$	<u>28,524.36</u>
Revised Estimate Amount	: S\$	<u>4,786.90</u>
"Check" Items Amount	: S\$	<u>1,281.30</u>
Market Value	: S\$	<u> </u>
LTA Reimbursement Value	: S\$	<u> </u>
Nett Value	: S\$	<u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-05-2019	Our Ref No. D19003481MFSH
Accident Date	23-05-2019	Claim Type. Third Party
Insured Vehicle	SH6400Y	Third Party Vehicle. SHD5747E
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 30 May 2019 2:26 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003481MFSH/1
Attachments: PRELI ADVISED SHD 5747E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHD 5747E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 29 May 2019 12:38 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003481MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 29 May 2019 12:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003481MFSH/1

Dear Sir/Mdm,

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 19 August 2019 10:55 AM
To: Denise Tay (LKKAUTO)
Subject: RE: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019 -- AAD1905-215

Hi Denise

Amount confirmed \$ 4,786.90 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 15 August, 2019 8:45 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019 -- AAD1905-215

Dear Wai Yin,

I've double check with Kenneth, he says is parts discount 25% not 10%.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 14 August 2019 1:53 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: RE: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019 -- AAD1905-215

Dear Wai Yin,

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 20 June 2019 1:45 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019 -- AAD1905-215

Hi Denise

Our COR amount \$5,307.20 (b4 GST).

Will send you photo after I get it from our workshop.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 17 June, 2019 2:33 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019

Dear Wai Yin,

Is repair done? can finalize?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 14 August 2019 1:16 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SHD5747E TP FIRST CAPITAL DOA: 23/5/2019 -- AAD1905-215
Attachments: SHD5747E 23.05.2019 - FCIL.pdf

Hi Denise

Please see the below working calculation.

SHD5747E - DOA 23.05.19		
PART	\$	458.60
	\$	318.80
	\$	14.70
	\$	552.60
	\$	112.70
	\$	1,547.27
	\$	232.00
	\$	232.00
		\$ 3,468.67
10%	\$	346.87
		<u>\$ 3,121.80</u>
S.NETT	\$	250.00
	\$	22.00
	\$	40.00
	\$	100.00
	\$	30.00
	\$	47.00
	\$	52.90
	\$	53.50
	\$	30.00
	\$	30.00
		<u>\$ 655.40</u>
LABOUR	\$	800.00
	\$	500.00
	\$	50.00
	\$	60.00
	\$	120.00
		<u>\$ 1,530.00</u>
		<u>\$ 5,307.20</u>

Thank You
Best Regards,
Ng Wai Yin

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD5747E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2B99716
Chassis No.:	JTDKB3FU703079230
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	17 Jan 2019
First Registration Date:	17 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$10,685.00

COE Expiry Date:	16 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,838.00
COE Rebate Amount:	\$16,670.00
Total Rebate Amount:	\$27,355.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5747E**AAD1905-215***Not Authored
Resuming Bk paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5747E

JTDKB3FU703079230

TOYOTA

PRIUS

23.5.2019

FCIL

17/1/2019

PART**LIST**

1	1 REAR BUMPER	\$	Bu	458.60	✓
2	1 REAR BUMPER RE-INFORCEMENT	\$	Bu	318.80	✓
3	1 REAR BUMPER TOWING COVER	\$	mt	14.70	✓
4	1 REAR BUMPER UNDER COVER (BLACK)	\$	Bu	552.60	✓
5	1 REAR BUMPER SIDE RETAINER LH	\$	Bu	112.70	X
6	1 REAR BUMPER SIDE RETAINER RH	\$	Di	112.70	✓
7	1 REAR TAILGATE	\$	Bu	1,547.27	✓
8	1 REAR TAILGATE OUTER GARNISH	\$	n	905.10	X
9	1 COVER, REAR COMBINATION LAMP, RH	\$	Bu	54.70	
10	1 COVER, REAR COMBINATION LAMP, RH	\$	Bu	54.70	
11	1 GARNISH, BACK DOOR SIDE, LH	\$	Bu	93.60	
12	1 GARNISH, BACK DOOR SIDE, RH	\$	Bu	93.60	
13	1 BOARD ASSY, BACK DOOR TRIM	\$	Bu	254.40	
14	1 PANEL ASSY, BACK DOOR TRIM, UPPER	\$	Bu	51.20	
15	1 REAR TAILGATE WEATHERSTRIP	\$	Bu	365.20	
16	1 REAR END PANEL	\$	n	602.10	7X
17	1 TAILLAMP LOWER RH	\$	Bu	548.40	X
18	1 TAILLAMP UPPER RH	\$	Bu	557.90	X
19	1 REAR BUMPER SIDE RH	\$	mt	232.00	✓
20	1 REAR BUMPER SIDE LH	\$	mt	232.00	✓
21	1 TAILLAMP LOWER LH	\$	Su	548.40	7X
22	1 TAILLAMP UPPER LH	\$	Su	557.90	7X
23	1 PAN, REAR FLOOR	\$	n	572.10	X
24	1 EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	n	77.00	X
25	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	n	192.90	X
26	1 EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	n	77.00	X
27	1 EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	n	192.90	X
28	1 PANEL, QUARTER WHEEL HOUSE, OUTER LH	\$	n	290.50	X

Trans-cab Auto Services Pte Ltd

AAD1905-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5747E

29	1 REAR FENDER LH	\$	<i>na</i>	817.50	X
30	1 REAR FENDER RH	\$	<i>na</i>	817.50	X

	\$	11,305.97
25%	\$	2,826.49
	\$	8,479.48

Special Nett

1	1SET PARKING AID	\$	<i>na</i>	700.00	<i>2500</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i>	22.00	<i>—</i>
3	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	<i>4000</i>
4	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	<i>2</i>
5	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>3000</i>
6	1 REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	<i>—</i>
7	1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	<i>—</i>
8	1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	<i>—</i>
9	1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	<i>3000</i>
10	1 REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	<i>3000</i>
11	1 REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	X

TOTAL \$ 1,415.40**TOTAL PARTS \$ 9,894.88****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,200.00	<i>8000</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>5000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	<i>500</i>

Trans-cab Auto Services Pte Ltd

AAD1905-215

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5747E

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	nn X
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	nn X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	nn X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of Rear fender fittings, attachments and perform water seepage test.	\$	170.00	nn X

TOTAL \$ 10,150.00**Over All Total \$ 28,524.36**

20044.88

(PART-BY-PART) Repair Days**20 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009498/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-08-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6400Y	Veh. Inspected	SHD 5747E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003481MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU703079230	Colour	METALLIC WHITE / RED	
Odometer	26841	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/05/2019	Inspection Date	29/05/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5747E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER TOWING COVER	MISSING	14.70	14.70
1	REAR BUMPER UNDER COVER (BLACK)	BENT	552.60	552.60
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	112.70	112.70
1	REAR TAILGATE	BENT	1,547.27	1,547.27
1	REAR TAILGATE OUTER GARNISH	TO REPAIR SEE LABOUR	905.10	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	COVER,REAR COMBINATION LAMP,RH	SERVICEABLE	54.70	-
1	GARNISH,BACK DOOR SIDE,LH	SERVICEABLE	93.60	-
1	GARNISH,BACK DOOR SIDE,RH	SERVICEABLE	93.60	-
1	BOARD ASSY,BACK DOOR TRIM	SERVICEABLE	254.40	-
1	PANEL ASSY,BACK DOOR TRIM,UPPER	SERVICEABLE	51.20	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	365.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	TAILLAMP LOWER RH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER RH	SERVICEABLE	557.90	-
1	REAR BUMPER SIDE RH	MTG CRACKED	232.00	232.00
1	REAR BUMPER SIDE LH	MTG CRACKED	232.00	232.00
1	TAILLAMP LOWER LH	SERVICEABLE	548.40	-
1	TAILLAMP UPPER LH	SERVICEABLE	557.90	-
1	PAN,REAR FLOOR	TO REPAIR SEE LABOUR	572.10	-
1	EXTENSION,REAR FLOOR SIDE PANEL,RH	TO REPAIR SEE LABOUR	77.00	-
1	EXTENSION,REAR FLOOR PAN TO QUARTER PANEL,LH	TO REPAIR SEE LABOUR	192.90	-
1	EXTENSION,REAR FLOOR SIDE PANEL,LH	TO REPAIR SEE LABOUR	77.00	-

Report Ref No. CS/FCI19009498/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	TO REPAIR SEE LABOUR	192.90	-
1	PANEL, QUARTER WHEEL HOUSE, OUTER LH	TO REPAIR SEE LABOUR	290.50	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	817.50	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	817.50	-
	LESS 25% DISCOUNT		-2,826.49	-867.17
			8,479.48	2,601.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	DENTED	700.00	250.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	22.00	22.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	REAR TAILGATE TOYOTA LOGO (SN)	NECESSARY	47.00	47.00
1	REAR TAILGATE WORDING "PRIUS" (SN)	NECESSARY	52.90	52.90
1	REAR TAILGATE WORDING "HYBRID" (SN)	NECESSARY	53.50	53.50
1	REAR TAILGATE STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER "6555-3333" (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
			1,415.40	655.40
	<u>LABOUR</u>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	800.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR TAILGATE OUTER GARNISH, REAR END PANEL, PAN, REAR FLOOR, EXTENSION, REAR FLOOR SIDE PANEL, RH, EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH, EXTENSION, REAR FLOOR SIDE PANEL, LH, EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH, PANEL, QUARTER WHEEL HOUSE, OUTER LH, REAR FENDER LH AND REAR FENDER RH.		4,200.00	500.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI19009498/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			10,150.00	1,530.00
GRAND TOTAL			20,044.88	4,786.90
RECOMMENDED COST OF REPAIRS				4,786.90

Report Ref No. CS/FCI19009498/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.