

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 03 Jun 2019

Preliminary Advice

Insured Vehicle No : SBN3328M

TP Vehicle No : SLK3665L

Make : TOYOTA COROLLA ALTIS

Date of Inspection : 31/05/2019

Inspection At : Esteem Performance Pte Ltd - Sin Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Accident Date : 25/05/2019

Assignment Date : 29/05/2019

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,686.16
Revised Amount	:S\$	2,305.40
Check Items (Estimated)	:S\$	2,359.77
Total	:S\$	4,665.17

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.