

ASS. REC. BY:

REF: 05/CT1/9009501/Ut d3n2 Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person): chong Boon Sen of CTI Date/Time: 29/5/19 @ 17:19pm

Estimated Cost: Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 4947G Insured: YM 532S

at Workshop m/s SME Motor Tel: 67 47 6106

of 1 kaki Bukit Ave 6 # 02-15

Policy No: DMCVSN17382918011 Claim No: SNM19D2 02352 C02

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 29/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:51pm @ 29/5/2019 Person Contacted: Sebastian Vehicle IN (OUT)

| Date/Time | Action/Instruction                    | Estimate (✓)   |
|-----------|---------------------------------------|----------------|
|           | GBG 4947G                             | X              |
|           | YM 532S - CS / MSG 170.4348 / Rlg ber | DVA: 13/5/2017 |
|           |                                       |                |
|           |                                       |                |
|           |                                       |                |

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen: 1

Consistent? : Yes or No

Est. Repairs:

5- days

Res.: Yes or No

Lum Sum:

1.3-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3 x 2FC

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G3G 4947G Yr Regn: 8 / 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM /

Make:

Toyota Hiace

C.C.

2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

142837

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P200220686

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

24/5/19

D.O.I.

30/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; Rear w/screens

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24 24380

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

1) 10/6 Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

TP

Lump Sum (I.B.I.) (\$ 5804 )

TOTAL

220

7/6/19 confirmed final by \$5804 with AH yang.

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Wednesday, 29 May 2019 11:19 AM  
**To:** Sebastian Kong  
**Cc:** assignments  
**Subject:** RE: YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019 / OUR REF: SNM19D202352

### WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Sebastian Kong [<mailto:sebastian@smemotor.com.sg>]

**Sent:** Wednesday, 29 May, 2019 10:35 AM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** Re: YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019 / OUR REF: SNM19D202352

Dear Boon Sen,

We refer to choose MARCUS CHUA to survey our client's vehicle.

Thank you

Regards  
Sebastian Kong  
SME MOTOR PTE LTD  
1 Kaki Bukit Ave 6,  
Blk D, #02-15/16/17/18  
AutoBay @ Kaki Bukit  
Singapore 417883.  
Tel: 6747 6106 (6 lines)  
Fax: 6744 2368

**From:** [peiyang@smemotor.com.sg](mailto:peiyang@smemotor.com.sg)

**Sent:** Monday, May 27, 2019 2:57 PM

**To:** Sebastian

**Subject:** Fw: YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019 / OUR REF: SNM19D202352

**From:** Chong Boon Sen

**Sent:** Monday, May 27, 2019 2:33 PM

**To:** [peiyang@smemotor.com.sg](mailto:peiyang@smemotor.com.sg)

**Subject:** RE: YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019 / OUR REF: SNM19D202352

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

|                |
|----------------|
| ADRIAN LING    |
| Kelvin Ang     |
| SEE CHEW SENG  |
| LOW SAR HUEI   |
| HONG FOOK CHOY |
| XING QUO QIANG |
| KENNETH KONG   |
| SIMON HO       |
| CHUA WEIJIE    |
| MARCUS CHUA    |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3, Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Monday, 27 May, 2019 2:30 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [peiying@smemotor.com.sg](mailto:peiying@smemotor.com.sg)

**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Subject:** FW: YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019

Dear Boon Sen,

Please conduct PRS on behalf of Elaine – TP:GBG4947G (SNM19D202352) soonest possible.  
File with Boon Sen – 63896171  
OIC - Elaine - 63896530

---

**From:** [peiying@smemotor.com.sg](mailto:peiying@smemotor.com.sg) [<mailto:peiying@smemotor.com.sg>]

**Sent:** Monday, 27 May 2019 1:50 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** Sebastian <[sebastian@smemotor.com.sg](mailto:sebastian@smemotor.com.sg)>; Jacob <[jacob.ang@smemotor.com.sg](mailto:jacob.ang@smemotor.com.sg)>

**Subject:** YOUR REF: YM532S , OUR REF: GBG4947G ACCIDENT ON 24/05/2019

Hi,

Forward all relevant documents to you. Kindly arrange your surveyor to inspect our client's vehicle.

Kindly advise liability.

Thanks,

Regards,  
Pei Ying

---

**From:** [ptr2@smemotor.com.sg](mailto:ptr2@smemotor.com.sg)

**Sent:** Monday, May 27, 2019 12:25 PM

**To:** SME Motor-Chia Pei Ying

**Subject:** Attached Image

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                         |
|-------------------------------------|-------------------------|
| <b>Vehicle Owner Particulars</b>    |                         |
| Owner ID Type:                      | Business                |
| Owner ID:                           | 3425C                   |
| <b>Vehicle Details</b>              |                         |
| Vehicle No.:                        | GBG4947G                |
| Vehicle to be Exported:             | No                      |
| Intended Deregistration Date:       | 03 Jun 2019             |
| Vehicle Make:                       | TOYOTA                  |
| Vehicle Model:                      | HIACE VAN TURBO 5DR MT  |
| Primary Colour:                     | Silver                  |
| Manufacturing Year:                 | 2017                    |
| Engine No.:                         | 1KD2701604              |
| Chassis No.:                        | JTFHT02P200220686       |
| Maximum Power Output:               | -                       |
| Open Market Value:                  | \$28,138.00             |
| Original Registration Date:         | 21 Aug 2017             |
| First Registration Date:            | 21 Aug 2017             |
| Transfer Count:                     | 0                       |
| Actual ARF Paid:                    | \$1,407.00              |
| <b>Intended PARF Rebate Details</b> |                         |
| PARF Eligibility:                   | No                      |
| PARF Eligibility Expiry Date:       | -                       |
| PARF Rebate Amount:                 | \$0.00                  |
| <b>Intended COE Rebate Details</b>  |                         |
| COE Expiry Date:                    | 20 Aug 2027             |
| COE Category:                       | C - Goods Vehicle & Bus |
| COE Period(Years):                  | 10                      |
| PQP Paid:                           | \$29,687.00             |
| COE Rebate Amount:                  | \$24,380.00             |
| <b>Total Rebate Amount:</b>         | <b>\$24,380.00</b>      |

The information contained herein is correct as at 03 Jun 2019

OK

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
 GST-201119451E RCB NO:201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

Singapore 079909

TEL: 63896111

FAX: 62247478

ATTN: Motor Claim Department

Your Ref No: 19/CN/TP-108 (05)

Claim Type: Third Party

Accident Date: 24/05/2019

TP Veh Reg No: YM532S

Estimate No: EST0004868

Date: 27 May 2019

Policy No: D18MTPCVE0025846

Veh Reg No: GBG4947G

Make/Model: TOYOTA HIACE

Chasis No: JTFHT02P200220686

Engine No: 1KD2701604

Reg. Date: 21/08/2017

## Estimate Repair Cost to Vehicle No :GBG4947G

| Description                                     | Quantity | List Price | Amount    |
|-------------------------------------------------|----------|------------|-----------|
|                                                 |          | <u>SS</u>  | <u>SS</u> |
| <b>List Price</b>                               |          |            |           |
| 1 REAR WINDSCREEN                               | 1 PC     | 991.50     | —         |
| 2 REAR GATE                                     | 1 PC     | 2,150.00   | —         |
| 3 REAR GATE OUTER GARNISH                       | 1 PC     | 155.00     | —         |
| 4 REAR GATE LOGO                                | 1 PC     | 68.00      | —         |
| 5 REAR GATE 'TOYOTA' STICKER                    | 1 PC     | 75.00      | —         |
| 6 REAR GATE LOCK                                | 1 PC     | 275.00     | —         |
| 7 REAR GATE INNER TRIM BOARD                    | 1 PC     | 666.90     | —         |
| 8 REAR BUMPER                                   | 1 PC     | 475.00     | —         |
| 9 REAR BUMPER CLIP                              | 10 PC    | 50.00      | —         |
| 10 REAR CORNER PANEL LH                         | 1 PC     | 195.00     | —         |
| 11 REAR TAIL LAMP LH                            | 1 PC     | 300.80     | —         |
| 12 REAR END PANEL -OUTER                        | 1 PC     | 331.70     | —         |
| 13 REAR FENDER LH                               | 1 PC     | 1,400.00   | —         |
| 14 REAR GATE LOCK STICKER                       | 1 PC     | 48.00      | —         |
|                                                 |          | 7,181.90   | —         |
|                                                 | Less 25% | 1,795.48   | 5,386.44  |
| <b>Special Net</b>                              |          |            |           |
| 15 REAR WINDSCREEN GUM                          | 1 PC     | 60.00      | 40        |
| 16 REAR NUMBER PLATE                            | 1 PC     | 35.00      | 20        |
| 17 REVERSE SENSOR                               | 1 PC     | 250.00     | 200       |
| 18 REAR GATE STICKER '70KM/H'                   | 1 PC     | 25.00      | 10        |
|                                                 |          | 370.00     | 370.00    |
| <b>Labour</b>                                   |          |            |           |
| 19 WIRE CHECKING                                | 1 UNIT   | 20.00      | —         |
| 20 REMOVE & REFIX REAR WINDSCREEN               | 1 UNIT   | 120.00     | 100       |
| 21 TRANSFER REAR GATE COMPONENT FROM OLD TO NEW | 1 UNIT   | 100.00     | 60        |
| 22 TUFF KOTE                                    | 1 UNIT   | 100.00     | 50        |
| 23 LABOUR CHARGE                                | 1 UNIT   | 1,200.00   | 850       |
| 24 SPRAY PAINTING                               | 1 UNIT   | 900.00     | 800       |
|                                                 |          | 2,440.00   | 2,440.00  |

Not Attached  
 The photo before painting.  
 30/5/19 p/p #5804

5804

# SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883  
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg  
GST:201119451E RCB NO:201119451E

**M/S :** CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAFT TOWER

Singapore 079909

TEL: 63896111

FAX: 62247478

ATTN: Motor Claim Department

Your Ref No: 19/CN/TP-108 (05)

Claim Type: Third Party

Accident Date: 24/05/2019

TP Veh Reg No: YM532S

**Estimate No:** EST0004868

Date: 27 May 2019

Policy No: D18MTPCVE0025846

Veh Reg No: **GBG4947G**

Make/Model: TOYOTA HIACE

Chasis No: JTFHT02P200220686

Engine No: 1KD2701604

Reg. Date: 21/08/2017

## Estimate Repair Cost to Vehicle No :GBG4947G

| Description | Quantity | List Price           | Amount      |
|-------------|----------|----------------------|-------------|
|             |          | <b>SS</b>            | <b>SS</b>   |
|             |          | Total                | SS 8,196.44 |
|             |          | Add GST @ 7%         | 573.75      |
|             |          | Total Amount Payable | SS 8,770.19 |

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED SEVENTY AND CENTS NINETEEN ONLY

**For SME Motor Pte Ltd**

AUTHORISED SIGNATURE





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009501/UTD3N2

Date: 13/06/2019

## REFERENCE

|                       |                                               |                      |                   |                           |
|-----------------------|-----------------------------------------------|----------------------|-------------------|---------------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN17382918011 |                           |
| Claimant Vehicle No : | GBG4947G                                      | Insured Vehicle No : | YM532S            |                           |
| Date of Loss:         | 24/05/2019                                    | Nature of Claim:     | TP                | Claim No: SNM19D202352C02 |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                                    |             |                   |
|-----------------------------|------------------------------------|-------------|-------------------|
| Reg No:                     | GBG4947G                           | Engine No:  | 1KD2701604        |
| Make & Model:               | TOYOTA HIACE, 3.0 D TURBO 5 DR (M) | Chassis No: | JTFHT02P200220686 |
| Reg. Date:                  | 21/08/2017 (Man. Year: 2017)       | Odometer:   | 142837 km         |
| Colour:                     | Silver                             |             |                   |
| Engine Capacity:            | 2982 cc                            |             |                   |
| Market Value/New Car Price: | N/A                                |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price         |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195 R15       | Rear Tyre Size:  | 195 R15       |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                         | 5,756.42        | 3,924.00        | 1,832.42        | 31.83        |
| Miscellaneous Items           | 0.00            | 0.00            | 0.00            |              |
| Labour                        | 2,440.00        | 1,880.00        | 560.00          | 22.95        |
| Paintwork Labour              | 0.00            | 0.00            | 0.00            |              |
| Towing                        | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (S\$)</b>      | <b>8,196.42</b> | <b>5,804.00</b> | <b>2,392.42</b> | <b>29.19</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>573.75</b>   | <b>406.28</b>   | <b>167.47</b>   | <b>29.19</b> |
| <b>Nett Amount (S\$)</b>      | <b>8,770.17</b> | <b>6,210.28</b> | <b>2,559.89</b> | <b>29.19</b> |

## INSPECTION

|                             |            |               |                           |
|-----------------------------|------------|---------------|---------------------------|
| Date of Assignment:         | 10/06/2019 | Inspected At: | Sme Motor Pte Ltd (HQ)    |
| Date Inspected:             | 30/05/2019 |               | 1 KAKI BUKIT AVE6, #02-15 |
|                             |            |               | Singapore 417883          |
| Estimated Period of Repair: | 5.0 days   |               |                           |

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

|                                                                                               |                                                                                                                                                                              |
|-----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Reference</b>                                                                              |                                                                                                                                                                              |
| <b>Part Source:</b> MRM-SG                                                                    | Version: 1.0 (Last Synchronised: 13 Jun 2019)                                                                                                                                |
| <b>Parts:</b> 213                                                                             | TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)                                                                                                          |
| <b>Labour:</b> Repairer's                                                                     | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b>                                                                            | (Unsubmitted, no print-code for GBG4947G)                                                                                                                                    |
| <b>Validity:</b>                                                                              | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *. |                                                                                                                                                                              |

## Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition      | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------|----------------|-------------|--------------|
| 1   | 1   |          | *REAR WINDSCREEN            | Shattered      | 991.50 FL   | *991.50 FL   |
| 2   | 1   |          | *REAR GATE                  | Badly Dented   | 2,150.00 FL | *2,150.00 FL |
| 3   | 1   |          | *REAR GATE OUTER GARNISH    | Bent/Cracked   | 155.00 FL   | *155.00 FL   |
| 4   | 1   |          | *REAR GATE LOGO             | Necessary      | 68.00 FL    | *68.00 FL    |
| 5   | 1   |          | *REAR GATE TOYOTA STICKER   | Necessary      | 75.00 FL    | *75.00 FL    |
| 6   | 1   |          | *REAR GATE LOCK             | Dented/Shorted | 275.00 FL   | *275.00 FL   |
| 7   | 1   |          | *REAR GATE INNER TRIM BOARD | Not Necessary  | 666.90 FL   | *- FL        |
| 8   | 1   |          | *REAR BUMPER                | Bent/Cracked   | 475.00 FL   | *475.00 FL   |
| 9   | 10  |          | *REAR BUMPER CLIP           | Necessary      | 50.00 FL    | *50.00 FL    |
| 10  | 1   |          | *REAR CORNER PANEL LH       | Repair         | 195.00 FL   | *- FL        |
| 11  | 1   |          | *REAR TAIL LAMP LH          | Broken         | 300.80 FL   | *300.80 FL   |
| 12  | 1   |          | *REAR END PANEL-OUTER       | Badly Dented   | 331.70 FL   | *331.70 FL   |
| 13  | 1   |          | *REAR FENDER LH             | Repair         | 1,400.00 FL | *- FL        |
| 14  | 1   |          | *REAR GATE LOCK STICKER     | Not Necessary  | 48.00 FL    | *- FL        |
| 15  | 1   |          | *REAR WINDSCREEN GUM        | Necessary      | 60.00 FS    | *40.00 FS    |
| 16  | 1   |          | *REAR NUMBER PLATE          | Bent           | 35.00 FS    | *20.00 FS    |
| 17  | 1   |          | *SET REVERSE SENSOR         | Shorted        | 250.00 FS   | *200.00 FS   |
| 18  | 1   |          | *REAR GATE STICKER 70KM/H   | Necessary      | 25.00 FS    | *10.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>7,551.90</b> | <b>5,142.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>1,795.48</b> | <b>1,218.00</b> |
| <b>Total Parts (\$\$)</b>                                  | <b>5,756.42</b> | <b>3,924.00</b> |

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

| No                             | Particulars                                  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                              |          |                 |                 |
| 1                              | WIRE CHECKING                                | New      | 20.00           | 20.00           |
| 2                              | REMOVE & REFIX REAR WINDSCREEN               | New      | 120.00          | 100.00          |
| 3                              | TRANSFER REAR GATE COMPONENT FROM OLD TO NEW | New      | 100.00          | 60.00           |
| 4                              | TUFF KOTE                                    | New      | 100.00          | 50.00           |
| 5                              | LABOUR CHARGE                                | New      | 1,200.00        | 850.00          |
| 6                              | SPRAY PAINTING                               | New      | 900.00          | 800.00          |
| <b>Gross Labour Cost (S\$)</b> |                                              |          | <b>2,440.00</b> | <b>1,880.00</b> |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;