

22/03/2019

ASS. REC. BY:

REF: C83/SPF19009505/GH3ST Special Instructions:Surveyor: WongASSIGNMENT (Office)From (Person): Frankie They of SPF Date/Time: 29/5/2019

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGG1612 Insured: QX950Eat Workshop m/s STK Auto Tel: 63860669of Blk 8 Kaki Bukit Ave 4 #03-21 premierPolicy No: _____ Claim No: AEMD/105/009/2019/068

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/5/19.
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 12:42pm 29/5/19 Person Contacted: Jing Jing Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	Estimate (x)
	SGG1612 - CS / MSG1694668 / KTH3d1	
	DAR Report #33501-	

D.O.A: 27/07/2016
Do Not Finalise

PRS
Gul

REF:

SPE

0926H

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s **STK Auto**
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **5** days Res.: Yes or No
 Lum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SG 1618** Yr Regn: **30 sep 2016**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Volkswagen Jetta** 1390
 Colour: **silver** A/C: Insured / Std / NI / NA
 Sp. Reading: **31550** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WVVZZZ168GM027099**
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD ☒ Rim or
 Tyre Size: F: **205/55R16**
 R: **17**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **28-05-19**
 Survey held at **w/s 31 sep 2016**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear w/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$3000 - \$4000 + 1 Sunday
	Repair days -> 5
	Weekend -> 1
	total -> 6

RECEIVED 26 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) **26/7 Typist** ☒ : Final Report

Date/Time, File Return to?

2)

Report Format : **TP - PRS**

Lump Sum / I.B.I. (\$) _____

Days Of Repair: **5**

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: **220**

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Wednesday, 29 May 2019 10:23 AM
To: Veron Chen (LKKAuto); assignments
Cc: Hafizul Farhan RAHMAT (SPF)
Subject: RE : Pre-Repair Inspection for Vehicle SGG 161Z

Your reference: SGG 161Z

Our reference: AEMD/105/009/2019/068

Veron,

Please conduct a Pre-Repair Inspection for vehicle SGG 161Z at the address listed below:

Workshop: STK AUTO (S) PTE LTD

Address: BLOCK 8 KAKI BUKIT AVENUE 4, #03-21 PREMIER@KAKI BUKIT, SINGAPORE 415875

Contact: JINGJING AT TEL: 63860669 OR GUOHUA AT TEL: 91237949

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 10:24
Date Of Accident	24/05/2019 18:55
Exact Location Of Accident	SHENTON WAY TOWARDS UNION STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGG161Z
Insured/Policyholder	
Name Of Registered Owner	GIAM MENG TUCK
NRIC No	S0080926H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97609963
Alternative Phone No	OFFICE-97609963
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA GP 1.4 TSI 90 A/T TL 1632G5

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103789934 PREMIUM
Cover Note Number	

Driver

Name of Driver	TAN BEE HONG
NRIC No	S1673586H
Date Of Birth	28/05/1964
Occupation	INDOOR
Date Of Driving Pass	24/02/1983
Driving Experience	36 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97995064
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	78 BAYSHORE ROAD #02-21 COSTA DEL SOL
Postcode	469991
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GIAM MENG TUCK
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINA BAY NPC
Police Station Address	ROAD: 70 MARINA VIEW , POSTCODE: 018962 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX950E
Vehicle Make/Model/Colour	TOYOTA LANDCRUISER 4.5 A
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	MOHAMMAD NAZARIE BIN ABDUL AZIZ
NRIC/Passport Number	S9235848H
Contact Number	93364864
Address	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to

Police Report

DECLARATION

I/We declare the foregoing particulars are true to my/our best knowledge.

[Signature]

Policyholder's Signature
Date & Time

27 MAY 2019

[Signature]

Driver's Signature
Date & Time

27 MAY 2019

IOAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Road-Teng-Centra-Perusahaan's Signature
Name

Date & Time

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	0926H
Vehicle No.:	SGG161Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 May 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T TL 1632G5
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	CAXF84240
Chassis No.:	WVWZZZ16ZGM027099
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,699.00
Original Registration Date:	30 Sep 2016
First Registration Date:	30 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$16,699.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2026
PARF Rebate Amount:	\$12,524.00
COE Expiry Date:	29 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$36,666.00
Total Rebate Amount:	\$49,190.00

The information contained herein is correct as at 29 May 2019

OK

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (✓)
(4) Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	258.64	OC	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	30 (SN) MC	1	40 (SN)
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	LH	OC	83.31
1149	993045	Rear Bumper Reinforcement	157	1	606.05
1150	992970	Rear Bumper Beam	102.15	CRA	1
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	LH	BR	55.35
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	200 (SN) DM	1	
1159	993327	Rear End Panel	962	Repair X	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	410.8	CRA	1
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	1450	Repair X	
1171	991328	Bootlid Emblem	10115.75	MC	1
1172	990356	Bootlid Handle	10115.75	MC	1
1173	995250	Bootlid Moulding	Tsi 1090	MC	1
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	280.15	CRA	1
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm	3056.15		
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor	1090: 2150.54		
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	4180.54		
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber	2090: 23790		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: **SGG1618**

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	588.18	Repair X	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

panel beating : 500
spray painting : 800
Remove & Refit Sensor : 40
wiring : 30
upholstery
Remove & Refit Cushion : 60

No of Items: _____ Assessor: _____

Original Copy



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Ref: CS3/SPF19009505/Gtd3s2

Date: 26-07-2019



ATTN: FRANKIE THAY

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 950E	Veh. Inspected	SGG 161Z
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2019/068	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	29/05/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WWZZZ16ZGM027099	Colour	SILVER
Odometer	31550 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	PIRELLI	6 mm
L/H Front Tyre	205/55R16	PIRELLI	6 mm
R/H Rear Tyre	205/55R16	PIRELLI	6 mm
L/H Rear Tyre	205/55R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/05/2019	Inspect Date / Time	29/05/2019 (03:40 PM)
Survey held at	STK AUTO (S) PTE LTD 8 KAKI BUKIT AVE 4 #03-21 PREMIER@KAKI BUKIT SSINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SGG 161Z

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,258.64
1	REAR BUMPER SIDE RETAINER LH	DEFORMED	83.31
1	REAR BUMPER REINFORCEMENT	BENT	606.05
1	REAR BUMPER BEAM	CRACKED	102.15
1	REAR BUMPER REFLECTOR LH	BROKEN	55.35
1	REAR END PANEL	TO REPAIR SEE LABOUR	-
1	REAR LH TAILLAMP	CRACKED	410.80
1	BOOTLID	TO REPAIR SEE LABOUR	-
1	BOOTLID EMBLEM LOGO	NECESSARY	115.75
1	BOOTLID JETTA LOGO	NECESSARY	82.10
1	BOOTLID TSI LOGO	NECESSARY	61.85
1	BOOTLID LAMP LH	CRACKED	280.15
1	REAR LH FENDER	TO REPAIR SEE LABOUR	-
	LESS 10% DISCOUNT		-305.62
			2,750.53
<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	40.00
1	REVERSE SENSOR (SN)	DAMAGED	200.00
			240.00
<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL, BOOTLID AND REAR LH FENDER.		500.00
	SPRAY PAINTING.		800.00
	REMOVE & REFIT SENSOR.		40.00
	WIRING.		30.00
	REMOVE & REFIT UPHOLSTERY.		60.00
			1,430.00
GRAND TOTAL			4,420.53
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,350.00

Report Ref No. CS3/SPF19009505/Gtd3s2



Report Ref No. CS3/SPF19009505/Gtd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

RECOMMENDED REPAIR DAYS : 5

WEEKEND : 1

TOTAL DAYS : 6

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.