

ASS. REC. BY:

REF: CS/MSG/19009507/7d301 Special Instructions:

Survey: Hwee TieASSIGNMENT (Office)

From (Person):

Meimen Chia Nyuk Rai

of

MSGDate/Time: 29/5/19 @ 10:50am

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB1261B

Insured:

SMF1865J

at Workshop m/s

SMRT

Tel:

6866 2872

of

60 Woodlands Ind. Park E4

Policy No:

A290964848AVW

Claim No:

594486

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:47am 29/5/19

Person Contacted:

ShantiVehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

SHB1261B-NS/INC1500509/K1g/bk3D.O.A: 25/3/2015SMF1865J-X29/5/19 @43pm Revised to Chia Nyuk Rai via Meimen.

ASS. RPT. BY

three Jte

REP:

MS/G

ASSIGNMENT

From:

Date:

29/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB1261B

at Workshop m/s:

SMRT

of

Woodlands Depot.

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB1261B

Yr Regn:

15 Nov 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1798

Colour:

maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

530270

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN36U105707407

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rip / STD A/Rim or

Tyre Size:

F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

27/5/19

D.O.I:

29/5/19

Survey held at

Smrt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/8/19

Final/IC Contd 83150 7 rpa dep
(Red: 8804.94, 73%)

RECEIVED 15 AUG 2019

[Signature]

05/19/2120
SME1865J.

15/8/2019

Date/Time, File Pass in?

15/8 Typist

Date/Time, File Enter in?

3

Report Format:

Lump Sum / L&M

TP

3150

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp

☐

Interview

☐

Tech. Insp

☐

Welding

Survey Fee:

Transportation:

3 + RS 4

Phone

Other:

211

200

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		29 May 2019 13:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GU LI ZHONG, ID: S8065253D, Tel: +6585115910		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB1261B	Date of Loss:	27/05/2019 08:00 - :59 [66 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 594486	Policy/Cover Note No.:	A29096848AVW (Comprehensive) Coverage: 21/09/2018 - 20/09/2019
Vehicle Reg. No. (Insured):	SME1865J	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/05/2019]		
Driver/Custodian (Insured):	CHEN MIN (), NRIC: S8261559H, Tel: +6585115910 Email:		
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED BY IHS) CAR IN 29/05/2019, LIAB: 100%. CONTACT: SHANTI @ 6866 2671/2 Manually assigned to LKK via email on 29/05/2019		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Wednesday, 29 May 2019 10:50 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: 2120 - 1261.pdf

SHB1261B - SURVEY (MSIG) DOA: 27/05/19 SME1865J (MSIG) Car in 29/05/19 (SMRT) Woodlands

Manual Assigned

Dear LKK

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis)
[mailto:BThaiyalN@smrt.com.sg]
Sent: Tuesday, 28 May 2019 3:18 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/ARC/AR & SC/Taxis) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis) <weisiong@smrt.com.sg>; Gan Kwai Leng (Auto Svcs/Claims & IA/Claims & IA/Taxis) <GANKWAIENG@smrt.com.sg>
Subject: RE: SHB1261B - SURVEY (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1261B** within 48 hours according to GIA guide line, involving your insured **SME1865J**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 31 May 2019

Preliminary Advice

Insured Vehicle No	: SME1865J	Accident Date	: 27/05/2019
TP Vehicle No	: SHB1261B	Assignment Date	: 29/05/2019
Make	: TOYOTA PRIUS ALPHA	Est. Duration of Repair	: 6.00
Date of Inspection	: 29/05/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,779.40
Revised Amount	:S\$	3,214.25
Check Items (Estimated)	:S\$	1,519.56
Total	:S\$	4,733.81

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1261B
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5919791
Chassis No.:	JTDKN36U105707407
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	15 Nov 2013
First Registration Date:	15 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Nov 2021
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	14 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$63,297.00
COE Rebate Amount:	\$19,449.00
Total Rebate Amount:	\$25,306.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 08:51
Date Of Accident	27/05/2019 08:50
Exact Location Of Accident	EAST COAST PARK SERVICE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1261B
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	SAHAR BIN ATAN
NRIC No	S1722404B
Date Of Birth	13/02/1965
Occupation	OUTDOOR
Date Of Driving Pass	16/01/1990
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	316
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELING IN MY LANE ALONG EAST COAST PARK SERVICE ROAD WITH ONE PASSENGER (MALE MALAY) ON BOARD. SUDDENLY A VEHICLE SME1865J DID NOT STOP AT THE STOP LINE TO LOOK OT FOR ONCOMING TRAFFIC, AS SUCH COLLIDED ONTO THE LEFT PORTION OF MY TAXI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME1865J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN MIN
NRIC/Passport Number	S8261559H
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 27/5/2019
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 27/5/2019
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:


SKETCH PLAN



A-5HB1261B

B - SME 1865 J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



DECLARATION

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature: _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



Case Details

Case Reference Number : TAX/05/19/2120
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1251B

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7060-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
 Accident Date and Time : 27/05/2019 12:50 AM
 Vehicle Age(In Months) : 66

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ MC
One Time Key In	Main			FENDER RRLH	1	766.80	766.80	30.00	536.76	Replace	1	536.76	Replace	✓ OO
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ MC
One Time Key In	Main			STICKER DECAL 5555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ MC
One Time Key In	Main			FENDER LINER RRLH	1	141.30	141.30	30.00	98.91	Replace	0	0	Check	✗ N/A
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	30.00	71.40	Replace	0	0	Check	✗ N/A
One Time Key In	Main			CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	30.00	44.73	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	30.00	4.13	Replace	0	0	Check	✗ N/A
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	30.00	47.67	Replace	0	0	Not Give	✗ N/A
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	30.00	161.56	Replace	0	0	Check	✗ N/A

Total Spare Part Cost 5,606.40

Surveyor Total 1,389.25

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,485.12

Final Sur Total 1,111.40

BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval				
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			QUARTER GLASS RRLH	1	168.10	168.10	30.00	117.67	Replace	1	117.67	Replace	• / APC	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	• / APC	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	• X NAI	
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	30.00	1,043.14	Replace	1	0	Repair	• X R	
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	30.00	49.28	Replace	0	0	Not Give	• X NAI	
One Time Key In	Main			MOULDING BODY, LH	1	673.60	673.60	30.00	471.52	Replace	1	0	Repair	• X R	
One Time Key In	Main			DOOR RRLH	1	954.50	954.50	30.00	668.15	Replace	1	0	Repair	• X R	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	30.00	321.02	Replace	1	321.02	Replace	• / BR	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	30.00	11.27	Replace	10	11.27	Replace	• / APC	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	30.00	143.99	Replace	0	0	Check	• X NAI	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	30.00	97.72	Replace	0	0	Check	• X NAI	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	• X NAI	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• / APC	
One Time Key In	Main			BUMPER LIP COVER RRLH	1	72.20	72.20	30.00	50.54	Replace	1	50.54	Replace	• / BR	
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	30.00	160.23	Replace	0	0	Check	• X NAI	
One Time Key In	Main			BUMPER SEAL, RR LH	1	62.23	62.23	30.00	43.56	Replace	1	43.56	Replace	• / CR4	

Total Spare Part Cost 5,606.40

Surveyor Total 1,389.25

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,485.12

Final Sur Total 1,111.40

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	30.00	66.36	Replace	1	66.36	Replace	BR
One Time Key In	Main			BUMPER SIDE RETAINER RRRH	1	94.80	94.80	30.00	66.36	Replace	0	0	Not Give	X MM
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	\$14.50	\$14.50	30.00	360.15	Replace	0	0	Check	X MM
One Time Key In	Main			END PANEL	1	602.10	602.10	30.00	421.47	Replace	0	0	Check	X MM
Total Spare Part Cost									5,606.40	Surveyor Total 1,388.25				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									4,485.12	Final Sur Total 1,111.40				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION REAR	1,014.00	800	
Total:			1,014.00	800.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
4	Main	TO RESPRAY REAR FENDER LH	378.00	200	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
6	Main	TO RESRAY REAR DOOR LH	378.00	200	
7	Main	TO RESPRAY RIM	180.00	50	
Total:			1,894.00	650.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,305.00	375.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	AK
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
3	Main	TO REMOVE / REFIT SEAT	120.00	40	AK
4	Main	TO REMOVE & REFIT FUEL TANK	120.00	40	AK
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125	AK
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	40	AK
8	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	AK
9	Main	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	40	AK
10	Main	TO REPLACE SUNDRY PARTS	100.00	0	
11	Main	TO WASH AND VACUUM	60.00	0	
12	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
Total:			1,305.00	375.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,485.12	1,111.40
Total Labour Cost	1,014.00	800.00
Total Spray Painting	1,854.00	650.00
Other	1,305.00	375.00
Overall Total	8,658.12	2,936.40
Lump Sum Repair Option		✓
Lump Sum Total	8,650.00	2,950.00
Surveyor Approved Amount		2,950.00
No of Repair Days*	7	6
Remarks		1's repair , photo after paint
Surveyor Name		Hwee Jie

Signature

Survey Date

Estimator Assessment(\$)



Surveyor Assessment(\$)



Save Clear


31/5/19

29/05/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX/05/19/2120	Date of Collection	1 / 1
Vehicle No	SUB 1261 B	Date of Request	03/06/2019
Vehicle Model	TOWIA PRMS	Number of Days to Expend (If any)	21

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR BUMPER Lip	1pc	✓ SCR
	Labom	10 SPRAY ROCKER PANEL BARNHILL LH	1pc	✓ \$200

\$160.23

\$100

<<Please submit photographs for damaged parts>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....
Signature of person making this declaration
(to be signed in front of an authorized witness)



I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / FO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB1261B
Case Reference Number	TAX05/19/2120
Registration Date	15/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SAHAR BIN ATAN
Type of Accident	Head to Rear
Accident Date and Time	27/5/2019 8:50 AM
Accident Reported Date and Time	27/5/2019 12:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24101686
Special Instruction to ARC, if any	TP
Prepared Date and Time	28/5/2019 2:26 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$2,054.00	\$750.00
Total Spare Part Cost	\$4,613.30	\$1,239.58
Total Other Cost	\$1,305.00	\$375.00
TOTAL COST	\$8,986.30	\$3,164.58
Lump Sum Total	\$5,000.00	\$3,150.00 (L/5)
Number of Repair Days	8.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / MSIG
ARC / Surveyor Sign Off Date	30/05/2019 7:32 AM	29/05/2019 3:51 PM
Signature		
Remarks	1/1 repair, photo after paint	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0137	Invoice Number	
Quotation Date	10.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION REAR	\$1,014.00	\$800.00
Total Labour	\$1,014.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$200.00	\$100.00
Total Spray Painting & Panel Beating	\$2,054.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$40.00
TO REMOVE & REFIT FUEL TANK	\$120.00	\$40.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$40.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
Total Other Costs	\$1,305.00	\$375.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace
		61602-47091	FENDER RR/LH	1.00	\$766.80	30.00	\$536.76	Replace	Replace

		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Check	X
	77350-47030	LID ASSY, FUEL	0.00	\$102.00	0.00	\$0.00	Replace	Check	Y
	77035-47090	CABLE SUB-ASSY, FUEL LID	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	77377-75010	RETAINER, FUEL LID CABLE	0.00	\$5.90	0.00	\$0.00	Replace	Check	X
	77300-52030	CAP ASSY, FUEL TANK	0.00	\$65.10	0.00	\$0.00	Replace	Not Given	X
	77201-47250	PIPE SUB-ASSY, FUEL NECK	0.00	\$230.60	0.00	\$0.00	Replace	Check	X
	62720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	30.00	\$117.67	Replace	Replace	
		SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611-47140	WHEEL, DISC	1.00	\$1,490.20	100.00	\$0.00	Replace	Repair	R
	62940-18060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Not Given	X
	75852-47900	MOULDING BODY, LH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	R
	67004-47080	DOOR RR/LH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	R
	52159-47995	BUMPER REAR	1.00	\$458.60	30.00	\$321.02	Replace	Replace	
	52161-18010	BUMPER CLIPS	10.00	\$1.61	30.00	\$11.27	Replace	Replace	
	52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X
	52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	
	76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	30.00	\$50.54	Replace	Replace	
	76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check	X
	52592-47021	BUMPER SEAL, RR LH	1.00	\$88.90	30.00	\$62.23	Replace	Replace	
	52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	30.00	\$66.36	Replace	Replace	
	52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
	58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	X
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
Total				\$7,707.45		\$1,389.25			

1549.48
- 202

1239.58
+ 800.00
+ 1125.00

3164.58

45\$ 3150/-

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	30.00	\$160.23	Replace	Replace
Total					228.90		160.23		

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		29 May 2019 13:28 Edit Adj Rpt	S\$3,150.00 Edit Estimates	S\$3,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GU LI ZHONG, ID: S8065253D, Tel: +6585115910								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB1261B	Date of Loss:	27/05/2019 08:00 - :59 [66 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 594486	Policy/Cover Note No.:	A29096848AVW (Comprehensive) Coverage: 21/09/2018 - 20/09/2019						
Vehicle Reg. No. (Insured):	SME1865J	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 28/06/2019]								
Driver/Custodian (Insured):	CHEN MIN (), NRIC: S8261559H, Tel: +6585115910 Email:								
Adj Asg. Remarks:	on WP. (MANUAL ASSIGNED BY IHS) CAR IN 29/05/2019. LIAB: 100%. CONTACT: SHANTI @ 6866 2671/2 Manually assigned to LKK via email on 29/05/2019								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB1261B (594486)
[SME1865J]
TP
SMRT TAXIS PTE LTD
May 27 2019 8:00AM
[GU LI ZHONG]
SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	31/05/19 13:43	Adjuster Immediate Advice				 Load HTM			
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	14/08/19 18:41	Odometer Reading				 Load JPG		☒	
2	14/08/19 18:41	Chassis Number				 Load JPG		☒	
3	14/08/19 18:41	General View				 Load JPG		☒	
4	14/08/19 18:41	General View				 Load JPG		☒	
5	14/08/19 18:41	General View				 Load JPG		☒	
6	14/08/19 18:41	General View				 Load JPG		☒	
7	14/08/19 18:41	General View				 Load JPG		☒	
8	14/08/19 18:41	General View				 Load JPG		☒	
9	14/08/19 18:41	General View				 Load JPG		☒	
10	14/08/19 18:41	General View				 Load JPG		☒	
11	14/08/19 18:41	General View				 Load JPG		☒	
12	14/08/19 18:41	General View				 Load JPG		☒	
13	14/08/19 18:41	General View				 Load JPG		☒	
14	14/08/19 18:41	General View				 Load JPG		☒	
15	14/08/19 18:41	General View				 Load JPG		☒	
16	14/08/19 18:41	General View				 Load JPG		☒	
17	14/08/19 18:41	General View				 Load JPG		☒	
18	14/08/19 18:41	General View				 Load JPG		☒	
19	14/08/19 18:41	General View				 Load JPG		☒	
20	14/08/19 18:41	General View				 Load JPG		☒	
21	14/08/19 18:41	Photographs of Damaged Items				 Load JPG		☒	
22	14/08/19 18:41	Photographs of Damaged Items				 Load JPG		☒	
23	14/08/19 18:41	Photographs of Damaged Items				 Load JPG		☒	
24	14/08/19 18:41	Photographs of Damaged Items				 Load JPG		☒	
25	14/08/19 18:41	Photographs of Damaged Items				 Load JPG		☒	
26	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
27	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
28	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
29	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
30	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
31	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
32	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
33	14/08/19 18:42	After Repair Photo				 Load JPG		☒	
34	14/08/19 18:42	After Repair Photo				 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	14/08/19 18:42	After Repair Photo	 Load JPG	☒
36	14/08/19 18:42	After Repair Photo	 Load JPG	☒
37	14/08/19 18:42	After Repair Photo	 Load JPG	☒
38	14/08/19 18:42	After Repair Photo	 Load JPG	☒
39	14/08/19 18:42	After Repair Photo	 Load JPG	☒
40	14/08/19 18:42	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/05/19 11:57	TP SHB1261B E-REPORT	 Load PDF	
2	29/05/19 11:57	PRI	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/09/19 11:51	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009507/ETD3E2

Date: 02/09/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29096848AVW

Claimant Vehicle No : SHB1261B

Insured Vehicle No : SME1865J

Date of Loss: 27/05/2019

Nature of Claim: TP

Claim No: 594486

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB1261B

Make & Model: TOYOTA PRIUS ALPHA, 1.8 (A)

Engine No: 2ZR5919791

Reg. Date: 15/11/2013 (Man. Year: 2013)

Chassis No: JTDKN36U105707407

Colour: Maroon

Odometer: 530270 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,010.84	1,549.48	6,461.36	80.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,373.00	1,925.00	2,448.00	55.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,383.84	3,474.48	8,909.36	71.94
Approved Total (Overridden) (S\$)		3,150.00		
Nett Amount (S\$)	12,383.84	3,150.00	9,233.84	74.56

INSPECTION

Date of Assignment: 29/05/2019

Date Inspected: 29/05/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2019)
Parts:	M1-MPV	TOYOTA PRIUS ALPHA 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB1261B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER RR/LH (DISC 30%)	Dented	766.80 F	*536.76 F
2	1		*QUARTER GLASS RR/LH (DISC 30%)	Necessary	168.10 F	*117.67 F
3	1		*BUMPER REAR (DISC 30%)	Broken	458.60 F	*321.02 F
4	1		*BUMPER CLIPS (DISC 30%) (10PCS)	Necessary	16.10 F	*11.27 F
5	1		*BUMPER LIP COVER RR/LH (DISC 30%)	Broken	72.20 F	*50.54 F
6	1		*BUMPER SEAL, RR LH (DISC 30%)	Crushed	88.90 F	*62.23 F
7	1		*BUMPER SIDE RETAINER RR/LH (DISC 30%)	Broken	94.80 F	*66.36 F
8	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
9	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
10	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
11	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
12	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
13	1		*REAR BUMPER LIP (DISC 30%)	Scratched	228.90 F	*160.23 F
14	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F
15	1		*LID ASSY, FUEL	Not Necessary	102.00 F	*- F
16	1		*CABLE SUB-ASSY, FUEL LID	Not Necessary	63.90 F	*- F
17	1		*RETAINER, FUEL LID CABLE	Not Necessary	5.90 F	*- F
18	1		*CAP ASSY, FUEL TANK	Not Necessary	68.10 F	*- F
19	1		*PIPE SUB-ASSY, FUEL NECK	Not Necessary	230.80 F	*- F
20	1		*TYRE	Not Necessary	126.74 F	*- F
21	1		*DUCT ASSY, QUARTER	Not Necessary	70.40 F	*- F
22	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
23	1		*ARM SUB-ASSY, RR BUMPER LH	Not Necessary	139.60 F	*- F
24	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
25	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
26	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
27	1		*UNDER COVER SUBASSY, RR FLOOR	Not Necessary	514.50 F	*- F
28	1		*END PANEL	Not Necessary	602.10 F	*- F
29	1		*WHEEL, DISC	Repair	1,490.20 F	*- F
30	1		*MOULDING BODY, LH	Repair	673.60 F	*- F
31	1		*DOOR RR/LH	Repair	954.50 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	8,010.84 1,549.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	800.00
2	SPRAY PAINT	New	2,054.00	750.00
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	40.00
4	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	0.00
5	TO REMOVE / REFIT SEAT	New	120.00	40.00
6	TO REMOVE & REFIT FUEL TANK	New	120.00	40.00
7	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM	New	125.00	125.00
8	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	40.00
10	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
11	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	40.00
12	TO REPLACE SUNDRY PARTS	New	100.00	0.00
13	TO WASH AND VACUUM	New	60.00	0.00
14	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
Gross Labour Cost (S\$)			4,373.00	1,925.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >