

22/07/2021

ASS. REC. BY:

REF:

CS/MSG/19009508/Jtd301

Special Instruction:

Surveyor: Amel JieASSIGNMENT (Office)

From (Person):

Meimien
Pauline Tham

of

MSG

Date/Time:

29/5/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHC 4077S

Insured:

SGR 9956E

at Workshop m/s

SMRT

Tel:

6866 2672

of

Go Woodlands Ind. Park E4

Policy No:

29063115@MY

Claim No:

594917

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:53am @ 24/5/19

Person Contacted:

ShantiVehicle IN/OUT

Date/Time

Action/Instruction

Estimate

(✓)SHC 4077S-WS/INC18021100/Ntbe2D.O.A. 18/11/2018SGR 9956E -x31/5/19 @1:38pmrevised to Pauline Tham via Meimien.

ASS. REC. BY: Hree Je

REF:

MSG

ASSIGNMENT

From:

Date:

21/5/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHC 40775

at Workshop m/s

SMRT

of

woodlands Depot

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 40775

Yr Regn:

12 Dec 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour

maroon

A/C:

Insured / Std / NI / NA

Sp. Reading

114216

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU303576176Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/5/19

D.O.I.

29/5/19

Survey held at

SmrtDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed P/P \$5159.84/- 5days. (Red. 8198.66; 61%)

05/19/2111
SGR9956E

RECEIVED 14 JUN 2019

Date/Time, File Pass to?



Prel. Report

1) 1416 Typist

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



West end (\$)

Survey Fee:

200

Transportation:

3 + RS, SI

Photos

Others

1

TOTAL

211

Report Format:

TP

Lump Sum / H/E (\$)

5159.84

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 10:56		29 May 2019 11:49 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOH KAH LAM, ID: S6842687A		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC4077S	Date of Loss:	25/05/2019 00:00 - :59 [17 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29063115QMY (Comprehensive) Coverage: 14/02/2019 - 13/02/2020
Vehicle Reg. No. (Insured):	SGR9956E	Policy No. (Claimant):	
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/05/2019]		
Driver/Custodian (Insured):	KOH AN PANG SAMUEL (), NRIC: S9710751C Email:		
Adj Asg. Remarks:	on WP.(manual assigned) Car in 29/05/2019. Liab: 100%. Contact: Shanti @ 6866 2671/2		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

- MSIG_SG (29/05/2019): Cancellation of Assignment: SHC4077S



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Sent: Wednesday, 29 May 2019 10:52 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Crystal Lee
Subject: Survey Request - Manual Assigned
Attachments: 2111 - 4077.pdf

SHC4077S - SURVEY (MSIG) DOA: 25/05/19 SGR9956E CAR IN 29/05/19 (WOODLANDS DEPOT)

Manual Assigned

Dear LKK

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui
Admin Officer, Claims Services
D: +65 6643 1320 | F: +65 6225 7402 | zihui_ong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis)
[mailto:BThaiyalN@smrt.com.sg]
Sent: Tuesday, 28 May 2019 3:03 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/AR & SC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/ARC/AR & SC/Taxis) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/AR & SC/Taxis) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/ARC/AR & SC/Taxis) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Claims & IA/Claims & IA/Taxis) <weisiong@smrt.com.sg>; Gan Kwai Leng (Auto Svcs/Claims & IA/Claims & IA/Taxis) <GANKWAI LENG@smrt.com.sg>
Subject: RE:SHC4077S - SURVEY (MSIG)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4077S** within 48 hours according to GIA guide line, involving your insured **SGR9956E**
Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 31 May 2019

Preliminary Advice

Insured Vehicle No	: SGR9956E	Accident Date	: 25/05/2019
TP Vehicle No	: SHC4077S	Assignment Date	: 29/05/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 5.00
Date of Inspection	: 29/05/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (WOODLANDS) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,601.40
Revised Amount	:S\$	5,293.68
Check Items (Estimated)	:S\$	148.80
Total	:S\$	5,442.48

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/05/2019 10:10
Date Of Accident	25/05/2019 06:55
Exact Location Of Accident	UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4077S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	SHIANIAN BIN SAFIAN
NRIC No	S1594509E
Date Of Birth	30/12/1963
Occupation	OUTDOOR
Date Of Driving Pass	29/12/2006
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	107B
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG UPPER THOMSON ROAD AT THE SECOND LEFT LANE WITH A PASSENGER ON BOARD WHEN THE VEHICLE SGR9956E CUT ACROSS THE LANES FROM MY RIGHT AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR9956E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH AN PANG SAMUEL
NRIC/Passport Number	S9710751C
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/05/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

THOMSON RD
BRADDELL RD

LORNE RO

NEPER THOMPSON RD

A-SHC 4077S
B-SGR 9956E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time: 25/5/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle



Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4077S
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS111832
Chassis No.:	JTDKB3FU303576176
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,880.00
Total Rebate Amount:	\$31,630.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 May 2019

OK

Section A - Accident Details



Registration Number	SHC4077S
Case Reference Number	TAX/05/19/2111
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SHIANIAN BIN SAFIAN
Type of Accident	Side Swipe
Accident Date and Time	25/5/2019 6:55 AM
Accident Reported Date and Time	25/5/2019 9:05 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101692
Special Instruction to ARC, if any	TP
Prepared Date and Time	28/5/2019 11:56 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Diagram

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$800.00
Total Spray Cost	\$2,592.00	\$950.00
Total Spare Part Cost	\$7,955.40	\$3,229.84
Total Other Cost	\$1,040.00	\$180.00
TOTAL COST	\$12,601.40	\$5,159.84 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / MSIG
ARC / Surveyor Sign Off Date	28/05/2019 1:46 PM	29/05/2019 3:41 PM
Signature		
Remarks	p/p repair, photo before paint.	



Case Details

Case Reference Number : TAX/05/19/2111
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4077S

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7052-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd
 Accident Date and Time : 24/05/2019 10:55 PM
 Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	30.00	699.83	Replace	1	699.83	Replace ▾	BUC	/
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	30.00	39.67	Replace	1	39.67	Replace ▾	ncc	/
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	30.00	937.20	Replace	1	937.20	Replace ▾	DD	/
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	hel	/
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace ▾	CRA	/
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	30.00	67.13	Replace	1	67.13	Replace ▾	CRA	/
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	30.00	432.00	Replace	1	0	Repair ▾		
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	30.00	148.80	Replace	0	0	Check ▾	nn	
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	30.00	1,166.32	Replace	0	0	Not Give ▾	nn	
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	30.00	131.85	Replace	1	131.85	Replace ▾	SCR	/

Total Spare Part Cost 7,955.40

Surveyor Total 3,363.68

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,955.40

Final Sur Total 3,363.68

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	30.00	932.93	Replace	1	0	Repair ▾	
One Time Key In	Main			WEATHERSTRIP, REAR DOOR , NO.2 , RH	1	33.20	33.20	30.00	24.90	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	30.00	618.60	Replace	1	0	Repair ▾	
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	30.00	101.85	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	nee /
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	30.00	1,166.32	Replace	0	0	Not Give ▾	nn
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	30.00	131.85	Replace	1	131.85	Replace ▾	scb /
Total Spare Part Cost									7,955.40	Surveyor Total		3,363.68		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									7,955.40	Final Sur Total		3,363.68		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,014.00	800	
Total:			1,014.00	800.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200	
3	Main	TO RESPRAY VIEW MIRROR	180.00	50	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
5	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			2,592.00	950.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY REAR FENDER RH	378.00	200	
7	Main	RESPRAY WHEEL CAP	360.00	0	
8	Main	TO RESPRAY RIM	360.00	0	
Total:			2,592.00	950.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER DOOR MECHANISM	240.00	50	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	40	
6	Main	TO REMOVE AND REFIX WING MIRROR	120.00	30	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
8	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,040.00	180.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,955.40	3,363.68
Total Labour Cost	1,014.00	800.00
Total Spray Painting	2,592.00	950.00
Other	1,040.00	180.00
Overall Total	12,601.40	5,293.68
Lump Sum Repair Option		
Lump Sum Total	0.00	5,293.68
Surveyor Approved Amount		5,293.68
No of Repair Days*	7	5

14938.50

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

p/p repair, photo before paint.

Surveyor Name

Hwee jie

Signature


3/5/19

Save

Clear

Survey Date

29/05/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1906-0140	Invoice Number	
Quotation Date	12.06.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$800.00
Total Labour	\$1,014.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
RESPRAY WHEEL CAP	\$360.00	\$0.00
TO RESPRAY RIM	\$360.00	\$0.00
Total Spray Painting & Panel Beating	\$2,592.00	\$950.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$40.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,040.00	\$180.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5380147080	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	30.00	\$653.17	Replace	Replace
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	30.00	\$37.03	Replace	Replace
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	30.00	\$874.72	Replace	Replace
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		8791047450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,373.50	10.00	\$1,236.15	Replace	Replace
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$89.50	30.00	\$62.65	Replace	Replace

BUC
NCC
TD
NCC
ORA
ORA

	75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair	✓
	53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X
	42611- 47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
	42602471 80	CAP SUB-ASSY, WHEEL	1.00	\$175.80	30.00	\$123.06	Replace	Replace	✓
	67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	100.00	\$0.00	Replace	Repair	✓
	67895470 10	WEATHERSTRIP, REAR DOOR, NO.2, RH	0.00	\$33.20	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	✓
	65637470 60	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
	42602471 80	CAP SUB-ASSY, WHEEL	1.00	\$175.80	30.00	\$123.06	Replace	Replace	✓
Total				\$10,292.50		\$3,229.84			

nm
 nm
 Sur
 nm
 nm
 nm
 nec
 nm
 Sur

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3229.84
 + 800.00

+ 1130.00

5159.84

14938.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 10:56		29 May 2019 11:49 Edit Adj Rpt	S\$5,159.84 Edit Estimates	S\$5,159.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH KAH LAM, ID: S6842687A								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4077S	Date of Loss:	25/05/2019 06:00 - :59 [17 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 594917	Policy/Cover Note No.:	29063115QMY (Comprehensive) Coverage: 14/02/2019 - 13/02/2020						
Vehicle Reg. No. (Insured):	SGR9956E	Policy No. (Claimant):							
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 28/06/2019]								
Driver/Custodian (Insured):	KOH AN PANG SAMUEL (), NRIC: S9710751C Email:								
Adj Asg. Remarks:	on WP.(manual assigned) Car in 29/05/2019. Liab: 100%. Contact: Shanti @ 6866 2671/2								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (29/05/2019): Cancellation of Assignment: SHC4077S 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4077S (594917)
[SGR9956E]
TP
SMRT TAXIS PTE LTD
May 25 2019 6:00AM
[KOH KAH LAM]
SMRT Automotive Services Pte Ltd


[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/05/19 13:38	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	13/06/19 16:37	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
23	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
24	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
25	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
26	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
27	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
28	13/06/19 16:38	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/05/19 10:57	OI GIA	1	Load PDF	
2	29/05/19 10:58	PRI Email	1	Load PDF	
3	29/05/19 10:58	TP GIA	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 11:41	email - manual assign	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009508/JTD3E2

Date: 26/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29063115QMY

Claimant Vehicle No : SHC4077S

Insured Vehicle No : SGR9956E

Date of Loss: 25/05/2019

Nature of Claim: TP

Claim No: 594917

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4077S

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZRS111832

Reg. Date: 12/12/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU303576176

Colour: Maroon

Odometer: 114216 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,292.50	3,229.84	7,062.66	68.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,646.00	1,930.00	2,716.00	58.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	14,938.50	5,159.84	9,778.66	65.46

INSPECTION

Date of Assignment: 29/05/2019

Date Inspected: 29/05/2019 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4077S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY, FR, RH (DISC 30%)	Buckled	933.10 F	*653.17 F
2	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 30%)	Necessary	52.90 F	*37.03 F
3	1		*PANEL SUB-ASSY, FRONT DOOR RH (DISC 30%)	Dented	1,249.60 F	*874.72 F
4	1		*COVER, OUTER MIRROR, RH (DISC 30%)	Cracked	89.50 F	*62.65 F
5	1		*CAP SUB-ASSY, WHEEL (DISC 30%)	Scratched	175.80 F	*123.06 F
6	1		*CAP SUB-ASSY, WHEEL (DISC 30%)	Scratched	175.80 F	*123.06 F
7	1		*MIRROR ASSY, OUTER REAR VIEW, RH (DISC 10%)	Cracked	1,373.50 F	*1,236.15 F
8	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
9	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
10	1		*LINER, FR FENDER, RH	Not Necessary	198.40 F	*- F
11	1		*WHEEL, DISC FRONT	Not Necessary	1,555.10 F	*- F
12	1		*WEATHERSTRIP REAR DOOR, NO.2, RH	Not Necessary	33.20 F	*- F
13	1		*LINER, REAR FENDER, RH	Not Necessary	135.80 F	*- F
14	1		*WHEEL, DISC	Not Necessary	1,555.10 F	*- F
15	1		*MOULDING ASSY, BODY ROCKER PANEL, RH	Repair	576.00 F	*- F
16	1		*PANEL SUB-ASSY, REAR DOOR, RH	Repair	1,243.90 F	*- F
17	1		*PANEL SUB-ASSY, FENDER REAR RH	Repair	824.80 F	*- F
					Total Parts (\$\$)	10,292.50 3,229.84

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	800.00
2	SPRAY PAINT	New	2,592.00	950.00
3	TO TRANSFER DOOR MECHANISM	New	240.00	50.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	40.00
6	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	40.00
8	TO REMOVE AND REFIX WING MIRROR	New	120.00	30.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			4,646.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >