

ESTIMATE

DATE OF ACCIDENT : 17/05/2019
VEHICLE : SMF3689H
MAKE & MODEL : TOYOTA NOAH
INSURANCE : EQ INSURANCE
SURVEYOR : EQ INSURANCE

PARTS		CONDITION	AMOUNT	
1.	FRONT BUMPER <i>Repair</i>		\$ 1800	+
2.	FRONT BUMPER GRILLE (LOWER) <i>new de her</i>		\$ 550	+
3.	FRONT BUMPER GRILLE (UPPER) <i>De her</i>		\$ 400	✓
4.	BONNET HINGE - LEFT <i>2 Best.</i>		\$ 65	✓
5.	BONNET HINGE - RIGHT		\$ 65	✓
6.	FRONT FENDER - RIGHT <i>Repair</i>		\$ 350	+
7.	HEADLAMP - RIGHT <i>cracked</i>		\$ 2100	✓
8.	FRONT SUPPORT BEAM ?		\$ 850	?
9.	FRONT SUPPORT PANEL <i>Buckled</i>		\$ 650	✓
10.	CENTRE SUPPORT BEAM <i>Best</i>		\$ 180	✓
11.	CONDENSOR ?		\$ 1800	?
SPECIAL NETT				
1.	FRONT BUMPER NUMBER PLATE & COVER <i>De her</i>		\$ 75	✓



JACK CARS

2.	CLIPS <i>Ne</i>		\$ 100	30
3.	AIRCON GAS <i>me</i>		\$ 120	60
	LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 2000	800
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS		\$ 1700	700
3.	TO CHECK LIGHTING SYSTEM , WIRING & REWIRE		\$ 250	30
4.	PROGRAMMING OF HEADLAMP		\$ 200	x
5.	ANTI RUST TREATMENT		\$ 120	x
	PARTS +10% :		\$ 9,691	
	SPECIAL NETT :		\$ 295	
	LABOUR :		\$ 4,270	
	TOTAL :		\$ 14,256	
	7% GST :		\$ 997.92	
	GRAND TOTAL :		\$ 15,253.92	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 30/05/19.
Not Authorized
Excess \$600. 65 Days