



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
 Tel : 6484 1221 Fax : 6484 7829
 385 Sin Ming Drive (Inside Vicom) Singapore 575718.
 Tel : 6753 2112 Fax : 6451 0394
 Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLJ 3143 G

TOYOTA PRIUS

JTDKB3FUX03539884

Submit By :

CARMEN LIM

Year Manufacture :

2016

Engine No. :

Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper side seal RH <i>CM</i>	1	\$87.30		—
2	Rear bumper under cover RH <i>CM</i>	1	\$187.60		—
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

274.90