


Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: 2100472846
 Claims No: 536586452354
 Sum Insured: _____ Excess: 600 06/6/19
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 100K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 04 888 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
 Person Contacted: _____

Veh No: SKB396S Yr Regn: 2016 / July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 Sedan cc 1375
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 60662 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WAU222F486A108332

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19

R: 255/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 06 mm
 L/Bal. 06 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 AUG.
SKB396S
30/5/19 @ 11.55am revert to Victor via Meimen.
06/6/19 @ 12.55pm Lats. Chang a formal cta via Meimen.
mv:
PV:
Nett:
06/6/19 @ 1.43pm informed George C/A to ex \$600 by email.
13/6/19 @ 4.55pm 2nd revert to Victor via Meimen. (supplementing)
14/6/19 @ 11.14am Victor informed C/A at \$9146 via Meimen.

RECEIVED 23 AUG 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 26/8 Meimen
 3) _____
 5) _____

2) _____
 4) _____
 6) _____

Prel. Report:
 Final Report:

Part Prices Check:

IN OUT

Survey Fee:

Basic & Add.
 S + RS, SI
 Photos
 Others
 TOTAL

Date:

200
11
211

Vehicle No. : SKB 3965 A/c - 07 Date: 28/05/19

11/7/19 @ 1.57m confirmed with Mr SOD final fig \$8013.28, 4 days by email.
(Ref # 17434.72, 69%)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 11 July 2019 1:57 PM
To: Boo seng yak; Carrine Leong; SUR; Chang Chee Sing;
jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SKB396S - OD AIG - SURVEYED 29 MAY 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$8,013.28 before excess \$600.00 & GST and 4 repair days. (as take out labour no. 2 \$280.00)

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 27 June 2019 4:25 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; SUR <sur@lkkauto.com>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SKB396S - OD AIG - SURVEYED 29 MAY 19

Hi Adrian and all,

Revised estimate is attached. Photographs were mailed to Admin on 7 Jun 19.

Please confirm repair cost of \$8293.28 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 May 2019 18:19	Cim Veh Model Changed		[I] Merimen Administrator
2	28 May 2019 18:19	Cim Created	Reg No: SKB396S, Policy No: 2100472846-02, Acct Date: 2019/05/28, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte, Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119069627	[I] Merimen Administrator
3	29 May 2019 16:53	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[I] LEE SU THING
4	29 May 2019 16:53	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] LEE SU THING
5	29 May 2019 16:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	29 May 2019 16:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/10	[A] LEE SU THING
7	29 May 2019 16:53	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
8	29 May 2019 16:53	Cim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	29 May 2019 16:53	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] LEE SU THING
10	29 May 2019 16:53	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	30 May 2019 10:51	Adj Rpt Initiated		[A] SHIAU CHAN
12	30 May 2019 10:51	Cim Dtl Modified	JPJ Reg. Date: -> 2016/07/01.	[A] SHIAU CHAN
13	30 May 2019 10:51	Cim Details Notified		[A] SHIAU CHAN
14	30 May 2019 11:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/06/10	[A] SHIAU CHAN
15	30 May 2019 11:55	Adj Mandate Request	Cur.Req:11905.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	04 Jun 2019 14:59	Cim Registration Modified	Init.Est.:>4,000 - 5,000, Excess: -> 600.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Gan, Hunchung
17	04 Jun 2019 14:59	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	06 Jun 2019 12:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/10, Mandate Remarks: RE-INSPECTION require on check item, hidden item and supplementary Before Painting require on rear end panel.	[I] Chang, Lois-KL
19	06 Jun 2019 12:35	Adj Mandate Set	Approved:8346.00:RE-INSPECTION require on check item, hidden item and supplementary Before Painting require on rear end panel.Reinsp:Yes.	[I] Chang, Lois-KL
20	13 Jun 2019 16:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/06/10	[A] SHIAU CHAN
21	13 Jun 2019 16:55	Adj Mandate Request	Cur.Req:12705.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	14 Jun 2019 11:14	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2019/06/10, Mandate Remarks: Supplementary ok RE-INSPECTION require on check item, hidden item and supplementary	[I] Koh, Victor-CK
23	14 Jun 2019 11:14	Adj Mandate Set	Approved:9146.00:Supplementary ok RE-INSPECTION require on check item, hidden item and supplementary	[I] Koh, Victor-CK
24	14 Jun 2019 15:51	Cim Registration Modified	Pol No:2100472846-02->2100472846.	[I] Kaur, Baljit

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2161262	30/05/2019 10:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKB396S		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 13 Jun 2019

Preliminary Advice

Vehicle No	: SKB396S	Accident Date	: 28/05/2019
Make	: AUDI A4	Policy No.	: 2100472846-02
Assignment Date	: 29/05/2019	Excess	: S\$600.00
Date of Inspection	: 29/05/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,448.00	(ESTIMATE \$24,048.00 + SUPPLEMENTARY \$1,400.00)
Revised Amount	:S\$	9,146.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	3,559.00	
Total	:S\$	12,705.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	62,621.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,379.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 6 June 2019 1:43 PM
To: Claims Dept; SUR
Subject: RE: OD CLAIMS FOR VEHICLE SKB 0396 S (veh in is in workshop)

Dear George,

As instructed by our client , please proceed to repair the insured vehicle SKB 396S (Excess \$600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 6 June 2019 10:17 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR VEHICLE SKB 0396 S (veh in is in workshop)

Dear Denise,

Please advise on approval status urgently.

Vehicle is in our compound.

Thank You.

Best Regards,

George Wong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902273W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 May 2019 18:19	Clim Veh Model Changed		[] Merimen Administrator
2	28 May 2019 18:59	Clim Created	Reg No: SKB3965, Policy No: 2100472846-02, Acct Date: 2019/05/28, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119069627	[I] Merimen Administrator
3	29 May 2019 16:53	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	29 May 2019 16:53	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	29 May 2019 16:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	29 May 2019 16:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/10	[A] LEE SU THING
7	29 May 2019 16:53	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] LEE SU THING
8	29 May 2019 16:53	Clim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	29 May 2019 16:53	Clim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] LEE SU THING
10	29 May 2019 16:53	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	30 May 2019 10:51	Adj Rpt Initiated		[A] SHIAU CHAN
12	30 May 2019 10:51	Clim Dtl Modified	JPI Reg. Date: -> 2016/07/01.	[A] SHIAU CHAN
13	30 May 2019 10:51	Clim Details Notified		[A] SHIAU CHAN
14	30 May 2019 11:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/06/10	[A] SHIAU CHAN
15	30 May 2019 11:55	Adj Mandate Request	Cur.Req:11905.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	04 Jun 2019 14:59	Clim Registration Modified	Init.Est.->4,000 - 5,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Gan, Hunchung
17	04 Jun 2019 14:59	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	06 Jun 2019 12:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/10. Mandate Remarks: RE-INSPECTION require on check item, hidden item and supplementary Before Painting require on rear end panel.	[I] Chang, Lois-Kl
19	06 Jun 2019 12:35	Adj Mandate Set	Approved:8346.00:RE-INSPECTION require on check item, hidden item and supplementary Before Painting require on rear end panel.Reinsp:Yes.	[I] Chang, Lois-KL

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2161262	30/05/2019 10:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKB3965		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 May 2019

Preliminary Advice

Vehicle No	: SKB396S	Accident Date	: 28/05/2019
Make	: AUDI A4	Policy No.	: 2100472846-02
Assignment Date	: 29/05/2019	Excess	: S\$0.00
Date of Inspection	: 29/05/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,048.00
Revised Amount	:S\$	8,346.00
Check Items (Estimated)	:S\$	3,559.00
Total	:S\$	11,905.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00
COE / PARF Rebate	:S\$	62,621.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,379.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4404C
Vehicle Details	
Vehicle No.:	SKB396S
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC (NAV)
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	CVN014209
Chassis No.:	WAUZZZF48GA108332
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$34,037.00
Original Registration Date:	01 Jul 2016
First Registration Date:	01 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$29,652.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2026
PARF Rebate Amount:	\$22,239.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,010.00
COE Rebate Amount:	\$40,382.00
Total Rebate Amount:	\$62,621.00

The information contained herein is correct as at 30 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 18:02
Date Of Accident	28/05/2019 15:00
Exact Location Of Accident	ORCHID HOTEL BASEMENT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB396S
Insured/Policyholder	
Name Of Registered Owner	TAN CHIN HUNG
NRIC No	S7884404C
Email Address	CHTAN@SGZHRO.COM
Mobile Phone No	(LOCAL) +65-92974123
Alternative Phone No	OTHERS-92974123

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100472846-02
Cover Note Number	

Driver

Name of Driver	TAN CHIN HUNG
NRIC No	S7884404C
Date Of Birth	13/08/1978
Occupation	INDOOR
Date Of Driving Pass	22/01/2007
Driving Experience	12 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92974123
Fax Number	(LOCAL) +65-92974123
Contact Number	OTHERS-92974123
Email Address	CHTAN@SGZHRO.COM

Address	27 UPPER SERANGOON VIEW #07-11
Postcode	534045
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE INCIDENT WAS HAPPENED IN A BASEMENT CARPARK. MISJUDGE THE MAIN PILLAR IN BETWEEN CARPARK LOT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Siti Nurul Huda
NRIC/IN No: S8917260L

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The incident was happened in a broadway carpark. This judge the main yellow in between car park lot.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Schwarzenberg
ID/IC/TIN No: 58402102

Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN CHIN HUNG
Period of Insurance : 01 Jul 2018 To 30 Jun 2019
Engine No. : CVN014209
Chassis No. : WAUZZZF48GA108332

Vehicle No. : SKB0396S
Policy No. : 2100472846-02
Endorsement No. :
Issued Date : 25 Jun 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered operative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN CHIN HUNG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 65 Ubi Road 1 Singapore 408669 63623223

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VL
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

09P000

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and important information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7884404C



Name

TAN CHIN HUNG

陈振宏

Race

CHINESE

Date of birth

13-06-1978

Sex

M

Country of birth

MALAYSIA

S7884404C

License Number: S7884404C

Name: TAN CHIN HUNG

Birth Date: 13 Aug 1978

Issue Date: 22 Jan 2007

001473518H



NRIC No. S7884404C



Date of issue

03-06-2009

27 UPPER SERANGOON VIEW #07-11
SINGAPORE 534045

NRIC No: S7884404C

Date: 31/01/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 2B: Motorcycles <= 200 CC
Class 2A: Motorcycles between 201 CC and 400 CC
Class 2: Motorcycles > 400 CC
Class 3: Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg

05 Dec 2015
11 Jan 2017
13 Mar 2018
13 Jan 2007

S / No. 9000278845

S7884404C

NP 428A



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0686/2019/DY
Date	:	29-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Chin Hung
Address	:	27 Upper Serangoon View #07-11 Singapore 534045
Telephone	:	HP +65 92974123
Type of Claim	:	Own Damage Claims
Policy No.	:	2100472846-02
Vehicle No	:	SKB 0396 S
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	Jul-16
Engine No	:	CVN 014209
Chassis No	:	WAUZZZF48GA108332
Mileage	:	-
Date In	:	28-May-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-May-19
Place of Accident	:	Orchird Hotel Basement Car-park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKB 0396 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$360.00 ✓	
2	To remove and trsansfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00 X ✓	
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00 ? X	
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. To repair lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,550.00 750 ✓	
5	To respray rear bumper, rear lid, both rear fenders hinges and end panelling. To carry out joint sealer works and stone chip treatment.	\$	4,300.00 1100 ✓	
6	To renew lhs rear exhaust silencer. To align to position.	\$	480.00 ? X	
7	To carry out diagnostic check.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$10,642.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 0396 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Dehorned</i>	\$ 2,015.00 ✓	1612
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 66.00 ✗	
3	REAR BUMPR SECURING STRIP <i>new</i>	\$ 203.00 ? ✗	
4	REAR BUMPER SPOILER <i>lit</i>	\$ 227.00 ✓	181.20
5	REAR BUMPER REFLECTOR - LH / RH <i>lit and</i>	\$ 76.00 38	29.68
6	REAR BUMPER CARRIER <i>Bent</i>	\$ 819.00 ✓	655.20
7	REAR BUMPER CARRIER SEAL <i>new</i>	\$ 25.00 ✓	20
8	REAR BUMPER GUIDE SECTION-LH <i>new</i>	\$ 40.00 ✗	
9	REAR BUMPER GUIDE SECTION-RH <i>new</i>	\$ 41.00 ✗	32.40 ✓
10	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>lit and</i>	\$ 40.00 ✗	31.84 ✓
11	REAR ANTENNA ASSEMBLY <i>new</i>	2 \$ 462.00 ✗	
12	REAR RETAINER FOR AERIAL <i>new</i>	\$ 23.00 ✗	
13	REAR VENT TRIM <i>new</i>	\$ 64.00 ✗	
14	REAR SENSOR <i>new</i>	2 \$ 462.00 ✗	
15	REAR SENSOR SEAL RING <i>new</i>	4 \$ 12.00 ✗	
16	REAR BUMPER WIRING	\$ 618.00 ✗	
17	REAR LID LOCK	\$ 227.00 ✗	
18	REAR LID LOCK COVER CAP	\$ 7.00 ✗	
19	REAR LID PUSH BUTTON	\$ 499.00 ✗	
20	REAR LID ANTI THEFT GUARD COVER <i>new</i>	\$ 58.00 ✗	
REAR - SUB SPARE PARTS CHARGES		\$ 5,984.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 0396 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID GASKET FLAP <i>Not new</i>	\$ 185.00	X
22	REAR PACKING ADHESIVE <i>Not new</i>	\$ 18.00	X
23	REAR LID AUDI EMBLEM	\$ 113.00	✓
24	REAR LID INSCRIPTION 'A4' <i>new</i>	\$ 87.00	✓
25	REAR LID INSCRIPTION 'TFSI' <i>new</i>	\$ 87.00	X
26	LED TAILLIGHT OUTER -LH/RH <i>crushed</i>	2 \$ 1,862.00	✓ 1489.60
27	LED TAILLIGHT OUTER TRIM-LH/RH <i>LH out.</i>	2 \$ 54.00	43.04 ✓
28	LED TAILLIGHT INNER-LH/RH <i>LH out LH in</i>	2 \$ 1,862.00	931 744.80
29	LED TAILLIGHT INNER TRIM-LH/RH <i>LH out</i>	2 \$ 54.00	27. 21.52
30	LED LICENCE PLATE LIGHT <i>new</i>	2 \$ 105.00	? X
31	REAR CROSS PANEL <i>new</i>	\$ 238.00	? X
32	REAR REINFORCEMENT CROSS PANEL <i>new</i>	\$ 461.00	X
33	REAR CROSS PANEL TRIM <i>new</i>	\$ 154.00	X
34	REAR SILENCER <i>new</i>	\$ 999.00	? X
35	REAR SILENCER DUAL CLIP <i>new</i>	\$ 45.00	X
36	REAR SILENCER BRACKET <i>new</i>	\$ 38.00	X
37	ACRYLIC SEALANT <i>new</i>	S/N \$ 180.00	? X
38	STONE CHIP <i>Not new</i>	S/N \$ 180.00	? X
39	CAVITY WAX <i>Not new</i>	S/N \$ 140.00	? X
40	REAR NO. PLATE <i>new</i>	\$ 60.00	X
41	SUNDRIES <i>Not new</i>	\$ 500.00	? X
TOTAL REAR SPARE PARTS CHARGES		\$ 13,406.00	
TOTAL LABOUR CHARGES		\$ 10,642.00	
GRAND TOTAL (FRONT + BACK)		\$ 24,048.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

25/4/8

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 29/05/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 04 days

LHK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after under painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- No legal manipulation is allowed
- Supplementary surveys must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0686/2019/DY/TF

Date

7-Jun-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKB 0396 S

Model No

A4 Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
<u>Parts</u>			

\$ -

LABORS

1

To repair and respray rhs rear fender.

\$ ~~1,400.00~~ ⁷⁵⁰ 800

TOTAL

\$ 1,400.00

For Premium Automobiles Pte Ltd

Adrian Ling
H.S.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0686/2019/DY/TF
Date	:	29-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

4 days - ok - jb - 27 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Chin Hung
Address	:	27 Upper Serangoon View #07-11 Singapore 534045
Telephone	:	HP +65 92974123
Type of Claim	:	Own Damage Claims
Policy No.	:	2100472846-02
Vehicle No	:	SKB 0396 S
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	Jul-16
Engine No	:	CVN 014209
Chassis No	:	WAUZZZF48GA108332
Mileage	:	-
Date In	:	28-May-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-May-19
Place of Accident	:	Orchird Hotel Basement Car-park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKB 0396 S

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	na
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. To repair lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,550.00	\$ 750.00
5	To respray rear bumper, rear lid, both rear fenders hinges and end panelling. To carry out joint sealer works and stone chip treatment.	\$	4,300.00	\$ 1,100.00
6	To renew lhs rear exhaust silencer. To align to position.	\$	480.00	na
7	Added labour charges - see attached	\$	1,400.00	\$ 750.00
8	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$12,042.00	\$ 3,432.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 0396 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,015.00	\$ 1,612.00
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPR SECURING STRIP	\$ 203.00	
4	REAR BUMPER SPOILER	\$ 227.00	\$ 181.20
5	REAR BUMPER REFLECTOR - LH / RH	\$ 76.00	\$ 29.68
6	REAR BUMPER CARRIER	\$ 819.00	\$ 655.20
7	REAR BUMPER CARRIER SEAL	2 \$ 25.00	\$ 20.00
8	REAR BUMPER GUIDE SECTION-LH	\$ 40.00	
9	REAR BUMPER GUIDE SECTION-RH	\$ 41.00	\$ 32.40
10	REAR BUMPER UPPER GUIDE SECTION-LH/RH	\$ 40.00	\$ 31.84
11	REAR BUMPER UPPER GUIDE SECTION PIN	2 \$ 5.00	
12	REAR ANTENNA ASSEMBLY	\$ 164.00	
13	REAR RETAINER FOR AERIAL	\$ 23.00	
14	REAR VENT TRIM	\$ 64.00	
15	REAR SENSOR	2 \$ 462.00	
16	REAR SENSOR SEAL RING	4 \$ 12.00	
17	REAR BUMPER WIRING	\$ 618.00	
18	REAR LID	TBC	
19	REAR LID LOCK	\$ 227.00	
20	REAR LID LOCK COVER CAP	\$ 7.00	
REAR - SUB SPARE PARTS CHARGES		\$ 5,134.00	\$ 2,562.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKB 0396 S

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
			\$	2,562.32
21	REAR LID PUSH BUTTON		\$ 499.00	
22	REAR LID ANTI THEFT GUARD COVER		\$ 58.00	
23	REAR LID GASKET FLAP		\$ 185.00	
24	REAR PACKING ADHSIVE		\$ 18.00	
25	REAR LID AUDI EMBLEM		\$ 113.00	
26	REAR LID INSCRIPTION ' A4 '		\$ 87.00	
27	REAR LID INSCRIPTION ' TFSI'		\$ 87.00	
28	LED TAILLIGHT OUTER -LH/RH	2	\$ 1,862.00	\$ 1,489.60
29	LED TAILLIGHT OUTER TRIM-LH/RH	2	\$ 54.00	\$ 43.04
30	LED TAILLIGHT INNER-LH/RH	2	\$ 1,862.00	\$ 744.80
31	LED TAILLIGHT INNER TRIM-LH/RH	2	\$ 54.00	\$ 21.52
32	LED LICENCE PLATE LIGHT	2	\$ 105.00	
33	REAR CROSS PANEL		\$ 238.00	
34	REAR REINFORCEMENT CROSS PANEL		\$ 461.00	
35	REAR CROSS PANEL TRIM		\$ 154.00	
36	REAR SILENCER		\$ 999.00	
37	REAR SILENCER DUAL CLIP		\$ 45.00	
38	REAR SILENCER BRACKET		\$ 38.00	
39	ACRYLIC SEALANT	S/N	\$ 180.00	
40	STONE CHIP	S/N	\$ 180.00	
41	CAVITY WAX	S/N	\$ 140.00	
42	REAR NO. PLATE WITH HOLDER	S/N	\$ 50.00	
43	SUNDRIES		\$ 500.00	
TOTAL REAR SPARE PARTS CHARGES		:	\$ 13,103.00	\$ 4,861.28
TOTAL LABOUR CHARGES			\$ 12,042.00	\$ 3,432.00
GRAND TOTAL (FRONT + BACK)			\$ 25,145.00	\$ 8,293.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0686/2019/DY/TF 7-Jun-19 Glory Tan 1 of 1 SKB 0396 S A4 Sedan 1.4 TFSI S
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
		\$ -	
<u>LABORS</u>			
1	To repair and respray rhs rear fender.	\$ 1,400.00	\$ 750.00
	TOTAL	\$ 1,400.00	\$ 750.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKB 396 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0686/2019/KK

22 Aug 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

1

total pages

RE: INSURANCE CLAIM FOR SKB 396 S, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SKB 396 S**, claimant, **Mr. Tan Chin Hung** please find the related document per attached.

1. A copy of the Original invoice no. 85014134 – S\$7,932.21.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKB 396 S

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:42

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014134 Date: 19/08/2019 Order: SKB0396S Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKB0396S (V 30551) Regn Date: 01/07/2016 Mileage: 62700 WIP No.: 54921

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAU2Z2F48GA108332 Engine: CVN 014209 Dept: U

You have been assisted by :- UB-Siti Marsilla (137)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGES	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.CUT OUT AND REWELD END PANELLING. TO REPAIR LHS REAR FENDER.REORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND LHS REAR FENDER. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REPAIR AND RESPRAY RHS REAR FENDER	750.00	1.00	750.00
X	A8W5945092C	LED TAIL LIGHT(LAST)	Less 020%	1.00	931.00
X	A8W5945091C	LED TAIL LIGHT	Less 020%	1.00	931.00
X	A8W5945093B	TAIL LIGHT	Less 020%	1.00	931.00
X	A8W0807309	BRACKET	Less 020%	1.00	819.00
X	A8W5807067A GRU	COVER	Less 020%	1.00	2015.00
X	A8W0807521K 9B9	SPOILER	Less 020%	1.00	226.50
X	A8W5807889	GUIDE	Less 020%	1.00	19.90
X	A8W5807890	GUIDE	Less 020%	1.00	19.90
X	A8W0807669	GASKET(LAST)	Less 020%	2.00	12.50
X	A8W5807454	GUIDE	Less 020%	1.00	40.50
X	A8W5945254	TRIM(LAST)	Less 020%	1.00	26.90
X	A8W5945253	TRIM	Less 020%	1.00	26.90
X	A8W0945105C	REFLECTOR	Less 020%	1.00	37.10
X	A8W5945255	TRIM	Less 020%	1.00	26.90
Parts 4,861.28					Sub-Total 7,413.28
Labour 0.00					7% GST 518.93
Sublet 3,152.00					Grand Total 7,932.21
Menus 0.00					
Lubricant 0.00					



19/8

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKB 396 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0686/2019/SM
11 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 Sedan 1.4 TFSI S
Vehicle Chassis No. : WAUZZZF48GA108332
Vehicle Regn No. : SKB 396 S
Vehicle Mileage : 58925 KM
Vehicle Owner : Mr. Tan Chin Hung
Certificate No : 2100472846-02
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 28th May 2019
Place : ORCHID HOTEL BASEMENT CARPARK
Repair Cost : \$ 7,932.21
WIP No. : 54921
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 16:17
Date : 11/6/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019		29 May 2019 16:53 Edit Adj Rpt	S\$8,013.28 Edit Estimates	S\$8,013.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]	
Insured:	TAN CHIN HUNG, ID: S7884404C, Tel: +6592974123, Email: CHTAN@SGZHRO.COM		
Vehicle Reg. No.:	SKB396S	Date of Loss:	28/05/2019 15:00 - :59 [34 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 5365864523SG	Policy/Cover Note No.:	2100472846 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/06/2019]		
Driver/Custodian:	TAN CHIN HUNG (40 / Male), NRIC: S7884404C, Tel: +6592974123 Email: CHTAN@SGZHRO.COM		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
- AIG_SG (14/06/2019): Alert - Adj Mandate Approved (S\$9146.00) - SKB396S - Claim Handler: Gan, Hunchun... - AIG_SG (06/06/2019): Alert - Adj Mandate Approved (S\$8346.00) - SKB396S - Claim Handler: Gan, Hunchun... - AIG_SG (04/06/2019): SKB396S / OD / 28/05/2019 / Coverage & Excess update		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB3965 (5365864523SG)
 OD
 May 28 2019 3:00PM
 [TAN CHIN HUNG]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	30/05/19 11:54	Adjuster Immediate Advice		Load HTM			
2	13/06/19 16:54	Adjuster Immediate Advice		Load HTM			
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	30/05/19 10:46	General View		Load JPG	☒		
2	30/05/19 10:46	General View		Load JPG	☒		
3	30/05/19 10:46	Chassis Number		Load JPG	☒		
4	30/05/19 10:46	General View		Load JPG	☒		
5	30/05/19 10:46	General View		Load JPG	☒		
6	30/05/19 10:46	General View		Load JPG	☒		
7	30/05/19 10:46	General View		Load JPG	☒		
8	30/05/19 10:46	General View		Load JPG	☒		
9	30/05/19 10:46	General View		Load JPG	☒		
10	30/05/19 10:46	General View		Load JPG	☒		
11	30/05/19 10:46	General View		Load JPG	☒		
12	30/05/19 10:46	General View		Load JPG	☒		
13	30/05/19 10:46	General View		Load JPG	☒		
14	30/05/19 10:46	General View		Load JPG	☒		
15	30/05/19 10:46	General View		Load JPG	☒		
16	30/05/19 10:46	General View		Load JPG	☒		
17	30/05/19 10:46	General View		Load JPG	☒		
18	30/05/19 10:46	General View		Load JPG	☒		
19	30/05/19 10:46	General View		Load JPG	☒		
20	30/05/19 10:46	General View		Load JPG	☒		
21	30/05/19 10:46	General View		Load JPG	☒		
22	30/05/19 10:46	General View		Load JPG	☒		
23	30/05/19 10:46	General View		Load JPG	☒		
24	30/05/19 10:46	General View		Load JPG	☒		
25	30/05/19 10:46	General View		Load JPG	☒		
26	30/05/19 10:46	General View		Load JPG	☒		
27	30/05/19 10:46	General View		Load JPG	☒		
28	30/05/19 10:46	General View		Load JPG	☒		
29	30/05/19 10:46	General View		Load JPG	☒		
30	30/05/19 10:46	General View		Load JPG	☒		
31	30/05/19 10:46	General View		Load JPG	☒		
32	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
33	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
34	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
35	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
36	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
37	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
38	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
39	13/06/19 16:49	Reinspection Photo		Load JPG	☒		
40	13/06/19 16:49	Reinspection Photo		Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
42	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
43	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
44	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
45	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
46	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
47	13/06/19 16:49	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/19 10:46	Singapore Accident Statement	 Load PDF	
2	30/05/19 10:46	Certificate of Insurance	 Load PDF	
3	30/05/19 10:46	Driver's Driving License	 Load PDF	
4	30/05/19 10:46	ESTIMATE	 Load PDF	
5	04/06/19 13:41	undertaking and interview form	 Load PDF	
6	13/06/19 16:51	SUPPLEMENTARY LIST	 Load PDF	
7	11/09/19 14:30	Workshop Invoice	 Load PDF	
8	11/09/19 14:30	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:16	Accident Photo	 Load JPG	☒
2	28/05/19 18:16	Accident Photo	 Load JPG	☒
3	28/05/19 18:16	Accident Photo	 Load JPG	☒
4	28/05/19 18:16	Accident Photo	 Load JPG	☒
5	28/05/19 18:16	Accident Photo	 Load JPG	☒
6	28/05/19 18:16	Accident Photo	 Load JPG	☒
7	28/05/19 18:16	Accident Photo	 Load JPG	☒
8	28/05/19 18:16	Accident Photo	 Load JPG	☒
9	28/05/19 18:16	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	28/05/19 18:13	Sketch Plan	 Load JPG	☒
2	28/05/19 18:13	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19009519/AQD3E2

Date: 11/09/2019

REFERENCE

Insured/Claimant:	TAN CHIN HUNG	Policy No:	2100472846	
Date of Loss:	28/05/2019	Nature of Claim:	OD	Claim No: 5365864523SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB396S		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN014209
Reg. Date:	01/07/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF48GA108332
Colour:	Black	Odometer:	60662 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,406.00	4,861.28	8,544.72	63.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,042.00	3,152.00	8,890.00	73.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,448.00	8,013.28	17,434.72	68.51
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	24,848.00	7,413.28	17,434.72	70.17
+ GST 7.00/7.00% (S\$)	1,739.36	518.93	1,220.43	70.17
Nett Amount (S\$)	26,587.36	7,932.21	18,655.15	70.17

INSPECTION

Date of Assignment:	29/05/2019	
Date Inspected:	29/05/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	2,015.00 FS	*1,612.00 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	1	*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*- FS
4	1	*REAR BUMPER SPOILER	Cut	227.00 FS	*181.20 FS
5	1	*REAR BUMPER REFLECTOR - LH / RH	N/S Cracked	76.00 FS	*29.68 FS
6	1	*REAR BUMPER CARRIER	Bent	819.00 FS	*655.20 FS
7	2	*REAR BUMPER CARRIER SEAL	Necessary	25.00 FS	*20.00 FS
8	1	*REAR BUMPER GUIDE SECTION - LH	Not Necessary	40.00 FS	*- FS
9	1	*REAR BUMPER GUIDE SECTION - RH	Damaged	41.00 FS	*32.40 FS
10	1	*REAR BUMPER UPPER GUIDE SECTION - LH / RH	N/S Damaged	40.00 FS	*31.84 FS
11	2	*REAR ANTENNA ASSEMBLY	Not Necessary	462.00 FS	*- FS
12	1	*REAR RETAINER FOR AERIAL	Not Necessary	23.00 FS	*- FS
13	1	*REAR VENT TRIM	Not Necessary	64.00 FS	*- FS
14	2	*REAR SENSOR	Not Necessary	462.00 FS	*- FS
15	4	*REAR SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
16	1	*REAR BUMPER WIRING	Not Necessary	618.00 FS	*- FS
17	1	*REAR LID LOCK	Not Necessary	227.00 FS	*- FS
18	1	*REAR LID LOCK COVER CAP	Not Necessary	7.00 FS	*- FS
19	1	*REAR LID PUSH BUTTON	Not Necessary	499.00 FS	*- FS
20	1	*REAR LID ANTI THEFT GUARD COVER	Not Necessary	58.00 FS	*- FS
21	1	*REAR LID GASKET FLAP	Not Necessary	185.00 FS	*- FS
22	1	*REAR PACKING ADHESIVE	Not Necessary	18.00 FS	*- FS
23	1	*REAR LID AUDI EMBLEM	Not Necessary	113.00 FS	*- FS
24	1	*REAR LID INSCRIPTION A4	Not Necessary	87.00 FS	*- FS
25	1	*REAR LID INSCRIPTION TFSI	Not Necessary	87.00 FS	*- FS
26	2	*LED TAILLIGHT OUTER - LH / RH	Cracked	1,862.00 FS	*1,489.60 FS
27	1	*LED TAILLIGHT OUTER TRIM - LH / RH	N/S Cut	54.00 FS	*43.04 FS
28	1	*LED TAILLIGHT INNER - LH / RH	N/S Cut	1,862.00 FS	*744.80 FS
29	1	*LED TAILLIGHT INNER TRIM - LH / RH	N/S Cut	54.00 FS	*21.52 FS
30	2	*LED LICENCE PLATE LIGHT	Not Necessary	105.00 FS	*- FS
31	1	*REAR CROSS PANEL	Not Necessary	238.00 FS	*- FS
32	1	*REAR REINFORCEMENT CROSS PANEL	Repair	461.00 FS	*- FS
33	1	*REAR CROSS PANEL TRIM	Not Necessary	154.00 FS	*- FS
34	1	*REAR SILENCER	Not Necessary	999.00 FS	*- FS
35	1	*REAR SILENCER DUAL CLIP	Not Necessary	45.00 FS	*- FS
36	1	*REAR SILENCER BRACKET	Not Necessary	38.00 FS	*- FS
37	1	*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
38	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
39	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
40	1	*REAR NO. PLATE	Not Necessary	60.00 FS	*- FS
41	1	*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNetl.

Total Parts (\$\$) 13,406.00 4,861.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	0.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND REWELD END PANELLING. TO REPAIR LHS REAR FENDER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,550.00	750.00
5	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS HINGES AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	4,300.00	1,100.00
6	TO RENEW LHS REAR EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REPAIR AND RESPRAY RHS REAR FENDER	New	1,400.00	750.00
Gross Labour Cost (S\$)			12,042.00	3,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >