

transmission

ASS. REC. BY:

REF:

08/FCI/9009522/RITd3

12

Special Instructions:

Surveyor: Robert

CWS

ASSIGNMENT (Office)

From (Person):

Maychua

of

FCI

Date/Time:

28/5/19 @ 5:24pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 9447A

Insured:

SHA 5740P

at Workshop m/s

Mover Automotive

Tel:

62723892

of

BK 1008 Bkt Manh lane 3 #01-04

Policy No:

Claim No:

D19003459 MF34

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

23/5/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:38am @ 29/5/19

Person Contacted:

Nithya

Vehicle IN/OUT

Date/Time

Action/Instruction Estimate (✓)

SMF 9447A-X

SHA 5740P-CS/FCI/8006178/Agln2

Don: 31/3/2018

12 July @ 1:21pm - revised via email preli advise

lump sum confirm \$54501 - (Red: 3333.37, 37%)

ASS. REC. BY:

REF:

FCI

6815A

ASSIGNMENT

From:

Date:

10/7/2019

Veh No:

SMF 9447A

Yr Regn: 2011 / MAR

Estimated Cost:

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

OD / ☒ TP / ☐ NS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

SMF 9447A

Make:

TOYOTA ALPHARO(A) c.c. 2362

at Workshop m/s

Mova Automotive

Colour

Black

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

of BIK 1008 Bkt merch June 3 #01-04

Sp. Reading

156988

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Insured:

Eng/No:

Policy No.

C/No:

JTEGD21/X08175713

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Moring

Modi: ☐ Nil / ☒ S/Rim / ☐ STD A/Rim or

(Policy Condition)


Tyre Size:

F:

235/50R18

R:

Remark: The veh had commenced its repair at the time of inspection.

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Bal. or Market Value:

SSK

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

23/05/19

D.O.I.

10/07/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Mova CBM

CA / REV / REP. / 24 HRS ^{1up}Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☒ N/S / ☐ UIC / ☐ Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 JUL 2019

Date/Time, File Pass to?

1) 29/7 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump ☒ On / ☐ L.B.B. ☐

54501-

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$

S + RS. \$



Interview (\$

Photos



Tech. Inve (\$

Cibles



Weekend (\$

TOTAL

160

50

50

44

304



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19003459MFSH

Date: 12/7/2019

Our Ref: CS/FCI19009522/R1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMF 9447A

Please be informed that we had conducted the inspection of the abovementioned vehicle 10/7/2019 at the premises of M/s Yew Tee Automobile have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,783.37</u>
Revised Estimate Amount	: S\$ <u>6,843.40</u>
"Check" Items Amount	: S\$ <u>0.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Rasul

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-05-2019	Our Ref No. D19003459MFSH
Accident Date	23-05-2019	Claim Type. Third Party
Insured Vehicle	SHA5740P	Third Party Vehicle. SMF9447A
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 29 July 2019 3:27 PM
To: Bobo Ong; Rasul (LKKAuto)
Subject: RE: SMF9447A FINALISATION

Dear Bobo,

Confirm finalise at lumpsum \$5450.00 with 5 repair days

Please submit your relevant documents to First Capital.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Bobo Ong <ongbobo@mova.com.sg>
Sent: Thursday, 25 July 2019 11:23 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: SMF9447A FINALISATION

Dear Rasul

Please see attached.

Kindly advise if we are able to finalise at lumpsum \$5450.00 with 5 repair days?

Best Regards,

Bo Bo

Estimator

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Thursday, 25 July 2019 8:58 AM

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 12 July 2019 1:21 PM
To: 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); May Chua Hui Chin
Subject: RE: SURVEY ASSESSMENT - D19003459MFSH/1
Attachments: PRELI ADVISED SMF 9447A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMF 9447A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 28 May, 2019 5:23 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003459MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Details	
Owner ID Type:	Singapore NRIC
Owner ID:	6815A
Vehicle Details	
Vehicle No.:	SMF9447A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD AUTO
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	2AZH661214
Chassis No.:	JTEGD21HX08175713
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$44,006.00
Original Registration Date:	29 Mar 2011
First Registration Date:	29 Mar 2011
Transfer Count:	5
Actual ARF Paid:	\$44,006.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2021
PARF Rebate Amount:	\$24,203.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$9,760.00
Total Rebate Amount:	\$33,963.00

The information contained herein is correct as at 11 Jul 2019

OK

55,000
33,963
21,037

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088854-2

Estimate

27/05/2019

MS FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SMF9447A

Veh Model :- TOYOTA ALPHARD

Estimate# :- CK419209

Claim # :-

ACC. Date :- 23/05/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT DOOR LH <i>bt</i>	1 PC	2,030.70	2,030.70
2.	FRONT DOOR LH LOWER GARNISH <i>sl</i>	1 PC	680.30	680.30
3.	FRONT DOOR LH WEATHERSTRIP <i>sl</i>	1 PC	247.60	247.60
4.	REAR DOOR LH <i>bt</i>	1 PC	2,580.50	2,580.50
5.	REAR DOOR LH LOWER GARNISH <i>sl</i>	1 PC	715.30	715.30
6.	REAR DOOR LH SIDE SEAL RUBBER (FRONT) <i>sl</i>	1 PC	116.50	116.50
7.	REAR DOOR LH LOWER SEAL (BOTTOM) <i>sl</i>	1 PC	116.50	116.50
8.	REAR DOOR LH WEATHERSTRIP <i>cut</i>	1 PC	220.30	220.30
9.	REAR DOOR LH ROLLER <i>X sl</i>	1 PC	175.80	175.80
10.	REAR FENDER COWLING LH <i>X sl</i>	1 PC	280.50	280.50
11.	REAR FENDER COWLING MUGGUARD FLAP LH <i>X sl</i>	1 PC	80.50	80.50
12.	REAR FENDER LH - REPAIR <i>+</i>	1 PC	R	
LIST TOTAL S\$				7,244.50
25% DISCOUNT S\$				-1,811.13
				5,433.37
SPECIAL NET ITEMS :				
1.	REAR RIM LH 18"	1 PC	1,500.00	1,500.00
SPECIAL NET TOTAL S\$				1,500.00
LABOUR :				
TO REPAIR REAR FENDER LH. TO REMOVE & REPLACE DAMAGED PARTS, STRAIGHTEN AND REALIGN AREAS				500 600.00
TO SPRAY PAINT ON AFFECTED AREAS				600 750.00
RUST PROOFING				60 80.00
TO REMOVE & REFIT DOOR MECHANISM, CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM				80 100.00
TO REMOVE & REFIX WHEEL RIM & CONDUCT BALANCING				40 60.00
TO CONDUCT WHEEL ALIGNMENT				60 80.00
TO CONDUCT SETTING FOR DOOR MECHANISM				40 80.00
LABOUR TOTAL S\$				1,850.00

Estimate

27/05/2019

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- **XA026**

Page # :- 1 135038

Veh # :- SMF9447A

Veh Model :- TOYOTA ALPHARD

Estimate# :- CK419209

Claim # :-

ACC. Date :- 23/05/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Move Building
 No. 22, Jalan Kijang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/06/08/04
 Singapore 159722
 Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088884-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

8,783.37

GST @ 7 %

614.84

AMOUNT DUE S\$

9,398.21

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Handwritten:
 Rasul
 Hp 90010068
 5 days
 w/s
 10/07/19 @ 1600
 Resy after repair

Main Office:
 Mova Building
 No. 22, Jalan Klang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

27/05/2019

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SMF9447A

Veh Model :- TOYOTA ALPHARD

Estimate# :- CK419209

Claim # :-

ACC. Date :- 23/05/19

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT DOOR LH <i>bt</i>	1 PC	2,030.70	2,030.70
2.	FRONT DOOR LH LOWER GARNISH <i>gk</i>	1 PC	680.30	680.30
3.	FRONT DOOR LH WEATHERSTRIP <i>re</i>	1 PC	247.90	247.00
4.	REAR DOOR LH <i>bt</i>	1 PC	2,580.50	2,580.50
5.	REAR DOOR LH LOWER GARNISH <i>de</i>	1 PC	715.30	715.30
6.	REAR DOOR LH SIDE SEAL RUBBER (FRONT) <i>re</i>	1 PC	116.50	116.50
7.	REAR DOOR LH LOWER SEAL (BOTTOM) <i>cut</i>	1 PC	116.50	116.50
8.	REAR DOOR LH WEATHERSTRIP <i>cut</i>	1 PC	220.30	220.30
9.	REAR DOOR LH ROLLER <i>X</i>	1 PC	175.80	175.80
10.	REAR FENDER COWLING LH <i>X</i>	1 PC	280.50	280.50
11.	REAR FENDER COWLING MUFFGUARD FLAP LH <i>X</i>	1 PC	80.50	80.50
12.	REAR FENDER LH - REPAIR	1 PC		
LIST TOTAL S\$				7,244.50
25% DISCOUNT S\$				-1,811.13
				5,433.37
SPECIAL NET ITEMS :				
1.	REAR RIM LH 18"	1 PC	1,500.00	1,500.00
SPECIAL NET TOTAL S\$				1,500.00
LABOUR :				
TO REPAIR REAR FENDER LH. TO REMOVE & REPLACE DAMAGED PARTS, STRAIGHTEN AND REALIGN AREAS				
TO SPRAY PAINT ON AFFECTED AREAS				
RUST PROOFING				
TO REMOVE & REFIT DOOR MECHANISM, CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM				
TO REMOVE & REFIT WHEEL RIM & CONDUCT BALANCING				
TO CONDUCT WHEEL ALIGNMENT				
TO CONDUCT SETTING FOR DOOR MECHANISM				
LABOUR TOTAL S\$				1,850.00

4942.75

6590.60

5000.00

25%

1400.00

4942.95

6842.85

20%

15474.36

412-5450

5 days

Parts = \$6583.50

-25% = \$4937.63

SN - \$ 500.00

Labour = \$1400.00

\$6837.63

Lumpsum = \$6800.00
 (-20% :)

\$5 Repair days.

500 \$/w cut

1,500.00

500 600.00

600 750.00

60 80.00

200 200.00

40 80.00

60 80.00

40 80.00

1,850.00

Estimate

27/05/2019

MS FIRST CAPITAL INSURANCE LIMITED
 36 Robinson Road
 #16-01 City House
 Singapore 068877.

Attention :- XA026

Page # :- 1 135038

Veh # :- SMF9447A

Veh Model :- TOYOTA ALPHARD

Estimate# :- CK419209

Claim # :-

ACC. Date :- 23/05/19

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Klang,
 Singapore 159419
 Tel : (65) 6476 3333
 Fax : (65) 6271 3891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/05/08/94
 Singapore 159722

Tel : (65) 6272 3892
 Fax : (65) 6270 8314
 Co. Reg. 199904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,783.37

GST @ 7 % 614.84

AMOUNT DUE S\$ 9,398.21

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Handwritten:
 Repair
 Hy 900 10068
 5 days
 w/s
 10/07/19 @ 1600
 Reay after repair

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19009522/R11d3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5740P	Veh. Inspected	SMF 9447A
Policy No.		Coverage (\$)	0.00
Claim No.	D19003459MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	28/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALPHARD (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JTEGD21HX08175713	Colour	BLACK
Odometer	156988	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	6 mm
L/H Front Tyre	235/50 R18	MICHELIN	6 mm
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/05/2019	Inspection Date	10/07/2019
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 9447A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR LH	BENT	2,030.70	2,030.70
1	FRONT DOOR LH LOWER GARNISH	SCRATCHED	680.30	680.30
1	FRONT DOOR LH WEATHERSTRIP	NECESSARY	247.60	247.60
1	REAR DOOR LH	BENT	2,580.50	2,580.50
1	REAR DOOR LH LOWER GARNISH	DEFORMED	715.30	715.30
1	REAR DOOR LH SIDE SEAL RUBBER (FRONT)	NECESSARY	116.50	116.50
1	REAR DOOR LH LOWER SEAL (BOTTOM)	SERVICEABLE	116.50	-
1	REAR DOOR LH WEATHERSTRIP	CUT	220.30	220.30
1	REAR DOOR LH ROLLER	SERVICEABLE	175.80	-
1	REAR FENDER COWLING LH	SERVICEABLE	280.50	-
1	REAR FENDER COWLING MUDGUARD FLAP LH	SERVICEABLE	80.50	-
1	REAR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,811.13	-1,647.80
			5,433.37	4,943.40
SPECIAL NETT ITEMS				
1	REAR RIM LH 18" (SN)	CUT	1,500.00	500.00
			1,500.00	500.00
LABOUR				
	TO REPAIR REAR FENDER LH. TO REMOVE & REPLACE DAMAGED PARTS, STRAIGHTEN AND REALIGN AREAS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		600.00	500.00
	TO SPRAY PAINT ON AFFECTED AREAS.		750.00	600.00
	RUST PROOFING.		80.00	60.00
	TO REMOVE & REFIT DOOR MECHANISM, CHECK & TEST POWER WINDOW & CENTRE LOCKING SYSTEM.		200.00	100.00
	TO REMOVE & REFIX WHEEL RIM & CONDUCT BALANCING.		60.00	40.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
	TO CONDUCT SETTING FOR DOOR MECHANISM		80.00	40.00
			1,850.00	1,400.00

Report Ref No. CS/FCI19009522/R1td3n2



GRAND TOTAL		8,783.37	6,843.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,450.00

Report Ref No. CS/FCI19009522/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.