

ASS. REC. BY:

REF: CS/FCI/9009524/Kgd3

Special Instruction:

Surveyor: Kennedy

## ASSIGNMENT (Office)

From (Person):

May chua

of

FCI

Date/Time:

28/5/19 @ 7.16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 5396J

Insured:

SHA 1200H

at Workshop m/s

Trans cab

Tel:

6287 6666

of

No. 2 Amk St. 63

Policy No:

Claim No:

D19003474MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/05/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10.35am @ 29/5/19

Person Contacted:

Zhouwei

Vehicle IN/OUT

| Date/Time        | Action/Instruction                | Estimate      |
|------------------|-----------------------------------|---------------|
|                  | SHD 5396J - CS/LPC/15016712/Kgd1  | DOA: 2/10/15  |
|                  | SHA 1200H - CC3/FCI/600458/Kth302 | DOA: 5/3/2016 |
| 30/5/19 @ 7.18pm | revised to May chua by email.     |               |
|                  |                                   |               |
|                  |                                   |               |
|                  |                                   |               |

ASS. REC. BY:

REF:

F021

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lump Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 3396J

Yr Regn:

11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tot Priv

C.C.

1798

Colour

M.P. White / R

A/C

Insured / Std / NI / NA

Sp. Reading

50106

T/Radio:

Insured / Std / NI / NA

Eng/No

C/No:

JTDKBFU 303077006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal:

9

mm

R/Bal:

6

mm

L/Bal:

9

mm

L/Bal:

6

mm

D.O.A

22/5/19

D.O.I

28/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

82113.73 (Red to 18731.42, 90%)

RECEIVED 31 MAY 2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



: Site Insp (S



: Interview (S



: Tech Invs (S



: Weekend (S

Survey Fee:

Transportation

S + RS \$

F + R

Others

350

Report Format:

7P

Lump Sum / I.B.I: (S

8113.73



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003474MFSH

Date: 30 May 2019

Our Ref: CS/FCI19009524/Kqd3

The Motor Claims Department  
MS First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 5396J**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/05/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

|                          |                        |
|--------------------------|------------------------|
| Workshop Estimate Amount | : S\$ <u>20,845.15</u> |
| Revised Estimate Amount  | : S\$ <u>2,113.73</u>  |
| "Check" Items Amount     | : S\$ <u>-</u>         |
| Market Value             | : S\$ <u>-</u>         |
| LTA Reimbursement Value  | : S\$ <u>-</u>         |
| Nett Value               | : S\$ <u>-</u>         |

Description of Damage:  
The vehicle sustained damages  
at the n/s rear body.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                    |                              |                               |
|--------------------|------------------------------|-------------------------------|
| Date               | 27-05-2019                   | Our Ref No. D19003474MFSH     |
| Accident Date      | 22-05-2019                   | Claim Type. Third Party       |
| Insured Vehicle    | SHA1200H                     | Third Party Vehicle. SHD5396J |
| Survey Location    | NO. 2 ANG MO KIO STREET 63   |                               |
| Contact Person.    | KEK ZHEWEI                   |                               |
| Contact No.        | 62876666/ 0                  | Fax No. 62571330              |
| Survey Type        | WITHOUT PREJUDICE:           |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD |                               |
| Contact Person     | NA                           | Fax No. 68416315              |
| Contact Number.    | NA                           |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                 |                         |
|-------------------|---------------------------------|-------------------------|
| Cc : Workshop     | TRANS-CAB AUTO SERVICES PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                              | TP Solicitor Fax No. NA |
| Officer Incharge  | MAY CHUA                        |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 31 May 2019 1:25 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: TP VEHICLE SHD 5396J (DOA: 22/05/2019) -- AAD1905-210  
**Attachments:** image001.wmz

Hi Shiau Chan

We confirmed COR amount \$2,113.73 (b4 GST).

Will send you photo when I get it from our workshop.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shiau Chan (LKKAuto) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 30 May, 2019 2:22 PM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHD 5396J (DOA: 22/05/2019)

Dear Wai Yin,

Based on our surveyor's estimate marking, the calculation of repair cost will be at \$2,113.73 and 3 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 30 May 2019 2:18 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'May Chua Hui Chin'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19003474MFSH/1  
**Attachments:** CSFCI19009524Kqd3.pdf

Dear May,

Re-send.

Enclosed herewith preliminary advice of SHD 5396J.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 30 May 2019 2:18 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'May Chua Hui Chin' <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003474MFSH/1

Dear May,

Enclosed herewith preliminary advice of SHD 5396J.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 29 May 2019 10:35 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'May Chua Hui Chin' <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003474MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 3878K   |

### Vehicle Details

|                               |                            |
|-------------------------------|----------------------------|
| Vehicle No.:                  | SHD5396J                   |
| Vehicle to be Exported:       | Yes                        |
| Intended Deregistration Date: | 24 May 2019                |
| Vehicle Make:                 | TOYOTA                     |
| Vehicle Model:                | PRIUS 5DR HATCHBACK (AUTO) |
| Primary Colour:               | Red                        |
| Manufacturing Year:           | 2018                       |
| Engine No.:                   | 2ZR2B76799                 |
| Chassis No.:                  | JTDKB3FU303077006          |
| Maximum Power Output:         | 90.0 kW (120 bhp)          |
| Open Market Value:            | \$26,605.00                |
| Original Registration Date:   | 22 Nov 2018                |
| First Registration Date:      | 22 Nov 2018                |
| Transfer Count:               | 0                          |
| Actual ARF Paid:              | \$14,247.00                |

### Intended PARF Rebate Details

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 21 Nov 2026 |
| PARF Rebate Amount:           | \$10,685.00 |

### Intended COE Rebate Details

|                             |                                      |
|-----------------------------|--------------------------------------|
| COE Expiry Date:            | 21 Nov 2026                          |
| COE Category:               | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):          | 8                                    |
| PQP Paid:                   | \$23,736.00                          |
| COE Rebate Amount:          | \$18,988.00                          |
| <b>Total Rebate Amount:</b> | <b>\$29,673.00</b>                   |

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 May 2019

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5396J****AAD1905-210***Not Authoised  
Repair By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 5396J**

JTDKB3FU303077006

TOYOTA

PRIUS

22.5.2019

**FCIL**

22/11/2018

**PART****LIST**

- |    |   |                                          |
|----|---|------------------------------------------|
| 1  | 1 | PANEL, FRONT DOOR, OUTER LH              |
| 2  | 1 | PANEL SUB-ASSY, FRONT DOOR, LH           |
| 3  | 1 | MOULDING ASSY, BODY ROCKER PANEL, LH     |
| 4  | 1 | PANEL SUB-ASSY, REAR DOOR, LH            |
| 5  | 1 | PANEL, REAR DOOR, OUTER LH               |
| 6  | 1 | REINFORCE SUB-ASSY, ROCKER, OUTER LH     |
| 7  | 1 | REINFORCEMENT SUB-ASSY, ROCKER PANEL, LH |
| 8  | 1 | BOARD SUB-ASSY, REAR DOOR TRIM, LH       |
| 9  | 1 | PANEL, QUARTER WHEEL HOUSE, OUTER LH     |
| 10 | 1 | REAR FENDER LH                           |
| 11 | 1 | REAR BUMPER SIDE LH                      |
| 12 | 1 | REAR FENDER LH                           |
| 13 | 1 | REAR BUMPER                              |
| 14 | 1 | REAR BUMPER SIDE RETAINER LH             |

|    |           |          |     |
|----|-----------|----------|-----|
| \$ | <i>n</i>  | 361.00   | X   |
| \$ | <i>n</i>  | 1,264.00 | X   |
| \$ | <i>sn</i> | 583.30   | X   |
| \$ | <i>n</i>  | 1,258.30 | ✓   |
| \$ | <i>sn</i> | 361.00   | } X |
| \$ | <i>n</i>  | 572.10   |     |
| \$ | <i>sn</i> | 336.60   |     |
| \$ | <i>sn</i> | 546.10   |     |
| \$ | <i>n</i>  | 290.50   |     |
| \$ | <i>n</i>  | 817.50   |     |
| \$ | <i>sn</i> | 232.00   |     |
| \$ | <i>n</i>  | 817.50   |     |
| \$ | <i>sn</i> | 458.60   |     |
| \$ | <i>sn</i> | 112.70   |     |

---

**\$ 8,011.20****25% \$ 2,002.80**

---

**\$ 6,008.40**

---

**Specical Nett**

- |   |   |                                |
|---|---|--------------------------------|
| 1 | 1 | REAR DOOR STICKER 'TRANS-CAB'  |
| 2 | 1 | FRONT DOOR STICKER '6555-3333' |
| 3 | 1 | REAR LEFT WHEEL RIM            |
| 4 | 1 | REAR LEFT WHEEL RIM COVER      |
| 5 | 1 | CLIP, REAR FENDER LINER        |

|    |           |          |             |
|----|-----------|----------|-------------|
| \$ | <i>n</i>  | 80.00    | <i>60sn</i> |
| \$ | <i>n</i>  | 80.00    | <i>60sn</i> |
| \$ | <i>sn</i> | 1,570.55 | X           |
| \$ | <i>sn</i> | 175.80   | X           |
| \$ | <i>n</i>  | 22.00    | X           |

**TOTAL \$ 1,928.35**

**Trans-cab Auto Services Pte Ltd**

AAD1905-210

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5396J

|                    |           |                 |
|--------------------|-----------|-----------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>7,936.75</b> |
|--------------------|-----------|-----------------|

**LABOUR**

|                                                                                                                                 |    |          |             |
|---------------------------------------------------------------------------------------------------------------------------------|----|----------|-------------|
| Putty And Spray Painting Of The Affected Portion.                                                                               | \$ | 3,000.00 | 660<br>4401 |
| Panel Beating, Knocking And Straightening The<br>Necessary Portion, Remove And Renewal Of Parts,<br>Adjust And Realign The Same | \$ | 3,000.00 | 3001        |
| To Rust-Proofing Of The Affected Areas.                                                                                         | \$ | 170.00   | 301         |
| To transfer of Rear Door fittings, attachments and<br>perform water seepage test.                                               | \$ | 170.00   | 601         |
| To transfer of Front Door fittings, attachments and<br>perform water seepage test.                                              | \$ | 170.00   | nn X        |
| To transfer of Rear Fender fittings, attachments and<br>perform water seepage test.                                             | \$ | 170.00   | nn X        |
| To check steering geometry and computer wheel<br>alignment                                                                      | \$ | 220.00   | nn X        |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>6,900.00</b> |
|--------------|-----------|-----------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>20,845.15</b> |
|-----------------------|-----------|------------------|

**(PART-BY-PART) Repair Days****10 DAYS****3 days**

14836.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                  |                                                                              |                             |                                                                                     |  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                     |                                                                              | Ref : CS/FCI19009524/Kqd3n2 |                                                                                     |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                              |                                                                              | Date : 03-06-2019           |  |  |
|                                                                                                                                                                                    |                                                                              | Code : FCI2                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                  |                                                                              |                             |                                                                                     |  |
| Insured Veh.                                                                                                                                                                       | SHA 1200H                                                                    | Veh. Inspected              | SHD 5396J                                                                           |  |
| Policy No.                                                                                                                                                                         |                                                                              | Coverage (\$)               | 0.00                                                                                |  |
| Claim No.                                                                                                                                                                          | D19003474MFSH                                                                | Excess (\$)                 | 0.00                                                                                |  |
| Assign From                                                                                                                                                                        | MAY CHUA                                                                     | Assign Date                 | 28/05/2019                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                      |                                                                              |                             |                                                                                     |  |
| Make & Model                                                                                                                                                                       | TOYOTA PRIUS (A)                                                             | c.c                         | 1798                                                                                |  |
| Engine No.                                                                                                                                                                         | HIDDEN                                                                       | Year of Reg.                | 2018                                                                                |  |
| Chassis No.                                                                                                                                                                        | JTDKB3FU303077006                                                            | Colour                      | M.P.WHITE / RED                                                                     |  |
| Odometer                                                                                                                                                                           | 50106                                                                        | Steering                    | IN ORDER                                                                            |  |
| Brakes                                                                                                                                                                             | IN ORDER                                                                     | Modification                | STANDARD ALLOY RIM                                                                  |  |
| General                                                                                                                                                                            | GOOD                                                                         |                             |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                      |                                                                              |                             |                                                                                     |  |
|                                                                                                                                                                                    | Size                                                                         | Make                        | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                                                                     | 195/65 R15                                                                   | GOODYEAR                    | 9 mm                                                                                |  |
| L/H Front Tyre                                                                                                                                                                     | 195/65 R15                                                                   | GOODYEAR                    | 9 mm                                                                                |  |
| R/H Rear Tyre                                                                                                                                                                      | 195/65 R15                                                                   | GOODYEAR                    | 6 mm                                                                                |  |
| L/H Rear Tyre                                                                                                                                                                      | 195/65 R15                                                                   | GOODYEAR                    | 6 mm                                                                                |  |
| <b>4. Description of Damages</b>                                                                                                                                                   |                                                                              |                             |                                                                                     |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                              |                             |                                                                                     |  |
| <b>5. General Information</b>                                                                                                                                                      |                                                                              |                             |                                                                                     |  |
| Accident Date                                                                                                                                                                      | 22/05/2019                                                                   | Inspection Date             | 29/05/2019                                                                          |  |
| Survey held at                                                                                                                                                                     | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                             |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                                                                 |                                                                              |                             |                                                                                     |  |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                             |                                                                                     |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                 |                                                                              |                             |                                                                                     |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                |                                                                              | <b>3 Working Days</b>       |                                                                                     |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5396J

| Qty                         | Description of Parts                              | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                   |                      |                           |                   |
| 1                           | PANEL,FRONT DOOR,OUTER LH                         | TO REPAIR SEE LABOUR | 361.00                    | -                 |
| 1                           | PANEL SUB-ASSY,FRONT DOOR,LH                      | TO REPAIR SEE LABOUR | 1,264.00                  | -                 |
| 1                           | MOULDING ASSY,BODY ROCKER PANEL,LH                | SERVICEABLE          | 583.30                    | -                 |
| 1                           | PANEL SUB-ASSY,REAR DOOR,LH                       | BENT                 | 1,258.30                  | 1,258.30          |
| 1                           | PANEL,REAR DOOR,OUTER LH                          | SERVICEABLE          | 361.00                    | -                 |
| 1                           | REINFORCE SUB-ASSY,ROCKER,OUTER LH                | TO REPAIR SEE LABOUR | 572.10                    | -                 |
| 1                           | REINFORCEMENT SUB-ASSY,ROCKER PANEL,LH            | SERVICEABLE          | 336.60                    | -                 |
| 1                           | BOARD SUB-ASSY,REAR DOOR TRIM,LH                  | SERVICEABLE          | 546.10                    | -                 |
| 1                           | PANEL,QUARTER WHEEL HOUSE,OUTER LH                | TO REPAIR SEE LABOUR | 290.50                    | -                 |
| 1                           | REAR FENDER LH                                    | TO REPAIR SEE LABOUR | 817.50                    | -                 |
| 1                           | REAR BUMPER SIDE LH                               | SERVICEABLE          | 232.00                    | -                 |
| 1                           | REAR FENDER LH                                    | TO REPAIR SEE LABOUR | 817.50                    | -                 |
| 1                           | REAR BUMPER                                       | SERVICEABLE          | 458.60                    | -                 |
| 1                           | REAR BUMPER SIDE RETAINER LH                      | SERVICEABLE          | 112.70                    | -                 |
|                             | LESS 25% DISCOUNT                                 |                      | -2,002.80                 | -314.57           |
|                             |                                                   |                      | 6,008.40                  | 943.73            |
| <b>SPECIAL NETT ITEMS</b>   |                                                   |                      |                           |                   |
| 1                           | REAR DOOR STICKER "TRANS-CAB" (SN)                | NECESSARY            | 80.00                     | 60.00             |
| 1                           | FRONT DOOR STICKER "6555-3333" (SN)               | NECESSARY            | 80.00                     | 60.00             |
| 1                           | REAR LEFT WHEEL RIM (SN)                          | SERVICEABLE          | 1,570.55                  | -                 |
| 1                           | REAR LEFT WHEEL RIM COVER (SN)                    | SERVICEABLE          | 175.80                    | -                 |
| 1                           | CLIP,REAR FENDER LINER (SN)                       | NOT NECESSARY        | 22.00                     | -                 |
|                             |                                                   |                      | 1,928.35                  | 120.00            |
| <b>LABOUR</b>               |                                                   |                      |                           |                   |
|                             | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. |                      | 3,000.00                  | 660.00            |

Report Ref No. CS/FCI19009524/Kqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                | Description of Parts                                                                                                                                                                                                                                                                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                    | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL,FRONT DOOR,OUTER LH,PANEL SUB-ASSY,FRONT DOOR,LH,REINFORCE SUB-ASSY,ROCKER,OUTER LH,PANEL,QUARTER WHEEL HOUSE,OUTER LH AND REAR FENDER LH. |               | 3,000.00                  | 300.00            |
|                                    | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                                                                                                                                            |               | 170.00                    | 30.00             |
|                                    | TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                      |               | 170.00                    | 60.00             |
|                                    | TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                     | NOT NECESSARY | 170.00                    | -                 |
|                                    | TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                                                                                                                                                                                                    | NOT NECESSARY | 170.00                    | -                 |
|                                    | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                                                                                                                                                                                                                                           | NOT NECESSARY | 220.00                    | -                 |
|                                    |                                                                                                                                                                                                                                                                                                    |               | 6,900.00                  | 1,050.00          |
|                                    | <b>GRAND TOTAL</b>                                                                                                                                                                                                                                                                                 |               | <b>14,836.75</b>          | <b>2,113.73</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                                                                                                                                                                                                                                                                                    |               |                           | <b>2,113.73</b>   |

Report Ref No. CS/FCI19009524/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.