

ASS. REC. BY:

REF:

CS/INC/9009527/A+d3b

Special Instruction:

Signature: ArhamASSIGNMENT (Office)

From (Person):

Cynthia Ang

of

INC

Date/Time:

22/5/19 @ 10:01am

Estimated Cost:

Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLL 8811T

Insured:

FR 8369T

at Workshop m/s

96 Motorsports

Tel:

63852138

of

62/64 Kaki Bukit Ave 6

Policy No:

Claim No:

MT/1046202-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9/19am @ 22/5/19

Person Contacted:

JudeVehicle IN/OUT

Date/Time

Action/Instruction

Estimate /SLL 8811T-XFR 8369T-X

4/9-

Confirm lump sum \$19200/- (Red: 8828.60; 31%)

REF: INC

## ASSIGNMENT

From:

Date:

29/5/19

Veh No:

SL8811T

at Regn:

2017, Jan.

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SL8811T

Make:

Honda Vezel

G.C.

1496

at Workshop n/s

96 Motorsports

Colour:

silver

A/C:

Insured / Std / NI / NA

of

62/64 Kaki Bukit Ave 6

Sp Reading

158943

T/Radio:

Insured / Std / NI / NA

Insured:

Eng No:

Policy No.

C/No:

211204299

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Normal / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Normal / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

days

Res.:

Yes or No

D.O.A.

D.O.I.

29/05/19 1237pm

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

96 Motorsport

CA / REV / REP. / 24 HRS <sup>1up</sup>Des. of Damages: ☒ Fr / Rear / O/S / N/S / ☒ U/C / ☒ Roodtop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP INC

MV: 73K

SV: 45.5K

Net: 27.5K

Date/Time, File Pass to?

1) 9/19 Typist

☐

Prel. Report

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

15

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

3 x RS. 24

Honor:

Other:

Total:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format:

TP

Lump

0

192001

290

290

## Denise Tay (LKKAuto)

---

**From:** estimator@96motorsports.com  
**Sent:** Wednesday, 4 September 2019 3:07 PM  
**To:** Denise Tay (LKKAuto); claims@96motorsports.com  
**Cc:** claims@96motorsports.com  
**Subject:** RE: FINALIZATION

Dear Denise,

We confirmed. Thanks!

*Best Regards,*

**BRYAN TENG**

Estimator

**96 MOTORSports**

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : [Claims@96motorsports.com](mailto:Claims@96motorsports.com)

Website: [www.96motorsports.com](http://www.96motorsports.com)

---

**From:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Sent:** Wednesday, 4 September, 2019 11:58 AM  
**To:** claims@96motorsports.com; estimator@96motorsports.com  
**Subject:** RE: FINALIZATION

Hi Royce,

Thank you, help me see the confirm for SLL 8811T.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** [claims@96motorsports.com](mailto:claims@96motorsports.com) <[claims@96motorsports.com](mailto:claims@96motorsports.com)>  
**Sent:** Wednesday, 4 September 2019 11:56 AM  
**To:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>; estimator@96motorsports.com  
**Subject:** RE: FINALIZATION

Dear Denise,

Please refer to the attached

## **Nivitha (LKK Auto)**

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 28 May 2019 10:01 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Thio Tse Kiat; Clarence Richard Anthony; Cynthia Ang  
**Subject:** TP CASES FARMED OUT TO LKK ON 28/05/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Clarence's instruction :-

| SN | OIC             | Claim No.      | Vehicle  | WorkShop Name                | WorkShop Address                                        | WorkShop Contact                | Survey Time | OI VEH   | DOA        | Additional Remarks |
|----|-----------------|----------------|----------|------------------------------|---------------------------------------------------------|---------------------------------|-------------|----------|------------|--------------------|
| 1  | Muhammad Airwan | MT/1046202-001 | SLL8811T | 96<br>MOTORSports<br>PTE LTD | 62/64<br>KAKI<br>BUKIT<br>AVENUE 6                      | Royce<br>Phua /<br>6702<br>6996 |             | FR8369T  | 25/05/2019 |                    |
| 2  | Charlotte Chew  | MT/1046273-001 | GY3077U  | 96<br>MOTORSports<br>PTE LTD | 62/64<br>KAKI<br>BUKIT<br>AVENUE 6                      | Jade Lim /<br>6702<br>6996      |             | SLJ1413R | 26/05/2019 |                    |
| 3  | Charlotte Chew  | MT/1041518-002 | FBF9597E | F T FASTTRACK                | 25 KAKI<br>BUKIT<br>ROAD 4<br>#01-77<br>SYNERGY<br>@ KB | FREDDIE<br>TAN /<br>67491002    |             | SKW1915C | 23/04/2019 |                    |

**Please contact workshops.**

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang  
Admin Assistant  
Motor Insurance  
T +65 6430 7900  
[www.income.com.sg](http://www.income.com.sg)

**income**  
more different



**in** with  
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
**Find out more at [income.com.sg/careers](http://income.com.sg/careers)**

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| ACCIDENT STATEMENT                                                           |                                        |
|------------------------------------------------------------------------------|----------------------------------------|
| Date Of Report                                                               | 27/05/2019 11:33                       |
| Date Of Accident                                                             | 25/05/2019 08:35                       |
| Exact Location Of Accident                                                   | SIMEI AVENUE / XILIN AVENUE            |
| Country/State of Loss                                                        | SINGAPORE                              |
| DETAILS OF OWN VEHICLE                                                       |                                        |
| Vehicle Registration Number                                                  | SLL8811T                               |
| Insured/Policyholder                                                         |                                        |
| Name Of Registered Owner                                                     | NASHA SERVICES                         |
| Co Reg No                                                                    | 53364990X                              |
| Email Address                                                                | NOEMAIL                                |
| Mobile Phone No                                                              |                                        |
| Alternative Phone No                                                         | OFFICE-86858811                        |
| Vehicle Particulars                                                          |                                        |
| Manufacturer                                                                 | HONDA                                  |
| Model                                                                        | VEZEL 1.5X CVT                         |
| Exact Purpose for which vehicle was being used at time of accident           |                                        |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                                     |
| If No, Please state action to be taken                                       | THIRD PARTY                            |
| Vehicle Category                                                             | PRIVATE HIRE                           |
| Insurance Company                                                            |                                        |
| Name of Insurance Company                                                    | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage                                                             | COMPREHENSIVE                          |
| Fleet Policy                                                                 | NO                                     |
| Policy Number                                                                | 5092568632-01 CLASSIC                  |
| Cover Note Number                                                            |                                        |
| Driver                                                                       |                                        |
| Name of Driver                                                               | TANG SOK YEE (DENG SHUYI)              |
| NRIC No                                                                      | S7442188A                              |
| Date Of Birth                                                                | 30/12/1974                             |
| Occupation                                                                   | OUTDOOR                                |
| Date Of Driving Pass                                                         | 09/03/1993                             |
| Driving Experience                                                           | 26 YEARS AND 2 MONTHS                  |
| Gender                                                                       | FEMALE                                 |
| Mobile Number                                                                | (LOCAL) +65-86858811                   |
| Fax Number                                                                   |                                        |
| Contact Number                                                               |                                        |
| EMail Address                                                                | NOEMAIL                                |

|                                                     |                                    |
|-----------------------------------------------------|------------------------------------|
| Address                                             | BLK 460 #08-310 TAMPINES STREET 42 |
| Postcode                                            | 520460                             |
| Was driver an employee of the Insured's Company     | NO                                 |
| If No, Relationship of the Driver with the Insured  | OTHER - SOLE PROPRIETOR            |
| Vehicle Registration Number of Driver's Own Vehicle | -                                  |
|                                                     | -                                  |
|                                                     | -                                  |
| Insurance Company of Driver's Own Vehicle           | -                                  |
|                                                     | -                                  |
|                                                     | -                                  |

#### General Information of the Accident

|                    |            |
|--------------------|------------|
| Type Of Accident   | SIDE SWIPE |
| Weather Conditions | CLEAR      |
| Road Surface       | DRY        |

#### Other Information

|                                                                                             |                                     |
|---------------------------------------------------------------------------------------------|-------------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                                  |
| Number of vehicles (including own vehicle) involved in the accident                         | 3                                   |
| Was any body injured in the Accident?                                                       | YES                                 |
| Was any injured conveyed to hospital by ambulance?                                          | YES                                 |
| Was any other material or property damaged?                                                 | YES                                 |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                  |
| Number of Passengers (Including Driver)                                                     | 2                                   |
| Passenger 1                                                                                 | NAME: : YE YINZHI<br>GENDER: : MALE |

#### Details of Police Action

|                                           |                                                                                    |
|-------------------------------------------|------------------------------------------------------------------------------------|
| Was the accident reported to the police?  | YES                                                                                |
| If Yes, Please state which Police Station |                                                                                    |
| Police Station Name                       | TAMPINES NORTH NEIGHBOURHOOD POLICE POST                                           |
| Police Station Address                    | ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 ,<br>COUNTRY: SINGAPORE |
| Police Station Contact                    | TEL NO: 1800-7818999 - FAX NO: 67838603                                            |
| Was notice of intended Prosecution given? | NO                                                                                 |
| If Yes, against whom?                     |                                                                                    |

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

#### Attachment(s)

|                                               |             |
|-----------------------------------------------|-------------|
| Are accident photos available for attachment? | YES         |
| Was there any video captured by Car Camera?   | YES         |
| Remarks/ Reasons:                             | WITH DRIVER |
| Was there any audio recorded?                 | NO          |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                     |
|-----------------------------|---------------------|
| Vehicle Registration Number | FR8369T             |
| Vehicle Make/Model/Colour   | YAMAHA XABRE TFX150 |
| Details Of Properties       |                     |
| Vehicle Category            | MOTORCYCLE          |
| Name of Driver              |                     |
| NRIC/Passport Number        |                     |
| Contact Number              |                     |

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJT1841J  
Vehicle Make/Model/Colour MAZDA3 1.6L SDN  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver FRANSTER  
NRIC/Passport Number  
Contact Number 91712212  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name TANG SOK YEE (DENG SHUYI)  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLL8811T  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name RIDER  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? FR8369T  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 3

Name PILLION  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? FR8369T  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance? YES  
Address  
Postcode

#### DETAILS OF INJURED PERSON 4

Name YE YINZHI (PASSENGER)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLL8811T

Were seat belts worn?

Was this injured conveyed to hospital by  
ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time **27 MAY 2019**

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: [vackbi@singnet.com.sg](mailto:vackbi@singnet.com.sg)  
Name:  
NRIC/FIN No.:

SKETCH PLAN Upper Changi Rd East - Xilin Ave - SIMEL AVE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per Police Report No: T/20190525/2088

DECLARATION

I/We declare that foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

27 MAY 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: yackb@singnet.com.sg

Name:

NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190525/2086

1 of 4

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-58 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No. T/20190525/2086

## REPORT OF A TRAFFIC ACCIDENT

|                                                                        |            |                                        |                              |                            |  |
|------------------------------------------------------------------------|------------|----------------------------------------|------------------------------|----------------------------|--|
| Date/Time Report Made:<br>25/05/2019 13:27                             |            | Vide Report No.:<br>G/20190525/0088    |                              | Station Diary No.:<br>15   |  |
| Name of Informant:<br>TANG SOK YEE                                     |            |                                        |                              |                            |  |
| Address:<br>APT BLK 460 TAMPINES STREET 42 #08-310 SINGAPORE<br>520460 |            |                                        |                              |                            |  |
| ID Type / ID No.:<br>NRIC NO / S7442186A                               |            | Contact No.:<br>Home/Office:           |                              | Mobile: 86858811 /         |  |
| Nationality:<br>SINGAPORE CITIZEN                                      |            | Email:                                 |                              |                            |  |
| Sex:<br>Female                                                         | Age:<br>44 | Date of Birth:<br>30/12/1974           | Type of Informant:<br>Driver |                            |  |
| Race:<br>Chinese                                                       |            | Language:                              |                              | Institution / School Name: |  |
| Occupation:<br>GRAB DRIVER                                             |            | Driving Licence Information:<br>Class: |                              | Date of Expiry:            |  |

|                                                                                                                                                       |                           |                                             |                                            |                                      |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|---------------------------------------------|--------------------------------------------|--------------------------------------|
| General Information of the Accident                                                                                                                   |                           |                                             |                                            |                                      |
| Type of Accident:                                                                                                                                     | Injury Attended by Police | Drink Drive:<br>No                          | Date/Time of Accident:<br>25/05/2019 08:35 | Type of Location:<br>X-Junction      |
| Location:<br>Along Road 1 Traveling Toward Road 2<br>SIMEI AVENUE<br>XILIN AVENUE<br>JUNCTION OF SIMEI AVENUE & XILIN AVENUE & UPPER CHANGI ROAD EAST |                           |                                             |                                            |                                      |
| Weather:<br>Clear                                                                                                                                     |                           | Road Surface:<br>Dry                        |                                            | Road Speed Limit:                    |
| Traffic Flow:<br>Dual Carriage Way                                                                                                                    |                           | Traffic Control:<br>Traffic Light - Working |                                            | Traffic Volume:<br>Moderate          |
| Type of Collision:<br>Between Moving Vehicles - Head To Side                                                                                          |                           |                                             |                                            | Anyone conveyed by ambulance:<br>Yes |

| Vehicle No. | Vehicle Type | Damage            | Count |
|-------------|--------------|-------------------|-------|
| FR8369T     | Motorcycle   | Slightly Damaged  | 1     |
| SJT1841J    | Car          | Seriously Damaged | 3     |
| SLL8811T    | Car          | Seriously Damaged | 1     |



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Tampines North NPP  
481 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999



T/20190525/2086

2 of 4

Report No. T/20190525/2086

**CONTINUATION OF REPORT**

|                                   |                                   |                                        |                                   |
|-----------------------------------|-----------------------------------|----------------------------------------|-----------------------------------|
| Any Pedestrian Involved: No       |                                   |                                        |                                   |
| No. of Pedestrians Injured: NIL   |                                   | Use of Pedestrian Crossing: NA         |                                   |
| Name                              | TANG SOK YEE                      | ID No.                                 | S7442188A                         |
| Related Vehicle                   | SLL8811T (Car)                    | Contact No.                            | 86856811                          |
| Hospital/Clinic                   | W Y TEH FAMILY CLINIC AND SURGERY | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | 25/05/2019                        | Date Discharge                         | 25/05/2019                        |
| No. of Days granted Medical Leave | 04                                | Degree of Injury                       | Slight                            |

**Brief Details.**

Traffic police attended to our incident as a passerby had called them and they gave me the report number G/20190525/0068. They advised me to lodge a police report. They have also seized the recording of my in-vehicle recording.

I am a Grab Driver.

On 25/05/2019, I was driving my vehicle (V1: SLL8811T) with one Grab passenger namely Yinzhi (HP: 97572575). At around 8:25am, I picked up the passenger at location B/299A Tampines Street 22 with destination to 6 Changi South Street 2.

At about 8:39am, I was driving along at junction of Simei Avenue towards Xilin Avenue I saw that the traffic light was green and continued to drive, as I drove by the junction, a motorcycle (V2: FR8369T) riding from the opposite direction from Xilin Avenue turned towards Upper Changi Rd East. This caused my V1 to crash into V2. Due to the crash, the vehicle (V3: SJT1841J) that was driving behind me swerved to the left and hit the traffic light between Upper Changi Rd East and Xilin Avenue to avoid the accident.

V2 had a male rider with one female pillion, both of them were conveyed by ambulance at scene. V3 driver was namely Franster (HP: 91712212) with three passengers Nor Hafizah (HP: +65 85755539) and Suhaimi (+60 18654669 / + 60122616946) and one child. V3's passengers informed me that they too saw that the traffic light was green and V1 and V3 had the right of way.

The damages to my V1 was the front-right bonnet was seriously dented in and windscreen cracked, both the airbags inflated and right tyres deflated. The car has since been towed away to a workshop. V3 was seriously damaged however V2 was slightly damaged, I am unsure to what extent was their damages.

After the accident, I felt stiffness at my back and shoulders, bruises at my hip and left arm and pain at my right ankle. I visited the doctor for a medical check-up and received 4 days MC. The doctor at the clinic informed me to go to A&E should the pain not subside.



**SINGAPORE  
POLICE FORCE**



T/20190525/2086

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-58 SINGAPORE  
520461  
Tel No: 1800-7818999

3 of 4

Report No. T/20190525/2086

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20190525/2006

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

4 of 4  
Report No. T/20190525/2006

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /  
Sgt 2 NURUL DIANA BINTE MOHAMAD  
ROBLAN

Signature Of Informant:

*[Signature]*

Signature Of Interpreter:

Not applicable

Date/Time:

25/05/2019 13:27

Officer In Charge Of Case:

TP / GRT /  
Sgt 3 BASHIDAH BINTE AZMAN  
Contact No: 65476216

Classification Of Case:

Authentication Stamp  
NP108



**SINGAPORE  
POLICE FORCE**

*[Signature]*  
SIGNATURE

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Business                             |
| Owner ID:                     | 4990X                                |
| Vehicle Details               |                                      |
| Vehicle No.:                  | 5LL8811T                             |
| Vehicle to be Exported:       | Yes                                  |
| Intended Deregistration Date: | 29 May 2019                          |
| Vehicle Make:                 | HONDA                                |
| Vehicle Model:                | VEZEL 1.5X CVT                       |
| Primary Colour:               | Silver                               |
| Manufacturing Year:           | 2016                                 |
| Engine No.:                   | L15B4404300                          |
| Chassis No.:                  | RU11204299                           |
| Maximum Power Output:         | 96.0 kW (128 bhp)                    |
| Open Market Value:            | \$21,314.00                          |
| Original Registration Date:   | 18 Jan 2017                          |
| First Registration Date:      | 18 Jan 2017                          |
| Transfer Count:               | 1                                    |
| Actual ARF Paid:              | \$11,840.00                          |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 17 Jan 2027                          |
| PARF Rebate Amount:           | \$8,880.00                           |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 17 Jan 2027                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$48,000.00                          |
| COE Rebate Amount:            | \$36,645.00                          |
| Total Rebate Amount:          | \$45,525.00                          |

The information contained herein is correct as at 29 May 2019

OK

500+ dealers competed to buy my car!

• Sell ur Car for More Cash  
 • Highest Price or Get \$100 Free  
 • Get Paid Now, Handover Later

SELL YOUR CAR

**FOR SALE BY OWNER**

**Post an Advertisement**  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad
 Advertiser Login
 Ways of Selling

**Volvo S60 T4.**

1 Owner Car. Service And Repair Record Are Kept In A File.  
 (Direct Owner - StarAd)

**KA-HUP**

**VALUE FOR MONEY**  
**VALUE FOR TIME**  
**A PEACE OF MIND**

**HOTLINE: 6741 9997** [VIEW OUR CARS](#)

Browse by Category 
 Save Search
 Print
 « Back ( 1 2 ) Next »
 Sort by Date Posted 
 20 results/page

28 vehicles **Search**  Advanced Search Search [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection: **vezel** | Any | Any | 2017 | Any | Any | Any | Available

☐ **Honda Vezel 1.5A S** | \$75,800 | \$8,900 /yr | 01-Jan-2017 | 1,496 cc | 24,899 km | SUV | Available

Low Interest Rate From 1.99%! In-house Loan Available! Full Accessories Equipped! Like Brand New! An Economical, Stylish And Powerful SUV That Would Appeal To Both Urbanites And Rugged Prospects. Buy ...

Dickson Automobile

Posted: 17-May-2019 | Tags: 2017 Honda Vezel, 2017 Honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

☐ **Honda Vezel 1.5A X** | \$71,800 | \$8,630 /yr | 06-Jan-2017 | 1,496 cc | 55,000 km | SUV | Available

Posted: 24-May-2019 | Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

☐ **Honda Vezel Hybrid 1.5A RS Honda Sensing** | \$85,000 | \$10,820 /yr | 10-Jan-2017 | 1,496 cc | 47,002 km | SUV | Available

**Fuel Type:** Petrol-Electric

Sheltered Car Park Everyday, Only Hand Wash By Owner And No One Else. Car Exterior Shiny Even Without Wax Or Clear Coat Because I Use Sonax Products For Washing. Average Petrol Consumption = 16.6km/...

**DIRECT OWNER**

Posted: 23-Apr-2019 | Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

☐ **Honda Vezel Hybrid 1.5A X** | \$80,000 | \$10,130 /yr | 20-Jan-2017 | 1,496 cc | 64,153 km | SUV | Available

**Fuel Type:** Petrol-Electric

1 Owner Only! Low Mileage Done! Not A Private Hirer Unit, Very Well Kept In Rare Condition, View And Believe. Buy It From Us With A Peace Of Mind, Discover The Greatness Of This Car. Consignment Unit!...

**CONSIGNMENT**

Prem Roy Motoring

Posted: 26-May-2019 | Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Car Buying
 Car Selling
 Car Ownership
 Car Aftermarket
 On The Move
 Lifestyle

**TYREPAC**

Buy 1 and 2nd car  
 Buy Tyres Online  
 Latest Special Offers from Tyrepac!

☐ **Honda Vezel 1.5A X** | \$71,500 | \$8,660 /yr | 25-Jan-2017 | 1,496 cc | - | SUV | Available

Elegant Silver SUV, One Owner Only, Low Maintenance Cost, Comes With Warranty, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 24-May-2019 | Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

☐ **Honda Vezel Hybrid 1.5A X Honda Sensing** | \$83,800 | \$10,610 /yr | 26-Jan-2017 | 1,496 cc | 53,800 km | SUV | Available

**Fuel Type:** Petrol-Electric

Most Popular SUV With Honda Sensing, \$2000 Republic Auto Workshop Credits. Enjoy Exclusive Interest Rates At 2.48%, Please Call/SMS/Whatsapp Now For Enquiries And Viewing Appointment.

Republic Auto

Posted: 25-Apr-2019 | Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

☐ **Honda Vezel 1.5A X** | \$75,800 | \$8,940 /yr | 02-Feb-2017 | 1,496 cc | - | SUV | Available

Balloon Scheme Available! We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Costs! Car In Original Condition! Low Mileage! Accident Free! In House Loan Or Bank Loan Available! No Need Gu...

**Compare**

**88 Motor Trading**

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$77,800****\$9,300 /yr****03-Feb-2017****1,496 cc****-****SUV****Available**

Full Loan Available At \$1.1k+/ Month We Can Help To Conver To Z10 Usage If Needed. In House Loan / Bank Loan Available! Balloon Scheme Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMar...

88 Motor Trading

★ Posted: 26-May-2019 Tags: 2017 honda vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$74,888****\$9,010 /yr****10-Feb-2017****1,496 cc****25,000 km****SUV****Available**

100% Loan Available, We Are Full Loan Specialist, 1 Owner, Accident Free Unit, Act Now To Test Drive Now!

Taxis

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$83,800****\$10,480 /yr****28-Feb-2017****1,496 cc****19,000 km****SUV****Available****Fuel Type:** Petrol-Electric

Hot Selling! Only 1 Owner Non Private Hire Vezel Hybrid With Low Mileage Clocked, Signature Chameleon Blue Colour, 18" Advant! S/Rims, Sporty Mugen Exhaust & Mugen Bodykit! Light Touch Boot Lights Mak...

Creative Auto

★ Posted: 16-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Sell your Car for \$3,000 More**

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3,000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!

**Honda Vezel 1.5A X Honda Sensing****\$73,800****\$8,740 /yr****03-Mar-2017****1,496 cc****30,000 km****SUV****Available**

"One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, ST...

Carway

★ Posted: 27-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$82,800****\$10,320 /yr****10-Mar-2017****1,496 cc****4,900 km****SUV****Available****Fuel Type:** Petrol-Electric

3 Years On 100000Km Warranty, High Trade In.

Prime Motor &amp; Leasing

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$77,888****\$9,090 /yr****16-Mar-2017****1,496 cc****37,000 km****SUV****Available**

Low Mileage, \$3k Worth Of Upgraded Audio System To Go With The Car. Still Under Warranty. Road Tax Renewed. High Loans Up To 80% Of The Car Price With Lowest Interest Rates From 2.28%. Trade In Welcom...

★ Posted: 25-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$76,800****\$8,930 /yr****28-Mar-2017****1,496 cc****36,271 km****SUV****Available**

Elegant Red SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available. Call Our Sales Rep For A Test Drive Now Before It's Sold!

★ Posted: 25-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$72,500****\$8,560 /yr****31-Mar-2017****1,496 cc****-****SUV****Available**

Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor &amp; Leasing

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A RS****\$89,600****\$11,080 /yr****07-Apr-2017****1,496 cc****49,000 km****SUV****Available****Fuel Type:** Petrol-Electric

100% Accident Free. 5 Years Warranty With Optima Works. Tuned By Honda Hybrid Specialist. Full Car Sound Proof Worth \$3000. Pioneer 5850. Original Leather Seats With Alcantara Fixtures, V-Kool Solar F...

Monster Motors Pte Ltd

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel 1.5A X****\$73,000****\$8,590 /yr****12-Apr-2017****1,496 cc****-****SUV****Available**

Elegant White SUV, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor &amp; Leasing

★ Posted: 24-May-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

SHOULD BE USED HISTORY

Compare

TPINC  
Daise.

| ATTN: |                                                               |                 |             |                |  |
|-------|---------------------------------------------------------------|-----------------|-------------|----------------|--|
| NO.   | DESCRIPTION - PARTS                                           | QTY             | PRICE       | ADJUSTED PRICE |  |
| 1     | BONNET <i>Distorted</i>                                       | 1               | \$ 965.40   | ✓ 965.40       |  |
| 2     | BONNET SIDE RUBBER L+R <i>RH cut</i>                          | <del>1SET</del> | \$ 50.00    | 25 25          |  |
| 3     | BONNET CENTER RUBBER <i>cut</i>                               | 2               | \$ 50.00    | ✓ 50           |  |
| 4     | BONNET INNER LOCK <i>damaged</i>                              | 1               | \$ 97.50    | ✓ 97.50        |  |
| 5     | BONNET LOCK CABLE <i>new</i>                                  | 1               | \$ 52.00    | x              |  |
| 6     | BONNET INSULATOR <i>crumpled</i>                              | 1               | \$ 142.30   | ✓ 142.30       |  |
| 7     | BONNET INSULATOR CLIP <i>new</i>                              | 1SET            | \$ 40.00    | ✓ 40           |  |
| 8     | BONNET HINGE <i>best</i>                                      | 2               | \$ 148.00   | ✓ 148          |  |
| 9     | BONNET STOPPER L+R <i>new</i>                                 | 2               | \$ 40.00    | +              |  |
| 10    | FRONT GRILLE <i>crushed</i>                                   | 1               | \$ 396.50   | ✓ 396.50       |  |
| 11    | FRONT GRILLE OUTER GARNISH <i>crushed</i>                     | 1               | \$ 395.40   | ✓ 395.40       |  |
| 12    | FRONT GRILLE OUTER GARNISH CHROME MOULDING L+R <i>crushed</i> | 2               | \$ 172.80   | ✓ 172.80       |  |
| 13    | FRONT GRILLE BADGE <i>new</i>                                 | 1               | \$ 55.00    | ✓ 55           |  |
| 14    | FRONT GRILLE TOP BRACKET <i>crushed</i>                       | 1               | \$ 58.00    | ✓ 58           |  |
| 15    | FRONT GRILLE CLIP <i>new</i>                                  | 1SET            | \$ 30.00    | ✓ 30           |  |
| 16    | FRONT BUMPER <i>Distorted</i>                                 | 1               | \$ 987.50   | 880 880        |  |
| 17    | FRONT BUMPER SIDE RETAINER L+R <i>new</i>                     | 2               | \$ 120.00   | ✓ 120          |  |
| 18    | FRONT BUMPER CLIP <i>new</i>                                  | 1SET            | \$ 50.00    | 30 30          |  |
| 19    | FRONT BUMPER FOG LAMP L+R <i>RH smashed</i>                   | 2               | \$ 734.00   | 367 367        |  |
| 20    | FRONT BUMPER FOG LAMP COVER L+R <i>RH Distorted</i>           | 2               | \$ 317.20   | 108.60         |  |
| 21    | FRONT BUMPER FOG LAMP COVER LED LIGHT L+R <i>new</i>          | 2               | \$ 200.00   | +              |  |
| 22    | FRONT BUMPER LOWER SKIRT <i>missing</i>                       | 1               | \$ 396.10   | ✓ 396.10       |  |
| 23    | FRONT BUMPER LOWER SKIRT CHROMR MOULDING <i>new</i>           | 1               | \$ 230.00   | x              |  |
| 24    | FRONT BUMPER UNDER COVER <i>Distorted</i>                     | 1               | \$ 171.30   | ✓ 171.30       |  |
| 25    | FRONT BUMPER UNDER COVER CLIP <i>new</i>                      | 1SET            | \$ 30.00    | ✓ 30           |  |
| 26    | HEAD LAMP L+R <i>RH crushed RH RH new</i>                     | 2               | \$ 2,300.40 | 1150.20        |  |
| 27    | HEAD LAMP BOTTOM RETAINER L+R <i>RH smashed</i>               | 2               | \$ 84.00    | 42             |  |
| 28    | HEAD LAMP SIDE BRACKET L+R <i>new</i>                         | 2               | \$ 50.00    | x              |  |
| 29    | HEAD LAMP CLIP <i>new</i>                                     | 1SET            | \$ 40.00    | ✓ 40           |  |
| 30    | FRONT FENDER L+R <i>Distorted</i>                             | 2               | \$ 1,260.00 | ✓ 1260         |  |
| 31    | FRONT FENDER ARCH PROTECTOR L+R <i>RH Distorted</i>           | 2               | \$ 474.50   | 237.30         |  |
| 32    | FRONT FENDER ARCH PROTECTOR CLIP <i>new</i>                   | 1SET            | \$ 30.00    | 15             |  |

|    |                                   |                               |      |    |           |               |
|----|-----------------------------------|-------------------------------|------|----|-----------|---------------|
| 33 | FRONT FENDER INNER SHIELD L+R     | RH Missing                    | 2    | \$ | 386.40    | 193.20        |
| 34 | FRONT FENDER INNER SHIELD CLIP    | new                           | 1SET | \$ | 30.00     | 15            |
| 35 | SUPPORT PANEL                     | Distorted                     | 1    | \$ | 674.50    | ✓ 674.50      |
| 36 | SUPPORT PANEL TOP GARNISH         | Distorted                     | 1    | \$ | 95.20     | ✓ 95.20       |
| 37 | SUPPORT PANEL TOP GARNISH CLIP    | new                           | 1SET | \$ | 20.00     | ✓ 20          |
| 38 | BRACE PANEL                       | new                           | 1    | \$ | -         | x             |
| 39 | HORH L+R                          | new                           | 2    | \$ | 120.00    | +             |
| 40 | AIR CON CONDENSER                 | Dented                        | 1    | \$ | 890.00    | ✓ 890         |
| 41 | CONDENSER SIDE GARNISH L+R        | RH Distorted                  | 2    | \$ | 90.00     | 45 45         |
| 42 | CONDENSER AIR CON PIPE            | new                           | 1    | \$ | 195.20    | +             |
| 43 | CONDENSER SUCTION PIPE            | Bent                          | 1    | \$ | 185.40    | ✓ 185.40      |
| 44 | CONDENSER DISCHARGE PIPE          | new                           | 1    | \$ | 210.70    | + 210.70      |
| 45 | CONDENSER FAN COWLING             | cracked                       | 1    | \$ | 98.40     | ✓ 98.40       |
| 46 | CONDENSER FAN MOTOR               | new                           | 1    | \$ | 328.20    | x 328.20      |
| 47 | CONDENSER FAN BLADE               | new                           | 1    | \$ | 68.20     | x 68.20       |
| 48 | RADIATOR                          | Distorted                     | 1    | \$ | 1,250.60  | ✓ 1250.60     |
| 49 | RADIATOR TOP MOUNTING L+R         | 3 pieces                      | 2    | \$ | 70.00     | ✓ 70          |
| 50 | RADIATOR TOP MOUNTING BRACKET L+R |                               | 2    | \$ | 80.00     | ✓ 80          |
| 51 | RADIATOR FAN COWLING              | cracked                       | 1    | \$ | 135.40    | ✓ 135.40      |
| 52 | RADIATOR FAN MOTOR                | new                           | 1    | \$ | 298.40    | x 298.40      |
| 53 | RADIATOR FAN BLADE                | new                           | 1    | \$ | 57.70     | x 57.70       |
| 54 | RESONATOR BOX AIR DUCT            | new                           | 1    | \$ | 245.60    | x 245.60      |
| 55 | WIPER TANK                        | Distorted                     | 1    | \$ | 97.20     | ✓ 97.20       |
| 56 | WIPER TANK MOTOR                  | cracked                       | 1    | \$ | 69.00     | ✓ 69          |
| 57 | BATTERY BOTTOM TRAY               | new                           | 1    | \$ | 28.20     | x             |
| 58 | BATTERY TOP BRACKET               | new                           | 1    | \$ | 26.40     | x             |
| 59 | AIR BAG IMPACT SENSOR L+R         | 2                             | 2    | \$ | 620.00    | ✓ 620         |
| 60 | FRONT STEERING AIR BAG            | Activated                     | 1    | \$ | 1,605.40  | ✓ 1605.40     |
| 61 | FRONT PASSENGER AIR BAG           |                               | 1    | \$ | 2,236.40  | ✓ 2236.40     |
| 62 | DASH BOARD                        | new                           | 1    | \$ | 920.60    | ✓ 920.60      |
| 63 | FRONT SEAT BELT L+R               | Activated                     | 2    | \$ | 1,162.80  | ✓ 1162.80     |
| 64 | FRONT SEAT BELT BUCKER L+R        | new                           | 2    | \$ | 640.00    | +             |
| 65 | SRS AIR BAG CONTROL UNIT          | Activated                     | 1    | \$ | 980.40    | ✓ 980.40      |
|    | Roof Top panel.                   | (+) Strg Air bag wire.        |      |    |           |               |
|    | Front w/s glass                   | (+) Passenger Air bag wire.   |      |    |           | 18867.90      |
|    | Front w/s glass mld.              | (+) Frt Side mirror glass RH. |      |    |           | 15094.32      |
|    | Frt door RH                       | (+) Frt door pillar RH        |      |    |           |               |
|    | Frt door lock RH                  | (+) Frt fender inner panel RH |      |    |           |               |
|    | Frt door hinge RH.                | (+) Engine mtg RH.            |      |    |           |               |
|    | Frt Absorber RH                   | (+) Frt bumper reinforcement  |      |    |           |               |
|    | Frt Knuckle RH                    |                               |      |    |           |               |
|    |                                   | SUBTOTAL                      |      | \$ | 13,560.20 | \$ 24664.30 - |
|    | Frt Knuckle bearing RH            | 20%                           |      | \$ | 2,712.04  | \$ -          |
|    | Frt lower arm RH.                 | PARTS TOTAL                   |      | \$ | 10,848.16 | \$ 19267.04 - |

| SPECIAL NETT |                                                         | QTY              | PRICE                    | PRICE        |
|--------------|---------------------------------------------------------|------------------|--------------------------|--------------|
| 1            | FRONT NUMBER PLATE WITH COVER <i>Done</i>               | 1                | \$ 120.00                | ✓ 60         |
| 2            | RADIATOR COOLANT <i>den</i>                             | 1                | \$ 100.00                | 40.          |
| 3            | BATTERY <i>den</i>                                      | 1                | \$ 200.00                | X            |
| 4            | SIDE SKIRT ( VEZEL ) RH <i>on Ld.</i>                   | 1                | \$ 400.00                | ✓            |
| 5            | FRONT MUD FLIP L+R <i>RH missing</i>                    | 2                | <del>450</del> \$ 380.00 | 65.          |
|              | <i>Front w/s glass Decalant</i>                         |                  |                          | 565          |
|              | <i>Front w/s glass tinted film</i>                      |                  |                          |              |
|              | <i>Front w/s glass ERP bracket</i>                      |                  |                          |              |
|              |                                                         | SPECIAL NETT 1   | \$ 1,200.00              | \$ -         |
| LABOUR       |                                                         | QTY              | PRICE                    | PRICE        |
| 1            | TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA | 1                | \$ 2,000.00              | 1500         |
| 2            | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA             | 1                | \$ 1,800.00              | 1600         |
| 3            | TO RUST PROOF ACCIDENT AFFECTED AREA                    | 1                | \$ 120.00                | 50           |
| 4            | TO R&R CARPET AND SEAT                                  | 1                | \$ 150.00                | X            |
| 5            | TO R&R AIR CON AND REFILL GAS                           | 1                | \$ 200.00                | 120          |
| 6            | TO R&R DASH BOARD                                       | 1                | \$ 500.00                | 200          |
| 7            | TO R&R AIR BAG SRS                                      | 1                | \$ 250.00                | ✓            |
| 8            | TO CHECK AND RESET AIR BAG FUNCTION                     | 1                | \$ 550.00                | 250          |
| 9            | TO REPROGRAM AND REDIANOS FAULT CODE                    | 1                | \$ 1,200.00              | X.           |
|              | <i>To R-R front w/s glass</i>                           | 1                | 150/-                    |              |
|              | <i>To check &amp; wheel alignment</i>                   |                  | 180/-                    |              |
|              | <i>To check H/Lamp bulbs &amp; wiring</i>               |                  | 120/-                    |              |
|              | <i>To R-R upholstery &amp; attachment parts</i>         |                  | 380/-                    |              |
|              | <i>To R-R front w/corrosion system</i>                  |                  | 180/-                    |              |
|              | <i>1) Front Tyre RH</i>                                 |                  | 250/-                    |              |
|              | <i>2) Front Rim RH</i>                                  |                  | 350/-                    |              |
|              |                                                         | LABOUR TOTAL     | \$ 6,770.00              | \$ -         |
|              |                                                         | GRAND TOTAL COST | \$ 18,818.16             | \$ 2802.60 - |

To R-R Engine belt & attached parts → 120/-  
 To R-R front w/corrosion system → 180/-  
 1) Front Tyre RH → 250/-  
 2) Front Rim RH → 350/-

To R-R Engine belt & attached parts → 120/-  
 Adrian King,  
 L/S 29/05/19.  
 15 Days.

76043.88

Supplementary: 4461.32

Total: 24110.64

H/S: 19.2K.

[illegible]



X

## 96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: estimator@96motorsports.com

Tel: 83118211

TP INC.  
Denise

VEHICLE NUM:

SLL 8811 T

MAKE & MODEL:

HONDA VEZEL

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

RU1 1204299

ATTN:

| NO. | DESCRIPTION - PARTS                                     | QTY  | PRICE       | ADJUSTED PRICE |
|-----|---------------------------------------------------------|------|-------------|----------------|
| 1   | BONNET Distorted                                        | 1    | \$ 965.40   | ✓              |
| 2   | BONNET SIDE RUBBER L+R RH cut                           | 1SET | \$ 50.00    | 25.            |
| 3   | BONNET CENTER RUBBER cut                                | 2    | \$ 50.00    | ✓              |
| 4   | BONNET INNER LOCK sand                                  | 1    | \$ 97.50    | ✓              |
| 5   | BONNET LOCK CABLE new                                   | 1    | \$ 52.00    | +              |
| 6   | BONNET INSULATOR crumpled                               | 1    | \$ 142.30   | ✓              |
| 7   | BONNET INSULATOR CLIP new                               | 1SET | \$ 40.00    | ✓              |
| 8   | BONNET HINGE Bent                                       | 2    | \$ 148.00   | ✓              |
| 9   | BONNET STOPPER L+R new                                  | 2    | \$ 40.00    | +              |
| 10  | FRONT GRILLE crumpled                                   | 1    | \$ 396.50   | ✓              |
| 11  | FRONT GRILLE OUTER GARNISH crumpled                     | 1    | \$ 395.40   | ✓              |
| 12  | FRONT GRILLE OUTER GARNISH CHROME MOULDING L+R crumpled | 2    | \$ 172.80   | ✓              |
| 13  | FRONT GRILLE BADGE new                                  | 1    | \$ 55.00    | ✓              |
| 14  | FRONT GRILLE TOP BRACKET crumpled                       | 1    | \$ 58.00    | ✓              |
| 15  | FRONT GRILLE CLIP new                                   | 1SET | \$ 30.00    | ✓              |
| 16  | FRONT BUMPER Distorted                                  | 1    | \$ 987.50   | 880            |
| 17  | FRONT BUMPER SIDE RETAINER L+R new                      | 2    | \$ 120.00   | ✓              |
| 18  | FRONT BUMPER CLIP new                                   | 1SET | \$ 50.00    | 30.            |
| 19  | FRONT BUMPER FOG LAMP L+R RH smashed                    | 2    | \$ 734.00   | 367.           |
| 20  | FRONT BUMPER FOG LAMP COVER L+R RH Distorted            | 2    | \$ 317.20   | 108.60.        |
| 21  | FRONT BUMPER FOG LAMP COVER LED LIGHT L+R new           | 2    | \$ 200.00   | +              |
| 22  | FRONT BUMPER LOWER SKIRT missing                        | 1    | \$ 396.10   | ✓              |
| 23  | FRONT BUMPER LOWER SKIRT CHROME MOULDING new            | 1    | \$ 230.00   | +              |
| 24  | FRONT BUMPER UNDER COVER Distorted                      | 1    | \$ 171.30   | ✓              |
| 25  | FRONT BUMPER UNDER COVER CLIP new                       | 1SET | \$ 30.00    | ✓              |
| 26  | HEAD LAMP L+R RH crumpled MH new                        | 2    | \$ 2,300.40 | 1150.20.       |
| 27  | HEAD LAMP BOTTOM RETAINER L+R RH smashed                | 2    | \$ 84.00    | 42             |
| 28  | HEAD LAMP SIDE BRACKET L+R new                          | 2    | \$ 50.00    | +              |
| 29  | HEAD LAMP CLIP new                                      | 1SET | \$ 40.00    | ✓              |
| 30  | FRONT FENDER L+R Distorted                              | 2    | \$ 1,260.00 | ✓              |
| 31  | FRONT FENDER ARCH PROTECTOR L+R RH Distorted            | 2    | \$ 474.60   | 237.30         |
| 32  | FRONT FENDER ARCH PROTECTOR CLIP new                    | 1SET | \$ 30.00    | 15             |

[illegible]

| SPECIAL NETT     |                                                         | QTY  | PRICE        | PRICE |
|------------------|---------------------------------------------------------|------|--------------|-------|
| 1                | FRONT NUMBER PLATE WITH COVER <i>Done</i>               | 1    | \$ 120.00    | 60    |
| 2                | RADIATOR COOLANT <i>done</i>                            | 1    | \$ 100.00    | 40.   |
| 3                | BATTERY <i>done</i>                                     | 1    | \$ 200.00    | X     |
| 4                | SIDE SKIRT ( VEZEL ) RH <i>could.</i>                   | 1    | \$ 400.00    | ✓     |
| 5                | FRONT MUD FLIP L+R <i>RH missing</i>                    | 1SET | \$ 380.00    | 65-   |
| SPECIAL NETT     |                                                         |      | \$ 1,200.00  | \$ -  |
| LABOUR           |                                                         | QTY  | PRICE        | PRICE |
| 1                | TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA | 1    | \$ 2,000.00  | 1500  |
| 2                | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA             | 1    | \$ 1,800.00  | 1600  |
| 3                | TO RUST PROOF ACCIDENT AFFECTED AREA                    | 1    | \$ 120.00    | 50    |
| 4                | TO R&R CARPET AND SEAT                                  | 1    | \$ 150.00    | X     |
| 5                | TO R&R AIR CON AND REFILL GAS                           | 1    | \$ 200.00    | 120   |
| 6                | TO R&R DASH BOARD                                       | 1    | \$ 500.00    | 220   |
| 7                | TO R&R AIR BAG SRS <i>3990</i>                          | 1    | \$ 250.00    | ✓     |
| 8                | TO CHECK AND RESET AIR BAG FUCTION                      | 1    | \$ 550.00    | 250   |
| 9                | TO REPROGRAM AND REDIANOS FAULT CODE                    | 1    | \$ 1,200.00  | X.    |
| LABOUR TOTAL     |                                                         |      | \$ 6,770.00  | \$ -  |
| GRAND TOTAL COST |                                                         |      | \$ 18,818.16 | \$ -  |

PAGE 2 OF 2

Adrian King,  
L/S 29/05/19.  
15 days.

total: 20015.48  
L/S: 16K.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19009527/Atd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 13-09-2019



ATTN : MUHAMMAD AIRWAN

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | FR 8369T       | Veh. Inspected | SLL 8811T  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1046202-001 | Excess (\$)    | 0.00       |
| Assign From  | CYNTHIA ANG    | Assign Date    | 28/05/2019 |

#### 2. Vehicle Particulars & Condition

|              |             |              |            |
|--------------|-------------|--------------|------------|
| Make & Model | HONDA VEZEL | c.c          | 1496       |
| Engine No.   | HIDDEN      | Year of Reg. | 2017       |
| Chassis No.  | RU11204299  | Colour       | SILVER     |
| Odometer     | 158943 KM   | Steering     | IN ORDER   |
| Brakes       | IN ORDER    | Modification | SPORTS RIM |
| General      | GOOD        |              |            |

#### 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 215/60 R16 | MICHELIN | 6 mm    |
| L/H Front Tyre | 215/60 R16 | MICHELIN | 6 mm    |
| R/H Rear Tyre  | 215/60 R16 | MICHELIN | 6 mm    |
| L/H Rear Tyre  | 215/60 R16 | MICHELIN | 6 mm    |

#### 4. Description of Damages

|                                                                                                            |
|------------------------------------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, UNDERCARRIAGE AND ROOFTOP PORTION.<br><br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------------------------------------------|

#### 5. General Information

|                |                                                                                     |                     |                         |
|----------------|-------------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 25/05/2019                                                                          | Inspect Date / Time | 29/05/2019 ( 12:37 PM ) |
| Survey held at | 96 MOTORSPORTS PTE LTD<br>62/64 KAKI BUKIT AVENUE 6<br>SINGAPORE 417893<br>ARK @ KB |                     |                         |

#### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

#### 5b. Estimate Days of Repair

|                                     |                 |
|-------------------------------------|-----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 15 Working Days |
|-------------------------------------|-----------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8811T

| Qty | Description of Parts                           | Condition                          | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------|------------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>             |                                    |                           |                   |
| 1   | BONNET                                         | DISTORTED                          | 965.40                    | 965.40            |
| 2   | BONNET SIDE RUBBER L+R                         | O/S CUT                            | 50.00                     | 25.00             |
| 2   | BONNET CENTER RUBBER                           | CUT                                | 50.00                     | 50.00             |
| 1   | BONNET INNER LOCK                              | DAMAGED                            | 97.50                     | 97.50             |
| 1   | BONNET LOCK CABLE                              | NOT NECESSARY                      | 52.00                     | -                 |
| 1   | BONNET INSULATOR                               | CRUMPLED                           | 142.30                    | 142.30            |
| 1   | SET BONNET INSULATOR CLIP                      | NECESSARY                          | 40.00                     | 40.00             |
| 2   | BONNET HINGE                                   | BENT                               | 148.00                    | 148.00            |
| 2   | BONNET STOPPER L+R                             | NOT NECESSARY                      | 40.00                     | -                 |
| 1   | FRONT GRILLE                                   | CRACKED                            | 396.50                    | 396.50            |
| 1   | FRONT GRILLE OUTER GARNISH                     | CRACKED                            | 395.40                    | 395.40            |
| 2   | FRONT GRILLE OUTER GARNISH CHROME MOULDING L+R | CRACKED                            | 172.80                    | 172.80            |
| 1   | FRONT GRILLE BADGE                             | NECESSARY                          | 55.00                     | 55.00             |
| 1   | FRONT GRILLE TOP BRACKET                       | CRACKED                            | 58.00                     | 58.00             |
| 1   | SET FRONT GRILLE CLIP                          | NECESSARY                          | 30.00                     | 30.00             |
| 1   | FRONT BUMPER                                   | DISTORTED                          | 987.50                    | 880.00            |
| 2   | FRONT BUMPER SIDE RETAINER L+R                 | NECESSARY                          | 120.00                    | 120.00            |
| 1   | SET FRONT BUMPER CLIP                          | NECESSARY                          | 50.00                     | 30.00             |
| 2   | FRONT BUMPER FOG LAMP L+R                      | O/S SMASHED                        | 734.00                    | 367.00            |
| 2   | FRONT BUMPER FOG LAMP COVER L+R                | O/S DEFORMED                       | 317.20                    | 108.60            |
| 2   | FRONT BUMPER FOG LAMP COVER LED LIGHT L+R      | NOT NECESSARY                      | 200.00                    | -                 |
| 1   | FRONT BUMPER LOWER SKIRT                       | MISSING                            | 396.10                    | 396.10            |
| 1   | FRONT BUMPER LOWER SKIRT CHROME MOULDING       | NOT NECESSARY                      | 230.00                    | -                 |
| 1   | FRONT BUMPER UNDER COVER                       | DEFORMED                           | 171.30                    | 171.30            |
| 1   | SET FRONT BUMPER UNDER COVER CLIP              | NECESSARY                          | 30.00                     | 30.00             |
| 2   | HEAD LAMP L+R                                  | O/S CRACKED / N/S<br>NOT NECESSARY | 2,300.40                  | 1,150.20          |
| 2   | HEAD LAMP BOTTOM RETAINER L+R                  | O/S SMASHED                        | 84.00                     | 42.00             |
| 2   | HEAD LAMP SIDE BRACKET L+R                     | NOT NECESSARY                      | 50.00                     | -                 |
| 1   | SET HEAD LAMP CLIP                             | NECESSARY                          | 40.00                     | 40.00             |

Report Ref No. CS/INC19009527/Atd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

| Qty | Description of Parts                 | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------|---------------|---------------------------|-------------------|
| 2   | FRONT FENDER L+R                     | DISTORTED     | 1,260.00                  | 1,260.00          |
| 2   | FRONT FENDER ARCH PROTECTOR L+R      | O/S DEFORMED  | 474.60                    | 237.30            |
| 1   | SET FRONT FENDER ARCH PROTECTOR CLIP | NECESSARY     | 30.00                     | 15.00             |
| 2   | FRONT FENDER INNER SHIELD L+R        | O/S MISSING   | 386.40                    | 193.20            |
| 1   | SET FRONT FENDER INNER SHIELD CLIP   | NECESSARY     | 30.00                     | 15.00             |
| 1   | SUPPORT PANEL                        | DISTORTED     | 674.50                    | 674.50            |
| 1   | SUPPORT PANEL TOP GARNISH            | DEFORMED      | 95.20                     | 95.20             |
| 1   | SET SUPPORT PANEL TOP GARNISH CLIP   | NECESSARY     | 20.00                     | 20.00             |
| 1   | BRACE PANEL (NPA)                    | NOT NECESSARY | -                         | -                 |
| 2   | HORN L+R                             | NOT NECESSARY | 120.00                    | -                 |
| 1   | AIR CON CONDENSER                    | DENTED        | 890.00                    | 890.00            |
| 2   | CONDENSER SIDE GARNISH L+R           | O/S DISTORTED | 90.00                     | 45.00             |
| 1   | CONDENSER AIR CON PIPE               | NOT NECESSARY | 195.20                    | -                 |
| 1   | CONDENSER SUCTION PIPE               | BENT          | 185.40                    | 185.40            |
| 1   | CONDENSER DISCHARGE PIPE             | NOT NECESSARY | 210.70                    | -                 |
| 1   | CONDENSER FAN COWLING                | CRACKED       | 98.40                     | 98.40             |
| 1   | CONDENSER FAN MOTOR                  | NOT NECESSARY | 328.20                    | -                 |
| 1   | CONDENSER FAN BLADE                  | NOT NECESSARY | 68.20                     | -                 |
| 1   | RADIATOR                             | DISTORTED     | 1,250.60                  | 1,250.60          |
| 2   | RADIATOR TOP MOUNTING L+R            | DAMAGED       | 70.00                     | 70.00             |
| 2   | RADIATOR TOP MOUNTING BRACKET L+R    | DAMAGED       | 80.00                     | 80.00             |
| 1   | RADIATOR FAN COWLING                 | CRACKED       | 135.40                    | 135.40            |
| 1   | RADIATOR FAN MOTOR                   | NOT NECESSARY | 298.40                    | -                 |
| 1   | RADIATOR FAN BLDE                    | NOT NECESSARY | 57.70                     | -                 |
| 1   | RESONATOR BOX AIR DUCT               | NOT NECESSARY | 245.60                    | -                 |
| 1   | WIPER TANK                           | DEFORMED      | 97.20                     | 97.20             |
| 1   | WIPER TANK MOTOR                     | DAMAGED       | 69.00                     | 69.00             |
| 1   | BATTERY BOTTOM TRAY                  | NOT NECESSARY | 28.20                     | -                 |
| 1   | BATTERY TOP BRACKET                  | NOT NECESSARY | 26.40                     | -                 |
| 2   | AIR BAG IMPACT SENSOR L+R            | ACTIVATED     | 620.00                    | 620.00            |
| 1   | FRONT STEERING AIR BAG               | ACTIVATED     | 1,605.40                  | 1,605.40          |
| 1   | FRONT PASSENGER AIR BAG              | ACTIVATED     | 2,236.40                  | 2,236.40          |
| 1   | DASH BOARD                           | TORN          | 920.60                    | 920.60            |

Report Ref No. CS/INC19009527/Atd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts                          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------|----------------------|---------------------------|-------------------|
| 2   | FRONT SEAT BELT L+R                           | ACTIVATED            | 1,162.80                  | 1,162.80          |
| 2   | FRONT SEAT BELT BUCKER L+R                    | NOT NECESSARY        | 640.00                    | -                 |
| 1   | SRS AIR BAG CONTROL UNIT                      | ACTIVATED            | 980.40                    | 980.40            |
| 1   | ROOF TOP PANEL (ADDITIONAL)                   | TO REPAIR SEE LABOUR | 1,260.60                  | -                 |
| 1   | FRONT W/S GLASS (ADDITIONAL)                  | SHATTERED            | 1,950.00                  | 1,488.20          |
| 1   | FRONT W/S GLASS MLD (ADDITIONAL)              | NECESSARY            | 85.00                     | 85.00             |
| 1   | FRONT DOOR RH (ADDITIONAL)                    | TO REPAIR SEE LABOUR | 1,046.00                  | -                 |
| 1   | FRONT DOOR LOCK RH (ADDITIONAL)               | NOT NECESSARY        | 310.00                    | -                 |
| 2   | FRONT DOOR HINGER RH (ADDITIONAL)             | NOT NECESSARY        | 130.00                    | -                 |
| 1   | FRONT ABSORBER RH (ADDITIONAL)                | BENT                 | 463.00                    | 463.00            |
| 1   | FRONT KNUCKLE RH (ADDITIONAL)                 | DAMAGED              | 454.70                    | 454.70            |
| 1   | FRONT KNUCKLE BEARING RH (ADDITIONAL)         | NECESSARY            | 268.50                    | 268.50            |
| 1   | FRONT LOWER ARM RH (ADDITIONAL)               | BENT                 | 398.70                    | 398.70            |
| 1   | STRG AIR BAG WIRE (ADDITIONAL)                | ACTIVATED            | 298.90                    | 298.90            |
| 1   | PASSENGER AIR BAG WIRE (ADDITIONAL)           | NOT NECESSARY        | 258.40                    | -                 |
| 1   | FRONT SIDE MIRROR GLASS RH (ADDITIONAL)       | MISSING              | 48.60                     | 48.60             |
| 1   | FRONT DOOR PILLAR RH (ADDITIONAL)             | TO REPAIR SEE LABOUR | 933.50                    | -                 |
| 1   | FRONT FENDER INNER PANEL RH (ADDITIONAL)      | DISTORTED            | 153.60                    | 153.60            |
| 1   | ENGINE MTG RH (ADDITIONAL)                    | NOT NECESSARY        | 223.60                    | -                 |
| 1   | FRONT BUMPER REINFORCEMENT (ADDITIONAL)       | DISTORTED            | 298.70                    | 298.70            |
|     | LESS 20% DISCOUNT                             |                      | -6,533.22                 | -4,565.16         |
|     |                                               |                      | 26,132.88                 | 18,260.64         |
|     | <b>SPECIAL NETT ITEMS</b>                     |                      |                           |                   |
| 1   | FRONT NUMBER PLATE WITH COVER (SN)            | DAMAGED              | 120.00                    | 60.00             |
| 1   | RADIATOR COOLANT (SN)                         | NECESSARY            | 100.00                    | 40.00             |
| 1   | BATTERY (SN)                                  | NOT NECESSARY        | 200.00                    | -                 |
| 1   | SIDE SKIRT (VEZEL) RH (SN)                    | CRACKED              | 400.00                    | 400.00            |
| 2   | FRONT MUD FLIP L+R (SN)                       | O/S DEFORMED         | 380.00                    | 65.00             |
| 1   | FRONT W/S GLASS SEALANT (SN) (ADDITIONAL)     | NECESSARY            | 80.00                     | 60.00             |
| 1   | FRONT W/S GLASS TINTED FILM (SN) (ADDITIONAL) | NECESSARY            | 500.00                    | 200.00            |
| 1   | FRONT W/S GLASS ERP BRACKET (SN) (ADDITIONAL) | NECESSARY            | 35.00                     | 35.00             |

Report Ref No. CS/INC19009527/Atd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

| Qty | Description of Parts                                                                                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | FRONT TYRE RH (SN) (ADDITIONAL)                                                                                                             | PUNCTURE      | 250.00                    | 180.00            |
| 1   | FRONT RIM RH (SN) (ADDITIONAL)                                                                                                              | CUT           | 350.00                    | 350.00            |
|     |                                                                                                                                             |               | 2,415.00                  | 1,390.00          |
|     | <b>LABOUR</b>                                                                                                                               |               |                           |                   |
|     | TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF ROOF TOP PANEL, FRONT DOOR RH AND FRONT DOOR PILLAR RH. |               | 2,000.00                  | 1,500.00          |
|     | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.                                                                                                |               | 1,800.00                  | 1,600.00          |
|     | TO RUST PROOF ACCIDENT AFFECTED AREA.                                                                                                       |               | 120.00                    | 50.00             |
|     | TO R&R CARPET AND SEAT.                                                                                                                     | NOT NECESSARY | 150.00                    | -                 |
|     | TO R&R AIR CON AND REFILL GAS.                                                                                                              |               | 200.00                    | 120.00            |
|     | TO R&R DASH BOARD.                                                                                                                          |               | 500.00                    | 220.00            |
|     | TO R&R AIR BAG SRS.                                                                                                                         |               | 250.00                    | 250.00            |
|     | TO CHECK AND RESET AIR BAG FUNCTION.                                                                                                        |               | 550.00                    | 250.00            |
|     | TO REPROGRAM AND REDIANOS FAULT CODE.                                                                                                       | NOT NECESSARY | 1,200.00                  | -                 |
|     | TO R&R FRONT W/S GLASS. (ADDITIONAL)                                                                                                        |               | 150.00                    | 120.00            |
|     | TO CHECK 4 WHEELS ALIGNMENT. (ADDITIONAL)                                                                                                   |               | 180.00                    | 80.00             |
|     | TO CHECK H/LAMP FOCUS AND WIRING. (ADDITIONAL)                                                                                              |               | 120.00                    | 30.00             |
|     | TO R&R UPHOSTERY AND ATTACHMENT PARTS. (ADDITIONAL)                                                                                         |               | 380.00                    | 60.00             |
|     | TO R&R FRONT UNDER CARRIAGE SYSTEM. (ADDITIONAL)                                                                                            |               | 180.00                    | 180.00            |
|     | TO R&R ENGINE MTG AND ATTACHMENT PARTS. (ADDITIONAL)                                                                                        | NOT NECESSARY | 120.00                    | -                 |
|     |                                                                                                                                             |               | 7,900.00                  | 4,460.00          |
|     | <b>GRAND TOTAL</b>                                                                                                                          |               | <b>36,447.88</b>          | <b>24,110.64</b>  |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>                                                     |               |                           | <b>19,200.00</b>  |

Report Ref No. CS/INC19009527/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M,MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.