

ASS. REC. BY:

REF:

01/AG/9009530/K4d3d

Special Instruction:

Summary:

Kunth
Munnen

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

29/5/19 @ 8:56am

Estimated Cost:

Bill to:

OD-TP+WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLS6807H

Insured:

at Workshop m/s

Motor Image

Tel:

96689313

of

19 Lorong 8 toa payoh

Policy No:

1700052-08-01

Claim No:

356049566656

Sum Insured:

Excess:

TBA 1000/-

Make of Veh:

(Client's Record)

D.O.A.

23/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:15am 29/5/19

Person Contacted:

Ismen

Vehicle IN/OUT

Date/Time

Action/Instruction

Tahung

SLS6807H-X

30/5 @ 15:06 - Seek mandate.

6/6 @ 13:01 - mandate approval by Chang Loi.

6/6 @ 1:27pm - Inform motor image authorise repair excess \$1000-
wheel alignment to conduct before repair.

ASS. REC. BY:

REF:

A/L

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

Part by Part \$6997.38 (Red: 14,336.57, 67%)

RECEIVED 26 NOV 2019

RECEIVED 03 MAR 2020

Data/Time, File Pass to?

28/12 Typist

Data/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

: \$ + RS \$

: P. - X

: Other

Add Fee:



: Site Insp \$



: Interview \$



: Tech. Insp \$



: Weekend \$

Report Format:

Lump Sum / L.B. \$

OD

6997.38

900

11

211

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 6 June 2019 1:27 PM
To: 'Mohamed Isman'; 'Sayedinah'
Cc: 'Daniel Jude'
Subject: RE: SLS 6807H / OD / AIG / DOA: 23/5/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLS 6807H (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

***Note** - To conduct all wheel alignment before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mohamed Isman <isman@motorimage.net>
Sent: Monday, 3 June 2019 8:37 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Sayedinah <sayedinah@motorimage.net>
Cc: Daniel Jude <danieljude@motorimage.net>
Subject: RE: SLS 6807H / OD / AIG / DOA: 23/5/2019

Dear Denise,

Attached is the documents you required.

Thank You.

Best Regards

Mohd Isman

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 9668 9313

Email: isman@motorimage.net

Website: www.tanchong.com : www.motorimage.net

View Received Message

This mail is associated with :

***SLS6807H (3560495666SG)**

OD

May 23 2019 4:10PM

[WANG ZHAOYUN]

Motor Image Enterprises Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 06/06/2019 13:01 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5016.00) - SLS6807H - Claim Handler: Gan, Hunchung

Approved:5016.00:- To conduct ALL WHEEL ALIGNMENT BEFORE repair. - RE-INSPECTION require on check item, hidden item and supplementary

DOCUMENTS SUMMARY

There are no documents.

SLS6807H - ARRANGE SURVEY 29/05/2019@1100HRS

From: Chin, Lee Ying

To: assignments, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 5/29/2019 8:56:39 AM

Attachments:  SLS6807H GIA REPORT - OD.PDF  SLS6807H OD ESTIMATE.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Mohamed Isman [mailto:isman@motorimage.net]

Sent: Wednesday, May 29, 2019 8:21 AM

To: Chin, Lee-Ying; AIG SGP, Claims-Survey

Cc: TPY Insurance Team

Subject: [EXTERNAL] SLS6807H - ARRANGE SURVEY 29/05/2019@1100HRS

Importance: High

This message is from an external sender; be cautious with links and attachments.

Hi Team,

Kindly assist to arrange survey for the above mentioned vehicle as mentioned

29/05/2019 -@ 1100hrs .

Thank You.

Best Regards

Mohd Isman

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 9668 9313

Email: isman@motorimage.net

Website: www.tanchong.com : www.motorimage.net

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 30 May 2019

Preliminary Advice

Vehicle No	: SLS6807H	Accident Date	: 23/05/2019
Make	: SUBARU FORESTER	Policy No.	: 1700052708-01
Assignment Date	: 29/05/2019	Excess	: S\$0.00
Date of Inspection	: 29/05/2019	Est. Duration of Repair	: 9.00
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and undercarriage parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,745.30
Revised Amount	:S\$	5,015.40
Check Items (Estimated)	:S\$	19,423.50
Total	:S\$	24,438.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	55,051.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,949.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1116Z
Vehicle Details	
Vehicle No.:	SL56807H
Vehicle to be Exported:	No
Intended Deregistration Date:	30 May 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0i-L CVT AWD SR
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	FB20YB14473
Chassis No.:	JF15J5KC5JG098770
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,744.00
Original Registration Date:	29 Sep 2017
First Registration Date:	29 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$13,744.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2027
PARF Rebate Amount:	\$10,308.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$44,743.00
Total Rebate Amount:	\$55,051.00

The information contained herein is correct as at 30 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2019 15:53
Date Of Accident	23/05/2019 16:10
Exact Location Of Accident	150 LORONG KISMIS S'PORE (598076)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS6807H
Insured/Policyholder	
Name Of Registered Owner	WANG ZHAOYUN
NRIC No	S7281116Z
Email Address	LAVENDERYUN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90090856
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 I-L CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL / LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700052708-01
Cover Note Number	

Driver

Name of Driver	WANG ZHAOYUN
NRIC No	S7281116Z
Date Of Birth	20/09/1972
Occupation	INDOOR
Date Of Driving Pass	05/04/2017
Driving Experience	2 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-90090856
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	LAVENDERYUN@HOTMAIL.COM

Address	APT BLK 289D BUKIT BATOK STREET 25 #17-170
Postcode	653289
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED DOCUMENTS AND VIDEO FOOTAGE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

Accident Sketch Plan

DESCRIPTION

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Time around 4:00 - 4:15 pm, 23 May 2018

I intended to make a 3 point turn ^{next to} the corner of 150 Lee Kuan Yew. However, I didn't realize that my foot was still on the accelerator instead of the brake. The car hit a piece of fence of the owner's property, knocked it down and landed on the grass in front of the owner's house. I was alone in the car, and the owners were not home but only ^{their} maid was around. There were no ^{any} injuries at all but only a piece of fence has been hit down. I made a call to A&A asset hotline at 4:40 pm after the owners came back home.

* REFER TO PICTURES & VIDEO FOOTAGE

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 24.05.18
11:18 am
Signed/Stamped only

Driver's Signature
(If driver is not the policyholder)
Date & Time: 11:18 am
24.05.18

Witnessing Officer's Signature
Name: DANIEL JOSE
NIC/FIN No.: SP001250

Accident Sketch Plan

Accident Sketch Plan

IMPORTANT NOTICE

- Please report promptly the details of the accident in respect of the claims process.
 - This Form must be completed by the Policyholder and/or the Authorized Signatory.
 - Information provided must be as prompt and accurate as possible. Any willful concealment or withholding of material facts may affect insurance cover under the associated policy/ policies.
 - The issue and acceptance of this Form by Insurers' companies is an acknowledgment of policy liability on the part of the Insurers' companies.
 - Any false reporting may be referred to the Police for investigation.
 - This report will be forwarded by the Insurers' to the Risk Response Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application to interested parties.
 - In the judgment of this report to the Insurers', you hereby consent to the archiving of this report at the Centre and be regarded as the report being made available aforesaid.
 - Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and extend that:
- My Insurer, my Insurer and the General Insurance Association of Singapore ("GIA"), may/are permitted to collect, use, disclose and/or process my personal data/personal information (set out in this Form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured the vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - investigating the accident and/or my claims;
 - carrying out and/or dealing with any instructions or responding to any enquiries by me;
 - administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as a written external cover of envelopes/mail packages); and/or
 - complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - All Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service provider agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - the information so collected under (ii) above may be shared / disclosed:
 - to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing from regulators, law enforcement and government agencies as reasonably required for the purposes stated; and
 - for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 11:20 AM

24.05.19

Driver's Signature

(If driver is not the policyholder)

Date & Time: 11:20 AM

24.05.19

Reporting Centre Personnel's Signat

Name: Daniel Joo

INSTRUM No: 09000080

ISSUING DATE: 20190524

INSURANCE CERT



CERTIFICATE OF INSURANCE

SUBARU AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Wang Zhaoyun
 Period of Insurance : 29 Sep 2018 To 28 Sep 2019
 Engine No. : FB20YB14473
 Chassis No. : JF15J5KC5JG08F770

Vehicle No. : SL56807H
 Policy No. : 1700052708-01
 Endorsement No. :
 Issued Date : 29 Aug 2018

ABOUT THE COVER

Make/Model	SUBARU Forester 2.0i	Sum Insured	Market Value	First Year of Registration	2017
Engine Capacity/Tonnage	1,995.00 CC	Off Peak Car	No	Insuring with COE/PARF	Yes
Driver Restriction	NA				

Person or Classes of Persons Entitled to Drive*

As the Policyholder
 During other person and is subject to the Policyholder's order with written permission.
 This policy will indemnify the Policyholder or any authorized driver only if found to meet the specified age condition.

We have to pay an additional sum of \$3,000 as "Young Driver Compensation (Driver Excess)" (YDCP) if you are of Your Authorized Driver is under 21 years old or under 25 years old and has less than 3 years driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This policy does not cover use for hire or reward, driving school, driving test, racing, pace-making, identity theft or age-related, fire damage of goods other than property in connection with any theft or business or use for any purpose inconsistent with Motor Trade.

Loss of Use 1500us - 1800us

* Limitations outlined stipulated by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 186) and Section 65 of the Road Transport Act 1987 (Singapore) are not to be induced under these headings.

EXCESS

Section 1
 Fire - \$0; Own Damage - \$1000; Theft - \$0; Flood Damage - \$0

Section 2
 Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

Wang Zhaoyun - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Motor Image Carworks Pte Ltd, No. 111, Looing & Tan Chong Road, Singapore 610054/610000

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour customer emergency hotline at 655 6108 6109. Alternatively, you may call us 100 million times, registering or 100 000 000 000. Simply search and download 100 000 000 000 000 on Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan : United Overseas Bank Limited

We hereby certify that this policy is issued in accordance with the provisions of the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act 1987 (Singapore) and Motor Vehicle (Third Party Risks) Rules, 1998 (Singapore).

160049219

TAN CHONG CREDIT SUBARU AGS
 311 BLK 11 TAMM ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 59622
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

2018/1

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLS6807H	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0219/2019	YEAR: 29-SEP-2017
ENGINE NO: FB20YB14473	CHASSIS NO: JF1SJ5KC5JG098770
DOA: 23/05/2019	TOA: 1610HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRONT PANEL & BONNET ⁷⁶⁰	\$1250.00 [?]
2.	RESPRAY FRONT BUMPER,FRONT PANEL & BONNET ⁶⁰⁰	\$1000.00 ⁹⁰⁰
3.	TRANSFER / BALANCE TYRE / RIM LH REAR	\$28.00 ✓
4.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIRS	\$684.00 ✓
5.	REMOVE/REFIX ESHAUST	\$114.00 [?]
6.	WHEEL ALIGNMENT	\$171.00 ✓
7.	MECHANICAL REPAIRS- ALTERNATOR,COMPRESSOR, STEERING PUMP	\$171.00 [?]
8.	FAULT DIAGNOSTIC	\$235.00 ✓
9.	TO CONDUCT PROTECTANT COATING	\$750.00 ²⁸⁰
10.	TO CONDUCT ANTI RUST COATING	\$290.00 [?]
11.	SUNDRIES	\$100.00 ³⁰⁰
12.	REMOVE/REFIX FRT HEADLAMP WAHSE & PIPING	\$125.00 ✓
Total Labour		\$4918.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	<i>Henrich CLKK</i>
HP / EMAIL:	<i>1</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	<i>7-9 days</i>

Not Authorised
Prework B4 paint
EXCER TBA

UK Auto Consultants hence notify the Repairer of the following:

- To remove before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action/claim(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
 Signature:
 Date:

Estimate

Date 05 / 27 / 2019

001 / 004

Name	QUOTATION FOR SL6807H	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SLJ5KCAJG098770

Part Number	Part Code Name	Part Code	Qty	Price
57709SG030A	BUMPER FACE-FRONT	FIG-590 57704	1	594.00
57711SG0009P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	288.00
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	126.00
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	36.00
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	36.00
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	12.60
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	12.60
57780SG010	PACKING-BUMPER,RIGHT	FIG-590 57780B	1	9.00
57780SG020	PACKING-BUMPER,LEFT	FIG-590 57780C	1	9.00
57731SG220	COVER-FRONT BUMPER	FIG-590 57731	1	4.40
53029SG0019P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	360.00
91121SG280A	FRONT GRILLE ASSEMBLY,LOWER	FIG-911 91121F	1	316.80
91121SG240A	FRONT GRILLE ASSEMBLY,CENTER	FIG-911 91121G	1	180.00
91121SG210A	FRONT GRILLE ASSEMBLY,UPPER	FIG-911 91121E	1	150.90
91165SG000	BRACKET-GRILL LOWER	FIG-911 91165JA	1	21.60
84002SG222	LAMP ASSEMBLY-HEAD RIGHT	FIG-840 84001A	1	2,380.00
		Page-Total		4,536.90

Memo	Grand Total
	22,745.30

Tel

Estimate

Date 05 / 27 / 2019

002 / 004

Name	QUOTATION FOR SL660TH	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF15J5KC6JG098770

Part Number	Part Code Name	Part Code	Q'ty	Price	
84002SG232	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	2,380.00	✓
57229SG0009P	HOOD COMPLETE-FRONT	FIG-550 57220	1	882.00	X
57310SG020	LOCK ASSEMBLY-FRONT HOOD	FIG-550 57310	1	72.00	X
57260SG0009P	HINGE COMPLETE-FRONT HOOD,RIGHT	FIG-550 57260	1	43.20	✓
57260SG0109P	HINGE COMPLETE-FRONT HOOD,LEFT	FIG-550 57260A	1	43.20	X
90815SG050	INSULATOR-FRONT HOOD	FIG-956 90815B	1	79.20	X
86636SG380A	COVER ASSEMBLY-LAMP WASHER NOZZLE,RIGHT	FIG-877 86636NA	1	54.00	✓
86636SG361	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	79.20	✓
28111SG130	DISK WHEEL-ALUMINIUM	FIG-290 28111	1	1,500.00	✓
56410SG050	UNDER COVER-FRONT	FIG-572 56410	1	158.40	✓
20101VA010	CROSS MEMBER COMPLETE-FRONT SUSPENSION	FIG-200 20101	1	472.00	✓
20401SG000	STABILIZER-FRONT	FIG-200 20401	1	169.20	✓
20420XA000	LINK ASSEMBLY-FRONT STABILIZER	FIG-200 20420	2	165.60	✓
20202SG000	LOWER ARM ASSEMBLY-FRONT,RIGHT	FIG-200 20202	1	493.20	✓
20202SG010	LOWER ARM ASSEMBLY-FRONT,LEFT	FIG-200 20202A	1	493.20	✓
20310SG100	STRUT COMPLETE-FRONT RIGHT	FIG-210 20310A	1	262.80	✓
		Page-Total		7,347.20	

Memo

Grand Total
22,745.30

--

Tel

Estimate

Date 05 / 27 / 2019

003 / 004

Name	QUOTATION FOR SL660TH	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ8EK7C
		Vin-Code	JF15J5KC5JG098770

Part Number	Part Code Name	Part Code	Q'ty	Price	
20310SG110	STRUT COMPLETE-FRONT LEFT	FIG-210 20310B	1	262.80	2
20320FG012	STRUT MOUNT-FRONT	FIG-210 20320	2	144.00	2
20152SG011	FRAME SUB ASSEMBLY-REAR SUSPENSION	FIG-201 20152	1	664.00	1 ✓
20451AL000	STABILIZER-REAR	FIG-201 20451	1	126.00	X
20464SC010	BUSHING-STABILIZER	FIG-201 20414	2	21.60	X
20470AJ010	LINK ASSEMBLY-STABILIZER-REAR	FIG-201 20470	2	172.80	2
20252SG001	REAR ARM ASSEMBLY, UPPER RIGHT	FIG-201 20250H	1	432.00	X
20252SG011	REAR ARM ASSEMBLY, UPPER LEFT	FIG-201 20250I	1	432.00	✓
20250AL011	LATERAL LINK ASSEMBLY-REAR	FIG-201 20250	017 2	136 252.00	2+
20250FG021	LATERAL LINK ASSEMBLY-FRONT	FIG-201 20250F	017 2	205.20 410.40	2+
20250FJ001	TRAILING ARM-REAR	FIG-201 20252	017 2	144 288.00	2+
34110SG050	STEERING GEAR BOX ASSEMBLY, EPS	FIG-347 34110A	1	2,545.20	2
20365SG110	SHOCK ABSORBER-REAR	FIG-211 20365	2	1,641.60	2
20370SG000	STRUT MOUNT-REAR	FIG-211 20370	2	208.80	2
44200SG080	EXHAUST PIPE ASSEMBLY-REAR	FIG-440 44200	1	745.20	X ✓
44300SG010	MUFFLER ASSEMBLY-RIGHT	FIG-440 44300A	1	601.20	X
		Page-Total		8,967.60	

Memo

Grand Total
22,745.30

--

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Tan Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SL5 6307H

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1 refix & remove Air cond condenser & radiator CAZ \$ 171.00 ✓

2 refix & remove wire harness CAZ \$ 230.00 ✓

3 _____

4 _____

5 _____

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____

MotorImage

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0219/2019
DATE : 06-JUN-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHEMTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : WANG ZHAYUN
ADDRESS : BLK 289D BUKIT BATOK STREET 25
#17-170
S(653289)
TELEPHONE NO : 9009 0856

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1700052708-01
VEHICLE NO : SLS6807H
MODEL CODE : SJ5EX7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20YB14473
CHASSIS NO : JF1SJSKC5JG098770
MILEAGE : 13704 KM
DATE IN : 06/06/2019
LIABILITY : 0.00
EXCESS CLAUSE : 1000.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 23/05/2019

Print Date : 25/11/2019
Print Time : 11:26:05

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SL86807E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	COCLATH	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)		
2	ZZ/001	CONDUCT OD CLAIM AIG DATE:23/05/2019 TIME:1610HRS LOCATION:150 LORONG KISMIS 5 (598076)		
3	ZZ/002	REPAIR/REPLACE FRONT BUMPER & FRONT PANEL	750.00	750.00 ✓
4	ZZ/003	RESPRAY FRONT BUMPER AND PANEL	400.00	600.00 ✓
5	ZZ/004	TRANSFER/BALANCE/RIM LH REAR	28.00	28.00 ✓
6	ZZ/005	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR	684.00	684.00 ✓
7	ZZ/006	CONDUCT 4 WHEEL ALIGNMENT	171.00	171.00 ✓
8	ZZ/007	CONDUCT FAULT DIAGNOSTIC AND RESET SYSTEM	235.00	235.00 ✓
9	ZZ/008	CONDUCT PROTECTANT COATING	280.00	280.00 ✓
10	ZZ/009	SUNDRIES	30.00	30.00 ✓
11	ZZ/011	REFIX & REMOVE AIRCOND CONDENSER & RADIATOR	171.00	171.00 ✓
12	ZZ/012	REFIX & REMOVE WIRE HARNESS (SUPP)	230.00	230.00 (CA) ✓
13	ZZ/013	REMOVE & REFIX EXHAUST	171.00	114.00 ✓
14	ZZ/10	REMOVE/REFIX FRT HEADLAMP WASHER AND PIPING	125.00	125.00 ✓
TOTAL LABOUR CHARGES			3275.00	3418.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL56807H

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	SUB FRAME ASSY R AND	20152SG011			✓ 684.00	OK
2	LINK ASSY R LAT R	20250AL011			✓ 126.00	OK
3	LINK ASSY R LAT F	20250FG021			✓ 205.20	OK
4	TRAILING ARM-REAR	20250FJ001			✓ 144.00	OK
5	ARM ASSY R UPR LH	20252SG011			✓ 432.00	OK
6	DISC WHEEL AL 17	28111SG130			✓ 1500.00	OK
7	EXH PIPE ASSY R	44200SG080			✓ 745.20	OK
8	UNDER COVER CDM FNA	56410SG050			✓ 138.40	OK
9	BRET CORNER F RH	57707SG000			✓ 36.00	OK
10	BRET CORNER F LH	57707SG010			✓ 36.00	OK
11	FRT BUMPER	57709SG030A			✓ 594.00	OK
12	ENERGY ABSOR F	57722SG020			✓ 126.00	OK
13	COVER HOOK F STD	57731SG220			✓ 4.40	OK
14	PACKING PAD	57780SG020			✓ 9.00	OK
15	NOZZLE H L WASHER LH (SUPP)	86636SG371			mi/ 79.20	OK ✓
16	NOZZLE COVER ASSY RH (SUPP)	PDI PARTS 86636SG380A			mi/ 54.00	OK ✓
17	GRILLE ASSY F CTRNG	PDI STOCK 91121SG240A			180.00	OK
SUB TOTAL			0.00	0.00	0.00	5113.40
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	1534.02
GRAND TOTAL			0.00	0.00	0.00	3579.38
OVERALL TOTAL			3579.38			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255



SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SL56807H

NETT ITEM	0.00
LESS 20 %	0.00
NETT AMOUNT	0.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	5113.40
LESS 30 %	-1534.02
S/LIST AMOUNT	3579.38
TOTAL LABOUR CHARGES	3418.00
TOTAL SPARE PARTS CHARGES	3579.38
TOTAL CHARGES	6997.38
LESS EXCESS	1000.00
TOTAL	5997.38
ADD 7 % GST	419.82
GRAND TOTAL	6417.20

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R001339
 Name 2: WANG ZHAOYUN
 Company: BLK 289D BUKIT BATOK STREET 25
 License: SLS6807H
 Year: 17
 Technician: KUGAN
 Odometer: 13697
 Date: 11.6.19 9:53


Subaru : Forester : 2016-18 (SJ)
4-Wheel Total Alignment



MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R001345
 Name 2: WANG ZHAOYUN
 Company: BLK 289D BUKIT BATOK STREET 25
 License: SLS6807H
 Year: 17
 Technician: KUGAN
 Odometer: 13697
 Date: 11.6.19 17:10

Subaru : Forester : 2016-18 (SJ)
4-Wheel Total Alignment



All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 6/18/2019 9:07:11 AM

Vehicle: Forester

VIN: JF1SJ5KC5JG098770

Model: 18MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 2 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			02597	703200	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					
Past	B14EB	Intake Door Actuator Stuck	02590	98600	ammo		**

<Keyless Access with Push Button Start : 0 piece>

<Automatic Light and Wiper : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			02597	703200	Current		
Past	B2401	Sensor Installation Incorrect					

<Combination Meter : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			02597	703200	Current		
Past	B1507	Outside Tempurter Sensor Open Detected	02582	1500	ommo		

<Multi-function Display : 0 piece>

<Auto Start Stop : 0 piece>

<Headlight / Foglight : 4 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time (msec)	Group		
			02597	703200	Current		
Past	B2905	LED Head Light Circuit LH	02564	19917200	ommo		**
Past	B2911	Steering Responsive Headlight Communication LH	02564	46131600	ommo		
Past	B2904	LED Headlight Circuit RH	02582	13365400	ommo		
Past	B2910	Steering Responsive Headlight Communication RH	02583	39579900	ommo		

All diagnosis code

TEL:

FAX:

Employee in charge:

E-mail:

Date and time: 6/18/2019 9:10:01 AM

Vehicle: Forester

VIN: JF1SJ5KCSJG098770

Model: 18MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp		Group	IG counter	FFD
			Trip Count (count)	Time (msec)			
Current	B14A1	Sunload Sensor Circuit Low/Open	02598	21100	Current		

<Keyless Access with Push Button Start : 0 piece>

<Automatic Light and Wiper : 0 piece>

<Combination Meter : 0 piece>

<Multi-function Display : 0 piece>

<Auto Start Stop : 0 piece>

<Headlight / Foglight : 0 piece>

Estimate

Date 05/27/2019

DB1 / 004

Name	QUOTATION FOR SL50807H	Tel(HOME)	
Address		Tel(OFFICE)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ52K7C
		Yrs-Code	JF15J5K6CJG098770

Part Number	Part Code Name	Part Code	Qty	Price	
57709SG030A	BUMPER FACE-FRONT	FIG-590 57704	1	<i>Avr/qr</i> 594.00	✓
57711SG0006P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	288.00	?
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	<i>Bu</i> 128.00	✓
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	<i>Dis</i> 36.00	✓
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	<i>Dis</i> 36.00	✓
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	12.60	?
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	12.60	?
57780SG010	PACKING-BUMPER,RIGHT	FIG-590 57780B	1	9.00	?
57780SG020	PACKING-BUMPER,LEFT	FIG-590 57780C	1	9.00	?
57731SG220	COVER-FRONT BUMPER	FIG-590 57731	1	440	?
53029SG0019P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	360.00	?
91121SG280A	FRONT GRILLE ASSEMBLY,LOWER	FIG-911 91121F	1	<i>fa</i> 316.80	?
91121SG240A	FRONT GRILLE ASSEMBLY,CENTER	FIG-911 91121G	1	<i>cm</i> 180.00	✓
91121SG210A	FRONT GRILLE ASSEMBLY,UPPER	FIG-911 91121E	1	150.90	?
91185SG000	BRACKET-GRILL LOWER	FIG-911 91185JA	1	21.60	?
84002SG222	LAMP ASSEMBLY-HEAD RIGHT	FIG-840 84001A	1	2,380.00	?
		Page-Total		4,536.00	

Memo

Grand Total
22,745.30

--

Tel

Estimate

Date 05 / 27 / 2019

002 / 004

Name	QUOTATION FOR ELBRICH	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	813
		Body Model	SJSEK7C
		Vin-Code	JP15J6K5J0098770

Part Number	Part Code Name	Part Code	Qty	Price	
840025G232	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	2,380.00	?
57229SG0006P	HOOD COMPLETE-FRONT	FIG-550 57220	1	882.00	X
57310SG020	LOCK ASSEMBLY-FRONT HOOD	FIG-550 57310	1	72.00	X
57260SG0006P	HINGE COMPLETE-FRONT HOOD,RIGHT	FIG-550 57260	1	43.20	X
57260SG0106P	HINGE COMPLETE-FRONT HOOD,LEFT	FIG-550 57260A	1	43.20	X
90815SG050	INSULATOR-FRONT HOOD	FIG-956 90815B	1	79.20	X
86636SG380A	COVER ASSEMBLY-LAMP WASHER NOZZLE,RIGHT	FIG-877 86636NA	1	54.00	✓
86636SG361	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	79.20	✓
28111SG130	DISK WHEEL-ALUMINIUM	FIG-290 28111	1	1,500.00	✓
56410SG050	UNDER COVER-FRONT	FIG-572 56410	1	156.40	✓
20101VA010	CROSS MEMBER COMPLETE-FRONT SUSPENSION	FIG-200 20101	1	472.00	?
20401SG000	STABILIZER-FRONT	FIG-200 20401	1	169.20	?
20420XA000	LINK ASSEMBLY-FRONT STABILIZER	FIG-200 20420	2	185.60	?
20202SG000	LOWER ARM ASSEMBLY-FRONT,RIGHT	FIG-200 20202	1	493.20	?
20202SG010	LOWER ARM ASSEMBLY-FRONT,LEFT	FIG-200 20202A	1	493.20	?
20310SG100	STRUT COMPLETE-FRONT RIGHT	FIG-210 20310A	1	262.80	?
		Page-Total		7,347.20	

Memo

Grand Total
22,745.30

--

Tel

Estimate

Date 05/27/2019

003 / 004

Name	QUOTATION FOR SL5600TH	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SUSK70
		Vin-Code	JF15JHCSJG096770

Part Number	Part Code Name	Part Code	Qty	Price	
20310SG110	STRUT COMPLETE-FRONT LEFT	FIG-210 20310B	1	362.80	7
20320FG012	STRUT MOUNT-FRONT	FIG-210 20320	2	144.00	7
20152SG011	✓ FRAME SUB ASSEMBLY-REAR SUSPENSION	FIG-201 20152	1	684.00	7
20451AL000	STABILIZER-REAR	FIG-201 20451	1	126.00	X
20454SC010	BUSHING-STABILIZER	FIG-201 20414	2	21.60	X
20470AJ010	LINK ASSEMBLY-STABILIZER, REAR	FIG-201 20470	2	172.80	7
20252SG001	REAR ARM ASSEMBLY, UPPER RIGHT	FIG-201 20250H	1	432.00	7
20252SG011	REAR ARM ASSEMBLY, UPPER LEFT	FIG-201 20250I	1	432.00	✓
20250AL011	✓ LATERAL LINK ASSEMBLY-REAR	FIG-201 20250	1	126.00	7
20250FG021	✓ LATERAL LINK ASSEMBLY-FRONT	FIG-201 20250F	1	410.40	7
20250FJ001	✓ TRAILING ARM-REAR	FIG-201 20252	1	288.00	7
34110SG050	STEERING GEAR BOX ASSEMBLY, EPS	FIG-347 34110A	1	2,545.20	7
20365SG110	SHOCK ABSORBER-REAR	FIG-211 20365	2	1,641.60	7
20370SG000	STRUT MOUNT-REAR	FIG-211 20370	2	208.80	7
44200SG080	✓ EXHAUST PIPE ASSEMBLY-REAR	FIG-440 44200	1	745.20	X
44300SG010	MUFFLER ASSEMBLY-RIGHT	FIG-440 44300A	1	601.20	?
		Page-Total		8,967.60	

Memo

Grand Total
22,745.30

Tax

Estimate

Name		QUOTATION FOR SL55807H		Date		05 / 27 / 2018		0041004	
Address				Tel(Home)					
				Tel(Office)					
				Tel(Portable)					
				Fax					
E-Mail				Model Name		SL5			
				Body Model		SUBER70			
				Vin-Code		JF1SJBKCSJG098779			

Part Number	Part Code Name	Part Code	Qty	Price
44370FG002	TAIL PIPE CUTTER	FIG-440 44371	1	72.00
26313SC001	HOUSING-FRONT AXLE,RIGHT	FIG-280 26313	1	237.60
26313SC011	HOUSING-FRONT AXLE,LEFT	FIG-280 26313A	1	237.60
26373FL000	HUB COMPLETE-FRONT AXLE	FIG-280 26362	2	331.20
902170049	NUT	FIG-280 N170049	2	21.60
26411SG021	HOUSING ASSEMBLY-REAR AXLE,RIGHT	FIG-281 26411	1	270.00
26411SG031	HOUSING ASSEMBLY-REAR AXLE,LEFT	FIG-281 26411A	1	270.00
26473FL040	HUB UNIT COMPL	FIG-281 26473	2	432.00
902170049	NUT	FIG-281 N170049	2	21.60
		Page-Total		1,893.60
		Sub-Total		22,745.30
		Total		22,745.30
		Tax		0.00
		Grand Total		22,745.30

Memo	Grand Total
	22,745.30

Tel

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SLS6807H	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0219/2019	YEAR: 29-SEP-2017
ENGINE NO: FB20YB14473	CHASSIS NO: JF1SJ5KC5JG098770
DOA: 23/05/2019	TOA: 1610HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRONT PANEL & BONNET	\$1250.00
2.	RESPRAY FRONT BUMPER,FRONT PANEL & BONNET	\$1000.00
3.	TRANSFER / BALANCE TYRE / RIM LH REAR	\$28.00
4.	DISMENTLE & REFIX UNDERCARRAIGE TO FACILITATE REPAIRS	\$684.00
5.	REMOVE/REFIX ESHAUST	\$114.00
6.	WHEEL ALIGNMENT	\$171.00
7.	MECHANICAL REPAIRS- ALTERNATOR,COMPRESSOR, STEERING PUMP	\$171.00
8.	FAULT DIAGNOSTIC	\$235.00
9.	TO CONDUCT PROTECTANT COATING	\$750.00
10.	TO CONDUCT ANTI RUST COATING	\$290.00
11.	SUNDRIES	\$100.00
12.	REMOVE/REFIX FRT HEADLAMP WAHSE & PIPING	\$125.00
	Total Labour	\$4918.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Henrich CLKK
HP / EMAIL:	
BEFORE PAINT:	Yes
DAYS GIVEN:	8-9 days

Not Authorised
The very Bk paint
Excess TBA

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255

Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535

25 Leng Kee Road Singapore 159097

Service Centre Tel: (65) 6703 8163 Fax : (65) 6479 1137

Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9

Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER**Invoice No: L509345****For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.****DATE REC'D: 06-Jun-2019****SERVICE ADVISOR: HOOI****JOB No.: L502351****MILEAGE: 13704****ID:**

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20YB14473
CHASSIS No.: JF1SJ5KCSJG098770
REGISTRATION No.: SLS6807H

ITEMS	CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODCLAI	CONDUCT BODYWORK REPAIR (OWN DAMAGE CLAIM)	
2	REMARK	CONDUCT OD CLAIM AIG DATE:23/05/2019 TIME:1610HRS LOCATION:150 LORONG KISMIS S (598076)	
3	INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338).	
5	INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
7	INS06	THE OWNER IS REQUIRED.	
8	INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
9	INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
10	INS09	CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
11	INS04	SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
12	REMARK	REPAIR/REPLACE FRONT BUMPER & FRONT PANEL	750.00
13	REMARK	RESPRAY FRONT BUMPER AND PANEL	600.00
14	REMARK	TRANSFER/BALANCE/RIM LH REAR	28.00
15	REMARK	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIR	684.00
16	REMARK	TO CONDUCT 4 WHEEL ALIGNMENT	171.00
17	REMARK	TO CONDUCT FAULY DIAGNOSTIC AND RESET SYSTEMS	235.00
18	REMARK	CONDUCT PROTECTANT COATING	280.00
19	REMARK	SUNDRIES	30.00

Certified True Copy

**Motor Image Enterprises Pte Ltd**

19 Lorong 8 Toa Payoh Singapore 319255
 Service Centre Tel (65) 64170100/101 Fax (65) 62535535
 25 Leng Kee Road Singapore 159097
 Service Centre Tel (65) 64764776 Fax (65) 64791137
 Website: www.motorimage.net

**TAX INVOICE**

GST Reg No. M2-0076975-9
 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER**Invoice No: L509345**

**For cash sales, payment will be
 endorsed on this invoice and no
 separate receipt will be issued.**

DATE REC'D: 06-Jun-2019**SERVICE ADVISOR: HOOI****JOB No.: L502351****MILEAGE: 13704****ID:**

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
 #07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20YB14473
CHASSIS No.: JF1SJ5KCSJG098770
REGISTRATION No.: SLS6807H

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
20	REMARK REFIX & REMOVE AIRCOND CONDENSER & RADIATOR	171.00
21	REMARK REFIX & REMOVE WIRE HARNESS	230.00
22	REMARK REMOVE & REFIX EXHAUST	114.00
23	REMARK REMOVE/REFIX FRONT HEADLAMP WASHER AND PIPING	125.00
	TOTAL(LABOUR)	3,418.00
1	SUB FRAME ASSY R AWD	478.80
	20152SG011(Qty : 1 @ 684.00 each(Discount 30.00%))	
2	LINK ASSY R LAT R	88.20
	20250AL011(Qty : 1 @ 126.00 each(Discount 30.00%))	
3	LINK ASSY R LAT F	143.64
	20250FG021(Qty : 1 @ 205.20 each(Discount 30.00%))	
4	TRAILING ARM-REAR	100.80
	20250FJ001(Qty : 1 @ 144.00 each(Discount 30.00%))	
5	ARM ASSY R UPR LH	302.40
	20252SG011(Qty : 1 @ 432.00 each(Discount 30.00%))	
6	DISC WHEEL AL 17	1,050.00
	28111SG130(Qty : 1 @ 1500.00 each(Discount 30.00%))	
7	EXH PIPE ASSY R	521.64
	44200SG080(Qty : 1 @ 745.20 each(Discount 30.00%))	
8	UNDER COVER COM FNA	110.88
	56410SG050(Qty : 1 @ 158.40 each(Discount 30.00%))	
9	BRKT CORNER F RH	25.20
	57707SG000(Qty : 1 @ 36.00 each(Discount 30.00%))	
10	BRKT CORNER F LH	25.20
	57707SG010(Qty : 1 @ 36.00 each(Discount 30.00%))	
11	FRT BUMPER	415.80
	57709SG030A(Qty : 1 @ 594.00 each(Discount 30.00%))	
12	ENERGY ABSOR F	88.20

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
Service Centre Tel (65) 64170100/101 Fax (65) 62535535
25 Leng Kee Road Singapore 159097
Service Centre Tel (65) 64764776 Fax (65) 64791137
Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9
Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L509345

**For cash sales, payment will be
endorsed on this invoice and no
separate receipt will be issued.**

DATE REC'D: 06-Jun-2019

SERVICE ADVISOR: HOOI

JOB No.: L502351

MILEAGE: 13704

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD
ADDRESS: 78 SHENTON WAY
#07-16 AIG BUILDING. S(079120)
TELEPHONE: 91007211
MODEL: FORESTER 2.0I-L AWD CVT
ENGINE No.: FB20YB14473
CHASSIS No.: JF1SJ5KC5JG098770
REGISTRATION No.: SLS6807H

ITEMS CODE	DESCRIPTION OF REPAIRS	AMOUNT
13	57722SG020(Qty : 1 @ 126.00 each(Discount 30.00%)) COVER HOOK F STD	3.08
14	57731SG220(Qty : 1 @ 4.40 each(Discount 30.00%)) PACKING RAD	6.30
15	57780SG020(Qty : 1 @ 9.00 each(Discount 30.00%)) NOZZLE H L WASHER LH	55.44
16	86636SG371(Qty : 1 @ 79.20 each(Discount 30.00%)) NOZZLE COVER ASSY RH	37.80
17	86636SG380A(Qty : 1 @ 54.00 each(Discount 30.00%)) GRILLE ASSY F CTRHG	126.00
	91121SG240A(Qty : 1 @ 180.00 each(Discount 30.00%)) TOTAL(SPARE PARTS)	3,579.38
	less INSURANCE EXCESS	1,000.00

Subtotal 5,997.38
GST(7%) 419.82
TOTAL \$6,417.20

DATE : 07-Jan-2020

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh Singapore 319255
T (65) 6417 0333 F (65) 6252 5655
W www.motorimage.net
Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured: **WANG ZHAOYUN**
Address of Insured: **BLK 289D BUKIT BATOK STREET 25 #17-170 S(653289)**
Name of Repairs: **MOTOR IMAGE ENTERPRISES PTE LTD / WORKSHOP**
Address of Repairs: **NO. 19 LORONG 8 TOA PAYOH SINGAPORE 319225**
Place of Accident: **150 LORONG KISMIS S(598076)**
Date of Accident: **23/05/2019** Vehicle No: **SLS6807H**
Policy No: **1700052708-01** Claim No: _____

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of **AIG ASIA PACIFIC INSURANCE PTE LTD** settling the repair costs stated above with the said repairers, I/We hereby release and discharge the said insurers from all further obligations and liabilities under the aforesaid policy in respect on and accident involving my/our said motor vehicle on or about the abovementioned date and place.

I/We agree that by virtue of such payment, all my/our rights and remedies in respect of the damages to the said Motor Vehicle are subrogated to the said Insurers in accordance with the laws governing such matters.

I/We hereby grant the said insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefore.
I/We further agree to furnish the said Insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their parts they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:

Company's Chop & Signature

DANIEL A JUDE

Name

19/06/2019

Date

INSURED:

S7281116Z

IC No. & Signature/Company's Chop

WANG ZHAOYUN

Name

19/06/2019

Date

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #08-16
CHARTIS BUILDING

SINGAPORE 079120

INV No. AC2001896
INV Date 05/03/2020
Reference CS/AIG19009530/Ktd3e2
Code AIG

**PROFESSIONAL SERVICE FEE**

Vehicle No. SLS 6807H
Insured Veh.
Claim No. 3560495666SG
Policy No. 1700052708-01
Accident Date 23/05/2019
Inspection Date 29/05/2019

AIG OD Express

Description	Total
Survey Inspection	200.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Subtotal	211.00
GST (7%)	14.77
Grand Total	225.77

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019		29 May 2019 17:34 Edit Adj Rpt	\$46,997.38 Edit Estimates	\$46,997.38 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	WANG ZHAOYUN, ID: S7281116Z, Tel: +6590090856, Email: LAVENDERYUN@HOTMAIL.COM								
Vehicle Reg. No.:	SLS6807H	Date of Loss:	23/05/2019 16:00 - :59 [19 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 3560495666SG	Policy/Cover Note No.:	1700052708-01 (Comprehensive)						
		Excess:	\$1,000.00						
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/06/2019]								
Driver/Custodian:	WANG ZHAOYUN (46 / Female) , NRIC: S7281116Z, Tel: +6590090856 Email: LAVENDERYUN@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/12/2019): Alert - Adj Mandate Approved (\$46997.38) - SLS6807H - Claim Handler: Gan, Hunchu... - AIG_SG (06/06/2019): Alert - Adj Mandate Approved (\$5016.00) - SLS6807H - Claim Handler: Gan, Hunchu... - AIG_SG (06/06/2019): Alert - Adj Mandate Approved (\$5016.00) - SLS6807H - Claim Handler: Gan, Hunchu... - AIG_SG (04/06/2019): SLS6807H / OD / 23/05/2019 / Coverage & Excess update - AIG_SG (04/06/2019): SLS6807H / OD / 23/05/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS6807H (3560495666SG)**
OD
May 23 2019 4:10PM
[WANG ZHAOYUN]
Motor Image Enterprises Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		☒			
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)												Thumbnail		Print				
1	24/05/19 16:01	Video - Accident [Linked Accident Report Documents]													Load MP4					
2	24/05/19 16:01	Video - Accident [Linked Accident Report Documents]													Load MP4					
3	24/05/19 16:02	Video - Accident [Linked Accident Report Documents]													Load MP4					
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	30/05/19 15:03	Adjuster Immediate Advice													Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	30/05/19 13:16	General View													Load JPG	☒				
2	30/05/19 13:16	General View													Load JPG	☒				
3	30/05/19 13:16	General View													Load JPG	☒				
4	30/05/19 13:16	General View													Load JPG	☒				
5	30/05/19 13:16	General View													Load JPG	☒				
6	30/05/19 13:16	General View													Load JPG	☒				
7	30/05/19 13:16	General View													Load JPG	☒				
8	30/05/19 13:16	General View													Load JPG	☒				
9	30/05/19 13:16	General View													Load JPG	☒				
10	30/05/19 13:16	General View													Load JPG	☒				
11	30/05/19 13:16	General View													Load JPG	☒				
12	30/05/19 13:16	General View													Load JPG	☒				
13	30/05/19 13:16	General View													Load JPG	☒				
14	30/05/19 13:16	General View													Load JPG	☒				
15	30/05/19 13:16	General View													Load JPG	☒				
16	30/05/19 13:16	General View													Load JPG	☒				
17	30/05/19 13:16	General View													Load JPG	☒				
18	30/05/19 13:16	General View													Load JPG	☒				
19	30/05/19 13:16	General View													Load JPG	☒				
20	30/05/19 13:16	General View													Load JPG	☒				
21	30/05/19 13:16	General View													Load JPG	☒				
22	30/05/19 13:16	General View													Load JPG	☒				
23	30/05/19 13:16	General View													Load JPG	☒				
24	30/05/19 13:16	General View													Load JPG	☒				
25	30/05/19 13:16	General View													Load JPG	☒				
26	30/05/19 13:16	General View													Load JPG	☒				
27	30/05/19 13:16	General View													Load JPG	☒				
28	30/05/19 13:16	General View													Load JPG	☒				
29	27/11/19 09:30	Reinspection Photo													Load JPG					

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
				☒
30	27/11/19 09:30	Reinspection Photo	Load JPG	☒
31	27/11/19 09:30	Reinspection Photo	Load JPG	☒
32	27/11/19 09:30	Reinspection Photo	Load JPG	☒
33	27/11/19 09:30	Reinspection Photo	Load JPG	☒
34	27/11/19 09:30	Reinspection Photo	Load JPG	☒
35	27/11/19 09:30	Reinspection Photo	Load JPG	☒
36	27/11/19 09:30	Reinspection Photo	Load JPG	☒
37	27/11/19 09:30	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	24/02/20 10:57	Repairer's Bill	Load PDF	
2	24/02/20 11:17	Signed DV	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/19 13:17	Certificate of Insurance	Load PDF	
2	30/05/19 13:17	estimate	Load PDF	
3	30/05/19 13:17	Singapore Accident Statement	Load PDF	
4	04/06/19 09:03	UNDERTAKING LETTER	Load PDF	
5	04/06/19 09:03	INTERVIEW FORM	Load PDF	
6	27/11/19 09:38	estimate and supplementary	Load PDF	
7	05/03/20 10:31	Workshop Invoice	Load PDF	
8	05/03/20 10:31	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	24/05/19 16:01	Video - Accident	Load MP4	
2	24/05/19 16:01	Video - Accident	Load MP4	
3	24/05/19 16:02	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	04/09/19 01:04	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	24/05/19 15:59	Accident Photo	Load JPG	☒
2	24/05/19 15:59	Accident Photo	Load JPG	☒
3	24/05/19 15:59	Accident Photo	Load JPG	☒
4	24/05/19 15:59	Accident Photo	Load JPG	☒
5	24/05/19 15:59	Accident Photo	Load JPG	☒
6	24/05/19 15:59	Accident Photo	Load JPG	☒
7	24/05/19 15:59	Accident Photo	Load JPG	☒
8	24/05/19 15:59	Accident Photo	Load JPG	☒
9	24/05/19 15:59	Accident Photo	Load JPG	☒
10	24/05/19 15:59	Accident Photo	Load JPG	☒
11	24/05/19 15:59	Accident Photo	Load JPG	☒
12	24/05/19 15:59	Accident Photo	Load JPG	☒
13	24/05/19 15:59	Accident Photo	Load JPG	☒
14	24/05/19 15:59	Accident Photo	Load JPG	☒
15	24/05/19 15:59	Accident Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
16	24/05/19 15:59	Accident Photo	 Load JPG	☒
17	24/05/19 15:59	Accident Photo	 Load JPG	☒
18	24/05/19 15:59	Accident Photo	 Load JPG	☒
19	24/05/19 15:59	Accident Photo	 Load JPG	☒
20	24/05/19 15:59	Accident Photo	 Load JPG	☒
21	24/05/19 15:59	Accident Photo	 Load JPG	☒
22	24/05/19 15:59	Accident Photo	 Load JPG	☒
23	24/05/19 15:59	Accident Photo	 Load JPG	☒
24	24/05/19 15:59	Accident Photo	 Load JPG	☒
25	24/05/19 15:59	Accident Photo	 Load JPG	☒
26	24/05/19 15:59	Accident Photo	 Load JPG	☒
27	24/05/19 15:59	Accident Photo	 Load JPG	☒
28	24/05/19 15:59	Accident Photo	 Load JPG	☒
29	24/05/19 15:59	Accident Photo	 Load JPG	☒
30	24/05/19 15:59	Accident Photo	 Load JPG	☒
31	24/05/19 15:59	Accident Photo	 Load JPG	☒
32	24/05/19 15:59	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thumbnail	Print
1	24/05/19 16:57	Accident Sketch Plan	 Load JPG	☒
2	24/05/19 16:57	Accident Sketch Plan	 Load JPG	☒
3	24/05/19 16:57	INSURANCE CERT	 Load JPG	☒
4	24/05/19 16:57	OWNER LICENSE AND NRIC	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG19009530/KTD3E2

Date: 05/03/2020

REFERENCE

Insured/Claimant: WANG ZHAOYUN Policy No: 1700052708-01
Date of Loss: 23/05/2019 Nature of Claim: OD Claim No: 3560495666SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS6807H**
Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20YB14473
Reg. Date: 29/09/2017 (Man. Year: 2017) Chassis No: JF1SJ5KC5JG098770
Colour: Metallic Dark Grey Odometer: 13697 km
Engine Capacity: 1995 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,114.95	3,609.38	12,505.57	77.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,219.00	3,388.00	1,831.00	35.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,333.95	6,997.38	14,336.57	67.20
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	20,333.95	5,997.38	14,336.57	70.51
+ GST 7.00/7.00% (S\$)	1,423.38	419.82	1,003.56	70.51
Nett Amount (S\$)	21,757.33	6,417.20	15,340.13	70.51

INSPECTION

Date of Assignment: 29/05/2019

Date Inspected: 29/05/2019 Inspected At:

Motor Image Enterprises Pte Ltd (Toa Payoh)
19 Lorong 8 Toa Payoh
Singapore 319255

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*BUMPER FACE-FRONT	Buckled / Cracked	594.00 FL	*594.00 FL
3	1		*BACK BEAM COMPLETE - FRONT	Repair	288.00 FL	*- FL
4	1		*ENERGY ABSORBER - FRONT BUMPER	Buckled	126.00 FL	*126.00 FL
5	1		*BRACKET - FRONT BUMPER CORNER, RIGHT	Distorted	36.00 FL	*36.00 FL
6	1		*BRACKET - FRONT BUMPER CORNER, LEFT	Distorted	36.00 FL	*36.00 FL
7	1		*BRACKET - FRONT BUMPER SIDE, RIGHT	Serviceable	12.60 FL	*- FL
8	1		*BRACKET - FRONT BUMPER SIDE, LEFT	Serviceable	12.60 FL	*- FL
9	1		*PACKING-BUMPER, RIGHT	Serviceable	9.00 FL	*- FL
10	1		*PACKING-BUMPER, LEFT	Necessary	9.00 FL	*9.00 FL
11	1		*COVER-FRONT BUMPER	Necessary	4.40 FL	*4.40 FL
12	1		*PANEL COMPLETE-RADIATOR	Repair	360.00 FL	*- FL
13	1		*FRONT GRILLE ASSEMBLY, LOWER	Serviceable	316.80 FL	*- FL
14	1		*FRONT GRILLE ASSEMBLY, CENTER	Cracked	180.00 FL	*180.00 FL
15	1		*FRONT GRILLE ASSEMBLY, UPPER	Serviceable	150.90 FL	*- FL
16	1		*BRACKET, GRILL LOWER	Serviceable	21.60 FL	*- FL
17	1		*LAMP ASSEMBLY-HEAD RIGHT	Serviceable	2,380.00 FL	*- FL
18	1		*LAMP ASSEMBLY-HEAD LEFT	Serviceable	2,380.00 FL	*- FL
19	1		*HOOD COMPLETE - FRONT	Repair	882.00 FL	*- FL
20	1		*LOCK ASSEMBLY - FRONT HOOD	Repair	72.00 FL	*- FL
21	1		*HINGE COMPLETE - FRONT HOOD, RIGHT	Repair	43.20 FL	*- FL
22	1		*HINGE COMPLETE - FRONT HOOD, LEFT	Repair	43.20 FL	*- FL
23	1		*INSULATOR-FRONT HOOD	Serviceable	79.20 FL	*- FL
24	1		*COVER ASSEMBLY-LAMP WASHER NOZZLE, RIGHT	Serviceable	54.00 FL	*- FL
25	1		*NOZZLE-LAMP WASHER, RIGHT	Serviceable	79.20 FL	*- FL
26	1		*DISK WHEEL - ALUMINIUM	Dented	1,500.00 FL	*1,500.00 FL
27	1		*UNDER COVER - FRONT	Dented	158.40 FL	*158.40 FL
28	1		*CROSS MEMBER COMPLETE - FRONT SUSPENSION	Serviceable	472.00 FL	*- FL
29	1		*STABILIZER - FRONT	Serviceable	169.20 FL	*- FL
30	2		*LINK ASSEMBLY - FRONT STABILIZER	Serviceable	165.60 FL	*- FL
31	1		*LOWER ARM ASSEMBLY-FRONT, RIGHT	Serviceable	493.20 FL	*- FL
32	1		*LOWER ARM ASSEMBLY-FRONT, LEFT	Serviceable	493.20 FL	*- FL
33	1		*STRUT COMPLETE-FRONT RIGHT	Serviceable	262.80 FL	*- FL
34	1		*STRUT COMPLETE-FRONT LEFT	Serviceable	262.80 FL	*- FL
35	2		*STRUT MOUNT - FRONT	Serviceable	144.00 FL	*- FL
36	1		*FRAME SUB ASSEMBLY - REAR SUSPENSION	Bent	684.00 FL	*684.00 FL
37	1		*STABILIZER - REAR	Serviceable	126.00 FL	*- FL
38	2		*BUSHING - STABILIZER	Serviceable	21.60 FL	*- FL
39	2		*LINK ASSEMBLY - STABILIZER, REAR	Serviceable	172.80 FL	*- FL
40	1		*LATERAL LINK ASSEMBLY-REAR (2PCS)	Distorted (1Pc Only)	252.00 FL	*126.00 FL
41	1		*LATERAL LINK ASSEMBLY-FRONT (2PCS)	Distorted (1Pc Only)	410.40 FL	*205.20 FL
42	1		*TRAILING ARM-REAR (2PCS)	Bent (1Pc Only)	288.00 FL	*144.00 FL
43	1		*STEERING GEAR BOX ASSEMBLY, EPS	Serviceable	2,545.20 FL	*- FL
44	2		*SHOCK ABSORBER-REAR	Serviceable	1,641.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*STRUT MOUNT-REAR	Serviceable	208.80 FL	*- FL
46	1		*EXHAUST PIPE ASSEMBLY-REAR	Bent	745.20 FL	*745.20 FL
47	1		*MUFFLER ASSEMBLY-RIGHT	Serviceable	601.20 FL	*- FL
48	1		*TAIL PIPE CUTTER	Serviceable	72.00 FL	*- FL
49	1		*HOUSING-FRONT AXLE, RIGHT	Serviceable	237.60 FL	*- FL
50	1		*HOUSING-FRONT AXLE, LEFT	Serviceable	237.60 FL	*- FL
51	2		*HUB COMPLETE-FRONT AXLE	Serviceable	331.20 FL	*- FL
52	2		*NUT	Serviceable	21.60 FL	*- FL
53	1		*HOUSING ASSEMBLY-REAR AXLE, RIGHT	Serviceable	270.00 FL	*- FL
54	1		*HOUSING ASSEMBLY-REAR AXLE, LEFT	Serviceable	270.00 FL	*- FL
55	2		*HUB UNIT COMPL	Serviceable	432.00 FL	*- FL
56	2		*NUT	Serviceable	21.60 FL	*- FL
57	1		*NOZZLE H L WASHERLH	Missing	79.20 FL	*79.20 FL
58	1		*NOZZLE COVER ASSY RH	Missing	54.00 FL	*54.00 FL
59	1		*REAR ARM ASSEMBLY, UPPER RIGHT	Serviceable	432.00 FL	*- FL
60	1		*REAR ARM ASSEMBLY, UPPER LEFT	Bent	432.00 FL	*432.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **22,978.50** **5,143.40**
 - List Item Discount on L Items 30.00/30.00% (S\$) 6,863.55 1,534.02

Total Parts (S\$) **16,114.95** **3,609.38**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR / REPLACE FRONT BUMPER, FRONT PANEL & BONNET	New	1,250.00	750.00
2	RESPRAY FRONT BUMPER, FRONT PANEL & BONNET	New	1,000.00	600.00
3	TRANSFER / BALANCE TYRE / RIM LH REAR	New	28.00	28.00
4	DISMENTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	New	684.00	684.00
5	REMOVE / REFIX EXHAUST	New	114.00	114.00
6	WHEEL ALIGNMENT	New	171.00	171.00
7	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	New	171.00	0.00
8	FAULT DIAGNOSTIC	New	235.00	235.00
9	TO CONDUCT PROTECTANT COATING	New	750.00	280.00
10	TO CONDUCT ANTI RUST COATING	New	290.00	0.00
11	REMOVE / REFIX FRT HEADLAMP WASHER / PIPING	New	125.00	125.00
12	REFIX & REMOVE AIRCOND CONDENSOR & RADIATOR	New	171.00	171.00
13	REFIX & REMOVE WIRE HARDNESS	New	230.00	230.00
Gross Labour Cost (S\$)			5,219.00	3,388.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >