

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SJS3588H	MODEL : FORESTER 2.0XT AWD CVT
REF NO:INS/IC/CHI/0218/2019	YEAR: 24-APR-2017
ENGINE NO: FA20B961316	CHASSIS NO: JF1SJGK85HG087226
DOA: 25/05/2019	TOA: 2217HRS
TYPE OF CLAIM: OD REC	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER & FRONT PANEL <i>3751</i>	\$1000.00
2.	RESPRAY FRONT BUMPER & FRONT PANEL <i>4001</i>	\$800.00
3.	TO CONDUCT FRONT LIGHTING TEST	\$28.00 ✓
4.	SUNDRIES	\$100.00 ?
5.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING <i>na</i>	\$125.00 ✓
6.		
7.		
8.		
9.		
10.		
	Total Labour	\$2053.00

DATE APPROVAL:	<i>29/5/19</i>
TIME APPROVAL:	<i>11.10am</i>
SURVEY BY:	<i>Kenneth (UKK)</i>
HP / EMAIL:	<i>1</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	<i>3 days</i>

Authorised
Resurvey B4 paint
Excess TBA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate

Date 05 / 28 / 2019

001 / 002

Name	QUOTATION FOR SJS3588H	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJGGKK8
		Vin-Code	JF1SJGK85HG087226

Part Number	Part Code Name	Part Code	Q'ty	Price	
57709SG011	BUMPER FACE-FRONT	FIG-590 57704	1	<i>594.00</i> 594.00	✓
57711SG0009P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	<i>288.00</i> 288.00	X
57722SG020	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	<i>126.00</i> 126.00	X
57707SG000	BRACKET-FRONT BUMPER CORNER,RIGHT	FIG-590 57707AF	1	<i>36.00</i> 36.00	X
57707SG010	BRACKET-FRONT BUMPER CORNER,LEFT	FIG-590 57707AG	1	<i>36.00</i> 36.00	✓
57707SG020	BRACKET-FRONT BUMPER SIDE,RIGHT	FIG-590 57707F	1	<i>12.60</i> 12.60	X
57707SG030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	12.60	7
57731SG090	COVER-FOG LIGHT,LEFT	FIG-590 84953O	1	<i>43.20</i> 43.20	✓
57731SG130	COVER-FRONT BUMPER,LEFT	FIG-590 57731B	1	12.60	7
84501AJ060	FOG LIGHT ASSEMBLY-FRONT	FIG-845 84501B	1	<i>272.00</i> 272.00	X
86636SG340V2	COVER ASSEMBLY-LAMP WASHER NOZZLE,RIGHT	FIG-877 86636NA	1	<i>54.00</i> 54.00	X
86636SG350V2	COVER ASSEMBLY-LAMP WASHER NOZZLE,LEFT	FIG-877 86636OA	1	<i>54.00</i> 54.00	X
86636SG361	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	<i>79.20</i> 79.20	X
86636SG371	NOZZLE-LAMP WASHER,LEFT	FIG-877 86636O	1	<i>79.20</i> 79.20	X
86636SG000	NOZZLE-WINDSHIELD WASHER	FIG-875 86636D	2	<i>57.60</i> 57.60	X
53029SG0019P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	<i>360.00</i> 360.00	X
		Page-Total		2,117.00	

Memo

Grand Total
2,135.00

--

Tel

Estimate

Date 05 / 28 / 2019

002 / 002

Name	QUOTATION FOR SJS3588H	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJGGKK8
		Vin-Code	JF1SJGK85HG087226

Part Number	Part Code Name	Part Code	Q'ty	Price
57780SG010	PACKING-BUMPER,RIGHT	FIG-590 57780B	1	<i>an</i> 9.00
57780SG020	PACKING-BUMPER,LEFT	FIG-590 57780C	1	9.00
		Page-Total		18.00
		Sub-Total		2,135.00
		Total		2,135.00
		Tax		0.00
		Grand Total		2,135.00

X
7

Memo

Grand Total
2,135.00

4188

--

Tel
