

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMF5178C	MODEL : FORESTER 2.0I-L AWD CVT
REF NO:INS/IC/CHI/0213/2019	YEAR: 15-NOV-2018
ENGINE NO: FB20YE39707	CHASSIS NO: JF1SJ5KC5JG112524
DOA: 19/05/2019	TOA: 1655HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER & END PANEL	\$1000.00
2.	RESPRAY REAR BUMPER & END PANEL	\$800.00
3.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	\$300.00
4.	SUNDRIES	\$100.00
5.		
6.		
7.		
8.		
9.		
10.		
	Total Labour	\$2200.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	<i>Kenneth</i>
HP / EMAIL:	<i>/</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	<i>03</i>

Not with air
Re-spray B & paint

Estimate

Date 05 / 22 / 2019

001 / 001

Name	QUOTATION FOR SMF5178C	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5KC5JG112524

Part Number	Part Code Name	Part Code	Q'ty	Price
57704SG012	BUMPER-FACE,REAR	FIG-591 57704A	1	13 / 540.00 ✓
57711SG0219P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	1 / 288.00 7 (PHOTO)
57707SG080	BRACKET-REAR BUMPER SIDE,RIGHT	FIG-591 57707H	1	12 14.40 X
57707SG090	BRACKET-REAR BUMPER SIDE,LEFT	FIG-591 57707I	1	12 14.40 X
57707SG070	BRACKET-REAR BUMPER CORNER,LEFT	FIG-591 57707AD	1	12 18.00 X
57707SG060	BRACKET-REAR BUMPER CORNER,RIGHT	FIG-591 57707AC	1	12 18.00 X
57731SG010NN	COVER-REAR BUMPER	FIG-591 57731C	1	12 12.60 X
E7710SG000	R BUMPER STEP S/S	FIG-591 57711D	1	un 460.00 X
84281SC010	REFLEX REFLECTOR ASSEMBLY-LEFT	FIG-842 84281A	1	12 20.40 X
84281SC000	REFLEX REFLECTOR ASSEMBLY-RIGHT	FIG-842 84281	1	12 20.40 X
		Page-Total		1,406.20
		Sub-Total		1,406.20
		Total		1,406.20
		Tax		0.00
		Grand Total		1,406.20

Memo

Grand Total
1,406.20

--

Tel
