

ASS. REC. BY:

REF:

CS/FCI19009541/At3

n2

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person):

Sitham

of

FCI

Date/Time: 28/5/19 @ 5:45pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GZ 7690S

Insured:

SHC7221Y

at Workshop m/s

N-Si Automofix

Tel:

68420051

of

2 laka Bukit Ave 2 # 01-18

Policy No:

Claim No:

D19003452 MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/05/2019

CA / REV / REP. / REV 24 HRS

cup

30/5/19

H.O.D. Endorsement:

Date/Time:

10.25 am @ 29/5/19

Person Contacted:

Zitiny

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X) Arrive on 30/5/19

call more than 3 times, Nkr In town Car In or not In. at last

call again on 5:25pm say Car In. so arrange tomorrow.

GZ7690S-NA/CTI19009541/24

D.O.A. 24/5/19

SHC7221Y-NA/CTI19009541/24

D.O.A. 24/5/19

lump sum \$6300/- (Red: 5329.43, 45%)

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

D / TF / WS / TP RES / OD RES / EVA / INV / MV

o Inspect Vehicle No: _____

t Workshop m/s: _____

f: _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

DAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: 627690S Yr Regn: 2006 August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c 2986

Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading: 640309 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTFUF34A03012185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C Yoko

R: 155 R15C Toray

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 30/05/19

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

COE Expiry: 28/08/21

MV 17K

LV 10321

NV: 6618

MV: 17K

PV: 10.4K

Nett: 6.6K

RECEIVED 17 SEP 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 1719 Typist

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1701.15
50
10
78
363

MOTOR SURVEY ASSIGNMENT

Date	27-05-2019	Our Ref No. D19003452MFSH
Accident Date	24-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7221Y	Third Party Vehicle. GZ7690S
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



- Need Advice on Tyres Change
- Arsenal Fans Fall in here... SEDIA..
- Hokkaido Summer Holidays

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

3/2012 Volvo Xc90 2.5 T5 @ 66800

Car In Supreb Condition, No Repaid Needed, Safer SUV / MPV 7 Seater In Town.
Bellamy Trading StarAd

PRIME MOTOR & LEASING

ICHANG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category Save Search Print « Back (1 2 3) Next » Sort by Date Posted 20 results/page

51 vehicles		Search		Dyna		Advanced Search		Search		View All							
Make		Model		Price		Depreciation		Reg Date		Eng Cap		Mileage		Veh Type		Status	
Search Selection		Dyna		Any		Any		> 10 year(s) old		Any		Any		Any		Available	



☐ **Toyota Dyna 150 3.0M (COE till 05/2024)** \$25,800 \$5,150 /yr 27-Dec-2002 2,986 cc - Truck Available

Fuel Type: Diesel

Don't Miss! Class 3 Box Lorry! New 5 Years COE! Cheapest In The Market! No Need To Repair! New 6 Months Road Tax! Box Height (6 1/2 Feet), Excellent Condition With 2 Sliding Door, Price Still Can Nego...

Posted: 30-May-2019 Tags: 2002 Toyota Dyna, 2002 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 07/2023)** \$21,888 \$5,300 /yr 16-Jul-2003 2,986 cc 385,891 km Truck Available

Fuel Type: Diesel

Car In Good Working Condition And Maintenance Is Done By Rms Ray Motorsports. Car Loan Is Available And Car Is Good For New Start Up Company For Transports Goods And Air Con Is Cold. Pm Us For Viewing...

Posted: 08-May-2019 Tags: 2003 Toyota Dyna, 2003 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 03/2024)** \$26,638 \$5,610 /yr 10-Mar-2004 2,986 cc - Truck Available

Fuel Type: Diesel

100% In House Loan Available. View To Believe! Don't Miss, Call Today!

Posted: 02-Apr-2019 Tags: 2004 Toyota Dyna, 2004 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (New 5-yr COE)** \$33,800 \$6,750 /yr 03-Mar-2005 2,986 cc - Truck Available

Fuel Type: Diesel

6.5 Feet Box With Power Tailgate. New Paintwork. Excellent Condition. Doorstep Viewing Can Be Arranged For Test Drive. Hurry Call Now!

Net Link Partners Pte Ltd

Posted: 24-May-2019 Tags: 2005 Toyota Dyna, 2005 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ **Toyota Dyna 150 3.0M (COE till 12/2021)** \$27,800 \$10,960 /yr 12-Dec-2006 2,982 cc - Truck Available

Fuel Type: Diesel

\$10,880 COE Rebate After Usage! Free 6 Months Road Tax And Inspection!. Value For Money. High Trade In And High Loan Possible! Call Now For An No Obligations Discussion! Door Step Viewing Possible!

Net Link Partners Pte Ltd

Posted: 14-May-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ **Toyota Dyna 150 3.0M (COE till 12/2021)** \$19,800 \$7,800 /yr 12-Dec-2006 2,982 cc - Truck Available

Fuel Type: Diesel

Very Well Maintained By Previous Owner. No Repairs Needed. Paint Work And Servicing All Done Up. Own This With Peace Of Mind.

Posted: 06-Apr-2019 Tags: 2006 Toyota Dyna, 2006 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

SHORTLISTED HISTORY

Compare



☐ Toyota Dyna 100 3.0M (COE till 04/2022) \$19,998 \$6,980 /yr 11-Apr-2007 2,982 cc - Truck Available

Fuel Type: Diesel

Best Assurance! 1 Year Warranty! Lowest Pricing In Market! New Paintwork And Leather Seats, Smooth Engine And Gear Box. Regular Maintained. Just Change Gearbox No Repairs Needed! Selling \$21,998, Easy...

CarQuotz Singapore

★ Posted: 30-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 05/2022) \$22,800 \$7,710 /yr 14-May-2007 2,982 cc - Truck Available

Fuel Type: Diesel

Good Condition. Negotiable.

CREAT OWNER

★ Posted: 26-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 07/2022) \$22,800 \$7,190 /yr 14-Aug-2007 2,982 cc - Truck Available

Fuel Type: Diesel

Toyota Dyna Box Lorry! Cheapest In The Market! No Need To Repair! Cold Airco! Box Height (6 1/2 Feet), Excellent Condition With 2 Sliding Door, Super Hi Trade-In! Loan Up To 100% Price Still Can Negoti...

PREMIUM AD

ABWIN Bus Pte Ltd

★ Posted: 30-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 08/2022) \$21,800 \$6,740 /yr 24-Aug-2007 2,982 cc - Truck Available

Fuel Type: Diesel

★ Posted: 24-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



That's a fine looking car interior

Customise your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.

Find out more!



☐ Toyota Dyna 150 3.0M (COE till 08/2022) \$22,800 \$7,000 /yr 03-Sep-2007 2,982 cc 272,000 km Truck Available

Fuel Type: Diesel

Think One Automobile & Trading

★ Posted: 23-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 08/2022) \$24,800 \$7,610 /yr 14-Sep-2007 2,982 cc - Truck Available

Fuel Type: Diesel

1 Owner Only. No Repairs Needed. Price Negotiable, High Loan With Low Interest Available, High Trade In. Contact Our Friendly Sales People For A Service You Will Never Forget! Book Your Appointment No...

PREMIUM AD

SG Motor Link Pte Ltd

★ Posted: 27-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 08/2022) \$22,300 \$6,850 /yr 28-Sep-2007 2,982 cc - Truck Available

Fuel Type: Diesel

PREMIUM AD

★ Posted: 19-Apr-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 10/2022) \$24,800 \$7,280 /yr 26-Oct-2007 2,982 cc - Truck Available

Fuel Type: Diesel

Good Condition Used Toyota Dyna With Box For Sale. New Paintwork, Interior Upholstery And Sliding Doors On Both Side Of Box. Loan Available. Contact Us Right Now To View!

I-Deal Auto Trading Pte Ltd

★ Posted: 24-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 150 3.0M (COE till 10/2022) \$24,800 \$7,260 /yr 29-Oct-2007 2,982 cc - Truck Available

Fuel Type: Diesel

Rare 10ft Box Lorry Suitable For Mover/Logistic. Timing Belt Just Change, Wear And Tear Replaced. Price Include New Paint Work, Color Of Your Choice! 100% Loan Available And Trade In Welcome. Call Now...

★ Posted: 29-May-2019 Tags: 2007 Toyota Dyna, 2007 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



☐ Toyota Dyna 100 3.0M (COE till 07/2022) \$21,800 \$6,870 /yr 26-Dec-2007 2,982 cc - Truck Available

Fuel Type: Diesel

COE Till July 2022, Good Condition,

SHORTLISTED HISTORY

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	0267E
Vehicle Details	
Vehicle No.:	GZ7690S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 D
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	5L5658648
Chassis No.:	JTFUF34Y903012185
Maximum Power Output:	-
Open Market Value:	\$23,681.00
Original Registration Date:	29 Aug 2006
First Registration Date:	29 Aug 2006
Transfer Count:	0
Actual ARF Paid:	\$1,185.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$23,127.00
COE Rebate Amount:	\$10,382.00
Total Rebate Amount:	\$10,382.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 30 May 2019

OK

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YLF MARKETING (S) PTE LTD
2 WOODLANDS SECTOR 1 #01-06
WOODLANDS SPECTRUM
SINGAPORE 758068

Contact : 67550177 97817949, 83494955

TP 1st Cap.
Denise.

ESTIMATE

Repair Code : CLM15256

Date in : 24/05/2019

Vehicle Num. : GZ7690S

Model : TOYOTA DYNA 150 D

Chassis/Eng# : JTFUF34Y903012185/5L5658648

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER Bent	1	521.60	✓ 521.60
FRONT BUMPER REINFORCEMENT BRACKET Bent.	1	581.60	378 581.60
FRONT GRILLE Cracked.	1	587.72	✓ 587.72
FRONT HEADLAMP L/R Cracked.	2	892.10	1,784.20 1290
FRONT HEADLAMP LOWER MOULDING L/R Not new	2	171.45	X 342.90
FRONT LH CORNER PANEL Dented.	1	275.00	✓ 275.00
FRONT LH CORNER PANEL BRACKET Not new	1	65.80	X 65.80
FRONT LH DOOR Repair	1	1658.80	X 1,658.80
FRONT LH DOOR STEP GARNISH Not	1	374.45	✓ 374.45
FRONT LH DOOR WEATHER STRIP Not new	1	169.10	X 169.10
FRONT LH SIDE MIRROR ASSY Cracked	1	689.90	✓ 689.90
FRONT PANEL Buckled	1	1378.70	1,378.70
FRONT PANEL 'DYNA' EMBLEM 3 new	1	86.90	✓ 86.90
FRONT PANEL 'LOGO' EMBLEM	1	51.20	✓ 51.20
FRONT PANEL CENTER PROTECTOR Cracked	1	291.33	✓ 291.33
FRONT PANEL LH CORNER PROTECTOR Cracked	1	199.75	✓ 199.75
FRONT WINDSCREEN GLASS RUBBER Not new	1	380.30	X 380.30
FRONT WIPER CENTER PANEL Not new	1	258.95	X 258.95

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YLF MARKETING (S) PTE LTD
 2 WOODLANDS SECTOR 1 #01-06
 WOODLANDS SPECTRUM
 SINGAPORE 758068

Contact : 67550177 97817949 , 83494955

ESTIMATE

Repair Code : CLM15256

Date in : 24/05/2019

Vehicle Num. : GZ7690S

Model : TOYOTA DYNA 150 D

Chassis/Eng# : JTFUF34Y903012185/5L5658648

FRONT WIPER LH SIDE GARNISH <i>cancel</i>	1	187.70	✓ 187.70
FRONT WIPER SIDE GARNISH CLIPS L/R - SET <i>new</i>	2	20.00	20 40.00
		Subtotal before discount	9,925.90
Percentage discount 25%			2,481.48
		Sub-total 1	7,444.43
FRONT BUMPER REFLECTIVE STICKER <i>new</i>	1	180.00	80 180.00
FRONT GRILLE CLIPS - SET <i>new</i>	1	40.00	20 40.00
FRONT HEADLAMP LOWER MOULDING CLIPS L/R - SET <i>new</i>	2	15.00	20 30.00
FRONT LH DOOR ART STICKER <i>Not New</i>	1	250.00	+ 250.00
FRONT LH DOOR COMPANY DETAIL STICKER <i>new</i>	1	50.00	30 50.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	+ 50.00
FRONT LH SIDE MIRROR DEFECTIVE STICKER <i>Not New</i>	1	80.00	+ 80.00
FRONT NUMBER PLATE <i>Best</i>	1	25.00	✓ 25.00
FRONT PANEL CENTER PROTECTOR CLIPS - SET <i>new</i>	1	20.00	✓ 20.00
FRONT WIPER CENTER PANEL CLIPS - SET	1	20.00	✓ 20.00
		Subtotal before discount	745.00
Percentage discount 0%			0.00
		Sub-total 2	745.00
		Parts-total	8,189.43

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

YLF MARKETING (S) PTE LTD

2 WOODLANDS SECTOR 1 #01-06

WOODLANDS SPECTRUM

SINGAPORE 758068

Contact : 67550177 97817949 , 83494955

ESTIMATE

Repair Code : CLM15256

Date in : 24/05/2019

Vehicle Num. : GZ7690S

Model : TOYOTA DYNA 150 D

Chassis/Eng# : JTFUF34Y903012185/5L5658648

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)

x 120.00

To remove, reinstall electrical wiring harness, check lighting. (to FR)

30 ~~50.00~~

To remove, reinstall windscreen. (to FR)

✓ 120.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

80 ~~100.00~~

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

x 100.00

To remove, reinstall dashboard fascia, meter reading and etc. (to FR)

x 250.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2510

11.00 ~~1,400.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

12.00 ~~1,200.00~~

To apply anti-rust chemical on repaired and replaced panel.

80 ~~100.00~~

Labour Total

3,440.00

Parts & Labour Total

11,629.43

*** This is a computer-generated document which requires no signature.***

page 3

Total: 7859.41

L/S: 6.3K:

08 Days.

6.3K

08 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009541/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7221Y	Veh. Inspected	GZ 7690S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003452MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	28/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JTFUF34Y903012185	Colour	WHITE	
Odometer	640309	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15C	YOKOHAMA	6 mm	
R/H Rear Tyre	155 R12C	JOURNEY	6 mm	
L/H Rear Tyre	155 R12C	JOURNEY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2019	Inspection Date	30/05/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 7690S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT	521.60	521.60
1	FRONT BUMPER REINFORCEMENT BRACKET	BENT	581.60	378.00
1	FRONT GRILLE	CRACKED	587.72	587.72
2	FRONT HEADLAMP L/R @\$892.10	CRACKED	1,784.20	1,290.00
2	FRONT HEADLAMP LOWER MOULDING L/R @\$171.45	NOT NECESSARY	342.90	-
1	FRONT LH CORNER PANEL	DENTED	275.00	275.00
1	FRONT LH CORNER PANEL BRACKET	NOT NECESSARY	65.80	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,658.80	-
1	FRONT LH DOOR STEP GARNISH	CUT	374.45	374.45
1	FRONT LH DOOR WEATHER STRIP	NOT NECESSARY	169.10	-
1	FRONT LH SIDE MIRROR ASSY	CRACKED	689.90	689.90
1	FRONT PANEL	BUCKLED	1,378.70	1,378.70
1	FRONT PANEL "DYNA" EMBLEM	NECESSARY	86.90	86.90
1	FRONT PANEL "LOGO" EMBLEM	NECESSARY	51.20	51.20
1	FRONT PANEL CENTER PROTECTOR	CRACKED	291.33	291.33
1	FRONT PANEL LH CORNER PROTECTOR	CRACKED	199.75	199.75
1	FRONT WINDSCREEN GLASS RUBBER	NECESSARY	380.30	380.30
1	FRONT WIPER CENTER PANEL	NOT NECESSARY	258.95	-
1	FRONT WIPER LH SIDE GARNISH	CRACKED	187.70	187.70
2	SET FRONT WIPER SIDE GARNISH CLIPS L/R @\$20.00	NECESSARY	40.00	20.00
	LESS 25% DISCOUNT		-2,481.48	-1,678.14
			7,444.42	5,034.41
SPECIAL NETT ITEMS				
1	FRONT BUMPER REFLECTIVE STICKER (SN)	NECESSARY	180.00	80.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	20.00
2	SET FRONT HEADLAMP LOWER MOULDING CLIPS L/R @\$15.00 (SN)	NECESSARY	30.00	20.00
1	FRONT LH DOOR ART STICKER (SN)	NOT NECESSARY	250.00	-
1	FRONT LH DOOR COMPANY DETAIL STICKER (SN)	NECESSARY	50.00	30.00
1	SET FRONT LH DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/FCI19009541/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH SIDE MIRROR DEFECTIVE STICKER (SN)	NOT NECESSARY	80.00	-
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
1	SET FRONT PANEL CENTER PROTECTOR CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT WIPER CENTER PANEL CLIPS (SN)	NECESSARY	20.00	20.00
			745.00	215.00
	LABOUR			
	TO REMOVE,REINSTALL AIR CON PARTS,VACUUMS,REFILL AIR CON GAS (TO FR).	NOT NECESSARY	120.00	-
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING (TO FR).		50.00	30.00
	TO REMOVE,REINSTALL WINDSCREEN (TO FR).		120.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		100.00	80.00
	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIMBOARD,MECHANISM LOCK AND HANDLE.	NOT NECESSARY	100.00	-
	TO REMOVE,REINSTALL DASHBOARD FASCIA,METER READING AND ETC (TO FR).	NOT NECESSARY	250.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,400.00	1,100.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT LH DOOR.		1,200.00	1,200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	80.00
-			-	-
-			-	-
-			-	-
			3,440.00	2,610.00
	GRAND TOTAL		11,629.42	7,859.41
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,300.00

Report Ref No. CS/FCI19009541/Atd3n2



Report Ref No. CS/FCI19009541/Atd3n2

MARKET VALUE: \$17,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,382.00=NETT VALUE: \$6,618.00

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.