



AIG Singapore
78 Shenton Way
Singapore 079120

Steve (LKK) WL Pte Ltd
LIS 29/5/19
Ry AL SM 4.30pm
7 days

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015380H

3RD PARTY CLAIM ESTIMATION

Vehicle number
Make / Model
Chassis number
Accident date
Reference

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Resurvey is on a "Without Prejudice" basis
• Legal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SLJ3113T
BMW 116D
WBAWZ0005C07745
26 May 2019
1905-91

Qty. Particulars 6.00

Qty.	Particulars	
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR RH SIDE PANEL (Spolier Rock-pan) / CUT	
1	REAR RH SIDE PANEL INNER TRIM X	
1	FRONT RH DOOR / DD	
1	FRONT RH DOOR PANEL INNER TRIM X	
1	FRONT RH DOOR LOCK ASSY ?	
1	FRONT RH DOOR REGULATOR X ?	
1	FRONT RH DOOR REGULATOR MOTOR X	
1	FRONT RH DOOR HANDLE X	
1	FRONT RH DOOR HANDLE INNER BRACKET X	
1	REAR RH DOOR PANEL / DD	
1	REAR RH DOOR PANEL INNER TRIM X	
1	REAR RH DOOR LOCK ASSY ?	
1	REAR RH DOOR REGULATOR ?	
1	REAR RH DOOR REGULATOR MOTOR X	
1	REAR RH DOOR HANDLE X	
1	REAR RH DOOR HANDLE INNER BRACKET X	
1	REAR RH KNUCKLE ?	
1	REAR RH KNUCKLE BEARING ?	
1	REAR RH LOWER ARM ?	
1	REAR RH UPPER TRAILING ARM X	
1	REAR RH SHOCK ABSORBER X	
1	REAR RH-WINDSCREEN MOULDING	
	Fend- R Re- / DD	
	RR	
<u>PARTS REPLACEMENT-S/NET ITEMS</u>		
1 SET	FRONT RH DOOR INNER TRIM CLIP / NLC	40.00 30
1 SET	REAR RH DOOR INNER TRIM CLIP / NLC	40.00 30
1 BOT	BRAKE FUILD / NLC	50.00 20
1	JOINT SEALANT / NLC	150.00 30
1	WINDSCREEN SEALANT	150.00 X
	RIM Re- RH / CUT	
<u>LABOURES</u>		
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 30
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00 80
3	REMOVE AND REFIT REAR WINDSCREEN	150.00
4	CHECK REAR WHEEL ALIGNMENT	150.00 60
5	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	200.00 /
6	TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO NEW	200.00 50
7	TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO NEW	200.00 50
8	PANEL BEATING ON AFFECTED AREAS	1400.00 1000
9	SPRAY PAINTING ON AFFECTED AREAS	1200.00 1000
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30