

Surname:

Kenneth

DOI:

29/5/19

Date / Time:

29/5/19

Registered in Merimen:

29/5/19

Pre-assign / CCU / FTE

SLJ 9585A



Insured Vehicle No.:

Claim No.:

Name of Insured:

CHUA KUN GUAH

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

28/5/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLK1588P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SLK1588P } WA/ALG 1900 9454/44 ; DOA: 28/5/19
 SLJ 9585A } - WA/ALG 1900 12466/42 ; DOA: 28/5/19

4/6/19 - CALLED OI, NO RESPONSE

2/8/19 - FILE (MS) TO HMK TO CLOSE

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

(w/GST)

S\$

6384.35

Loss of Rental (LOR):

S\$

300.00

(

4

days) x \$75

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

6686.35

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirms with:

Email

Call

Payee 1:

S\$

6686.35

Name 1:

Hui Yang Motor Pte Ltd

Payee 2: (Striker if N/A)

S\$

-

Name 2:

Payee 3: (Striker if N/A)

S\$

-

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

6/8/19

Kd
輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

28/05/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLK1588P

1pc	rear tailgate "PRIUS" emblem	Re	S	61.75	✓
1pc	rear tailgate "HYBRID" emblem	Re	S	53.75	✓
1pc	rear tailgate "TOYOTA" logo	Re	S	61.10	✓
1pc	rear tailgate outer garnish	Re	S	741.35	X
1pc	rear bumper 423.00	CM	S	928.35	✓
2pcs	rear bumper side retainer @\$141.40	Re	S	282.80	X
2pcs	rear bumper side lower bumper @\$274.45	Re	S	548.90	X
1pc	rear bumper diffuser	Re/CM	S	379.00	✓
1pc	rear bumper reinforcement	Re	S	458.00	✓
1pc	rear end panel	Re	S	970.25	X
1pc	rear end panel inner garnish	Re	S	381.90	X
2pcs	front headlamp @\$2250.00	CM	S	4,500.00	2x
1pc	front bumper 495.00	Re	S	972.45	✓
1pc	front bumper number plate garnish	CM	S	181.25	✓
2pcs	front bumper side retainer @\$131.35	CM	S	262.70	4x
15pcs	front bumper clip @\$5.00	Re	S	75.00	✓
1pc	front bumper "TOYOTA" logo	Re	S	95.85	✓
1pc	front bumper centre grille	CM	S	381.85	✓
1pc	front bumper top rubber 68.90	Re	S	281.70	2x
1pc	front bumper lower grille 240.70	CM	S	281.85	✓
1pc	front bumper top sponge	CM	S	172.40	✓
				<hr/>	
				\$ 12,072.20	
	less 25%			\$ 3,018.05	
				<hr/>	
				\$ 9,054.15	
1 set	rear parking sensor	Shan	s.nett	\$ 280.00	200m
2 set	front & rear number plate & casing	Re/CM	s.nett	\$ 100.00	90m
	wiring		\$	60.00	30m
	tuffkote	Re	S	80.00	X
	spray painting		\$	1,400.00	80m
	labour charges		\$	1,400.00	700m
	Total			<hr/>	
				\$ 12,374.15	

辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

Ally
Vehicle in
LKK

28/05/2019

Owner: HYMS CAR LEASING PTE LTD

Not Authorised
Recovery Bq claim
4-5 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLK1588P

1pc	rear tailgate "PRIUS" emblem	RM	\$ 61.75	✓
1pc	rear tailgate "HYBRID" emblem	RM	\$ 53.75	—
1pc	rear tailgate "TOYOTA" logo	RM	\$ 61.10	—
1pc	rear tailgate outer garnish	RM	\$ 741.35	X
1pc	rear bumper	CM	\$ 928.35	✓
2pcs	rear bumper side retainer @\$141.40	RM	\$ 282.80	X
2pcs	rear bumper side lower bumper @\$274.45	RM	\$ 548.90	X
1pc	rear bumper diffuser	RM	\$ 379.00	✓
1pc	rear bumper reinforcement		\$ 458.00	?
1pc	rear end panel	RM	\$ 970.25	X
1pc	rear end panel inner garnish	RM	\$ 381.90	X
2pcs	front headlamp @\$2250.00		\$ 4,500.00	?
1pc	front bumper	RM	\$ 972.45	✓
1pc	front bumper number plate garnish	CM	\$ 181.25	✓
2pcs	front bumper side retainer @\$131.35	old	\$ 262.70	✓
15pcs	front bumper clip @\$5.00	RM	\$ 75.00	—
1pc	front bumper "TOYOTA" logo	RM	\$ 95.85	✓
1pc	front bumper centre grille	CM	\$ 381.85	✓
1pc	front bumper top rubber Pr?	RM	\$ 281.70	✓
1pc	front bumper lower grille		\$ 281.85	?
1pc	front bumper top sponge		\$ 172.40	?
less 25%			\$ 12,072.20	
			\$ 3,018.05	
			\$ 9,054.15	
1set	rear parking sensor	s.nett	\$ 280.00	?
2set	front & rear number plate & casing	s.nett	\$ 100.00	90.00
	wiring		\$ 60.00	30.00
	tuffkote	RM	\$ 80.00	X
	spray painting		\$ 1,400.00	800.00
	labour charges		\$ 1,400.00	?
	Total		\$ 12,374.15	

LOI Auto Care Centre hereby
the Repair of the following:
• To repair / replace / repaint /
• To replace / repair / replace /
• To replace / repair / replace /
• To replace / repair / replace /
• To replace / repair / replace /
• To replace / repair / replace /
• To replace / repair / replace /
• To replace / repair / replace /



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) - Fax: 64514658

Reg No. 201629438M

Date: 22/07/2019

AIG Asia Pacific Insurance Pte Ltd

Motor Claims Department

78 Shenton Way

#08-16 AIG Building

Singapore 079120

**RE: ACCIDENT INVOLVING SLK1588P, SLJ9585A & SHC6151Y ON 28/05/2019
ALONG CHANGI SOUTH AVENUE 1 TOWARDS XILIN AVENUE**

SETTLEMENT OF OUR CLAIM FOR SLK1588P

Part By Part repair cost as recommended by surveyor (TP0666)	\$ 6,384.35
04 Days Loss of Use @ \$75,00 per day	\$ 300.00
TP Insurance Enquiry	\$ 2.00
Total	<u>\$ 6,686.35</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

Jia Le (LKK Auto)

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Friday, 2 August 2019 11:53 AM
To: Jia Le (LKK Auto)
Cc: Admin A
Subject: Re: LOD for Vehicle SLK1588P DOA: 28/05/2019
Attachments: SKM_C28719080212050.pdf

Importance: High

Hi Carlor,

Attached signed D.V fyns.

Thank you & Regards,
Sandra

From: Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Sent: Friday, August 2, 2019 11:29 AM
To: Hui Yang Motor <hui_yang_motor@hotmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: LOD for Vehicle SLK1588P DOA: 28/05/2019

WITHOUT PREJUDICE

Dear Marcus,

We confirmed settlement as follows:-

1. Cost of Repair (w/GST)	\$ 6,384.35
2. Loss of Rental (4days x \$75.00)	\$ 300.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 6,686.35

Please sign the DV and return to us.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Carlor Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

From: Shu Pei (LKKAuto)
Sent: Tuesday, 23 July 2019 7:50 PM
To: Hui Yang Motor
Cc: Admin A; Jia Le (LKK Auto)
Subject: FW: LOD for Vehicle SLK1588P DOA: 28/05/2019
Importance: High

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC4/AIG19009553/Kda3	Jia Le

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Tuesday, 23 July 2019 4:53 PM
To: Admin A <admin-a@lkkauto.com>
Subject: LOD for Vehicle SLK1588P DOA: 28/05/2019
Importance: High


Dear Sir/Mdm,

Attached LOD for your perusal.

Kindly advise OIC pertaining to this case please.?

Thank you & Regards,
Marcus Loh

TP Claim for SLK1588P against SLJ9585A / DOA: 28/05/2019

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/29/2019 2:12:19 PM
Attachments:  SKM_C28719052914040.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

2.42pm @ 29/5/19
Vehicle In
person @ Bel
sur @ Kenneth

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Wednesday, May 29, 2019 1:52 PM
To: AIG SGP, Claims-Survey
Subject: [EXTERNAL] TP Claim for SLK1588P against SLJ9585A / DOA: 28/05/2019
Importance: High

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,

Please refer to attached estimate and help to arrange surveyor soonest possible cos SLK1588P already in workshop.

Will pass surveyor the GIA report during survey.

Date of accident: 28/05/2019 @ 18:20hrs

Our Client's vehicle: SLK1588P

Your Insured vehicle: SLJ9585A

Thank you & Regards,
Bel
Tel: 6451 5752

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19009553/Kda3

07 JUNE 2019

CHUA KIM SING
9 LOR 27A GEYLANG
#01-14
SINGAPORE 388134

Dear Sir/Madam,

**ACCIDENT INVOLVING SLJ 9585A(AIG) / SLK 1588P/ OTHERS ALONG/ AT
CHANGI SOUTH AVE 1 JUNC WITH XILIN AVE ON 28/05/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLK 1588P against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: jjale@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, HYMS Car Leasing Pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all our correspondences with any party in connection with our claim.

Arising from an accident involving our motor vehicle registration number SLK1588P and other vehicles registration number SLJ9585A and SHC6151Y along Changi South Avenue 1 towards Xilin Avenue on 28/05/2019.

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.

A handwritten signature in black ink is written over a circular stamp. The stamp contains the text "HYMS Car Leasing Pte Ltd" around a central dot.

Signature of authorised person (and or a company) (if any)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HUI YANG MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,384.35 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. SLK 1588P that was damaged pursuant to the accident which occurred on 28/05/2019 (date) along CHANGI SOUTH AVENUE 1 TOWARDS XILIN AVENUE (location) involving vehicle no/s SLJ 9585A. This is pursuant to the inspection conducted on 29/05/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner HYMS CAR LEASING PTE LTD ("the third party claimant") of vehicle no. SLK 1588P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLK 1588P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 6th (day) of August (month) 20 19 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)

THIS SETTLEMENT RELATES TO CLAIM FOR THE COSTS OF REPAIR AND LOSS OF USE/ COSTS OF HIRING REPLACEMENT VEHICLE ONLY. IT EXPRESSLY EXCLUDES ANY CLAIM FOR PERSONAL INJURIES.



HUI YANG MOTOR PTE LTD

Bill To:

AIG Asia Pacific Insurance Pte Ltd
Motor Claims Department
78 Shenton Way
#08-16 AIG Building
Singapore 079120

TAX INVOICE


TP Claim Invoice No: TP0666
Bill Date: 22/07/2019

	Description	Amount
	Date of Accident : 28/05/2019 Owner : HYMS CAR LEASING PTE LTD Vehicle No : SLK1588P Make & Model : <u>TOYOTA PRIUS HYBRID</u>	
	<u>Part By Part Repair cost as recommended by surveyor.</u>	\$ 5,966.68
	Sub-Total :	\$ 5,966.68
	Add 7% GST :	\$ 417.67
	Total Amount SGD :	\$ 6,384.35

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive
#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com


H/P: 98625891 Office: 64515752 Fax : 64514658

HYMS CAR LEASING PTE LTD

BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721
ROC: 201320561K GST Register No: 201320561K HP:83336725 FAX: 64514658


RENTAL AGREEMENT

RA:1389

HIRER'S NAME: TAN SONG TECK	
NRIC NO: S1757391H	CONTACT NO: 9296 3121
ADDRESS: BLK 290B COMPASSVALE CRESCENT #10-S2 SINGAPORE 542290	
VEHICLE REG NO: SLK1588P	MAKE & MODEL: TOYOTA PRIUS
COMMENCING START DATE: 24/09/18	COMMENCING END DATE: 23/09/19
RENTAL PER DAY: \$75 + CDR \$42 + CDR \$42 + CDR \$42	DEPOSIT: \$1500 RECONTRACT
FUEL: 	VEHICLE MILEGE:

REAR

TOP



FRONT

D = DENT

S = SCRATCHES

C = CHIPS

R = RUST

M = MISSING

REMARKS

- If vehicle return within 12 months from the commencing start date, deposit of \$1500 will not be refund.
- After 11 months from the commencing start date, hirer can terminate by giving 1 mth advance notice . If fail to do so, deposit of \$1500 will not be refunded.
- 1st party excess per claim \$3000
- 3rd party excess per claim \$2500
- Malaysia excess double

Tan Song Teck

Tan Song Teck

Signature Of Hirer

*The Hirer shall not use the Vehicle for any other commercial activity other than solely for the purposes of providing transportation service requested by GrabCar user via the Grab app. Failing which, we reserve the absolute right and option to terminate this Car Rental Agreement, forfeiting your deposit, and you shall be required to return the car immediately and you shall continue to be liable for rental due for the remaining rental term.

TAX INVOICE

Our Ref No: GR-19-084957

Date of Request: 29/05/2019

Your Ref No: Online Purchase

Hui Yang Motor Pte Ltd
176 Sin Ming Drive #04-02
Sin Ming AutoCare
Singapore 575721

Dear Sir/Madam,

Enquiry Date 29/05/2019
Enquiry By Bel Chew Shu Jing
TP Vehicle No. SLJ9585A
Accident Date 28/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 Edit Reg		29 May 2019 00:00 Edit Adj Rpt	S\$5,966.67 Edit Estimates	S\$5,966.67 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHUA KIM SING (CAI JINSHENG) , ID: S7419725F								
Main Claimant:	HYMS CAR LEASING PTE LTD , Co. Reg. No.: 201320561K								
Vehicle Reg. No.:	SLK1588P	Date of Loss:	28/05/2019 00:00 - :59 [28 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9361061095SG	Policy/Cover Note No.:	2100495782 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLJ9585A	Policy No. (Claimant):	999994505						
		Excess:							
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJQian.Ler@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (30/05/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK1588P (9361061095SG)
[SLJ9585A]
TP
HYMS CAR LEASING PTE LTD
May 28 2019 12:00AM
[CHUA KIM SING (CAI JINSHENG)]
Hui Yang Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
2	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
3	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
4	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
5	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
6	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
7	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
8	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
9	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
10	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
11	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
12	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
13	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
14	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
15	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
16	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
17	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
18	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
19	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
20	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
21	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
22	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
23	02/08/19 12:26	Odometer Reading											1	Load JPG	<input checked="" type="checkbox"/>		
24	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
25	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
26	02/08/19 12:26	Chassis Number											1	Load JPG	<input checked="" type="checkbox"/>		
27	02/08/19 12:26	General View											1	Load JPG	<input checked="" type="checkbox"/>		
28	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
29	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
30	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
31	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
32	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
33	02/08/19 12:32	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
34	02/08/19 12:32	Reinspection Photo											1	Load JPG			

Letters / Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 12:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 20:03	ACKNOWLEDGEMENT EMAIL TO AIG DD 29.05.2019	 Load PDF	
2	29/05/19 20:03	EMAIL FROM AIG DD 29.05.2019	 Load PDF	
3	29/05/19 20:03	TP ESTIMATE	 Load PDF	
4	31/05/19 09:11	TP GIA REPORT	 Load PDF	
5	16/07/19 08:45	TP EST	 Load PDF	
6	08/08/19 14:26	WORKSHOP INVOICE	 Load PDF	
7	08/08/19 14:26	AUTHORISATION TO ACT FORM	 Load PDF	
8	08/08/19 14:26	Release Voucher	 Load PDF	
9	08/08/19 14:26	RENTAL RECEIPT	 Load PDF	
10	08/08/19 14:26	LTA SEARCH	 Load PDF	
11	08/08/19 14:26	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/05/19 09:43	OI GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SLJ9585A (Insd veh)	Model:	TOYOTA PRIUS HYBRID 1.8
	SLK1588P (TP veh)		S (A)
Date of Accident:	28/05/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	13,240.34
Final Repair Cost	:	\$	6,384.34
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	300.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,686.34
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hui Yang Motor Pte Ltd	:	\$ 6,686.34
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 Aug
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009553/KDA3Q2
Date: 08/08/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100495782
Claimant Vehicle No :	SLK1588P	Insured Vehicle No :	SLJ9585A
Date of Loss:	28/05/2019	Nature of Claim:	TP
		Claim No:	9361061095SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK1588P	Engine No:	2ZR6702427
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S (A)	Chassis No:	ZVW506015866
Reg. Date:	06/01/2017 (Man. Year: 2016)	Odometer:	295746 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	AGENDA 9 mm	Rear Left Side:	AGENDA 9 mm
Front Right Side:	AGENDA 9 mm	Rear Right Side:	AGENDA 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,434.15	4,436.67	4,997.48	52.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,530.00	1,410.00	47.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,374.15	5,966.67	6,407.48	51.78
+ GST 7.00/7.00% (S\$)	866.19	417.67	448.52	51.78
Nett Amount (S\$)	13,240.34	6,384.34	6,856.00	51.78
+ Car Rental (4.0 x S\$75.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,686.34		

INSPECTION

Date of Assignment:	29/05/2019	
Date Inspected:	29/05/2019 Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	61.75 FL	*61.75 FL
2	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	53.75 FL	*53.75 FL
3	1		*REAR TAILGATE TOYOTA LOGO	Necessary	61.10 FL	*61.10 FL
4	1		*REAR TAILGATE OUTER GARNISH	Repair	741.35 FL	*- FL
5	1		*REAR BUMPER	Cracked	928.35 FL	*423.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Serviceable	282.80 FL	*- FL
7	2		*REAR BUMPER SIDE LOWER BUMPER	Serviceable	548.90 FL	*- FL
8	1		*REAR BUMPER DIFFUSER	Dented / Cut	379.00 FL	*379.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	458.00 FL	*458.00 FL
10	1		*REAR END PANEL	Repair	970.25 FL	*- FL
11	1		*REAR END PANEL INNER GARNISH	Serviceable	381.90 FL	*- FL
12	1		*FRONT HEADLAMP	O/S Mtg Cracked	4,500.00 FL	*2,250.00 FL
13	1		*FRONT BUMPER	Buckled	972.45 FL	*495.00 FL
14	1		*FRONT BUMPER NUMBER PLATE GARNISH	Cracked	181.25 FL	*181.25 FL
15	1		*FRONT BUMPER SIDE RETAINER	O/S Distorted	262.70 FL	*131.35 FL
16	15		*FRONT BUMPER CLIP	Necessary	75.00 FL	*75.00 FL
17	1		*FRONT BUMPER TOYOTA LOGO	Necessary	95.85 FL	*95.85 FL
18	1		*FRONT BUMPER CENTRE GRILLE	Cracked	381.85 FL	*381.85 FL
19	1		*FRONT BUMPER TOP RUBBER	Necessary	281.70 FL	*68.90 FL
20	1		*FRONT BUMPER LOWER GRILLE	Cracked	281.85 FL	*240.70 FL
21	1		*FRONT BUMPER TOP SPONGE	Cracked	172.40 FL	*172.40 FL
22	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
23	2		*SET FRONT & REAR NUMBER PLATE & CASING	Necessary	100.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	12,452.20	5,818.90
- List Item Discount on L Items 25.00/25.00% (S\$)	3,018.05	1,382.23
Total Parts (S\$)	9,434.15	4,436.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	60.00	30.00
2	TUFFKOTE	New	80.00	0.00
3	SPRAY PAINTING	New	1,400.00	800.00
4	LABOUR CHARGES	New	1,400.00	700.00
Gross Labour Cost (\$\$)			2,940.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >