

All
Vehicle in

輝 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

28/05/2019

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLK1588P

1pc	rear tailgate "PRIUS" emblem	\$ 61.75
1pc	rear tailgate "HYBRID" emblem	\$ 53.75
1pc	rear tailgate "TOYOTA" logo	\$ 61.10
1pc	rear tailgate outer garnish	\$ 741.35
1pc	rear bumper	\$ 928.35
2pcs	rear bumper side retainer @\$141.40	\$ 282.80
2pcs	rear bumper side lower bumper @\$274.45	\$ 548.90
1pc	rear bumper diffuser	\$ 379.00
1pc	rear bumper reinforcement	\$ 458.00
1pc	rear end panel	\$ 970.25
1pc	rear end panel inner garnish	\$ 381.90
2pcs	front headlamp @\$2250.00	\$ 4,500.00
1pc	front bumper	\$ 972.45
2pcs	front bumper side retainer @\$131.35	\$ 262.70
15pcs	front bumper clip @\$5.00	\$ 75.00
1pc	front bumper "TOYOTA" logo	\$ 95.85
1pc	front bumper centre grille	\$ 381.85
1pc	front bumper top rubber	\$ 281.70
1pc	front bumper lower grille	\$ 281.85
1pc	front bumper top sponge	\$ 172.40

\$ 11,890.95

less 25%

\$ 2,972.74

\$ 8,918.21

1set	rear parking sensor	s.nett \$ 280.00
------	---------------------	------------------

wiring	\$ 60.00
--------	----------

tuffkote	\$ 80.00
----------	----------

spray painting	\$ 1,400.00
----------------	-------------

labour charges	\$ 1,400.00
----------------	-------------

Total	<u>\$ 12,138.21</u>
-------	---------------------

