

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6930 R

1 pc	Bootlid emblem X <i>ha</i>	\$ 27.00
1 pc	Bootlid CRDi X <i>"</i>	\$ 29.00
1 pc	Bootlid o/s reflector @ \$350.00 X <i>ct</i>	\$ 350.00
1 pc	o/s tail lamp <i>oe</i>	\$ 421.00
1 pc	Rear bumper <i>ohant</i>	\$ 696.00
1 pc	Rear bumper lower cover X <i>sm</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X <i>sm</i>	\$ 58.00
1 pc	Rear bumper inner sponge X <i>sm</i>	\$ 114.00
1 pc	Rear bumper reinforcement X <i>m</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X <i>sm</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X <i>sm</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X <i>sm</i>	\$ 36.00
1 pc	Rear bumper n/s reflector @ \$46.00 <i>uef</i>	\$ 46.00
		\$ 2,734.00
Less 10%		\$ 273.40
		\$ 2,460.60

S/NETT

1 set	Rear bumper clips <i>rec</i>	\$ 48.00
1 set	Bootlid stickers <i>rec</i>	\$ 100.00
1 set	Reverse sensor X <i>sm</i>	\$ 280.00
Sundry		\$ 50.00 <i>2</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 <i>30</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>X 2</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$ 850.00 <i>300</i>
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel		\$ 800.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels.		\$ 150.00 <i>X 2</i>
		\$ 5,038.60

Kohar'ikis

30/5/19 1005h

3 bp

4s

Atk Paper photo

Consultants here to notify
 • To resurvey (display damaged parts) during resurvey
 • No illegal modification is allowed
 • Supplementary terms must be resurveyed and approved to approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.