

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-May-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6930 R

1 pc	Bootlid emblem	\$	27.00
1 pc	Bootlid CRDi	\$	29.00
1 pc	Bootlid o/s reflector @ \$350.00	\$	350.00
1 pc	o/s tail lamp	\$	421.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00
1 pc	Rear bumper inner sponge	\$	114.00
1 pc	Rear bumper reinforcement	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00
1 pc	Rear bumper n/s reflector @ \$46.00	\$	46.00
		\$	2,734.00
		Less 10%	\$ 273.40
		\$	2,460.60

S/NETT

1 set	Rear bumper clips	\$	48.00
1 set	Bootlid stickers	\$	100.00
1 set	Reverse sensor	\$	280.00
	Sundry	\$	50.00
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.	\$	850.00
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$	800.00
	To apply rustproofing on the repaired and replaced panels.	\$	150.00
		\$	5,038.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**