

ASS. REC. BY:

REF: CS/C1219009565 / K9.dish Special Instruction:

Survivor: Kenneth

**ASSIGNMENT (Office)**

From (Person): Ong Chin Liat

of C12

Date/Time: 29.5.19 12.20pm

Estimated Cost:

Bill to:

**OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SLN 1864B

Insured: GBA 9933U

at Workshop m/s Lat Huat

Tel: 64538110

of 160 SLN ming Drive # 04-01

Policy No: DINEVSA 30563418000

Claim No: SAM 191202244

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 30.5.19 9.09a.m

Person Contacted:

Jenny

H.O.D. Endorsement:

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 1864B-X
	GBA 9933U -NA/INC 140041551 h4
06/8/19 @	10.31am confirmed with Jenny final fig @ 2951.17, 7 days.
	(Red 80%, 0%)
	7/8

ASS. REC. BY:

REF

C71

## ASSIGNMENT

From: Date: 10/6/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 1864B

at Workshop m/s Lai Huet

of 160 SN ming Dmz # 04-01/02

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAG Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1.21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN 1864B

Yr Regn:

09, 17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

c.c.

1496

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

58703

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBM 42A8G0346071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

14/5/19

D.O.I.

10/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

06/08/19. CR checked. P13 present.

RECEIVED 13 AUG 2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

3 + RS, \$1

Photos

Others

TOTAL

Report Format :

MER-7P

Lump Sum / I.B.I. (\$) 2951.17

970

270

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 Sendback Est	29 May 2019 13:04 S\$2,905.17	29 May 2019 17:26 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	YOKOKAMA SIGNS PTE LTD, Co. Reg. No.: B52958948J								
Main Claimant:	LEE HUNG PENG, ID: S7886033B								
Vehicle Reg. No.:	SLN1864B	Date of Loss:	14/05/2019 19:00 - :59 [24 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202244	Policy/Cover Note No.:	DMCVSN30563418000						
Vehicle Reg. No. (Insured):	GBA9933U	Policy No. (Claimant):	MS005063						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/06/2019]								
Driver/Custodian (Insured):	-- ( / Male) , NRIC: 0 Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## **Shiau Chan (LKKAuto)**

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 6 August 2019 10:21 AM  
**To:** Jenny Lim  
**Subject:** FINALISE OF TP VEHICLE SLN 1864B (DOA: 14/05/2019)

Dear Jenny,

WITHOUT PREJUDICE

Confirm final fig \$2,951.17 before GST and 7 repair days. (finalise amount subject to our principal approval)

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 6033B

### Vehicle Details

Vehicle No.: SLN1864B  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 28 May 2019  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT  
Primary Colour: Silver  
Manufacturing Year: 2016  
Engine No.: P520374480  
Chassis No.: JM6BM42A8G0346071  
Maximum Power Output: 88.0 kW (118 bhp)  
Open Market Value: \$18,988.00  
Original Registration Date: 25 Apr 2017  
First Registration Date: 25 Apr 2017  
Transfer Count: 0  
Actual ARF Paid: \$13,988.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 24 Apr 2027  
PARF Rebate Amount: \$10,491.00

### Intended COE Rebate Details

COE Expiry Date: 24 Apr 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$52,000.00  
COE Rebate Amount: \$41,121.00  
**Total Rebate Amount: \$51,612.00**

The information contained herein is correct as at 28 May 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/05/2019 12:33
Date Of Accident	14/05/2019 19:55
Exact Location Of Accident	TRAFFIC LIGHT OF BLK 264 SERANGOON CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1864B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE HUNG PENG
NRIC No	S7886033B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96196822
Alternative Phone No	OTHERS-96196822

### Vehicle Particulars

Manufacturer	MAZDA
Model	3 1.5L
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MS005063
Cover Note Number	

### Driver

Name of Driver	CHIN KAH LAI
NRIC No	S7969067H
Date Of Birth	10/09/1979
Occupation	INDOOR
Date Of Driving Pass	17/10/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96175304
Fax Number	
Contact Number	
Email Address	JINJANE39@YAHOO.COM

Address	BLK 222 ANG MO KIO AVENUE 1 #10-723
Postcode	560222
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE ZEE YEE GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA9933U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(if driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Poh Kwee Choo  
S6840583A15-May-2019  
12:29pm



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14th May 2019 around 7:38pm, I was ~~at~~ stopping at the pedestrian traffic light in front of Serangoon Central HDB car park. While the pedestrians were crossing the road, a small truck plate number GBA 9933U hit my car ~~side~~ right side of the back and the bumper and right lamp etc damage. The ~~truck~~ managed to stop in front of the red light.

The driver name Amy, handphone number 9615 0664

My car number is SLN1864B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Jnt. Kwee Choo  
NRIC/FIN No.: S6840583A

6021112, P-4524211, Term, V18

15-May-2019 12:29pm

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7969067H



Name

CHIN KAH LAI

陈家丽

Race

CHINESE

Date of birth

10-09-1979

Sex

F

Country of birth

MALAYSIA

S7969067H

REPUBLIC OF SINGAPORE DRIVING LICENCE

IDENTITY CARD NO. S7969067H



CHIN KAH LAI

Date of birth 10 Sep 1979

Valid until 17 Oct 2014



002356704H



8124337

IDENTITY CARD NO. S7969067H



Nationality

MALAYSIAN

Date of issue

12-08-2011

Address

APT BLK 222 ANG MO KIO AVENUE 1  
#10-723  
SINGAPORE 560222

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 17 Oct 2014  
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 17 Oct 2014



Licence No: S7969067H

HP 428A

# Tokio Marine Insurance Singapore Ltd.

(Company Reg. No: 192300014M) (GST Reg No: M2-0000023-4)

20 McCallum Street #09-01 Tokio Marine Centre Singapore 060046

T: (65) 6221 6111 F: (65) 6221 4355 / (65) 6224 0895 E: [tmis@tokiomarine.com.sg](mailto:tmis@tokiomarine.com.sg) W: [www.tokiomarine.com](http://www.tokiomarine.com)

A member of the  
Tokio Marine Group



**TOKIO MARINE**  
INSURANCE GROUP

## Certificate of Insurance

FORM MX1

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Policy No.: MS005063 (Private Car)

- |  |  |                                |
|--|--|--------------------------------|
| 1. Index Mark and Registration Number of Vehicle                               | SLN1864B   | Chassis No.: JM6BM42A8G0346071 |
| 2. Name of Policyholder  | LEE HUNG PENG  |                                |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 25/04/2019 (00:00:00)  |                                |
| 4. Date of Expiry of Insurance   | 24/04/2020   |                                |
| 5. Persons or Class of Persons entitled to drive*                              | (a) The Policyholder.<br>(b) Any other person who is driving on the Policyholder's order or with his permission. |                                |

\* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

### 6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

### IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost/destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

### ADDITIONAL INFORMATION

Account No: 1986DDA

Insurance Plan:	Comprehensive Approved Workshop Plan		
Limit for total loss or theft:	Prevailing Market Value		
Policy Excess:	Own Damage Claims	SGD 600.00	(Original Excess : SGD 600.00)
	Additional Excess for Unnamed Driver(s)	SGD 500.00	
	Additional Excess for Young or Inexperience Driver(s)	SGD 3,500.00	
	WindScreen Excess	SGD 100.00	
Financial Interest:	HONG LEONG FINANCE LTD		

TOKIO MARINE INSURANCE SINGAPORE LTD.

Authorized Signature

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 29/05/2019 11:45 AM

Full Report

Registration: SLN 1864B

Printed: 29/05/2019 11:45 AM

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 9933U	Date of Incident:	14/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	


**Vehicle Details**

<b>Vehicle</b>			
Manufacturer:	MAZDA		
Model:	3 (BM/BN)		
Sub Model:	SPORT		
Model Sheet Number:	36 68 35		
Registration:	SLN 1864B		
VIN number:			
Odometer:	57732		
<b>Model Specs</b>			
FROM 03/2017	AIR CONDITIONING	FOG LAMPS	REAR PARKING SYSTEM
1.5 LTR 74KW	6-SPEED GEARBOX	TYRES 205/60 VR 16	4-DOOR SALOON
TWO COAT METALLIC	PREPARE OFF VEHICLE		

*Not Authorised  
 Respray B6 paint  
 7 days*

**Labour**

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
S1705A-R-X	R + R L/FR SILL PANEL COVER		2.0	8.40
S1705A-R-X	R + R R/FR SILL PANEL COVER		2.0	8.40
NO NUMBER	RENEW R/R SIDE PANEL		80.0	336.00
NO NUMBER	RENEW R/R WHEELHOUSE REAR REINFORCEMENT		7.0	29.40
S0206G-R-X	RENEW REAR BUMPER		5.0	21.00
	INCLUDES: RR BUMPER, BOTH OUT REARLAMPS AND ALL REQUIRED ATTACHED-PARTS REMOVE AND REFIT			
S1709X-R-X	R + R REAR END PANEL TRIM		2.0	8.40
NO NUMBER	R + R BOOTLID		1.0	4.20
S1402C-R-X)	R + R REAR SCREEN		15.0	63.00
NO NUMBER	R + R CENTRE CONSOLE		3.0	12.60
NO NUMBER	R + R BOTH FRONT SEATS		5.0	21.00
NO NUMBER	R + R REAR SEAT CUSHION COVER		2.0	8.40



**Lai Huat (Meng Kee) Motor Pte  
Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 29/05/2019 11:45 AM

Full Report

Registration: SLN 1864B

Printed: 29/05/2019 11:45 AM

		WU	Price SGD
NO NUMBER	R + R SEAT BACKREST	3.0	12.60
S1715A-R-X)	R + R FLOOR CARPET (SEAT REMOVED)	3.0	12.60
	INCLUDES: R + R LOWER TRIMS		
NO NUMBER	R + R LUGG COMPARTMENT CARPET	2.0	8.40
S1710X-R-X)	R + R PARCEL SHELF	1.0	4.20
1001	REV SENSOR REMOVE+REFIT	✓	40.00*
4194	R/TAILLAMP PANEL REPAIR	10.0* ✓	42.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>14.30</b>	<b>143.0</b>
<b>Fixed Rate</b>			<b>600.60</b>
			<b>40.00</b>
<b>Total of Labour</b>			<b>640.60</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/REINF EXTENSION SURFACE PAINT	4.0
	R/R SIDE PANEL NEW PART PAINTING	28.0
	REAR BUMPER NEW PART PAINT K1R	14.0
	R/R COVER CAP NEW PART PAINT K1R	3.0
	RIGHT SILL MOULDING SURFACE PAINT PLAST.	6.0
	R/TAILLAMP PANEL SURFACE PAINT	4.0

**Paint Material Per Part**

Code	Description	Price SGD
2720	R/REINF EXTENSION SURFACE PAINT	2.49
3482	R/R SIDE PANEL NEW PART PAINTING	39.05
2581	REAR BUMPER NEW PART PAINT K1R	72.32
2612	R/R COVER CAP NEW PART PAINT K1R	0.98
2188	RIGHT SILL MOULDING SURFACE PAINT PLAST.	16.84
4194	R/TAILLAMP PANEL SURFACE PAINT	2.49

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01,**  
**#04-02 & #07-03, Sin Ming**  
**Autocity**  
**575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 29/05/2019 11:45 AM

Full Report

Registration: SLN 1864B

Printed: 29/05/2019 11:45 AM

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		59.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>89.0</b>	<b>373.80</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	39.05
New Part Painting - Plastic K1R	73.30
Surface-/Blend Paint	4.98
Surface Painting Plastic	16.84
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>171.77</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
1377	SPACER PART	C00150897			0.00
1379	SPACER	BHN950896			0.00
2581	REAR BUMPER	BHR250221A8N	B20	✓	620.00
2612	R/R COVER CAP	BHN150EK1BB	M17	✓	15.00
2622	R/INN BUMPER BRACKET	BHN1502H1A		C14 ✓	16.00
2720	R/REINF EXTENSION	BJY77041X		B1	125.00
3160	REAR SCREEN BOND KIT	KNGKWI2	AK N2	✓	0.00
3161	REAR SCREEN SEAL	BHN150611C	M	✓	28.00
3282	R/R OUTER LAMP CPL	B45A51150B		A1 ✓	325.00
3482	R/R SIDE PANEL	B6YS7041X	B1	✓	450.00
f: OEM Parts	<b>Savings</b>				0.00
n: Non-OEM Parts	<b>Subtotal</b>				1,579.00
u: Used parts	<b>Fixed Sundry Parts Price</b>				100.00
	<b>Total</b>				<b>1,679.00</b>

**Extras**

Code	Description	Price SGD
1000	W/S SEALANT SN	40.00*
	<b>Total Extras</b>	<b>40.00</b>

**Lai Huat (Meng Kee) Motor Pte  
Ltd  
160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 29/05/2019 11:45 AM

Full Report

Registration: SLN 1864E

Printed: 29/05/2019 11:45 AM

Price SGD

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,579.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>1,679.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 143.0 WU X 42.00 SGD/h	600.60	
Fixed Rate	40.00	
<b>Total of Labour</b>		<b>640.60</b>
<b>Total Of Extras</b>		<b>40.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 89.0 WU X 42.00 SGD/h	373.80	
Material Cost	171.77	
<b>Total Paint Including Material</b>		<b>545.57</b>
<b>Repair Cost Excludes GST</b>		<b>2,905.17</b>
GST (+7.0%)		<b>203.36</b>
<b>Repair Cost Included GST</b>		<b>3,108.53</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

# 來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity  
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722  
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg  
UEN: 199407592C

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

--

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70538
Policy No:		Date of Loss:	14/05/2019
Vehicle Reg. No.:	SLN1864B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHIN KAH LAI	Driver (Insured):	--
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	25/04/2017
Vehicle Colour:	SILVER		
Engine No:	P520374480	Chassis No:	JM6BM42A8G0346071
Odometer:	57732 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	1,579.00
Miscellaneous Items	140.00
Labour	640.60
Paintwork Labour	545.57
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,905.17</b>
<b>+ GST 7.00% (S\$)</b>	<b>203.36</b>
<b>Nett Amount (S\$)</b>	<b>3,108.53</b>

This claim is handled by: JENNY LIM LAI FOONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System



**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 29 May 2019)**Parts:** 143      MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0) \***Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/29/05/2019 13:04**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SPARE PARTS	0.00	0.00	*1,579.00 F
Total Parts (S\$)						1,579.00

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/29/05/2019 13:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	MISCELLANEOUS	40.00 ✓
2	1	SUNDRY PARTS <i>RL</i>	100.00 ✓
Sub Total (S\$)			140.00

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TOTAL PAINT INCLUDING MATERIAL	New	545.57 ✓
<u>Labour Items</u>			
2	TOTAL OF LABOUR	New	640.60 ✓
Gross Labour Cost (S\$)			1,186.17

Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/29/05/2019 13:04. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# 來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity  
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722  
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg  
UEN: 199407592C

## (SUPPLEMENTARY)

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)  
YOKOKAMA SIGNS PTE LTD

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	70538
Policy No:	DMCVSN30563418000	Date of Loss:	14/05/2019
Vehicle Reg. No.:	SLN1864B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHIN KAH LAI	Driver (Insured):	--
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	25/04/2017
Vehicle Colour:	SILVER		
Engine No:	P520374480	Chassis No:	JM6BM42A8G0346071
Odometer:	57732 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Present Location:	LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS	Amount
Parts	46.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>46.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>3.22</b>
<b>Nett Amount (S\$)</b>	<b>49.22</b>
<b>+ Previous Estimates (S\$)</b>	<b>3,108.53</b>
<b>Claim Total (S\$)</b>	<b>3,157.75</b>



**REPAIR DETAILS****Reference****Part Source:** MRM-SG    **Version:** 1.0 (Last Synchronised: 01 Aug 2019)**Parts:** 143    MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's    (Price-denominated Standard List)**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/01/08/2019 10:14**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RR BUMPER CLAMP KIT	0.00	0.00	*4.00 F <i>all</i>
2	1		*R/R VENT HOUSING	0.00	0.00	*42.00 F <i>87</i>
<b>Total Parts (S\$)</b>						<b>46.00</b>

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/01/08/2019 10:14. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SLN1864B/01/08/2019 10:14. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 01/08/2019 10:11 AM

Full Report

Registration: SLN 1864B

Printed: 01/08/2019 10:11 AM

## Summary Information

### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 9933U	Date of Incident:	14/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

## Vehicle Details

### Vehicle

Manufacturer:	MAZDA
Model:	3 (BM/BN)
Sub Model:	SPORT
Model Sheet Number:	36 68 35
Registration:	SLN 1864B
VIN number:	
Odometer:	57732

### Model Specs

FROM 03/2017	AIR CONDITIONING	FOG LAMPS	REAR PARKING SYSTEM
1.5 LTR 74KW	6-SPEED GEARBOX	TYRES 205/60 VR 16	4-DOOR SALOON
TWO COAT METALLIC	PREPARE OFF VEHICLE		

## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
S1705A-R-X	R + R L/FR SILL PANEL COVER		2.0	8.40
S1705A-R-X	R + R R/FR SILL PANEL COVER		2.0	8.40
NO NUMBER	RENEW R/R SIDE PANEL		80.0	336.00
NO NUMBER	RENEW R/R WHEELHOUSE REAR REINFORCEMENT		7.0	29.40
S0206G-R-X	RENEW REAR BUMPER		5.0	21.00
	INCLUDES: RR BUMPER, BOTH OUT REARLAMPS AND ALL REQUIRED ATTACHED-PARTS REMOVE AND REFIT			
S1709X-R-X	R + R REAR END PANEL TRIM		2.0	8.40
NO NUMBER	R + R BOOTLID		1.0	4.20
S1402C-R-X)	R + R REAR SCREEN		15.0	63.00
NO NUMBER	R + R CENTRE CONSOLE		3.0	12.60
NO NUMBER	R + R BOTH FRONT SEATS		5.0	21.00
NO NUMBER	R + R REAR SEAT CUSHION COVER		2.0	8.40

**Lai Huat (Meng Kee) Motor Pte Ltd**

**160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming**

**Autocity  
575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 01/08/2019 10:11 AM

Full Report

Registration: SLN 1864B

Printed: 01/08/2019 10:11 AM

		WU	Price SGD
NO NUMBER	R + R SEAT BACKREST	3.0	12.60
S1715A-R-X)	R + R FLOOR CARPET (SEAT REMOVED)	3.0	12.60
	INCLUDES: R + R LOWER TRIMS		
NO NUMBER	R + R LUGG COMPARTMENT CARPET	2.0	8.40
S1710X-R-X)	R + R PARCEL SHELF	1.0	4.20
1001	REV SENSOR REMOVE+REFIT		40.00*
4194	R/TAILLAMP PANEL REPAIR	10.0*	42.00
	<b>Labour Cost</b>	<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>	<b>14.30</b>	<b>143.0</b>
	<b>Fixed Rate</b>		<b>600.60</b>
			<b>40.00</b>
	<b>Total of Labour</b>		<b>640.60</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/REINF EXTENSION SURFACE PAINT	4.0
	R/R SIDE PANEL NEW PART PAINTING	28.0
	REAR BUMPER NEW PART PAINT K1R	14.0
	R/R COVER CAP NEW PART PAINT K1R	3.0
	RIGHT SILL MOULDING SURFACE PAINT PLAST.	6.0
	R/TAILLAMP PANEL SURFACE PAINT	4.0

**Paint Material Per Part**

Code	Description	Price SGD
2720	R/REINF EXTENSION SURFACE PAINT	2.49
3482	R/R SIDE PANEL NEW PART PAINTING	39.05
2581	REAR BUMPER NEW PART PAINT K1R	72.32
2612	R/R COVER CAP NEW PART PAINT K1R	0.98
2188	RIGHT SILL MOULDING SURFACE PAINT PLAST.	16.84
4194	R/TAILLAMP PANEL SURFACE PAINT	2.49



**Lai Huat (Meng Kee) Motor Pte Ltd**

**160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming**

**Autocity  
575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 01/08/2019 10:11 AM

Full Report

Registration: SLN 1864B

Printed: 01/08/2019 10:11 AM

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		59.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
<b>Total</b>	<b>10 WU/h</b>	<b>89.0</b>	<b>373.80</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	39.05
New Part Painting - Plastic K1R	73.30
Surface-/Blend Paint	4.98
Surface Painting Plastic	16.84
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>171.77</b>

**Spare Parts**

prices as at 2015-06-01/01

Code	Description	Part Number	Supplier	Price SGD
<del>1377</del>	<del>SPACER PART</del>	<del>C00150897</del>		<del>0.00</del>
<del>1379</del>	<del>SPACER</del>	<del>BHN950896</del>		<del>0.00</del>
2581	REAR BUMPER	BHR250221A8N		620.00
2612	R/R COVER CAP	BHN150EK18B		15.00
2622	R/INN BUMPER BRACKET	BHN1502H1A		16.00
2650	RR BUMPER CLAMP KIT	USE SINGLE PARTS		4.00
2720	R/REINF EXTENSION	BJY77041X		125.00
<del>3160</del>	<del>REAR SCREEN BOND KIT</del>	<del>KNGKW12</del>		<del>0.00</del>
3161	REAR SCREEN SEAL	BHN150611C		28.00
3282	R/R OUTER LAMP CPL	B45A51150B		325.00
3482	R/R SIDE PANEL	B6YS7041X		450.00
3786	R/R VENT HOUSING	D35051920A		42.00 ✓
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			1,625.00
u: Used parts	<b>Fixed Sundry Parts Price</b>			100.00
	<b>Total</b>			<b>1,725.00</b>

**Extras**

Code	Description	Price SGD
------	-------------	-----------

**Lai Huat (Meng Kee) Motor Pte  
Ltd  
160 Sin Ming Drive, #04-01,  
#04-02 & #07-03, Sin Ming  
Autocity  
575722**

Claim Reference: TP-GBA 9933U

Assessment number: 70538

Version: 1810

Date calculated: 01/08/2019 10:11 AM

1000

W/S SEALANT SN

**Total Extras**

Full Report

Registration: SLN 1864B

Printed: 01/08/2019 10:11 AM

Price SGD

40.00\*

40.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,625.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		<b>1,725.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 143.0 WU X 42.00 SGD/h	600.60	
Fixed Rate	40.00	
<b>Total of Labour</b>		<b>640.60</b>
<b>Total Of Extras</b>		<b>40.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 89.0 WU X 42.00 SGD/h	373.80	
Material Cost	171.77	
<b>Total Paint Including Material</b>		<b>545.57</b>
<b>Repair Cost Excludes GST</b>		<b>2,951.17</b>
GST (+7.0%)		206.58
<b>Repair Cost Included GST</b>		<b>3,157.75</b>

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

## ...CLAIM SUBFOLDER...(Pending for Survey Report)



















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 <a href="#">Sendback Est</a>	29 May 2019 13:04 <b>S\$2,905.17</b>	29 May 2019 17:26 <a href="#">Edit Adj Rpt</a>	<b>S\$2,951.17</b> <a href="#">Edit Estimates</a>	<b>S\$2,951.17</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	01 Aug 2019 10:14	01 Aug 2019 10:14 <b>S\$46.00</b>	01 Aug 2019 10:14			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	YOKOKAMA SIGNS PTE LTD, Co. Reg. No.: B52958948J								
Main Claimant:	LEE HUNG PENG, ID: S7886033B								
Vehicle Reg. No.:	SLN1864B	Date of Loss:	14/05/2019 19:00 - :59 [24 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202244	Policy/Cover Note No.:	DMCVSN30563418000						
Vehicle Reg. No. (Insured):	GBA9933U	Policy No. (Claimant):	MS005063						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/06/2019]								
Driver/Custodian (Insured):	-- ( / Male), NRIC: 0 Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















## Claim Documents

SLN1864B (SNM19D202244)  
[GBA9933U]  
TP  
LEE HUNG PENG  
May 14 2019 7:00PM  
[YOKOKAMA SIGNS PTE LTD]  
Lai Huat (Meng Kee) Motor Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/05/19 18:01	Accident Statement	Load HTM	<input type="checkbox"/>
2	16/05/19 09:43	Addendum Sheet	Load TIF	<input type="checkbox"/>
3	16/05/19 09:46	Accident Statement Addm. #1	Load HTM	<input type="checkbox"/>
4	16/05/19 11:09	Addendum Sheet	Load TIF	<input type="checkbox"/>
5	16/05/19 11:10	Accident Statement Addm. #2	Load HTM	<input type="checkbox"/>
6	18/05/19 11:02	Addendum Sheet	Load TIF	<input type="checkbox"/>
7	18/05/19 11:04	Accident Statement Addm. #3	Load HTM	<input type="checkbox"/>
8	29/05/19 11:32	Addendum Sheet	Load TIF	<input type="checkbox"/>
9	29/05/19 11:32	Accident Statement Addm. #4	Load HTM	<input type="checkbox"/>
10	29/05/19 13:04	Repairer Estimates	Load HTM	<input type="checkbox"/>
11	01/08/19 10:14	Repairer Estimates Suppl. #1	Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/05/19 11:56	Rear View	Load JPG	<input checked="" type="checkbox"/>
2	29/05/19 11:56	Rear View Left	Load JPG	<input checked="" type="checkbox"/>
3	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
4	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
5	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
6	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
7	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
8	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
9	29/05/19 11:56	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
10	29/05/19 11:56	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
11	29/05/19 11:56	Tyre - Michelin	Load JPG	<input checked="" type="checkbox"/>
12	29/05/19 11:56	Tyre size	Load JPG	<input checked="" type="checkbox"/>
13	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
14	29/05/19 11:56	Rear View Right	Load JPG	<input checked="" type="checkbox"/>
15	29/05/19 11:56	Rear View	Load JPG	<input checked="" type="checkbox"/>
16	29/05/19 11:56	Right View	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
2	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
3	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
4	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
5	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
6	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
7	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
8	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>
9	06/08/19 10:03	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
10	06/08/19 10:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	06/08/19 10:03	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
12	06/08/19 10:03	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
13	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
15	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
16	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
17	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	06/08/19 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	29/05/19 13:04	E-filed GIA report	 Load PDF	
2	29/05/19 13:04	Driver's NRIC & Driving Licence	 Load PDF	
3	29/05/19 13:04	Certificate of Insurance	 Load PDF	
4	29/05/19 13:04	Enquire PARF / COE Rebate for Registered Vehicle	 Load PDF	
5	29/05/19 13:04	Audatex Report	 Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/05/19 17:27	INSD GBA9933U GIA REPORT	 Load PDF	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/19 13:48	Supplementary	 Load PDF	

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/05/19 18:01	Accident Statement	 Load HTM	
2	16/05/19 09:43	Addendum Sheet	 Load TIF	
3	16/05/19 09:46	Accident Statement Addm. #1	 Load HTM	
4	16/05/19 11:09	Addendum Sheet	 Load TIF	
5	16/05/19 11:10	Accident Statement Addm. #2	 Load HTM	
6	18/05/19 11:02	Addendum Sheet	 Load TIF	
7	18/05/19 11:04	Accident Statement Addm. #3	 Load HTM	
8	29/05/19 11:32	Addendum Sheet	 Load TIF	
9	29/05/19 11:32	Accident Statement Addm. #4	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/05/19 09:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/05/19 09:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/05/19 09:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/05/19 09:46	CHASSIS NUMBER	 Load JPG	<input checked="" type="checkbox"/>
5	16/05/19 11:10	SCENE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	15/05/19 12:45	CERTIFICATE OF INSURANCE	 Load TIF	
2	15/05/19 12:45	DRIVER'S NRIC + DRIVING LICENCE	 Load TIF	
3	18/05/19 11:02	OWNER'S NRIC + DRIVING LICENCE	 Load TIF	
4	18/05/19 11:02	Sketch Plan	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009585/KQD3E2

Date: 16/08/2019

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30563418000

Claimant Vehicle No: SLN1864B Insured Vehicle No: GBA9933U

Date of Loss: 14/05/2019 Nature of Claim: TP Claim No: SNM19D202244

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN1864B**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520374480

Reg. Date: 25/04/2017 (Man. Year: 2016) Chassis No: JM6BM42A8G0346071

Colour: Metallic Grey Odometer: 58703 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,625.00	1,625.00	0.00	0.00
Miscellaneous Items	140.00	140.00	0.00	0.00
Labour	640.60	640.60	0.00	0.00
Paintwork Labour	545.57	545.57	0.00	0.00
Towing	0.00	0.00	0.00	0.00
<b>Gross Total (S\$)</b>	<b>2,951.17</b>	<b>2,951.17</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>206.58</b>	<b>206.58</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>3,157.75</b>	<b>3,157.75</b>	<b>0.00</b>	<b>0.00</b>

### INSPECTION

Date of Assignment: 29/05/2019 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 10/06/2019 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #04-01, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 7.0 days

---

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2019)
<b>Parts:</b>	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN1864B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		1,579.00 F	*1,579.00 F
<b>Supplementary #1</b>						
2	1		*RR BUMPER CLAMP KIT	Necessary	4.00 F	*4.00 F
3	1		*R/R VENT HOUSING	Dented	42.00 F	*42.00 F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>1,625.00</b>	<b>1,625.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	MISCELLANEOUS	40.00	40.00
2	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			140.00	140.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT INCLUDING MATERIAL	New	545.57	545.57
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	640.60	640.60
Gross Labour Cost (S\$)			1,186.17	1,186.17

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;