

A Fine Darby Motors Company
 200 Leg. Hl. 141421496 DOT Reg. No. M2 102 1814
 Toll Free Number: 1-800-225-2269

101 Alexandra Road
Prime Barbz Performance Centre
Singapore 159541
Fax: 63747770

280, Tampung Ararat Road
East Coast Centre
Singapore 438186
Fax: 63449773

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's part(s) must be resurveyed and subject to final approval from Insurance Company

Signature: 20081 - X

30 MAY 2019

GST REG. NO : M2 - 0020081 - X

Estimate No. : b1 51351
Date Estimated : 29/05/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

Lok Lian Leong
1 Tanjong Rhu Road
#05-03

Singapore 436879

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ5174D	DX52304	31/01/2013	520iA	0

DESCRIPTION	VALUE
Replacing right front door	850 1,275.00
Spray right front door	196 885.00
To conduct checks on all doors and bootlid central locking system for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	200 X 118.00
Sundries	40 X 80.00
Total Labour is:	2,535.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR	1	1,774.50	1,774.50
SEAL DOOR FRT	1	168.85	168.85
Total Parts :			1,943.35



Labour 1	:	2,535.00
Parts	:	1,943.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	313.48
Grand Total	:	4,791.83

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51351**
Date Estimated : **29/05/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Lok Lian Leong
1 Tanjong Rhu Road
#05-03

Singapore 436879

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ5174D	DX52304	31/01/2013	520iA	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To make good the front right door and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job	850.00	0	850.00
To respray front right door.	796.00	0	796.00
To conduct checks on all doors and bootlid central locking system for proper function.	150.00	0	150.00
Sundries	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
				#
				#
				#

QD	END PARTY	DATE
	Taufik LK	29/5/19 3

Total Labour : 1,836.00 ✓
Total Parts :
Total Repair Costs less Excess: 1,836.00
GST @7%: 128.52
Grand Total : 1,964.52

LOSS OF USE = \$100 X 3 DAYS