

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 51199**
Date Estimated : **15/05/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

REPAIR FOR -
Wong Loke Ching
85 Yishun Street 81
#07-06

Singapore 768447

- ACCOUNT - 100
NTUC Income Ins Co-operative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556
Motor Department

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD2439E	3G76260	10/08/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace bumper and attachments include knocking out dents caused by the accident	850.00		850.00
To spray paint rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function	150.00		150.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR TRIM UNDERRIDE PROTECTION (X L	105.40	1.00		105.40
REAR BUMPER PANEL PRIMED	770.80	1.00		770.80
REAR BUMPER MIDDLE TRIM PANEL (PDC)	242.80	1.00		242.80
REAR BUMPER TRIM BOTTOM (LINES)	216.00	1.00		216.00
# EXPANDING RIVET BLACK *	1.35	10.00		13.50

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,348.50
Total Labour & Parts :	3,512.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,512.50
GST @7%:	245.88
Grand Total :	3,758.38