

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP 111

Cecilia.

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

ESTIMATE

Repair Code : CLM15271

Date in : 27/05/2019

Vehicle Num. : SLU2419K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31226854/LEB5926868

Contact : 66550005 93872220

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>deformed</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>deformed.</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>cracked.</i>	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R <i>deformed.</i>	2	195.00	✓ 390.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	✓ 46.00
REAR END PANEL <i>Dented</i>	1	415.60	✓ 415.60
REAR END PANEL ANTENNA SENSOR <i>cracked</i>	1	60.10	✓ 60.10
REAR END PANEL BUZZLE SENSOR	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH <i>deformed</i>	1	98.00	✓ 98.00
REAR EXHAUST ALUMINIUM HEAT SHIELD <i>cracked.</i>	1	55.00	✓ 55.00
REAR EXHAUST CHROME TAIL PIPE <i>new</i>	1	135.00	✗ 135.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	✗ 33.00
REAR EXHAUST SILENCER BOX <i>new</i>	1	517.70	✗ 517.70
REAR EXHAUST SILENCER BOX GASKET	1	48.30	✗ 48.30
REAR FENDER ARCH GARNISH L/R <i>cracked</i>	2	195.00	✓ 390.00
REAR FENDER INNER TRIM GARNISH L/R <i>deformed</i>	2	295.00	✓ 590.00
REAR FLOOR JACK PANEL <i>rip</i>	1	95.00	✗ 95.00
REAR FLOOR PANEL <i>Buckled.</i>	1	1060.00	✓ 1,060.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 93872220

ESTIMATE

Repair Code : CLM15271

Date in : 27/05/2019

Vehicle Num. : SLU2419K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31226854/LEB5926868

REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>cracked</i>	1	485.30	✓ 485.30
REAR FLOOR PANEL CROSS MEMBER (NO:1) <i>Bent</i>	1	180.00	✓ 180.00
REAR FLOOR PANEL CROSS MEMBER (NO:2) <i>Repair</i>	1	250.00	X 250.00
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Del</i>	1	430.30	<i>306</i> 430.30
REAR HYBRID INVERTER AIR BLOWER <i>cracked.</i>	1	540.00	✓ 540.00
REAR HYBRID INVERTER AIR DUCT <i>cracked</i>	1	98.00	✓ 98.00
REAR HYBRID INVERTER BLOWER AIR DUCT	1	138.70	✓ 138.70
• REAR HYBRID INVERTER TOP COVER <i>Bent</i>	1	397.70	✓ 397.70
REAR HYBRID INVERTER TRAY GARNISH <i>Del</i>	1	285.40	✓ 285.40
REAR LH BODY EXTENSION UPPER PANEL <i>Repair</i>	1	160.00	X 160.00
REAR NUMBER PLATE LAMP L/R <i>Item</i>	2	25.80	X 51.60
REAR TAILGATE <i>Dist</i>	1	953.30	✓ 953.30
REAR TAILGATE 'HYBRID' EMBLEM <i>Item</i>	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM <i>Item</i>	1	56.20	✓ 56.20
REAR TAILGATE INNER PULL GARNISH <i>He New</i>	1	27.50	X 27.50
REAR TAILGATE INNER TRIM GARNISH <i>cracked</i>	1	153.40	✓ 153.40
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	180.00	✓ 180.00
REAR TAILGATE MECHANISM LOCK STRIKER <i>Not New</i>	1	27.50	X 27.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 93872220

ESTIMATE

Repair Code : CLM15271

Date in : 27/05/2019

Vehicle Num. : SLU2419K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31226854/LEB5926868

REAR TAILGATE OPENER BUTTON SENSOR <i>Ne m</i>	1	175.50	X	175.50
REAR TAILGATE OUTER GARNISH <i>Ne m</i>	1	220.00	X	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>Ne m</i>	1	25.00	X	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R <i>Ne m</i>	2	38.50	40.	77.00
REAR TAILGATE REFLECTOR L/R <i>cracked</i>	2	413.20	✓	826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>Ne m</i>	2	18.50	X	37.00
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	96.80	✓	96.80
REAR TAILGATE WINDSCREEN INNER SEAL <i>10447</i>	2	50.00	✓	100.00
REAR TAILGATE WINDSCREEN MOULDING <i>8357.60</i>	2	50.00	✓	100.00
REAR TAILLAMP L/R <i>cracked</i>	2	474.60	✓	949.20

Subtotal before discount 12,411.40

Percentage discount 20% 2,482.28

Sub-total 1 9,929.12

REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Ne m</i>	1	30.00	10	30.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET	2	30.00	✓	60.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>Ne m</i>	2	30.00	✓	60.00
REAR FLOOR PANEL INSULATOR MAT <i>Ne m</i>	1	300.00	20	300.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 93872220

ESTIMATE

Repair Code : CLM15271

Date in : 27/05/2019

Vehicle Num. : SLU2419K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31226854/LEB5926868

REAR NUMBER PLATE	<i>Not Nec</i>	1	25.00	X	25.00
REAR NUMBER PLATE HOLDER	<i>Nec</i>	1	50.00	X	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	<i>Nec</i>	1	100.00	30	100.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>Not Nec</i>	660	40.00	X	40.00
REAR TAILGATE REVERSE CAMERA	<i>Not Nec</i>	1	400.00	X	400.00
REAR TAILGATE SPOILER CLIPS - SET	<i>Not nec</i>	1	50.00	X	50.00
REAR TAILGATE WINDSCREEN SEALANT	<i>Nec</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET	<i>Nec</i>	2	30.00	40	60.00
Subtotal before discount					1,485.00
Percentage discount 0%					0.00
Sub-total 2					1,485.00
Parts-total					11,414.12

LABOUR

To reset system after repair works	100.00
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30.00
To remove, reinstall tailgate windscreen	✓ 120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1200.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	80.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 93872220

ESTIMATE

Repair Code : CLM15271

Date in : 27/05/2019

Vehicle Num. : SLU2419K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31226854/LEB5926868

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1400 2,000.00

To mount vehicle on to Car 'O' Liner.

X 300.00

To apply anti-rust chemical on repaired and replaced panel.

/ 100.00

To remove, reinstall tailgate mechanism and check for function

/ 80.00

To remove and reinstall hybrid converter unit, hose bracket and other attachment parts. Diagnosis, repair and check for function.

2790

580 1,000.00

Labour Total

5,830.00

Parts & Labour Total

17,244.12

*** This is a computer-generated document which requires no signature.***

page 5

total: 12807.60

w/s 12.2K

11 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1020
11 Days