

ESTIMATE TO REPAIR

VEHICLE NO. : SMA 4129 C
 MAKE : HONDA
 MODEL : FIT 1.3GF CVT
 YEAR : 2018
 CHASSIS NO : GK31318294

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 29-May-19
 DATE OF ACCIDENT : 27-May-19
 THIRD PARTY REF : AN 9139 P / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 492.70
1 pc	N/S Rear Bumper Retainer				\$ 16.90
1 pc	N/S Rear Bumper Garnish				\$ 20.70
10 pcs	Rear Bumper Clips		\$ 3.90		\$ 39.00
1 pc	Rear End Panel				\$ 390.00
1 pc	N/S Taillamp				\$ 237.40
1 pc	Tailgate				\$ 850.00
1 pc	Tailgate FIT Emblem				\$ 35.10
1 pc	Rear Windscreen Moulding				\$ 95.20
					\$ 2,177.00
	Less 20%				\$ 435.40
					\$ 1,741.60
1 pc	Rear Number Plate	S.Nett			\$ 40.00
1 pc	Rear Number Plate Seal	S.Nett			\$ 60.00
1 pc	Rear Windscreen Sealant	S.Nett			\$ 40.00
	To putty and spray painting				\$ 800.00
	To remove and refix rear windscreen glass				\$ 120.00
	To transfer tailgate fittings				\$ 80.00
	To anti-rust				\$ 50.00
	Labour Charges				\$ 600.00
TG/RA-	Total				\$ 3,531.60

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd