

2/00/2019

ASS. REC. BY:

REF: CS/INC19009584 / Rtd3m Special Instruction:

Surveyor: RahatASSIGNMENT (Office)From (Person): MT Survey of INC Date/Time: 10.06am @ 24/5/19

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLW 8061H Insured: SJH 3041Bat Workshop m/s pegusus Tel: 6513 7748of 74 Kien Teck RoadPolicy No: _____ Claim No: MT/1046470-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/05/2019
(Client's Record)CA / REV / REP. / REV 24 HRS ^(up) H.O.D. Endorsement: _____Date/Time: 10.11am @ 24/5/19 Person Contacted: Mee Key Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Johnmoti ✓</u>
	<u>SLW 8061H - X</u>
	<u>SJH 3041B - X</u>
	<u>Done repair will sent finalise.</u>

Signature P. Rame

REF:

72009

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 8061H

at Workshop m/s: PEHASUS

of 74, KIAN TCK

Insured: NTUC

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLW 8061H Yr Regn: 2018 / MAR

Type: C M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 3 SEDAN 1.5 AT C.C. 1496

Colour: GRY A/C: Insured / Std / NI / NA

Sp. Reading: 100687 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BN22A8H6162251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/05/19 D.O.I. 29/05/19 2.26pm

Survey held at PEHASUS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/9 @ 11:34 am Email confirm \$2750/- Cred: 13650.60, 83%

Date/Time, File Pass to?

☐ : Preli. Report

1) 19/9 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

\$ * RS. SI

Photos

Others

TOTAL

250

Report Format :

TP

Lump sum / I.B.I: (\$) 2750/-

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Wednesday, 29 May 2019 10:25 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 29/05/2019

Hi LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: MTSurvey
Sent: Wednesday, 29 May 2019 10:06 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 29/05/2019

Re-send

From: MTSurvey
Sent: Wednesday, 29 May 2019 10:01 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 29/05/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1	Jeff Lin	MT/1045936-002	SLT758A	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Mee Key / 5513 7748	14:00-16:00	SJN2804S	23/05/2019
2	Jeff Lin	MT/1046470-001	SLW8061H	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Kala / 65137748		SJH3041B	28/05/2019
3	David Phua	MT/1044436-002	SMD2439E	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	CAROLINE / 63190174	10:00-12:00	SLM9488G	13/05/2019
4	Azhari	MT/0963852-002	GBF121D	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		SJH3026X	02/10/2017
5	Muhammad Airwan	MT/1046282-002	SLH7639C	TRANS EUROKARS PTE LTD	27A TANJONG PERIURU SINGAPORE 609042	EVA / 6331 0683		SKU4273L	27/05/2019
6	Ivan Lim	PC/0634039	XE3835C	SNG AH TEE MTR	3 PIONEER RD NORTH #01-18	DARREN @ 62685183		PROPERTY	12/04/2019

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 19 September 2019 11:34 AM
To: Vivian Tan
Cc: Pegasus Engineering; lawrencesim@pegasusengrg.com.sg
Subject: RE: Finalise For SLW8061H (DOA 28/05/2019)

Dear Vivian,

Confirm finalized lump sum \$2,750, 8 working days

Please submit your documents to NTUC directly

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Tan <vivian.pegasusengrg@gmail.com>
Sent: Tuesday, 17 September, 2019 2:25 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; ar_claims@pegasusengrg.com.sg; lawrencesim@pegasusengrg.com.sg
Subject: RE: Finalise For SLW8061H (DOA 28/05/2019)

WITHOUT PREJUDICE

Dear Mr. Rasul & LKK Admin,

Finalise amount @ Lump Sum \$2,750.00 @ 08 working days.

Parts - \$1,310.40

SN - \$275.00

Labour - \$1,840.00

Total - \$3,425.00 (Less 20%)

--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 16:23
Date Of Accident	28/05/2019 05:15
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE BEDOK NORTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW8061H
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96433241
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	LEE KOK WAH
NRIC No	S6929629G
Date Of Birth	22/09/1969
Occupation	OUTDOOR
Date Of Driving Pass	04/08/1987
Driving Experience	31 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96433241
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 505 JELAPANG ROAD #11-432
Postcode	670505
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 28 MAY 2019 AT ABOUT 0516HRS, I WAS DRIVING MY PASSENGER TO AIRPORT. JUST BEFORE BEDOK NORTH AVE 3, VEH B SJH3041B SIDE SWIPED MY LEFT PORTION OF MY CAR. I WAS ON THE MIDDLE LANE OF 3 LANES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH3041B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD RUZAINI BIN ZAILANI
NRIC/Passport Number	S8709678E
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

FRONT AND DRIVER'S DOOR

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


28.05.2019
0920hrs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Kyari Yong

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28-05-2019 at about 0516 hrs I was driving my passenger to airport just before Bedok North Ave 3 Vch B SJH3041B side swiped my left portion of my car. I was on the middle lane of 3 lanes.
No one was injured

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time
28-05-2019
0920 hrs

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.: Kevin Yong



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : KALAH VARATHARAJOO Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 28/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR LHS <i>repair</i>	1	1,245.0000	1,245.00
2	FRONT DOOR OUTER CHROME MOULDING LHS <i>X sue</i>	1	135.0000	135.00
3	FRONT DOOR TOP REVEAL MOULDING LHS <i>X sue</i>	1	185.0000	185.00
4	FRONT DOOR WEATHERSTRIP LHS <i>X sue</i>	1	188.0000	188.00
5	FRONT DOOR OUTER HANDLE LHS <i>repair</i>	1	213.0000	213.00
6	FRONT DOOR LOCK LHS <i>X sue</i>	1	168.0000	168.00
7	FRONT DOOR REGULATOR LHS <i>X sue</i>	1	158.0000	158.00
8	FRONT DOOR REGULATOR MOTOR LHS <i>X sue</i>	1	195.0000	195.00
9	FRONT DOOR INNER TRIM BOARD LHS <i>X sue</i>	1	695.0000	695.00
10	FRONT DOOR INNER TRIM BOARD CLIPS LHS <i>X sue</i>	10	5.0000	50.00
11	FRONT DOOR LOCK HANDLE CAP LHS <i>X sue</i>	1	58.0000	58.00
12	REAR DOOR LHS <i>repair bt</i>	1	1,140.0000	1,140.00
13	REAR DOOR OUTER CHROME MOULDING LHS <i>X sue</i>	1	135.0000	135.00
14	REAR DOOR TOP REVEAL MOULDING LHS <i>X sue</i>	1	185.0000	185.00
15	REAR DOOR WEATHERSTRIP LHS <i>X sue</i>	1	188.0000	188.00
16	REAR DOOR OUTER HANDLE LHS <i>X sue</i>	1	213.0000	213.00
17	REAR DOOR LOCK LHS <i>X sue</i>	1	168.0000	168.00
18	REAR DOOR REGULATOR LHS <i>X sue</i>	1	158.0000	158.00
19	REAR DOOR REGULATOR MOTOR LHS <i>X sue</i>	1	195.0000	195.00
20	REAR DOOR INNER TRIM BOARD LHS <i>X sue</i>	1	695.0000	695.00
21	REAR DOOR INNER TRIM BOARD CLIPS LHS <i>X sue</i>	10	5.0000	50.00
22	REAR DOOR LOCK HANDLE CAP LHS <i>X sue</i>	1	58.0000	58.00
23	CENTER PILLAR LHS <i>X sue</i>	1	989.0000	989.00

C/F 0.00

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : KALAH VARATHARAJOO Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	---

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 28/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	FRONT FENDER LHS <i>repair</i>	1	395.0000	395.00
25	SIDE MIRROR LHS <i>new</i>	1	498.0000	498.00
26	SIDE MIRROR COVER LHS <i>repair</i>	1	155.0000	155.00
27	SIDE MIRROR LIGHT LHS <i>XSC</i>	1	105.0000	105.00
28	REAR FENDER LHS <i>repair</i>	1	1,185.0000	1,185.00
29	REAR BUMPER <i>repair</i>	1	1,075.0000	1,075.00
30	REAR BUMPER SIDE RETAINER LHS <i>XSC</i>	1	55.0000	55.00
31	LESS 20% FOR ITEM 1 - 30	1	-2,186.4000	-2,186.40
32	FRONT WHEEL HUP CAP LHS <i>SC</i>	1	125.0000	125.00
33	FRONT RIM LHS <i>repair</i>	1	500.0000	500.00
34	FRONT TYRE LHS <i>XSC</i>	1	400.0000	400.00
35	REAR FENDER CLEAR STICKER LHS <i>new</i>	1	25.0000	25.00
36	REAR WHEEL HUP CAP LHS <i>SC</i>	1	125.0000	125.00
37	REAR TYRE LHS <i>XSC</i>	1	400.0000	400.00
38	REAR RIM LHS <i>repair</i>	1	500.0000	500.00
39	TO REMOVE & TRANSFER DOOR MECHANISM TO THE NEW DOOR <i>XSC</i>	1	380.0000	380.00
40	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT ON THE AFFECTED AREAS	1	150.0000	150.00
41	TO KNOCKING & PANEL BEATING	1	2,500.0000	2,500.00
42	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	1	2,200.0000	2,200.00
43	TO CONDUCT WHEEL ALLIGNMENT	1	150.0000	150.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : KALAH VARATHARAJOO
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Third Party Insurer : NTUC
Model : MAZDA 3	Date of Accident : 28/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
44	TO REMOVE & REPLACE TYRE & RIM <i>Xny</i>	1	100.0000	100.00
45	TO CONDUCT WHEEL BALANCING <i>Xny</i>	1	100.0000	100.00

30/5/19

Repair
Hp 90010068

8 days

4/5

29/05/19 @ 1440

Resury after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey *C* after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total 16,400.60
GST(7.00%) 1,148.04
Total (SGD) 17,548.64

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer in Charge : KALAH VARATHARAJOO
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn: :
Tel :
Fax No. :

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Third Party Insurer : NTUC
Model : MAZDA 3		Date of Accident : 28/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT DOOR LHS <i>repair</i>	1	1,245.0000	1,245.00
2	FRONT DOOR OUTER CHROME MOULDING LHS <i>X</i>	1	135.0000	135.00
3	FRONT DOOR TOP REVEAL MOULDING LHS <i>X</i>	1	185.0000	185.00
4	FRONT DOOR WEATHERSTRIP LHS <i>X</i>	1	188.0000	188.00
5	FRONT DOOR OUTER HANDLE LHS <i>repair</i>	1	213.0000	213.00
6	FRONT DOOR LOCK LHS <i>X</i>	1	168.0000	168.00
7	FRONT DOOR REGULATOR LHS <i>X</i>	1	158.0000	158.00
8	FRONT DOOR REGULATOR MOTOR LHS <i>X</i>	1	195.0000	195.00
9	FRONT DOOR INNER TRIM BOARD LHS <i>X</i>	1	695.0000	695.00
10	FRONT DOOR INNER TRIM BOARD CLIPS LHS <i>X</i>	10	5.0000	50.00
11	FRONT DOOR LOCK HANDLE CAP LHS <i>X</i>	1	58.0000	58.00
12	REAR DOOR LHS <i>repair</i>	1	1,140.0000	1,140.00
13	REAR DOOR OUTER CHROME MOULDING LHS <i>X</i>	1	135.0000	135.00
14	REAR DOOR TOP REVEAL MOULDING LHS <i>X</i>	1	185.0000	185.00
15	REAR DOOR WEATHERSTRIP LHS <i>X</i>	1	188.0000	188.00
16	REAR DOOR OUTER HANDLE LHS <i>X</i>	1	213.0000	213.00
17	REAR DOOR LOCK LHS <i>X</i>	1	168.0000	168.00
18	REAR DOOR REGULATOR LHS <i>X</i>	1	158.0000	158.00
19	REAR DOOR REGULATOR MOTOR LHS <i>X</i>	1	195.0000	195.00
20	REAR DOOR INNER TRIM BOARD LHS <i>X</i>	1	695.0000	695.00
21	REAR DOOR INNER TRIM BOARD CLIPS LHS <i>X</i>	10	5.0000	50.00
22	REAR DOOR LOCK HANDLE CAP LHS <i>X</i>	1	58.0000	58.00
23	CENTER PILLAR LHS <i>X</i>	1	989.0000	989.00

1140-W
228-W
912-W



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : KALAH VARATHARAJOO
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Thirld Party Insurer : NTUC
Mndel : MAZDA 3		Date of Accident : 28/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	FRONT FENDER LHS <i>repair</i>	1	395.0000	395.00
25	SIDE MIRROR LHS <i>new</i>	1	498.0000	498.00
26	SIDE MIRROR COVER LHS <i>repair</i>	1	155.0000	155.00
27	SIDE MIRROR LIGHT LHS <i>X su</i>	1	105.0000	105.00
28	REAR FENDER LHS <i>repair</i>	1	1,185.0000	1,185.00
29	REAR BUMPER <i>repair</i>	1	1,075.0000	1,075.00
30	REAR BUMPER SIDE RETAINER LHS <i>X su</i>	1	55.0000	55.00
31	LESS 20% FOR ITEM 1 - 30	1	-2,186.4000	-2,186.40
32	FRONT WHEEL HUP CAP LHS <i>sc</i>	1	125.0000	125.00
33	FRONT RIM LHS <i>repair</i>	1	500.0000	500.00
34	FRONT TYRE LHS <i>X</i>	1	400.0000	400.00
35	REAR FENDER CLEAR STICKER LHS <i>new</i>	1	25.0000	25.00
36	REAR WHEEL HUP CAP LHS <i>sc</i>	1	125.0000	125.00
37	REAR TYRE LHS <i>X su</i>	1	400.0000	400.00
38	REAR RIM LHS <i>repair</i>	1	500.0000	500.00
39	TO REMOVE & TRANSFER DOOR MECHANISM TO THE NEW DOOR <i>X</i>	1	380.0000	380.00
40	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT ON THE AFFECTED AREAS	1	150.0000	150.00
41	TO KNOCKING & PANEL BEATING	1	2,500.0000	2,500.00
42	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	1	2,200.0000	2,200.00
43	TO CONDUCT WHEEL ALLIGNMENT	1	150.0000	150.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800
Officer in Charge : KALAH VARATHARAJOO
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1359	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLW8061H	Chassis No. : JM6BN22A8H0162251	Third Party Insurer : NTUC
Model : MAZDA 3		Date of Accident : 28/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
44	TO REMOVE & REPLACE TYRE & RIM <i>X^{an}</i>	1	100.0000	100.00
45	TO CONDUCT WHEEL BALANCING <i>X^{an}</i>	1	100.0000	100.00

P - \$ 1310.40
SN - \$ 275.00
C - \$ 1840.00

\$ 3425.40

45 - 2750/-

1840

Panel
HP 90010068

8 days

4/5

29/05/19 @ 1440

Resury after paint

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	16,400.80
GST(7.00%)	1,148.04
Total (SGD)	17,548.64

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19009584/R1td3n2
73 BRAS BASAH ROAD Date: 20-09-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 3041B	Veh. Inspected	SLW 8061H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1046470-001	Excess (\$)	0.00
Assign From	MT SURVEY	Assign Date	29/05/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 SEDAN 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JM6BN22A8H0162251	Colour	GREY
Odometer	100687 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/05/2019	Inspect Date / Time	29/05/2019 (02:26 PM)
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 8061H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR LHS	TO REPAIR SEE LABOUR	1,245.00	-
1	FRONT DOOR OUTER CHROME MOULDING LHS	SERVICEABLE	135.00	-
1	FRONT DOOR TOP REVEAL MOULDING LHS	SERVICEABLE	185.00	-
1	FRONT DOOR WEATHERSTRIP LHS	SERVICEABLE	188.00	-
1	FRONT DOOR OUTER HANDLE LHS	TO REPAIR SEE LABOUR	213.00	-
1	FRONT DOOR LOCK LHS	SERVICEABLE	168.00	-
1	FRONT DOOR REGULATOR LHS	SERVICEABLE	158.00	-
1	FRONT DOOR REGULATOR MOTOR LHS	SERVICEABLE	195.00	-
1	FRONT DOOR INNER TRIM BOARD LHS	SERVICEABLE	695.00	-
10	FRONT DOOR INNER TRIM BOARD CLIPS LHS @\$5.00	SERVICEABLE	50.00	-
1	FRONT DOOR LOCK HANDLE CAP LHS	SERVICEABLE	58.00	-
1	REAR DOOR LHS	BENT	1,140.00	1,140.00
1	REAR DOOR OUTER CHROME MOULDING LHS	SERVICEABLE	135.00	-
1	REAR DOOR TOP REVEAL MOULDING LHS	SERVICEABLE	185.00	-
1	REAR DOOR WEATHERSTRIP LHS	SERVICEABLE	188.00	-
1	REAR DOOR OUTER HANDLE LHS	SERVICEABLE	213.00	-
1	REAR DOOR LOCK LHS	SERVICEABLE	168.00	-
1	REAR DOOR REGULATOR LHS	SERVICEABLE	158.00	-
1	REAR DOOR REGULATOR MOTOR LHS	SERVICEABLE	195.00	-
1	REAR DOOR INNER TRIM BOARD LHS	SERVICEABLE	695.00	-
10	REAR DOOR INNER TRIM BOARD CLIPS LHS @\$5.00	NOT NECESSARY	50.00	-
1	REAR DOOR LOCK HANDLE CAP LHS	SERVICEABLE	58.00	-
1	CENTER PILLAR LHS	SERVICEABLE	989.00	-
1	FRONT FENDER LHS	TO REPAIR SEE LABOUR	395.00	-
1	SIDE MIRROR LHS	SCRATCHED	498.00	498.00
1	SIDE MIRROR COVER LHS	TO REPAIR SEE LABOUR	155.00	-
1	SIDE MIRROR LIGHT LHS	SERVICEABLE	105.00	-
1	REAR FENDER LHS	TO REPAIR SEE LABOUR	1,185.00	-

Report Ref No. CS/INC19009584/R1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,075.00	-
1	REAR BUMPER SIDE RETAINER LHS	SERVICEABLE	55.00	-
	LESS 20% DISCOUNT		-2,186.40	-327.60
			8,745.60	1,310.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL HUP CAP LHS (SN)	SCRATCHED	125.00	125.00
1	FRONT RIM LHS (SN)	TO REPAIR SEE LABOUR	500.00	-
1	FRONT TYRE LHS (SN)	SERVICEABLE	400.00	-
1	REAR FENDER CLEAR STICKER LHS (SN)	NECESSARY	25.00	25.00
1	REAR WHEEL HUP CAP LHS (SN)	SCRATCHED	125.00	125.00
1	REAR TYRE LHS (SN)	SERVICEABLE	400.00	-
1	REAR RIM LHS (SN)	TO REPAIR SEE LABOUR	500.00	-
			2,075.00	275.00
	<u>LABOUR</u>			
	TO REMOVE & TRANSFER DOOR MECHANISM TO THE NEW DOOR.	NOT NECESSARY	380.00	-
	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT ON THE AFFECTED AREAS.		150.00	80.00
	TO KNOCKING & PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR LHS,FRONT DOOR OUTER HANDLE LHS,FRONT FENDER LHS,SIDE MIRROR COVER LHS,REAR FENDER LHS,REAR BUMPER,FRONT RIM LHS AND REAR RIM LHS.		2,500.00	600.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		2,200.00	1,100.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO REMOVE & REPLACE TYRE & RIM.	NOT NECESSARY	100.00	-
	TO CONDUCT WHEEL BALANCING.	NOT NECESSARY	100.00	-
			5,580.00	1,840.00
	GRAND TOTAL		16,400.60	3,425.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,750.00

Report Ref No. CS/INC19009584/R1td3n2



Report Ref No. CS/INC19009584/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.