



19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SBR9818E	MODEL : FORESTER 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0222/2019	YEAR: 22-MAR-2019
ENGINE NO: FB20YF33887	CHASSIS NO: JF1SK7KL5KG006565
DOA: 28/05/2019	TOA: 0849HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRONT BUMPER,FRT PANEL & BONNET	\$1250.00 7501
2.	RESPRAY FRONT BUMPER,FRT PANEL & BONNET	\$1000.00 8001
3.	REMOVE & REFIX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIR	\$171.00 ✓
4.	TO CONDUCT FRONT LIGHTING TEST	\$28.00 ✓
5.	SUNDRIES	\$100.00 301
6.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00 ✓
7.		
8.		
9.		
10.		
Total Labour		\$2674.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Menner CLKK
HP / EMAIL:	/
BEFORE PAINT:	Yes
DAYS GIVEN:	6 days

Not with aia

Pushing 84 paint

At NLS



Fax: 62564315

6 days

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

Date 05 / 29 / 2019

001 / 003

Name	QUOTATION FOR SBR9818E	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S14
		Body Model	SK7AKFL
		Vin-Code	JF1SK7KL5KG006565

Part Number	Part Code Name	Part Code	Q'ty	Price	
57702SJ000	BUMPER FACE-FRONT	FIG-590 57704	1	<i>Ref/CM</i> 504.00	✓
57711SJ0609P	BACK BEAM COMPLETE-FRONT	FIG-590 57711	1	324.00	?
57705SJ010	ENERGY ABSORBER-FRONT BUMPER	FIG-590 57705	1	72.00	?
57707SJ040	BRACKET-ACTIVE GRILLE AIR SHUT TER,FRONT	FIG-590 57707AP	1	43.20	?
57705SJ030	ENERGY ABSORBER-LOWER	FIG-590 57705C	1	39.60	?
57707SJ000	BRACKET-FRONT BUMPER CORNER,RI GHT	FIG-590 57707AF	1	<i>Ref</i> 36.00	X
57707SJ010	BRACKET-FRONT BUMPER CORNER,LE FT	FIG-590 57707AG	1	<i>Ref</i> 36.00	✓
57707SJ020	BRACKET-FRONT BUMPER SIDE,RIGH T	FIG-590 57707F	1	<i>Ref</i> 12.30	X
57707SJ030	BRACKET-FRONT BUMPER SIDE,LEFT	FIG-590 57707G	1	<i>Ref</i> 12.30	✓
57734SJ020	BUMPER GUARD-FRONT	FIG-590 57734	1	180.00	?
57731SJ000	COVER-FRONT BUMPER	FIG-590 57731	1	5.40	?
57731SJ160	COVER-FOG LIGHT,RIGHT	FIG-590 84953N	1	<i>Ref</i> 122.40	X
X 57731SJ170 <i>NS</i>	COVER-FOG LIGHT,LEFT	FIG-590 84953O	1	<i>CM</i> 122.40	✓
53029SJ0009P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	<i>Ref</i> 370.80	✓
91121SJ030	FRONT GRILLE ASSEMBLY,UPPER	FIG-911 91121E	1	<i>Ref/CM</i> 504.00	✓
91121SJ130	FRONT GRILLE ASSEMBLY,LOWER	FIG-911 91121F	1	<i>CM</i> 538.20	✓
		Page-Total		2,922.60	

Memo

Grand Total
10,998.20

--

Tel

Estimate

Date 05 / 29 / 2019

002 / 003

Name	QUOTATION FOR SBR9818E	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S14
		Body Model	SK7AKFL
		Vin-Code	JF1SK7KL5KG006565

Part Number	Part Code Name	Part Code	Q'ty	Price	
91165SJ010	BRACKET-GRILL LOWER	FIG-911 91165JA	1	32.40	?
84002SJ020	LAMP ASSEMBLY-HEAD RIGHT	FIG-840 84001A	1	2,380.00	✓
84002SJ030	LAMP ASSEMBLY-HEAD LEFT	FIG-840 84001B	1	2,380.00	✓
84501SJ000	FOG LIGHT ASSEMBLY-FRONT RIGHT	FIG-845 84501	1	367.20	X
84501SJ010	FOG LIGHT ASSEMBLY-FRONT LEFT	FIG-845 84501A	1	367.20	?
57229SJ0009P	HOOD COMPLETE-FRONT	FIG-550 57220	1	1,008.00	✓
57310SJ020	LOCK ASSEMBLY-FRONT HOOD	FIG-550 57310	1	72.00	?
57311AG010	STRIKER-FRONT HOOD	FIG-550 57311	1	36.00	?
57260SJ0009P	HINGE COMPLETE-FRONT HOOD,RIGHT	FIG-550 57260	1	54.00	✓
57260SJ0109P	HINGE COMPLETE-FRONT HOOD,LEFT	FIG-550 57260A	1	54.00	✓
90815SJ100	INSULATOR-FRONT HOOD	FIG-956 90815B	1	108.00	X
86636SJ120W6	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,RIGHT	FIG-877 86636NA	1	54.00	X
86636SJ130W6	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,LEFT	FIG-877 86636OA	1	54.00	X
86636SJ100	NOZZLE-LAMP WASHER,RIGHT	FIG-877 86636N	1	79.20	X
86636SJ110	NOZZLE-LAMP WASHER,LEFT	FIG-877 86636O	1	79.20	?
57120SJ0009P	FENDER COMPLETE-FRONT,RIGHT	FIG-540 57110	1	367.20	X
		Page-Total		7,492.40	

Memo

Grand Total
10,998.20

--

Tel

Estimate

Date 05 / 29 / 2019

003 / 003

Name	QUOTATION FOR SBR9818E	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S14
		Body Model	SK7AKFL
		Vin-Code	JF1SK7KL5KG006565

Part Number	Part Code Name	Part Code	Q'ty	Price
57120SJ0109P	FENDER COMPLETE-FRONT,LEFT	FIG-540 57110A	1	367.20
59110SJ000	MUD GUARD,FRONT RIGHT	FIG-541 59110B	1	108.00
59110SJ010	MUD GUARD,FRONT LEFT	FIG-541 59110C	1	108.00
		Page-Total		583.20
		Sub-Total		10,998.20
		Total		10,998.20
		Tax		0.00
		Grand Total		10,998.20

7
X
X

Memo

Grand Total
10,998.20

13,672.20

--

Tel
