

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 07 Jun 2019

Preliminary Advice

Insured Vehicle No	: XD8817C		
TP Vehicle No	: SJG4823K	Accident Date	: 21/03/2019
Make	: HONDA STREAM	Assignment Date	: 30/05/2019
Date of Inspection	: 04/06/2019	Est. Duration of Repair	: 6 days
Inspection At	: Ngs Motorsport Pte Ltd (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK AutoPoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,063.28
Revised Amount	:S\$	3,427.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,427.04
Lump Sum Repair	:S\$	2,750.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP